SGI

Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A382873

Station #: 71821

Station Name: Lonestar Auto Repair & Towing

Technician #: 88286

Technician Name: Leonard Lanegraff

Signing Officer #: 87961

Signing Officer Name: Cody Hobelsberger

Customer Details:

Name: PERNINTSKY FARMS LTD

Address: BOX 700, WILKIE, Saskatchewan, S0K 4W0

Inspection Completed Date: 28Oct2026

Inspection Expiry Date: 31Oct2027

Vehicle Details:

VIN: 1W11DFJT29B250268

Hubometer Reading:

Year: 2009

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

SGI

Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71821

Station Name: Lonestar Auto Repair & Towing

Technician #: 88286

Technician Name: Leonard Lanegraff

Signing Officer #: 87961

Signing Officer Name: Cody Hobelsberger

Customer Details:

Name: PERNINTSKY FARMS LTD

Address: BOX 700, WILKIE, Saskatchewan, S0K 4W0

Vehicle Details:

VIN: 1W11DFJT29B250268

Hubometer Reading:

Year: 2009

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	MULTIPLE LIGHTS OUT
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments	
x				Hyd Brake System/Components (3.1)		
		x		Air Brake System/Components (3.2)	RR ABS SENSOR	
x				Elec Brake System/Components (3.1)		
x				Wheel Bearings (9)		
		x		Tires/Wheels (9)	RMO	
x				Self-Steering Axle (2&4)		
x				Frame/Crossmembers/Mounts (8)		
x				Suspension/Axles (2)		
x				Exhaust/Emission System (1)		
x				Sliding Axle Assembly (if equipped) (8)		

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 7 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 6 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in
Wheel3-On : Tire Tread Depth: 6 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in
Wheel4 : Tire Tread Depth: 6 mm
Brake(1): No Brake
N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 12 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in
Wheel3-On : Tire Tread Depth: 15 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in
Wheel4 : Tire Tread Depth: 9 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 9 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 9 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in
Wheel3-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 69.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 10 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A382873	Inspection Completed Date: 28Oct2026