

03974229

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspect
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-965-0920

Manitoba



Date Inspection Started 08 01 2016
Date Inspection Completed 09 01 2016
Inspection Expiry Date 31 01 2017

Station Number A64105 Station Name Road Warner Mobile Repair Inc
Mechanic Number M911816 Mechanic Signature [Signature] Station Phone Number 999-5359
Vehicle Owner Alliance free care Inc
Address 42 Ryan Wirthway East St Red Lake, Ontario R2E 0R2 City Red Lake Province Ontario Postal Code R2E 0R2 Phone 777-8733

- ☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number C6A781 Prov. MB NSC # MB099390 Odometer Reading 160007 Odom. Type ☒ km ☐ mi
Vehicle Identification Number 1F DUF 5G T6 D1 E B 9 D H 2 R Make Ford Model F-550 Year 2013 Unit # B41
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	8mm	8mm	38.401	38.410		
2	8mm	8mm	38.701	38.696		
3						
4						
5						
Final Measurement						

Section 4 - Steering: Defects (if any) 1F-Both side upper lower ball joints
1E- Pitman Arm loose 1G- Right side upper + lower tie rod 1C- left tie rod

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) 1C- Right tail lamp New 1F- Right Rear turn signal New

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	15			100	100		
2	13	13			100	100		
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not