



BRITISH
COLUMBIA

Ministry of Transportation
and Infrastructure
Commercial Vehicle
Inspection Report

FINAL INSPECTION
CONFIRMATION NUMBER

15274267

DECAL
NUMBER

FP56100

DECAL EXPIRY DATE

31 OCT 2021

INSPECTION RESULT: **Pass**
INSPECTION TYPE: **Complete**
REASON FOR INSPECTION: **New**
COLLISION REPAIR FACILITY:

WORK ORDER #

INSPECTION START DATE
12 APR 2021 11:27

INSPECTION COMPLETE DATE
12 APR 2021 12:44

REASON NOTE:

TECHNICIAN NAME:

PHONE #:

INSPECTOR'S NUMBER: **201862**
INSPECTOR'S NAME: **CHESNEY, STEPHEN GEORGE**
LICENCE EXPIRY DATE: **28-FEB-2022**

OWNER/LESSEE: **CWB National Leasing Inc. CWB National Leasing Inc.**

ADDRESS: **1525 Buffalo Pl.**

CITY: **Winnipeg**

PROV: **MB**

POSTAL CODE: **R3T 1L9**

FACILITY NUMBER: **04320**

REGISTRATION #:

REGISTRATION #:

PLATE:

FACILITY NAME: **PEERLESS LIMITED**

YEAR: **2022**

MAKE: **PEERLESS**

MODEL:

BODY STYLE:

VIN: **2PLB04128NBC18907**

INSPECTION CLASS: **3 - Trailer and semi-trailer**

ODOMETER:

0 KM

FUEL TYPE:

UNIT/FLEET #:

BRAKE TYPE: **Air**

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out of Service "NA" Not Applicable

	F	R	P	PC	O	NA		F	R	P	PC	O	NA
Section 1 - Power Train						✓	Pressure Fuel						
							Liquid Propane Gas						✓
							Compressed Natural Gas						✓
Section 2 - Suspension			✓				Pressure Fuel Inspector's Name & Number						
Section 3 - Hydraulic Brakes						✓	Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm)						
Section 3A - Air Brakes						✓	Axle # 1 2 3 4 5 6 7 8 9						
Section 4 - Steering						✓	Type: Clamp Clamp						
Section 5 - Instruments Auxiliary Equipment						✓	Size: 30 30						
Section 6 - Lamps			✓				Left: 38 38						
Section 7 - Electrical System						✓	Right: 44 38						
Section 8 - Body & Frame						✓	Comments:						
Section 9 - Tires & Wheels						✓	Air Brake Camshaft Rotation Measurement (degrees)						
Section 10 - Couplers & Hitches						✓	Axle # 1 2 3 4 5 6 7 8 9						
Section 11 - Other Vehicle Components						✓	Left: 0 0						
General Inspection Comments:							Right: 0 0						
							Comments:						
							Brake Lining/Pad Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Lining (S Lining (S						
							Left: 19 19						
							Right: 19 19						
							Comments:						
							Potor/Drum Measurement (mm)						
							Axle # 1 2 3 4 5 6 7 8 9						
							Type: Drum Drum						
							Left: 419 419						
							Right: 419 419						
							Comments:						

Inspector's Name **CHESNEY, STEPHEN GEORGE**

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, N3C/NIP at the Commercial Vehicle Safety Enforcement Branch, by writing to P.O. Box 180, Stn. Prov. Gov't, Victoria, BC V8W 8J2, by e-mailing to vehicle.inspections@gov.bc.ca or calling 250-952-0577.

CVSE0014 (100615)