

03951313

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

F05-7

Vehicle Standards and Inspection
Box 45064 Regent Postal
Winnipeg, MB, R2C 6C7
1-204-666-0020

Manitoba

A951017

Date Inspection Started
DAY 07 MO. 05 YR. 25

Date Inspection Completed
DAY 07 MO. 05 YR. 25

Inspection Expiry Date
DAY 31 MO. 05 YR. 26

Station Number 177124 Station Name Ocean Trailer WPG City
Mechanic Number M017410 Mechanic Signature 204-840-7364 Station Phone Number
Vehicle Owner C. KEAY INVESTMENTS LTD
Address City Province Postal Code Phone

☒ Pass/Safe Vehicle Licence Number TG17512 Prov. M.B. NSC
☐ Fail/Unsafe Vehicle Vehicle Identification Number 52129R513R10EM10938154 Make MAZDA Model 2000 Year 2014 Unit # 86433
☐ Fail/Hazardous ☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H BA Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C <u>D</u> E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>20mm</td> <td>15mm</td> <td>44mm</td> <td>44mm</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>19mm</td> <td>18mm</td> <td>47mm</td> <td>44mm</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	20mm	15mm	44mm	44mm			2	19mm	18mm	47mm	44mm			3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	20mm	15mm	44mm	44mm																																																																					
2	19mm	18mm	47mm	44mm																																																																					
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
X		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>9</td> <td>10</td> <td>10</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>2</td> <td>8</td> <td>8</td> <td>10</td> <td>10</td> <td>90</td> <td>90</td> <td>90</td> <td>90</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	10	9	10	10	90	90	90	90	2	8	8	10	10	90	90	90	90	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	10	9	10	10	90	90	90	90																																																																	
2	8	8	10	10	90	90	90	90																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

Ce document peut être obtenu en français sur demande