

04004706

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



F05-6

Vehicle Standards and Inspect
Box 45004 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-955-0820

Manitoba



A996887

Date
Inspection
Started DAY MO. YR.

09 08 21

Date
Inspection
Completed DAY MO. YR.

09 06 21

Inspection
Expiry
Date DAY MO. YR.

30 06 21

Station
Number

A164145

Station Name

New Kalsi Semi Trailer

City

204 333 9256

Mechanic
Number

M101317

Mechanic Signature

Station Phone Number

Vehicle Owner

Sandra Farms International Ltd

Address

City

Province

Postal Code

Phone

☒ Pass/Safe Vehicle☒ Fail/Unsafe Vehicle☐ Fail/HazardousLicence
Number

TIM31322

Prov. MB

NSC #

Odometer
ReadingOdom.
Type

km mi

Vehicle Identification
Number

20EEFF43561101175199

Make

DOP

Model

Dech

Year

06

Unit #

62710

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 3 (A) Air Leakage 16 (D) Brake Adjuster
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X	X	Section 9 - Tire & Wheel: Defects (if any) 4 (B) Valve stem LT side inner Tire Front Axle

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	9/16	16555	16554	1 1/2	1 1/2
2	9/16	9/16	16563	16553	1 1/2	1 1/2
3	9/16	1/2	16550	16578	1 1/2	1 1/2
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1								
2	7	7	7	7	100	100	100	100
3	8	8	6	6	100	100	100	100
4	6	8	7	7	100	100	100	100
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: