

04080474

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba F07-1

Vehicle Safety Box 45384 Regent Postal Out Winnipeg, MB, R2G 5G7 1-204-685-0203

Manitoba DECA

C072281

Date Inspection Started: 13 04 26
 Date Inspection Completed: 14 04 26
 Inspection Expiry Date: 30 04 27

Station Number: A512913 Station Name: JAZ MECHANICAL LTD
 Mechanic Number: M319710 Mechanic Signature: [Signature]
 Station Phone Number: 2049976075

Vehicle Owner: CDJP ENT. LTD
 City: _____ Province: _____ Postal Code: _____ Phone: _____

Address: _____ City: _____ Province: _____ Postal Code: _____

License Number: TG3949
 Vehicle Identification Number: 2C191213135A1CK17161312
 Make: CANADIAN Model: DOD BUMP Year: 2002 Unit #: 738

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Confirmed legal Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

Mark "X" under "P" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section	Defects (if any)	Brake Inspection Type: (A) B C D E	Circle appropriate Letter for Internal Brake Component Inspection																																																																												
X		Section 1 - Power Train	Defects (if any)																																																																														
X		Section 2 Suspension	Defects (if any)																																																																														
X	X	Section 3 - Brake Systems	3H (3A) 16A- 5-CAMS WORN 16A- 5-CAM BUSHINGS 16H- ADJ. BRAKES	<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1 1/2</td> <td>3 1/4</td> <td>16.571</td> <td>16.568</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>1 1/2</td> <td>1 1/16</td> <td>16.564</td> <td>16.572</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>3</td> <td>7/8</td> <td>7/8</td> <td>16.514</td> <td>16.577</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1 1/2	3 1/4	16.571	16.568	1 1/2	1 1/2	2	1 1/2	1 1/16	16.564	16.572	1 1/2	1 1/2	3	7/8	7/8	16.514	16.577	1 1/2	1 1/2	4							5																																			
Axle	Lining		Drum/Rotor			Stroke																																																																											
	L	R	L	R	L	R																																																																											
1	1 1/2	3 1/4	16.571	16.568	1 1/2	1 1/2																																																																											
2	1 1/2	1 1/16	16.564	16.572	1 1/2	1 1/2																																																																											
3	7/8	7/8	16.514	16.577	1 1/2	1 1/2																																																																											
4																																																																																	
5																																																																																	
X		Section 4 - Steering	Defects (if any)																																																																														
X		Section 5 - Instruments & Auxiliary Equipment	Defects (if any)																																																																														
X	X	Section 6 - Lamps	1F- LEFT SIGNAL LIGHTS INOP 1H- MARKER LIGHTS INOP																																																																														
X		Section 7 - Electrical System	Defects (if any)																																																																														
X	X	Section 8 - Body	21A- R/R HUDFLAP INSECURE																																																																														
X	X	Section 9 - Tire & Wheel	4A- TIRE PSI LOW																																																																														
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>4</td> <td>13</td> <td>10</td> <td>100</td> <td>80</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>19</td> <td>21</td> <td>17</td> <td>12</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> <td></td> </tr> <tr> <td>3</td> <td>14</td> <td>19</td> <td>13</td> <td>5</td> <td>100</td> <td>100</td> <td>100</td> <td>90</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>				Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	10	4	13	10	100	80	100	100	100	2	19	21	17	12	100	100	100	100		3	14	19	13	5	100	100	100	90	100	4										5										
Axle	Tread Depth				Air Pressure																																																																												
	Initial		Corrected		Initial		Corrected																																																																										
	L	R	L	R	L	R	L	R																																																																									
1	10	4	13	10	100	80	100	100	100																																																																								
2	19	21	17	12	100	100	100	100																																																																									
3	14	19	13	5	100	100	100	90	100																																																																								
4																																																																																	
5																																																																																	
X		Section 10 - Coupling Devices	Defects (if any)																																																																														

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

PRESENT THIS COPY WHEN REGISTERING VEHICLE