10/20/25, 10:10 AM HEM Data Dashboard



#### **2019 Kenworth T680**

#### **Test Information**

Engine PACCAR MX/MX-13 (12.9)

'IN <u>1XKYDP9XXKJ996828</u>

**Driveline** Class 8 6x4

**Body** Truck-Tractor MDHD: CBE (Cab Behind Engi

**Test Time** Oct. 17, 2025, 8:56 a.m.

File Length 84.421 s

### **Usage**

Label	Value	Units
Engine Odometer	727,837	mi
Engine Total Hours of Operation	16,257.05	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	64	%

### **Engine On/Off**

Engine running

## **Check Engine Light**

No check engine lights on

10/20/25, 10:10 AM HEM Data Dashboard

# **Emissions Deleted/Tampered**

No

Faults					
<b>DM</b> Active	Controller Name Engine #1	SPN Name Engine Exhaust Gas Recirculation 1 Valve 1 Control 1	<b>FMI Name</b> Other Failure Mode	Count 1	
Active	Engine #1	Engine Exhaust Gas Recirculation 1 Valve 2 Control	Other Failure Mode	1	
Active	Engine #1	Auxiliary Equipment Supply Pressure	Voltage Below Normal	126	
Emissions Previous	Engine #1	Engine Speed	Erratic, Intermittent, or Incorrect	4	
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Voltage Below Normal	1	
Emissions Previous	Engine #1	Aftertreatment 1 Outlet Gas Sensor 1 Power In Range	Erratic, Intermittent, or Incorrect	1	
Emissions Previous	Engine #1	Engine Crankcase Ventilation Hose Disconnected	Low-most severe	1	
Emissions Previous	Engine #1	Engine Fuel Pump Pressurizing Assembly #1	High-moderate severity	1	