

F12-1



PURGED

This vessel has been cleaned and tested for the hazardous environments checked off below. Vessel may contain water residue & will build LEL's if sealed. Must be tested prior to repair.

Company Name : XDI Energy Unit # : 806A

Purge Media Used (Check all that apply):

Water	☐
Steam	☐
Nitrogen	☒

Worker	Date	H2S		Oxygen		LEL	
		Yes	No	Yes	No	Yes	No
<u>Grey</u>	<u>11-17-25</u>		☒		☒		☒

VIN# S/N 457-

Print Name (Tester): Grey Pagan

Signature (Tester): [Signature]

**WARNING IT IS DRIVERS RESPONSIBILITY TO
CHECK ALL VALVES, HATCHES, ETC... PRIOR TO LOADING**