



# DIESEL VEHICLE INSPECTION REPORT



## VEHICLE OWNER INFORMATION

Date of Test 05/30/2025

Name **TIM MARSHBURN**  
 Address **8595 W 51ST AVE**  
 City **ARVADA** State **CO** Zip Code **80002**

## EMISSIONS TEST FACILITY INFORMATION

Station Number <b>13148</b>	Station Name <b>Akisp Diesel Emissions</b>	Serial # <b>1314865218</b>
Inspection Cost \$ <b>85</b>	Station Address <b>2531 W. 62nd Ct. Unit K</b>	
	<b>Denver, CO 80221</b>	

## VEHICLE INFORMATION

Vehicle Identification Number <b>1HTSDAAM0SH677819</b>				
Model Year <b>1995</b>	Vehicle Make <b>INTL</b>	Vehicle License Plate <b>7362037</b>		
GVWR <b>33500</b>	Vehicle Class <b>HD</b>	Non CO. License Plate <b>NO</b>		
# of Cylinders <b>6</b>	Engine Make <b>INTL</b>	Engine Type <b>TURBO</b>	Odometer <b>58755</b>	
Transmission Type <b>AUTO</b>	Vehicle smoke repairs last 60 days? <b>NO</b>		DR2365	<b>NO</b>

FIRST TEST		Inspector Number <b>13132</b>	AFTER REPAIRS TEST		Inspector Number
Heavy duty vehicle dynamometer lug down test			Heavy duty vehicle dynamometer lug down test		
Snap	<b>7% OPACITY</b>		Snap		
Zero Shift	<b>0% OPACITY</b>		Zero Shift		
Engine Rate	<b>6% OPACITY</b>		Engine Rate		
90%	<b>4% OPACITY</b>		90%		
80%	<b>6% OPACITY</b>		80%		
70%	<b>8% OPACITY</b>		70%		
Zero Shift	<b>0% OPACITY</b>		Zero Shift		
Results <b>PASS</b>			Results		

EMISSIONS CONTROL SYSTEMS		FIRST	FINAL	REPAIR INFORMATION
Pump Seals	Air Fuel Adjustment	<b>PASS</b>		Fail Repair Cost \$ <b>0.00</b>
Boost Compensation / Aneroid		<b>PASS</b>		Re-insp. Cost \$
Electronic Engine Controls		<b>NA</b>		Date of Retest
Trap / Catalytic Converter		<b>NA</b>		
Positive Crankcase Ventilation System		<b>NA</b>		
Exhaust Gas Recirculation System		<b>NA</b>		

## OVERALL RESULTS

Initial Test <b>PASS</b>
Retest
Waiver

200