



## 2023 Kenworth T680

### Test Information

|                      |                                          |
|----------------------|------------------------------------------|
| <b>Engine</b>        | CUMMINS ISX / X15 (15.0)                 |
| <b>Engine Serial</b> | CMMNS*6X1u21D1500000000*80395945*162153  |
| <b>VIN</b>           | <a href="#">3WKYD49XXPF989159</a>        |
| <b>Driveline</b>     | Class 8 6x4                              |
| <b>Body</b>          | Truck-Tractor MDHD: CBE (Cab Behind Engi |
| <b>Test Time</b>     | Sept. 10, 2025, 10:06 a.m.               |
| <b>File Length</b>   | 42.364 s                                 |

### Usage

| Label                                                        | Value    | Units |
|--------------------------------------------------------------|----------|-------|
| Engine Odometer                                              | 552,408  | mi    |
| Odometer (Instrument Cluster #1)                             | 551,858  | mi    |
| Engine Total Hours of Operation                              | 17,369.4 | h     |
| Aftertreatment 1 Diesel Particulate Filter Soot Load Percent | 26       | %     |

### Engine On/Off

Engine running

### Check Engine Light

No check engine lights on

## Emissions Deleted/Tampered

No

## Faults

| <u>DM</u>          | <u>Controller Name</u>     | <u>SPN Name</u>                           | <u>FMI Name</u>                     | <u>Count</u> |
|--------------------|----------------------------|-------------------------------------------|-------------------------------------|--------------|
| Previous           | Engine #1                  | Engine Coolant Level 1                    | Low-moderate severity               | 1            |
| Previous           | Engine #1                  | Manufacturer Assignable SPN               | Voltage Below Normal                | 1            |
| Previous           | Brakes - System Controller | J1939 Network #1. Primary Vehicle Network | Erratic, Intermittent, or Incorrect | 127          |
| Previous           | Headway Controller         | Headway Controller Forward Antenna        | Voltage Below Normal                | 127          |
| Previous           | Proprietary                | Forward View Imager System                | Voltage Below Normal                | 1            |
| Emissions Previous | Engine #1                  | Manufacturer Assignable SPN               | Voltage Below Normal                | 1            |