



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD43822
Decal Expiry Date: 2025-Apr-30
Inspection Number: 21098525

Inspection Result
PASS

FACILITY:	ADVANCE TRUCK & HEAVY / S6882	INSP. TYPE:	Complete	INSP. START:	2024-Oct-07 07:30 AM PDT
INSPECTOR:	PEPPER, CODY CHARLES / 113416	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Oct-07 09:43 AM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	14675598	VIN:	1FUJGEBG2GLHB8107
PLATE #:	WA2947	UNIT/FLEET#:	Freightlin	OWNER/LESSEE NAME:	Valiant Financial Services, (lessor) R N L Rental Network LTD. (lessee)
LICENCED GVW(kg):	45000	BODY STYLE:	Truck Tractor	ADDRESS:	1007 Industrial way, 1007 industrial way Squamish, British Columbia V8B0H1, Canada
VEHICLE YEAR:	2016	ODOMETER:	273568 KM		
MAKE:	FREIGHTLIN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	20	Automatic	30	30	17			14	
2	Clamp	30L	Automatic	32	32	14	18	14	13	✓
3	Clamp	30L	Automatic	32	32	14	14	14	13	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	42	44
2	39	37
3	37	34

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	19	19
Lining (Shoe)	19	20

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: PEPPER, CODY CHARLES

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Oct-07 09:43 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.