

rb **RITCHE BROS. Diagnostic Report**
Auctioneers®

2015 International DuraStar 4300

Test Information	
Engine	International DT466/Maxxforce DT (7.6)
Engine Serial	INT *466171241308436M13CARB ESS EXEMPT*466HM2Y3523946
VIN	1HTMMAAN8FH602549
Driveline	Class 7 4x2
Body	Truck MDHD: Conventional
Test Time	March 19, 2026, 9:13 a.m.
File Length	65.549 s

Usage			
Label	Value	Units	
Engine Odometer	2,918	mi	
Odometer (Instrument Cluster #1)	2,935	mi	
Engine Total Hours of Operation	1,116.85	h	
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	69	%	

Engine On/Off
Engine running

Check Engine Light
No check engine lights on

Emissions Deleted/Tampered
Yes

Faults				
<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Body Controller	Operator Input device for Cab Climate Control	Erratic, Intermittent, or Incorrect	1
Previous	Body Controller	J1587	Abnormal Update Rate	1
Previous	Body Controller	Cab HVAC Mode Control Actuator	Erratic, Intermittent, or Incorrect	2
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	6
Previous	Body Controller	Manufacturer Assignable SPN	Out of Calibration	6