

Description	Work Done	Completed
Inspection - Front End Loader	OFF SITE	10/26/2024
Inspection - Front End Loader	completed	09/24/2024
Inspection - Front End Loader	completed	09/17/2024
A Service - Front End Loader - External Contractor	CSA CONTRACT	09/10/2024
Inspection - Front End Loader	COMPLETED	09/10/2024
Inspection - Front End Loader	completed	09/03/2024
AC NOT COOLING / COOLANT PRESSURE LOW	WASH CONDENSER AND RADIATOR CORES INSPECT A/C PRESSURES DIAGNOSE FAULT CODE - REPLACED COOLANT PRESURE SENSOR	08/11/2024
CROWD CYLINDER REPAIRS @ BILLET	REPAIRS DONE AT BILLET	08/20/2024
Westrac FEL0089 14/08/24 Transmission Drain Plug Assembly	Completed	08/17/2024
Inspection - Front End Loader FEL0089	COMPLETED	08/27/2024
Westrac 01/08/24 Hydraulic Oil Filter Transmission Oil Filter Air Filter	Completed	08/02/2024
Inspection - Front End Loader	completed daily	08/13/2024
inspect seat collapse front right corner	inspect seat collapse front right corner	08/26/2024
Wheel Loader System Subscription	SUBSCRIPTION	07/24/2024
B Service - Front End Loader - External Contractor	CSA CONTRACT	07/30/2024
parts order	ordered	07/21/2024
VALVE & NUT-HEX	ORDERED VALVE & NUT-HEX	07/19/2024
Inspection - Front End Loader	COMPLETED DAILY	07/31/2024
Inspection - Front End Loader	complete	07/23/2024
A Service - Front End Loader - External Contractor	CSA CONTRACT	07/22/2024
Fire suppression system repairs	completed e-fire	07/23/2024

Inspection - Front End Loader	completed daily	07/17/2024
A Service - Front End Loader - External Contractor	CSA CONTRACT	07/15/2024
Inspection - Front End Loader	completed daily	07/17/2024
C Service - Front End Loader - External Contractor	CSA CONTRACT	08/11/2024
Artic movement	End of project	08/06/2024
Smoke Bomb Cab Test	OLD WO, COMPLETE WITH NEW	07/31/2024
Inspection - Front End Loader	COMPLETED DAILY	07/02/2024
Inspection - Front End Loader	complete	06/27/2024
A Service - Front End Loader - External Contractor	completed	06/26/2024
Inspection - Front End Loader	completed	06/26/2024
A Service - Front End Loader - External Contractor	CSA CONTRACT	06/12/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
B Service - Front End Loader - External Contractor	CSA CONTRACT	05/31/2024
Inspection - Front End Loader	completed daily	05/21/2024
Inspection - Front End Loader	completed daily	05/21/2024
Inspection - Front End Loader	completed daily	05/15/2024
A Service - Front End Loader - External Contractor	CSA CONTRACT	05/15/2024
Parts used	Completed	05/11/2024
Smoke Bomb Cab Test	completed	05/29/2024
Inspection - Front End Loader	completed daily	05/14/2024
Warranty Tire fitment	Completed at Kaltires	04/30/2024
Inspection - Front End Loader	completed daily	05/14/2024
D Service - Front End Loader - External Contractor	CSA CONTRACT	04/25/2024
A Service - Front End Loader - External Contractor	COMPLETED	04/24/2024
Inspection - Front End Loader	COMPLETED	04/24/2024
A/C	CHECK A/ C SYSTEM FOR LEAKS REPLACED SOME COMPONENTS, REGAS & CHECKED	03/30/2024
Billet engineering FEL0089 Steer cylinder	ordered	04/10/2024
Inspection - Front End Loader	completed	04/15/2024

WESTRAC ORDER - A/C NOT WORKING	COMPLETED	04/05/2024
IVMS Faults	completed	05/29/2024
A/C Repairs	COMPLETED	04/24/2024
Inspection - Front End Loader	completed daily	04/04/2024
Inspection - Front End Loader	completed daily	04/04/2024
Inspection - Front End Loader	completed	03/25/2024
Inspection - Front End Loader	completed	03/19/2024
KALTIRE - FIT NEW TYRE TO CUSTOMER SUPPLIED WHEEL SENT FROM SITE	FIT NEW TYRE TO CUSTOMER SUPPLIED WHEEL SENT FROM SITE - KALTIRE	03/14/2024
Inspection - Front End Loader	completed	03/19/2024
DOG BONE / TYRE & SEAT	completed	03/25/2024
replace dog bone bushes	completed	03/05/2024
Inspection - Front End Loader	completed daily	03/10/2024
Steering cylinder	Completed	03/03/2024
Supply parts A/C condenser	completed	03/05/2024
Smoke Bomb Cab Test	completed	03/05/2024
Inspection - Front End Loader	completed daily	03/10/2024
B Service - Front End Loader - External Contractor	CSA CONTRACT	03/08/2024
auto greaser	Completed	02/16/2024
steer cylinder	Completed	02/15/2024
Inspection - Front End Loader	COMPLETED	02/13/2024
Inspection - Front End Loader	completed daily	02/09/2024
Inspection - Front End Loader	completed daily	02/09/2024
Inspection - Front End Loader	completed daily	02/09/2024
Inspection - Front End Loader	completed daily	02/09/2024
A Service - Front End Loader - External Contractor	completed by CSA CONTRACT	02/09/2024
Smoke Bomb Cab Test	CSA CONTRACT	01/29/2024
Inspection - Front End Loader	Complete	01/22/2024
C Service - Front End Loader - External Contractor	CSA CONTRACT	01/29/2024
Inspection - Front End Loader	completed daily	01/07/2024
Inspection - Front End Loader	completed each morning	12/31/2023
Inspection - Front End Loader	COMPLETED AND WO'S CREATED FOR REPAIRS	12/24/2023

B Service - Front End Loader - External Contractor	CSA CONTRACT - PAUL	01/03/2024
DEFECTS	COMPLETED	02/13/2024
Inspection - Front End Loader	COMPLETED DAILY	12/17/2023
Inspection - Front End Loader	COMPLETED DAILY	12/17/2023
Inspection - Front End Loader	As per work order	12/06/2023
Inspection - Front End Loader	Complete	12/06/2023
Bucket & Teeth Repairs	COMPLETED	02/13/2024
A Service - Front End Loader - External Contractor	as per workorder	11/28/2023
Smoke Bomb Cab Test	As per work order	12/06/2023
Inspection - Front End Loader	All work done in accordance with work plan.	11/24/2023
B Service - Front End Loader - External Contractor	CSA CONTRACT	11/18/2023
Inspection - Front End Loader	work done on WO-YAK-021-499	11/24/2023
A Service - Front End Loader - External Contractor	A Service - Front End Loader	11/05/2023
Inspection - Front End Loader	COMPLETE	11/07/2023
D Service - Front End Loader - External Contractor	CSA CONTRACT	11/06/2023
A Service - Front End Loader - External Contractor	Service is completed	10/21/2023
REPLACE REVERSE CAMERA	Fitted	10/28/2023
multiple faults	as per work order	10/21/2023
GOLDMONT OFFSITE REPAIRS	GOLDMONT REPAIRED	10/04/2023
HYDRAULIC LINE LEAKING	HYD HOSE REMOVED MADE NEW HOSE UP FITTED HYDRAULIC HOSE TESTED HYDRAULIC SYSTEM TOPPED UP HYD OIL RELEASED BY ISAAC WYKSTRA	10/07/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/24/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/24/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/10/2023
Inspection - Front End Loader	complete with new WO	10/03/2023
Defects as per Work Plan	As per work order	09/17/2023
Inspection - Front End Loader	COMPLETED WITH NEW WO	09/23/2023
Inspection - Front End Loader	As per work order	09/17/2023

Inspection - Front End Loader	As per work order	09/17/2023
B Service - Front End Loader - External Contractor	As per work order	09/10/2023
Install Goanna Bars	BUCKET CHEEKS BUILT UP ON THIS AREAS WITH WELD CHOCKY BOLCKS INSTALLED ON FRONT OF CHEEKS COMPLETE BY TAYLOR	08/27/2023
A Service - Front End Loader - External Contractor	CSA CONTRACT	09/06/2023
Inspection - Front End Loader	COMPLETED BY H2	08/26/2023
REPAIRS	Repaired all defects	09/07/2023
Inspection - Front End Loader	with new wo	08/10/2023
Inspection - Front End Loader	CSA CONTRACT	08/09/2023
B Service - Front End Loader - External Contractor	CSA CONTRACT	08/09/2023
left arm rest does not raise	Repaired cable	09/07/2023
C Service - Front End Loader - External Contractor	CSA CONTRACT	08/09/2023
Inspection - Front End Loader	COMPLETE	08/03/2023
A Service - Front End Loader - External Contractor	CSA CONTRACT	08/09/2023
Heater / Wiggins Valve	FUEL CAP FILTER/BREATHER REPLACED	08/09/2023
Inspection - Front End Loader	Completed - Crack in windscreen found	07/06/2023
Install Goanna Bars	BUCKET CHEEKS BUILT UP ON THIS AREAS WITH WELD CHOCKY BOLCKS INSTALLED ON FRONT OF CHEEKS new work order created	08/24/2023
REPLACE REAR TYRES	kaltire - completed	07/14/2023
WINDSCREEN REPAIR	complete by deans auto glass	08/23/2023
REPAIRS / Welding	RHS mirror smashed REPLACED Grease Seat (squeaks) GREASED Hydraulic oil filter fault - HIGH TEMP FLUSHED AND COOLANT RH +LHS Rear step bent FITTED NEW Rear Fan guard Damage COSMETIC STILL USABLE	06/29/2023
Caterpillar 988H Front End Loader (B service)	WESTRAC - COMPLETED SERVICE	06/23/2023
Inspection - Front End Loader	COMPLETE	06/29/2023
Install Goanna Bars	AS PER WO-YAK-019-989	07/04/2023

Inspection - Front End Loader	completed	06/18/2023
Caterpillar 988H Front End Loader (D service)	completed by westrac	05/13/2023
Cracked windscreen	WINDOW CHECKED AND OK, DEANS	06/02/2023
Faulty E-Stop	Tested & replaced damaged faulty E-Stop Test - OK	03/31/2023
Thermostat change out required	Completed - Westrac	02/02/2023
Caterpillar 988H Front End Loader (C service)	Completed - Westrac	02/02/2023
R/H rear body panel damaged	Fix damaged R/H rear body panel	02/16/2023
R/H rear hand rail damaged	Completed	01/26/2023
Fire suppression display wiring	Completed	01/28/2023
Emergency ladder & steps required to be fitted	replaced with new	02/08/2023
Clean cooler packs / covers	Completed	01/26/2023
R/H hand rail	Completed	01/26/2023
LH Axle cooler high pressure swivel leak	Completed	01/26/2023
Caterpillar 988H Front End Loader (B service)	Completed by Westrac	01/03/2023
Arm rest strut broken completely away.	Completed	01/03/2023
Caterpillar 988H Front End Loader (D service)	Completed by Westrac - Hamish and Paul	12/14/2022
Isolator broken	Replaced Isolator	11/10/2022
Caterpillar 988H Front End Loader (C service)	CSA	11/03/2022
Isolator broken	Completing due to using a DBL UP WO# WO-YAK-018-041	10/31/2022
Caterpillar 988H Front End Loader (A service)	CSA	10/18/2022
Caterpillar 988H Front End Loader (A service)	Not Required	09/21/2022
Caterpillar 988H Front End Loader (A service)	Not Required	09/21/2022
Caterpillar 988H Front End Loader (B service)	Not Required	09/21/2022
Caterpillar 988H Front End Loader (A service)	CSA Service	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Service	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Service	09/16/2022
Caterpillar 988H Front End Loader (B service)	CSA Service	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Services	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Services	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Services	09/16/2022
Caterpillar 988H Front End Loader (A service)	CSA Services	09/16/2022

Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/09/2022
Caterpillar 988H Front End Loader (D service)	westrac	07/09/2022
Caterpillar 988H Front End Loader (C service)	westrac	07/09/2022
Caterpillar 988H Front End Loader (A service)	westrac	07/09/2022
Caterpillar 988H Front End Loader (B service)	westrac	07/09/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/07/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/07/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/07/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/07/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/08/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/08/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/08/2022
Services carried out by Westrac on all 988K XE's as per contract	mid life	07/08/2022
Front end loader-generic (E service)	Done as per westrac	07/09/2022
Caterpillar 988H Front End Loader (C service)	as per westrac	07/09/2022
Caterpillar 988H Front End Loader (C service)	as per westrac	07/09/2022
Caterpillar 988H Front End Loader (A service)	as per westrac	07/09/2022

Caterpillar 988H Front End Loader (A service)	as per westrac	07/09/2022
Caterpillar 988H Front End Loader (A service)	as per westrac	07/09/2022
Caterpillar 988H Front End Loader (B service)	as per westrac	07/09/2022
GPS not working	Position partners travelled to site. Serviced and calibrated units	05/09/2022
Caterpillar 988H Front End Loader (C service)	as per work plan	04/16/2022
defect	replace tyre chains	04/06/2022
Fit chains to front wheels	Fit front tyre chains	04/06/2022
Replace front uni joint	Removed damaged uni joint Fit new uni joint Replaced bolts and tensioned Greased unis	04/15/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	05/03/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	05/03/2022
oil leak trans a/c n/w	remove and replace trans hose topped up a/c gas to 1.8kg	02/20/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
carry out tasks	completed	02/24/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	02/22/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	01/21/2022
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	01/26/2022
A/C FAULT	REMOVED AND REPLACED A/C HOSE	01/04/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022

Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/22/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/22/2021
Services carried out by Westrac on all 988K XE's as per contract	Carry out replacement of Gearbox Oil & Filter	12/16/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/26/2022
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/22/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/22/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/22/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	01/05/2022
Front end loader-generic (E service)	Service asset as per attached service sheet	01/05/2022
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	01/04/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	01/05/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	12/31/2021
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	01/05/2022
A/C COMPRESSOR	A/C COMPRESSOR	12/27/2021

a/c issue	a/c issue bent rear panel wiring loom	12/11/2021
Services carried out by Westrac on all 988K XE's as per contract	Services carried out by Westrac on all 988K XE's as per contract	12/13/2021
Front end loader-generic (E service)	Service asset as per attached service sheet as per csa westrac servicing	01/26/2022
Caterpillar 988H Front End Loader (C service)	carried out by westrac	11/30/2021
Caterpillar 988H Front End Loader (A service)	carried out by westrac	11/30/2021
carry out tasks	completed	02/24/2022
3099 - Door Seal	Remove and replace door seal	11/08/2021
REPAIRS	Replaced door seal & checked for dust in cab	11/08/2021
OIL LEAK AT FILTER HOUSING	REPLACED BOTH REMOTE OIL FILTER HOUSING HOUSES	11/01/2021
carry out tasks	completed	02/24/2022
leaking hose crowd cylinder	swoped hose off fell00089	10/27/2021
0558 - HOLE IN TOOTH	REPLACE ALL BUCKET TEETH (8 IN TOTAL)	10/10/2021
0526 - gear select fault, leaking engine oil hose	inching pedal needs calibrating oil hose from filter housing to oil cooler needs replacing 12746 hr	10/01/2021
0517 - A/C	replace A/C dryer and TX valve gas A/C - 1.8kg clean out disc condensor 12732 hr	09/29/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	10/14/2021
Front end loader-generic (E service)	As per service sheet	09/28/2021
Fire Suppression Fault and GPS without Power	As per service sheet	09/23/2021
YAK 0848- LOADER WONT' START + NO CAB POWER	DIAGNOSE & TEST ELECTRICAL CONNECTIONS 13425 HRS	09/15/2021
1629 - Tyre chains	Tighten up tyre chains 12,322 hours	09/07/2021
Caterpillar 988H Front End Loader (D service)	As per service sheet	09/23/2021
Caterpillar 988H Front End Loader (B service)	service carried out by westrac	09/21/2021

0829 - A/C not working	Topped up R134A 116,174 hours	08/03/2021
1570 - LHS BOOM GREASE LINE GUARD CAME OFF	REPAIR GUARD AND REFIT 11268 HR	07/18/2021
0400 - REPLACE POS 3 AND 4 TYRES	CHANGE OUT POS 3 AND 4 TYRES WITH BLACK RUBBER TYRE FITTING 11101 HR	07/14/2021
1453 - MIRROR, GREASE HOSE	SECURE RH AND LH MIRROR ASSEMBLY FIT NEW GREASE HOSE 11203 HR	07/15/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	07/28/2021
0161 - Steps, wheel chocks	Replace lower step and rear step runner on N/S Secure wheel chocks Check other faults and order parts 10,917 hours Parts Door rubber Reverse camera Fire Extinguisher and bracket N/S Seat arm rest Receiver drier Cabin filter	06/27/2021
0001 - Replace step	Remove and replace steps 10,976 hours	06/30/2021
0157 - Rim lock tab unserviceable, drivers heater unserviceable	Rim lock tab unserviceable, drivers heater unserviceable 10,889 bours	06/26/2021
0155 - Break down - oil leak	Secure oil fitting on transmission Remove and refit skid plates No HOURS supplied	06/25/2021

WR 03216	10498 HR 1. AUTO GREASE PISTON HOUSING ON BOOM - DOG BONE HAD SNAPPED ITS MOUNTS AND WAS HANGING 2. DRILLED OUT OLD BOLTS AND EXTRACTED THEM. RETAPPED THREAD TO M10 X 1.5 3. REFITTED AND SECURED HOUSING USING NEW BOLTS	06/01/2021
03022 - CUT OFF OLD BOLTS AND GUMS, FIT NEW GUMS	10449 HR CUT OFF OLD BOLTS AND GUMS (?), FIT NEW GUMS	05/26/2021
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	07/07/2021
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	07/07/2021
Caterpillar 988H Front End Loader (D service)	carried out	07/31/2021
03087 - REPLACE TILT CYLINDER RHS	REPLACE TILT CYLINDER RHS - TEST - ALL OK TOP UP HYDRAULIC OIL	05/10/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	07/06/2021
WR 02936	RESECURED BOTH R/V MIRRORS PARTS TO BE ORDERED: X2 PIVOT BOLTS X2 SPRINGS X2 SPACER BLOCKS X2 NUTS X2 PLASTIC CAPS	05/02/2021
03003 - BUCKET TEETH (G.E.T) REPLACED 8X	9922 HR 03003 - BUCKET TEETH (G.E.T) REPLACED 8X	04/30/2021
Caterpillar 988H Front End Loader (B service)	9893 HR Service asset as per attached service sheet	05/22/2021
03003 - Bucket teeth (G.E.T) replace 8x	Bucket teeth (G.E.T) replace 8x 9,893 hours	04/30/2021

02936 - RESECURED BOTH R/V MIRRORS	RESECURED BOTH R/V MIRRORS PARTS TO BE ORDERED: X2 PIVOT BOLTS X2 SPRINGS X2 SPACER BLOCKS X2 NUTS X2 PLASTC CAPS 9922 HR	05/02/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	05/11/2021
03051 - WIPER ARM OUT OF POSITION, SWAP WIPER WITH 88	WIPER ARM OUT OF POSITION, SWAP WIPER WITH 88 9592 HR	04/13/2021
02902 - Find cab strut to left hand arm rest	- Find cab strut to left hand arm rest 9,525 Hours	04/10/2021
00105 - Fixed steps and seat loose	Fixed steps and seat loose 8,765 hours	03/28/2021
00117 - Broken grease line, diagnose fixed and repaired	Broken grease line, diagnose fixed and repaired 9000 hours	04/01/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	04/16/2021
00831 - Seat inspection, fit new seat	Seat inspection - okay New seat fitted 01/04 9,363 hours	04/03/2021
00823 - Drill dog bone holes out, retap 3, fit bracket and refit grease lug	Drill dog bone holes out, retap 3, fit bracket and refit grease lug 9,289 hours	03/30/2021
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	04/16/2021
Caterpillar 988H Front End Loader (A service)	Carry out Service as per attached service sheets	03/28/2021
Caterpillar 988H Front End Loader (B service)	Carry out Service as per attached service sheets	03/19/2021
01393 - FIX TILT SENSOR WIRING	FIX TILT SENSOR WIRING 8286 HR	02/02/2021

00356 - REMOVE BLOWN CYLINDER HOSE. GO TO HEAVY SHED, MAKE NEW HOSE. FIT NEW HOSE. TOP UP HYDRAULIC OIL	REMOVE BLOWN CYLINDER HOSE. GO TO HEAVY SHED, MAKE NEW HOSE. FIT NEW HOSE. TOP UP HYDRAULIC OIL 8343 HR	02/05/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	03/16/2021
Caterpillar 988H Front End Loader (D service)	Service asset as per attached service sheet	02/13/2021
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	02/04/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	02/07/2021
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	01/20/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	01/03/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet.carried out by westrtac (CSA)	12/20/2020
Caterpillar 988H Front End Loader (C service)	service carried out by westrac	12/15/2020
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	12/08/2020
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	11/24/2020
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	11/01/2020
Caterpillar 988H Front End Loader (D service)	Service asset as per attached service sheet	10/31/2020
Caterpillar 988H Front End Loader (A service)	Carry out service - Westrac 6,173 hours	10/16/2020
Caterpillar 988H Front End Loader (B service)	service carried out by westrac	10/05/2020
Caterpillar 988H Front End Loader (A service)	service is carried out by westrac (CSA)	09/26/2020
Caterpillar 988H Front End Loader (C service)	carry out service as per	09/15/2020
Caterpillar 988H Front End Loader (A service)	carry out service as per service sheet	09/02/2020
Caterpillar 988H Front End Loader (B service)	carry out service as per service sheet	08/25/2020
Caterpillar 988H Front End Loader (A service)	asset under csa	08/10/2020
Caterpillar 988H Front End Loader (D service)	Service asset as per attached service sheet	07/27/2020
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet carried out by westrac	07/17/2020
Caterpillar 988H Front End Loader (A service)	Service carried out by Westrac	07/06/2020
Caterpillar 988H Front End Loader (B service)	CARRIED OUT BY WESTRAC	06/25/2020
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet carried out by westrac	06/27/2020

Caterpillar 988H Front End Loader (C service)	C SERVICE CARRIED OUT CONTACTOR	06/10/2020
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet carried out by contractor westrac	06/27/2020
Caterpillar 988H Front End Loader (A service)	A Service	05/27/2020
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	05/25/2020
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	05/13/2020
Caterpillar 988H Front End Loader (D service)	Carry out service as per service sheet	05/01/2020
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet	04/28/2020
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	04/28/2020
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	04/19/2020
Caterpillar 988H Front End Loader (B service)	B Service	04/01/2020
Caterpillar 988H Front End Loader (A service)	A SERVICE Changed out engine oil and oil filter	03/27/2020
Product Link	Drove to site and up to ROM where loaders are, found loader had all latest flash files except for trans ECM, re flashed trans ECM calibrated, Pay load on ET. Tried to change product link config would not accept new config.	03/12/2020
Caterpillar 988H Front End Loader (C service)	Carry out service	03/06/2020
Caterpillar 988H Front End Loader (B service)	Carry out service	02/21/2020
Broken grease line	Repair broken grease lines	05/26/2020
Banging sound under seat	Repaired seat	05/17/2020
Caterpillar 988H Front End Loader (A service)	500 Hour Service by Westrac	02/13/2020
Snapped grease fitting	Replaced snapped grease fitting	01/29/2020
WESTRAC CALLED TO PICTON	Travel to Berth 8 Inspect machine and found the power to be dropping out when attempting to start machine Remove covers and found a loose cable on the back of the isolator. Tightened cable, test and all was good. Carried out the download of ECU's	11/12/2019

