

03920499

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba GO3-7

Vehicle Standards and Inspections
Box 46084 Regent Postal Office
Winnipeg, MB, R2C 6C7
1-204-965-0920

Manitoba DECA

A875598

Date Inspection Started
DAY 11 MO. 11 YR. 11

Date Inspection Completed
DAY 12 MO. 11 YR. 11

Inspection Expiry Date
DAY 31 MO. 11 YR. 15

Station Number 11111111 OCEAN TRAILER WPG.

Mechanic Number 156217 Mechanic Signature [Signature] City [City]

Vehicle Owner C KEN INVESTMENTS LTD. Station Phone Number [Number]

Address [Address] City [City] Province [Province] Postal Code [Postal Code] Phone [Phone]

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

License Number 1X111111 Prov. AB NSO [NSO]

Vehicle Identification Number 11111111111111111111111111111111 Make [Make] Model [Model] Year [Year] Unit # [Unit #]

☒ Confirmed legible Vehicle Identification Number on vehicle

Odometer Reading 5893 Odom. Type [Type] Unit [Unit]

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	11/16	11/16	10.520	10.525	1.5	1.5
2	11/16	11/16	10.505	10.520	1.5	1.5
3	11/16	11/16	10.520	10.520	1.5	1.5
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	11	10	10	9	90	90	90	90
2	11	11	11	10	90	90	90	90
3	11	10	11	11	90	90	90	90
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: