


04103075

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba  604-4

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba  C091882

Date Inspection Started DAY: 10 MO: 05 YR: 26	Station Number AF 2273	Station Name JAZ MECHANICAL LTD	City Winnipeg
Date Inspection Completed DAY: 10 MO: 05 YR: 26	Mechanic Number M3777P	Mechanic Signature 	Station Phone Number 204 9976075
Inspection Expiry Date DAY: 31 MO: 05 YR: 27	Vehicle Owner BRANT PALMER		
Address		City	Province
Postal Code		Phone	
☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number 7520005	Prov. MB	NSC #
Vehicle Identification Number 2R7F542256D144VBR		Make JAZ	Model TRUCK CRIB
☒ Confirmed legible Vehicle Identification Number on vehicle		Odometer Reading	Odom. Type km ☐ mi ☐
Year 2006		Unit # 7006	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	7/16	1/2	16.567	16.560	1/12	1/12
2	9/16	7/16	16.571	16.575	1/12	1/12
3						
4						
5						
Final Measurement						

Axle	Initial		Corrected	
	L	R	L	R
1	15	15	9	11
2	13	14	14	13
3				
4				
5				

Axle	Initial		Corrected	
	L	R	L	R
1	100	100	100	100
2	100	100	100	100
3				
4				
5				

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: