

Date Inspection Started: 23 04 26
 Date Inspection Completed: 23 04 26
 Inspection Expiry Date: 30 04 27

Station Number: A60170 Station Name: 218 REPAIR LTD
 Mechanic Number: M94614 City: 204-746-4715
 Vehicle Owner: HANK STORM
 Address: Rob 339 City: EMERSON MB Postal Code: R0A 0G0 Phone:

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: L1BWA3018 Prov. MB NSC #: MR 6387760 Odometer Reading: 19265 Odom. Type: km mi
 Vehicle Identification Number: 1V-DAF5G1Y61S1E1S1Y41153 Make: DYNEX Model: F550 Year: 06 Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: Defects (if any) Circle Brake Type

Brake Inspection Type: A B **C** D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	11.4	11.0	38.70	40.6		
2	12.1	12.4	38.01	38.40		
3						
4						
5						
Final Measurement						

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	10	10			85	85		
2	9	9	9	10	85	85	85	85
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____