04131436

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL VOID WITHOUT SEAL

Manitoba C114135

	DAY	MO.	YR.
Date Inspection Started	02	10	26
Date Inspection Completed	23	10	26
Inspection Expiry Date	31	10	27

Station Number: A 1506 — Station Name: RTM TRANSPORT LTD NE — City:

Mechanic Number: M 42 07 — Mechanic Signature: [signature] — Station Phone Number: 204-849-2242

Vehicle Owner: RTM TRANSPORT LTD

Address | City | Province | Postal Code | Phone

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number | Prov. | NSC # | Odometer Reading | Odom. Type [ ] km [ ] mi

Vehicle Identification Number: 1P9RT53B145477013 — Make: MUV ALL — Model: 5370 SFTD — Year: 2004 — Unit #

[X] Confirmed legible Vehicle Identification Number on vehicle

2004 OMM

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck (GVWR ____ KGS) ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Defects (if any) 8A BRAKE SERVICE VALVE LEAKING AIR — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) 1H RIGHT CENTRE MARKER TURN SIGNAL NOT WORKING; 1L LICENCE PLATE LIGHT N/F
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 4A
		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining Inch		Drum/Rotor Inch		Stroke Inch	
Axle	L	R	L	R	L	R
1	.67	.64	16.54	16.54	1.5	1.5
2	.65	.65	16.54	16.57	1.5	1.5
3						
4						
5						
	Final Measurement					

Tread Depth 32nds — Air Pressure PSI

	Tread Depth Initial				Tread Depth Corrected				Air Pressure Initial				Air Pressure Corrected			
Axle	L		R		L		R		L		R		L		R	
1	16	12	14	12				18	100	100	100	100				
2	10	14	14	13					100	0	100	100		100		
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: NOT REGISTERED

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE