



# Commercial Vehicle Inspection Report

Decal Number: PY08425  
Decal Expiry Date: 2025-Nov-30  
Inspection Number: 21341807

Inspection Result:  
**PASS**

FACILITY: NORTHERN B.C. TRUCKERS' / N5398  
INSPECTOR: WASSENAR, MICHAEL ANTHONY / 200357  
WORK ORDER #:  
INSR. TYPE: Complete  
INSR. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
INSR. REASON: Semi-annual  
INSR. START: 2025-May-06 07:45 AM MST  
INSR. COMPLETE: 2025-May-06 08:45 AM MST

VEHICLE JUR: British Columbia  
PLATE #: WL6283  
LICENCED GVW(kg): 53500  
VEHICLE YEAR: 2020  
MAKE: PETERBILT  
MODEL:  
REGI: 13659845  
UNIT/FLEET#: 16  
BODY STYLE: Logging Truck  
ODOMETER: 222986 KM  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE: Diesel  
VIN: 1NPTXATXSLD882047  
OWNER/LESSEE NAME: KROPP LOGGING LTD., N/A  
ADDRESS: BOX 74  
Pouce Coupe, British Columbia  
VOC2C0, Canada

|                                                 |                |
|-------------------------------------------------|----------------|
| Vehicle Identification (VIN)                    | Passed         |
| Section 1 - Power Train                         | Passed         |
| Section 2 - Suspension                          | Passed         |
| Section 3 - Brake System                        | Not Applicable |
| Section 3A - Air Brakes                         | Passed         |
| Section 3H - Hydraulic Brakes                   | Not Applicable |
| Section 4 - Steering                            | Passed         |
| Section 5 - Instruments and Auxiliary Equipment | Passed         |
| Section 6 - Lamps                               | Passed         |
| Section 7 - Electrical System                   | Passed         |
| Section 8 - Frame and Body                      | Passed         |
| Section 9A - Tires                              | Passed         |
| Section 9B - Wheels                             | Passed         |
| Section 10 - Coupling Devices                   | Passed         |
| Section 11 - Other Vehicle Components           | Not Applicable |

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

| Axles | Type  | Size | Slack Adj. | Left | Right | Tire Tread Depth (mm) |         |         |         | Steering |
|-------|-------|------|------------|------|-------|-----------------------|---------|---------|---------|----------|
|       |       |      |            |      |       | Outer L               | Inner L | Inner R | Outer R |          |
| 1     | Clamp | 24   | Automatic  | 28   | 28    | 10                    |         |         | 10      |          |
| 2     | Clamp | 30   | Automatic  | 26   | 26    | 19                    | 19      | 19      | 19      | ✓        |
| 3     | Clamp | 30   | Automatic  | 26   | 26    | 19                    | 19      | 19      | 19      |          |
| 4     | Clamp | 30   | Automatic  | 30   | 28    | 19                    | 19      | 19      | 19      |          |

Comment:

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQV/P at the Commercial Vehicle Safety Enforcement

CVS00014

5/7/2025 10:06:02 AM MST



# Commercial Vehicle Inspection Report

Decal Number: PY08425  
Decal Expiry Date: 2025-Nov-30  
Inspection Number: 21341807

Inspection Result:  
**PASS**

## Air Brake Camshaft Rotation (degrees)

| Axes | Left | Right |
|------|------|-------|
| 1    | 0    | 0     |
| 2    | 0    | 0     |
| 3    | 0    | 0     |
| 4    | 0    | 0     |

Comment:

## Brake Lining/Pad (mm)

| Lining/Pad    | Left | Right |
|---------------|------|-------|
| Lining (Shoe) | 18   | 18    |
| Lining (Shoe) | 17   | 17    |
| Lining (Shoe) | 16   | 16    |
| Lining (Shoe) | 16   | 16    |

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

| Rotor/Drum | Left   | Right  |
|------------|--------|--------|
| Drum       | 418.00 | 419.00 |
| Drum       | 419.00 | 419.00 |
| Drum       | 420.00 | 420.00 |
| Drum       | 420.00 | 420.00 |

Comment:

## Inspection Comments:

Has this Vehicle been road tested? ☒ No Road Test Date:  
Inspector: WASSENAAR, MICHAEL ANTHONY Signature: \_\_\_\_\_

Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-May-07 10:07 AM MST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/7/2025 10:08:02 AM MST