



Commercial Vehicle Inspection Report

Decal Number: GH68127
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21235641

606-1
Inspection Result:
PASS

FACILITY: TIM'S TRAILER REPAIRS / S15840 INSP. TYPE: Complete INSP. START: 2025-Feb-12 10:30 AM PST
INSPECTOR: FRANCIS, TIMOTHY GLENN / 112695 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Feb-12 12:00 PM PST
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 10423795 VIN: 1JJV532DXCL647847
PLATE #: 51129J UNIT/FLEET#: V5318 OWNER/LESSEE NAME: C.Sanghera Trans Ltd, C.Sanghera Trans Ltd
LICENCED GVW(kg): 999999 BODY STYLE: Van Trailer ADDRESS: 110-6638 152a St, 110-6638 152a St
VEHICLE YEAR: 2012 ODOMETER: Surrey, British Columbia
MAKE: WABASH HUB ODOMETER: V3S5X5, Canada
MODEL: DVCVH BRAKE TYPE: Air
FUEL TYPE:

| | |
|---|----------------|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Not Applicable |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Not Applicable |
| Section 5 - Instruments and Auxiliary Equipment | Not Applicable |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
|-------|-------|------|------------|------|-------|---------|---------|---------|---------|----------|
| 1 | Clamp | 30 | Automatic | 32 | 32 | 5.6 | 6.4 | 6.4 | 5.6 | |
| 2 | Clamp | 30 | Automatic | 32 | 32 | 6.4 | 6.4 | 7.1 | 7.1 | |

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
|-------|------|-------|---------------|------|-------|------------|--------|--------|
| 1 | 20 | 20 | Lining (Shoe) | 21 | 21 | Drum | 419.12 | 419.12 |
| 2 | 20 | 20 | Lining (Shoe) | 21 | 21 | Drum | 419.12 | 419.12 |

Comment:

Comment: All four wheels of brakes and drums replaced

Comment:


Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: FRANCIS, TIMOTHY GLENN

Signature: 

This Inspection Report was submitted to CVSE on 2025-Feb-12 12:08 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

2/12/2025 12:06:59 PM PST

