03986358 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba G067

Vehicle Standards and Ins... Box 45064 Regent Postal C... Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba **C057739**

Date Inspection Started	15 DAY	06 MO.	26 YR.	Station Number A6160	Station Name Rolling Hills Repair City
Date Inspection Completed	16 DAY	06 MO.	26 YR.	Mechanic Number M10046	Mechanic Signature 204-871-6025 Station Phone Number
Inspection Expiry Date	30 DAY	06 MO.	27 YR.	Vehicle Owner TM Olmstead Farms	Address City Province Postal Code Phone

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number TH6646 Prov. MB NSC # — Odometer Reading — Odom. Type ☐ km ☐ mi

Vehicle Identification Number 2DEGBSA3361019490 Make Doepker Model Hopper Year 06 Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR 35000 KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
✓		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type. Defects (if any): 14B RM/RR Brake Chambers
✓		**Section 4 - Steering:** Defects (if any)
✓		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X	X	**Section 7 - Electrical System:** Defects (if any) 1C. Trailer Plug
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 1B. RRI Tire fail
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	0.417	0.463	16.587	16.549	1.50	1.50
2	0.625	0.630	16.536	16.582	1.50	1.50
3	0.650	0.523	16.554	16.553	1.50	1.50
4						
5						
	Final Measurement					

	Tread Depth MM								Air Pressure PSI							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	6	10	10	8					100	100	100	100				
2	8	10	8	7					100	100	100	100				
3	7	7	0	9			15		100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____

Signature

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

20372138 MCC ©2023. All rights reserved. — 9355

03986358

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba