03986357 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba

G06

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C057738

Austin MB

Date Inspection Started	15 DAY	06 MO.	26 YR.	Station Number	A6160	Station Name: Rolling Hills Repair — City: Austin MB
Date Inspection Completed	16 DAY	06 MO.	26 YR.	Mechanic Number	M10946	Mechanic Signature — Station Phone Number: 204-871-6025
Inspection Expiry Date	30 DAY	06 MO.	27 YR.			

Vehicle Owner: TM Olmstead Farms

Address | City | Province | Postal Code | Phone

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TH6647 Prov.: MB NSC #: Odometer Reading: Odom. Type ☐ km ☐ mi

Vehicle Identification Number: 2DEGBSA266101944911 Make: Doepker Model: Hopper Year: 06 Unit #:

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR 35000 KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
✓		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) — Circle Brake Type
✓		**Section 4 - Steering:** Defects (if any)
✓		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 1B. RRO Tire fail
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	0.390	0.709	16.536	16.538	1.00	1.00
2	0.737	0.719	16.600	16.570	1.00	1.00
3						
4						
5						
	Final Measurement					

	Tread Depth MM								Air Pressure PSI							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	9	9	7	10					90	90	90	90	100	100	100	100
2	6	3	5	0				15	90	90	100	90	100	100		100
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE

20372138 MCC ©2023. All rights reserved. — 9355