

**rb RITCHIE BROS. Diagnostic Report**  
Auctioneers®

**2020 Kenworth T680**

| Test Information     |  |
|----------------------|--|
| <b>Engine</b>        | PACCAR MX/MX-13 (12.9)                   |
| <b>Engine Serial</b> | PCAR*MX26U19D13*Y204135*00000000         |
| <b>VIN</b>           | <a href="#">1XKYDP9X0LJ964939</a>        |
| <b>Driveline</b>     | Class 8 6x4                              |
| <b>Body</b>          | Truck-Tractor MDHD: CBE (Cab Behind Engi |
| <b>Test Time</b>     | April 23, 2026, 3:57 p.m.                |
| <b>File Length</b>   | 44.578 s                                 |

| Usage  |          |       |  |
|--|----------|-------|--|
| Label  | Value    | Units |  |
| Engine Odometer  | 627,007  | mi    |  |
| Odometer (Cab Controller - Primary)                          | 627,016  | mi    |  |
| Engine Total Hours of Operation                              | 15,316.7 | h     |  |
| Aftertreatment 1 Diesel Particulate Filter Soot Load Percent | 57       | %     |  |

| Engine On/Off  |
|----------------|
| Engine running |

| Check Engine Light        |
|---------------------------|
| No check engine lights on |

| Emissions Deleted/Tampered |
|----------------------------|
| No                         |

| Faults    |                            |   |                      |              |
|-----------|----------------------------|---|----------------------|--------------|
| <u>DM</u> | <u>Controller Name</u>     | <u>SPN Name</u>                           | <u>FMI Name</u>      | <u>Count</u> |
| Previous  | Brakes - System Controller | Wheel Sensor ABS Axle 1 Left              | Low-most severe      | 1            |
| Previous  | Brakes - System Controller | Wheel Sensor ABS Axle 1 Right             | Abnormal Update Rate | 1            |
| Previous  | Brakes - System Controller | J1939 Network #1. Primary Vehicle Network | Failure              | 5            |