

03969146

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 4524 Forest Postal Office
Winnipeg, MB, R2G 5G7
1-204-985-0520



Date Inspection Started: DAY 01, MO. 11, YR. 215
 Date Inspection Completed: DAY 03, MO. 11, YR. 215
 Inspection Expiry Date: DAY 31, MO. 10, YR. 216

Station Number: A112311
 Station Name: MARION TRACKING LTD Wpg
 City: A960615

Mechanic Number: M1501514
 Mechanic Signature: [Signature]
 Station Phone Number: 204-237-3171

Vehicle Owner: MARION TRACKING LTD
 Address: 578 McTAVISH ST Wpg MB R2J0E6
 City: Wpg Province: MB Postal Code: R2J0E6 Phone: 237-3171

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: INOT1
 Vehicle Identification Number: 3D16WA16E49A66117115A
 Make: RAM Model: Sevic Box Year: 11

Odometer Reading: 180031
 Odom. Type: km mi

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

G.V.W.R. 17485 KGS

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: <u>3H</u> 3A Defects (if any) Circle Brake Type Brake Inspection Type: A B C <u>D</u> E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">MM Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>14</td> <td>14</td> <td>37.74</td> <td>37.25</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>11</td> <td>38.45</td> <td>38.57</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	MM Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	14	14	37.74	37.25			2	11	11	38.45	38.57			3							4							5							Final Measurement																					
Axle	MM Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	14	14	37.74	37.25																																																																				
2	11	11	38.45	38.57																																																																				
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) #4A Gauge NOT WORKING																																																																						
X	X	Section 6 - Lamps: Defects (if any) #1 C RS Tail Light NOT WORKING. #1 J ID Lite on cab RS NOT WORKING																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) #4A CORRECTED TIRES PSI.																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">MM Tread Depth</th> <th colspan="4">PSI Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>12</td> <td>12</td> <td>12</td> <td>80</td> <td>80</td> <td>110</td> <td>110</td> </tr> <tr> <td>2</td> <td>7</td> <td>12</td> <td>12</td> <td>12</td> <td>80</td> <td>80</td> <td>110</td> <td>110</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	MM Tread Depth				PSI Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	12	12	12	12	80	80	110	110	2	7	12	12	12	80	80	110	110	3									4									5								
Axle	MM Tread Depth				PSI Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	12	12	12	12	80	80	110	110																																																																
2	7	12	12	12	80	80	110	110																																																																
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a ice Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: