



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM14625
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21901975

Inspection Result:
PASS

FACILITY: G. BAUMEISTER LTD. / S16090 INSP. TYPE: Complete INSP. START: 2026-Aug-28 12:00 PM MST
INSPECTOR: STONES, JOSHUA / 302012 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Aug-31 01:10 PM MST
WORK ORDER #: SHOP 2837 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 02108725 VIN: 1XKDD80X3XR955481
PLATE #: VL9273 UNIT/FLEET#: t235 OWNER/LESSEE NAME: COMPASS SERVICES FSJ LTD,
COMPASS SERVICES FSJ LTD
LICENCED GVW(kg): 55000 BODY STYLE: Truck Tractor ADDRESS: 10148 TUNDRA STREET
VEHICLE YEAR: 1999 ODOMETER: 809391 KM Fort St John, British Columbia
MAKE: KENWORTH HUB ODOMETER: V1J8C5, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) #2 axle diff leaking and trans output seal leaking, both class 3
Section 2 - Suspension	Repaired (same day) #2 axle hanger pivot bushings and rear #1 axle spring pins/bushings
Section 3 - Brake System	Repaired (same day) both slacks #2 axle have torn boots and brakes wearing abnormally
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) Power steering box excessive input play
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) fifth wheel slider has crack in rearmost p/s bracket
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.8	31.8	11			12	✓
2	Clamp	30	Automatic	38.1	38.1	10	8	6	8	
3	Clamp	30	Automatic	38.1	38.1	15	16	6	7	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17.5	15.9
Lining (Shoe)	14.3	14.3
Lining (Shoe)	15.9	14.3

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.79	419.56
Drum	420.29	420.34
Drum	419.68	420.22

Comment:

Inspection Comments:

All wheels torqued to 500ft lbs

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: STONES, JOSHUA

Signature:

This Inspection Report was submitted to CVSE on 2026-Aug-31 01:15 PM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

8/31/2026 1:15:08 PM MST