



Commercial Vehicle Inspection Report

Decal Number: PA11797
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21821931

Inspection Result:

PASS

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	32	Lining (Shoe)	20	20	Drum		
2	62	47	Lining (Shoe)	16	18	Drum		
3	58	65	Lining (Shoe)	17	16	Drum		
4	65	48	Lining (Shoe)	16	18	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: PEREGOODOFF, DAVID JAMES

Signature:

[Signature]

This Inspection Report was submitted to CVSE on 2026-Jun-23 09:57 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/23/2026 9:57:07 AM MST



Commercial Vehicle Inspection Report

Decal Number: PA11797
Decal Expiry Date: 2026-Dec-31
Inspection Number: 21821931

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS' / INSP. TYPE: Complete
N5398 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW
INSPECTOR: PEREGOODOFF, DAVID JAMES / 5501 kg or more
112485 INSP. REASON: Semi-annual
WORK ORDER #: INSP. START: 2026-Jun-23 08:00 AM MST
INSP. COMPLETE: 2026-Jun-23 09:00 AM MST

608-3

VEHICLE JUR: British Columbia REGI: 11616068 VIN: 1XKDP4EX5GR979275
PLATE #: WR8478 UNIT/FLEET#: T203 OWNER/LESSEE NAME: COMPASS, SERVICES FSJ LTD
LICENCED GVW(kg): 55000 BODY STYLE: Truck Tractor ADDRESS: 10148 TUNDRA ST
VEHICLE YEAR: 2016 ODOMETER: 838758 KM Fort St John, British Columbia
MAKE: KENWORTH HUB ODOMETER: V1J8C5, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) R LOW/HIGH BEAMS, L AIR CLEANER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	32	30
2	Clamp	30	Automatic	40	42
3	Clamp	30	Automatic	45	45
4	Clamp	30	Automatic	42	45

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
25			25	✓
25	25	25	25	
20	20	20	20	
19	19	20	20	

Comment:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/23/2026 9:37:07 AM MST