



Vehicle History Summary

Fleet #	ATT 054
Registration	XP27JT
Make	Kenworth
Model	T409
VIN / Chassis #	6F5000000HA459693
Build Date	2017

Date	Reading / Units	Type / Repairer Notes	Repairer
		front BAB mount bushes, front engine mount, front spring bushes, power steering reservoir R-20365	Maxx Truck Repairs Pty Ltd
		UHF Repair R-20955	
		After treat light R-21048	
		airconditioning faulty R-20529	Internal
		power loss R-21136	
04/08/2026	956,234 kms	A - 30 days S-15664 A service	Blair Wade, Corey Pollard, Simon Wade
30/07/2026		Lazy Axle Fault R-21098 REMOVE ABS PLUG CLEAN OUT BOTH PLUGS REFIT ABS PLUG	
29/07/2026	986,653 kms	check clearance light R-20780 CHECKED ALL LIGHTS AND WORKING	Simon Wade (Mechanic)
27/07/2026	954,476 kms	Truck tarp R-20950 INSTALL 2 NEW TARP CABLES AND ADJUST BELT TENSION	Simon Wade (Mechanic)
27/07/2026		trailer blinkers R-21072 At time of inspection no fault found	Corey Pollard
27/07/2026		truck step / rail R-21040 At time of inspection no faults found	Corey Pollard
27/07/2026	954,476 kms	Truck tarp R-21023 INSTALL 2 NEW TARP CABLES	Blair Wade, Corey Pollard
24/07/2026		Crack in Fuel Tank R-20599 Supply * Fuel Cap * Support - Fuel Tank * Crossmember F/Tank * Anchor-Offset Xmember Fuel Tank * Braided Hose	Blair Wade, multispares
24/07/2026		Limp Mode R-20981 Supply * Air Filter * Fuel Filter - ISX CR * Fuel/Water Filter - 10 Micron Longlife * Oil Filter	Blair Wade, multispares
23/07/2026		steer tyres T-3838 Upon inspection passenger side steer tire has not reached wear indicator and has air	
13/07/2026		Limp Mode R-20981 CONNECT COMPUTER DIAGNOSE ISSUE REPLACE PRE FILTER FOR FUEL CLEAR ALL CODES	Blair Wade
02/07/2026	986,653 kms	tarp plugs R-20946 INSTALL NEW TARP MALE AND FEMALE ELECTRICAL PLUGS ADJUST TRAILER TARP BELTS	Blair Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
02/07/2026		tarp plugs R-20947 INSTALL NEW TARP PLUG	
26/06/2026	946,000 kms	B - 30k S-15580	MAAS REPAIRS
11/06/2026		Tarp cable Fraying R-20450 REPLACED CABLES	Internal
04/06/2026	943,379 kms	A - 15/30 days S-15476	Simon Wade
19/05/2026	986,653 kms	parker lights R-20690 TRACE PARKER LIGHT ISSUE RESET CIRCUIT BREAKER NO FAULT FOUND ON TEST	Simon Wade (Mechanic)
18/05/2026	939,911 kms	Crack in Fuel Tank R-20599 REMOVE FUEL TANK AND SEND TO SLOANEBUILT FOR REPAIR INSTALL NEW J BRACKET TO O/S FRONT FUEL TANK REPAIR DAMAGED CROSSOVER MOUNT INSTALL NEW CROSSOVER BRACKET INSTALL NEW O/S FUEL TANK CROSSOVER TAP INSTALL NEW O/S FUEL TANK STRAP RUBBERS	Blair Wade
18/05/2026	939,911 kms	A - 15/30 days S-15320 A SERVICE NEXT B - 946,253	Simon Wade (Mechanic)
18/05/2026		cracked windscreen R-19578 BEEN DONE CHECKED ON 18/05/26	B&D Automotive Camden
15/05/2026	939,910 kms	Batteries R-20642 INSTALL 4 NEW N70ZZMF BATTERIES	Blair Wade
15/05/2026	986,653 kms	bonnet stainless trim R-20644 RERIVET STAINLESS TRIM ON O/S BONNET ARCH	Simon Wade (Mechanic)
02/04/2026	927,835 kms	engine code R-20372 CHECK ENGINE CODE FOUND COOLANT LOW FILL COOLANT INSTALL NEW RADIATOR CAP (SEALING RUBBER SPLIT)	Blair Wade
01/04/2026	926,909 kms	chassis stay bar, n/s rear tail lightan, n/s tail light bar, resecure hydraulic hoses R-20364 RESECURE HYDRAULIC HOSES UNDER CHASSIS TIGHTEN CHASSIS STAY BAR STRAIGHTEN DAMAGED N/S REAR TAIL LIGHT BAR REPLACE 1 X RED LED N/S REAR TAIL LIGHT	Maxx Truck Repairs Pty Ltd
01/04/2026	926,909 kms	A - 15/30 days S-15188	
26/03/2026	926,557 kms	BIN STUCK R-20334 REMOVED BROKEN AIRLINE INSTALL NEW AIRLINE AND TEST FUNCTION	Blair Wade, LA Diesel
24/03/2026		REMOVE TURBO R-20306 REMOVE TURBO AWAITING PARTS	Maxx Truck Repairs Pty Ltd
11/03/2026		hub cap steer R-20223	Internal
05/03/2026	916,936 kms	A - 15/30 days S-15098	Simon Wade (Mechanic)
04/03/2026	1 kms	tarp adjuster repair, Tarp switch R-20131 INSTALL NEW FRONT TARP SWITCH TRACE TARP STOPPING ISSUE FOUND DAMAGED O/S TARP ADJUSTER MOUNT AND REPAIRED ADJUSTED TARP SENSATIVITY AND TEST	Simon Wade (Mechanic)
04/03/2026		adjust clutch & clutch brake R-20132 ADJUST CLUTCH AND CLUTCH BRAKE	Simon Wade (Mechanic)
27/02/2026	9 kms	clutch adjust R-20098 ADJUSTED CLUTCH AND CHECKED CLUTCH BRAKE	Simon Wade (Mechanic)
26/02/2026	916,253 kms	Heater Tap, NEW COOLANT R-20097	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		INSTALL NEW COOLANT INSTALL NEW LOWER HEATER TAP	
24/02/2026		left hand tail light R-19810 Was Repaired and this Fault was for the Trailer not the truck (R-20079)	Internal
23/02/2026		C services repairs R-20065 INSTALL 1 X NEW SPOTTER MIRROR TIDY O/S DRAWBAR CABLES MAKE AND INSTALL NEW LEFT UHF HANDPIECE MOUNT INSTALL NEW ENGINE COOLANT	Simon Wade (Mechanic)
19/02/2026	916,253 kms	C - 120k/ Annual S-15037 Next B Service Due 946,253 KM	Simon Wade (Mechanic)
06/02/2026		L/H Back Tail Light R-19929 INSTALL NEW RED LED LIGHT	Mack Dubbo
05/02/2026		Replace tyre R-19962 TYRE REPAIRED	All Tyres Australia
30/01/2026		Tyre replacement R-19892 TYRE REPLACED	All Tyres Australia
08/01/2026		faulty UHF R-19546 check both uhfs from end of yard no fault found	Internal
08/01/2026	902,628 kms	A - 15/30 days S-14682 ETHAN WOOLNOUGH, Simon Wade (Mechanic)	
08/01/2026		axle brake lining R-19746 New O/S axle 3 brake lining installed	ETHAN WOOLNOUGH
08/12/2025		Tail gate Lights R-19587 opened up new repair, as this Fault is for the trailer YO17JE.	Internal
28/11/2025	891,844 kms	Bushes / R&R sway bars R-19534 pro axle	
25/11/2025		ring feeder R-19508 Red bush plate installed	ETHAN WOOLNOUGH, Simon Wade
25/11/2025		Seat pan / Seat R-19495 New seat base installed	Jake Doughty (Mechanic)
25/11/2025		seat belt R-18933 Done on 25/11/25 R-19495	Internal
21/11/2025	891,818 kms	B SERVICE REPAIRS R-19486 All repairs attached on Invoice # 3024	A&C Heavy Repairs Pty Ltd, Simon Wade (Mechanic)
21/11/2025		Various Repairs R-19574 Radiator stay support bushes Engine pipe small leak developing Bent fuel crossover / Tank support bar. repaired during service	Simon Wade (Mechanic)
12/11/2025	890,577 kms	B - 40k S-14336 ADJUSTED BY ANDREW AND RECHECK OK Torque ro bushes upper starting to tear Not required yet Repaired lights LH and rh step inop Seat belt free up by Ethan Hydraulic oil appears contaminated Ethan Exhaust isolators worn	Andrew Grindrod, Blake's Torque & Tinker
07/11/2025		adjust tarp cables R-19182 Re calibrated tarp Adjust cables Re align tarp Fixed bearing bracket	A&C Heavy Repairs Pty Ltd, ETHAN WOOLNOUGH
05/11/2025		Trailer tarp wire R-19200 Trailer tarp not truck	Internal

Date	Reading / Units	Type / Repairer Notes	Repairer
16/10/2025		Tyre replacement R-19176	Eagle Truck Centre
15/10/2025		Clutch Flywheel R-19117	Maxx Truck Repairs Pty Ltd
07/10/2025		A - 15/30 days S-14243 TRANSMISSION FILTER	multispare
06/10/2025		fit new pto pump R-19139	Maxx Truck Repairs Pty Ltd
30/09/2025	873,612 kms 204,618 hrs	repairs R-18910 BSPP 90 DEG. MALE X LP NIPPLE BSPT X BSPP BONDED SEAL SUIT BSPP THREAD	Hydraulink
29/09/2025	873,612 kms 204,618 hrs	repairs R-18784 CLUTCH KIT - GEN EATON 2050 MAN ADJ PD FLYWHEEL - CUMMINS ISX SIGNATURE 10"BORE CLUTCH INSTALLATION KIT - 2" 10 SPLINE HINGED CLUTCH BRAKE 2" SHAFT STD LINK ROD END - 3/8" F & M (WITH STUD) REAR SEAL KIT - ISX GASKET - FLYWHEEL HOUSING ISX GASKET - SHIFT LEVER HOUSING EATON GASKET (LID) SHIFT BAR HOUSING LEVER CLUTCH CONTROL *BUY-IN* CLUTCH RELEASE KIT *BUY-IN* CLUTCH LEVER *BUY-IN* SPIGOT BEARING 6306 HI-TEMP LEVER CLUTCH CONTROL	multispare
23/09/2025		adjust clutch brake R-18756 broken clutch springs, battery will be tested	Maxx Truck Repairs Pty Ltd
03/09/2025	873,612 kms	A - 15/30 days S-13690	Blair Wade, Simon Wade
03/09/2025	868,617 kms	A - 15/30 days S-13744 A SERVICE NEXT B - 886,641	Blair Wade
28/08/2025		fuel gauge R-18925 Changed fuel gauge	Internal
28/08/2025	867,675 kms 204,618 hrs	HUB CAP - STEER R-18621 HUB CAP - STEER	multispare
21/08/2025	865,829 kms 148,113 hrs	Front windscreen R-18573 s/f l/h front windscreen to 2017 kenworth t409	BD AUTO GLASS PTY LTD
18/08/2025		1st tarps front & back R-18403 tarps replaced via power tarps	sloanbuilt trailers
18/08/2025		Faulty Tarps R-18278 replaced power tarps	sloanbuilt trailers
14/08/2025		A service repairs R-18394 wind screen replaced. power steering hoses changed thru shaft on next month order Tyres changed all Tyres	
08/08/2025		A - 15/30 days S-13477 ADBLUE FILTER - SPIN ON WATER FILTER 0 UNITS DIFF FILTER TRANSMISSION FILTER DRIVE BELT - DAYCO DRIVE BELT STEERING FILTER - PAPER TYPE KIT UNLOADER VALVE TURBO 2000 FILTER ONLY - WATER ONLY - TURBO 2000 ADBLUE FILTER - IN TANK CABIN FILTER - PLASTIC FRAMED	multispare
06/08/2025	865,280 kms	A - 15/30 days S-13471 Multiple lights out on step Will order C kit for it	Blair Wade
06/08/2025		camera R-17059 KC replace3d all defective parts	
04/08/2025	857,100 kms	Engine R-18377	Cummins South Pacific Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
31/07/2025		lazy axle R-18328 Replace air fitting at lazy axle	Simon Wade (Mechanic)
31/07/2025		rear diff leak R-17098 Air leak repaired at firewall Tighten and wash both diffs	Simon Wade (Mechanic)
31/07/2025		tarp belts R-18288 Install new tarp belts	Simon Wade (Mechanic)
31/07/2025		tarp belts R-18327 Install new tarp belts	Simon Wade (Mechanic)
30/07/2025		faulty UHF R-17073 Install new uhf	Simon Wade (Mechanic)
30/07/2025		multiple repairs R-17156 Tarp belts replaced Steering wheel replaced ABS plug cleaned	Simon Wade (Mechanic)
30/07/2025		ABS fault R-18935 repaired dirty plug	Internal
30/07/2025		number plates R-15085 New number plates installed	Blair Wade, Simon Wade
23/07/2025	862,502 kms	steering wheel R-18203 New steering wheel installed	
23/07/2025	862,502 kms	seat belt R-18202 New seat belt installed	
23/07/2025	861,876 kms	Engine tune R-18204 done a jake brake tune and replaced worn solenoids	Cummins South Pacific Pty Ltd
21/07/2025	861,808 kms 148,113 hrs	SIDE MARKER AMBER LED R-18180 SIDE MARKER AMBER LED	
18/07/2025	861,808 kms 148,113 hrs	DIFF SEAL - UNITISED, SEAT BELT - RHS - WITHOUT PRETENSIONER R-18167 DIFF SEAL - UNITISED SEAT BELT - RHS - WITHOUT PRETENSIONER	multisparres
16/07/2025	861,241 kms	over take stickers R-18141 New over take stickers installed	
16/07/2025	861,241 kms	coolant tap R-18142 Driver complained of coolant frequently getting topped up. Coolant tap was changed	
07/07/2025	857,594 kms 148,113 hrs	air filter, FUEL FILTER - ISX CR, FUEL/WATER FILTER - 10 MICRON LONGLIFE, oil filter R-18059 AIR FILTER FUEL FILTER - ISX CR FUEL/WATER FILTER - 10 MICRON LONGLIFE OIL FILTER	multisparres
30/06/2025	856,043 kms 148,113 hrs	HADLEY 500 HCV W/BRACKETS R-18026 HADLEY 500 HCV W/BRACKETS	multisparres
30/06/2025		Left tank leaking Diesel R-20381 blair repaired with new fitting	Internal
30/06/2025	865,223 kms	B - 30k S-15311	Simon Wade
25/06/2025	853,736 kms	bin reflective tape R-17999 Remove old reflective bin tape Install new bin reflective tape to truck and trailer	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
25/06/2025	853,736 kms	bug deflector R-17998 Remove bug deflector	Simon Wade (Mechanic)
19/06/2025		brake lights R-17952 changed light	Jacob Rennex-Apprentice Mechanic
16/06/2025	852,702 kms 148,113 hrs	after hours, puncture repair T-3520 AFTER HOURS/TIME (HOURS) PUNCTURE REPAIR	All Tyres Australia
16/06/2025		Fault T-3513	All Tyres Australia
16/06/2025		Fault T-3514 REPAIRED FLAT TYRE	All Tyres Australia
10/06/2025	849,014 kms 148,113 hrs	CHROMESAFE 33MM ROUND PUSH FIT R-17884 CHROMESAFE 33MM ROUND PUSH FIT	multispare
10/06/2025	849,014 kms	A - 15/30 days S-13856	Blair Wade, Simon Wade
06/06/2025	848,784 kms	yellow park valve R-17872 New yellow button and park valve installed	Simon Wade
06/06/2025	848,784 kms	leveling valve R-17871 New 3rd axcel N/S leveling valve installed	Simon Wade
06/06/2025	848,784 kms	coolant leak R-17873 Coolant leak Pressure tested coolant system found leak coming from bottom radiator hose clamp Tighten clamp	Simon Wade
28/05/2025		auto tarp R-17824 TIGHTEN AND STRAIGHTEN TARP	Simon Wade (Mechanic)
21/05/2025		Tailshaft centre bearing R-17743 Install new tailshaft centre bearing	Simon Wade (Mechanic)
21/05/2025		Front Step Lights R-17744 Repair step light wiring	Simon Wade (Mechanic)
20/05/2025	845,345 kms 148,113 hrs	brake test R-17703 RECTIFY BRAKES FAILING ON BRAKE TEST	Sydney Trucks and Machinery
15/05/2025	844,749 kms 148,113 hrs	airbag assy R-17669 AIRBAG ASSY - AIRGLIDE 10.5" RIDE HEIGHT	multispare
14/05/2025		air brake R-17647 New foot valve New brakes Brake adjust Brake test- passed test at STM	Simon Wade
13/05/2025	844,395 kms	A - 15/30 days S-13252 A SERVICE NEXT B - 851,124 - PTO Hose Leaking - Both Diffs Leaking	Blair Wade
29/04/2025		steering column R-17462 Install new steering column gas strut	Simon Wade (Mechanic)
29/04/2025		prestart R-17464 Repaired front diff yoke nut leak Installed new tailshaft centre bearing Cameras repaired by K&C auto	Simon Wade (Mechanic)
15/04/2025	8,422,500 kms 148,113 hrs	battery box cover R-17404	multispare

Date	Reading / Units	Type / Repairer Notes	Repairer
BATTERY BOX COVER SPECIAL BUY IN PART , CANNOT BE RETURNED FOR CREDIT ETA 1 DAY T409 REGO CP01BZ			
14/04/2025	843,585 kms	steering column gas strut R-17401 Install new steering column gas strut	Simon Wade (Mechanic)
14/04/2025	843,585 kms	Bonnet mirror R-17400 Install new bonnet mirror	Simon Wade (Mechanic)
14/04/2025	843,585 kms	tailshaft unis R-17399 Install new tailshaft centre bearing Install new diff yoke nut and seal spline to front diff front yoke	Simon Wade (Mechanic)
03/04/2025	844,040 kms	A - 15/30 days S-13060 A SERVICE NEXT B - 851,124 - New Airbag Fitted - 2x Steer Slack Adjusters Fitted	Blair Wade
03/04/2025	844,040 kms	front slack adjusters R-17360 Replaced steer slack adjusters on service	Blair Wade
03/04/2025	844,040 kms	airbag tear R-17359 Replaced axle 2 rear N/S airbag	Blair Wade
19/03/2025	834,245 kms	C - 100k/ Annual S-12738 AF26417 ATT054 AIR FILTER D100A4 173.63 347.26 1 1 FF5776 ATT054 FUEL FILTER - ISX CR D100C2 60.34 60.34 1 1 FS19764 ATT054 FUEL/WATER FILTER - 10 MICRON LONGLIFE D100C3 35.01 35.01 1 1 LF14000NN ATT054 OIL FILTER D100C1 58.10 58.10	multispare
19/03/2025	834,265 kms	C - 100k/ Annual S-12093	Blair Wade
11/03/2025	840,997 kms	A - 15/30 days S-13008 A SERVICE NEXT B - 851,124 - Diff Yoke Nut & Seal - Tailshaft Uni Bearing - 2nd Diff Leaking - Steering Wheel	Blair Wade
03/03/2025		camera R-17116 reglue camera on window	Simon Wade (Mechanic)
26/02/2025		wipers R-16900 2 x new wipers installed	Simon Wade (Mechanic)
26/02/2025		Windscreen chip R-15734 New windscreen installed	Simon Wade (Mechanic)
26/02/2025		step lights R-16902 Repair step light wiring	Blair Wade
26/02/2025		dolly tyres R-16903 Tyres sorted by all tyres aus	Simon Wade (Mechanic)
26/02/2025		Prestart fault R-16904 not a fault	Simon Wade (Mechanic)
26/02/2025		wipers R-16905 Install 2 x new wipers	Simon Wade (Mechanic)
26/02/2025		Crack in window R-16899 2 x new windows installed	Simon Wade (Mechanic)
26/02/2025		cracked window R-16898 2 x new windows installed	Simon Wade (Mechanic)
26/02/2025		tarps R-16896 Tarps are booked this year	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
26/02/2025		tarps R-16897 Tarps are booked this year	Simon Wade (Mechanic)
26/02/2025		Air leak R-16901 Repair air line near air drier	Simon Wade (Mechanic)
06/02/2025		air con fan R-16760 accessories need to be on	Simon Wade (Mechanic)
04/02/2025	832,345 kms	A - 15/30 days S-12900 A SERVICE NEXT B - 851,124 - Replaced Both Fan Belts	Blair Wade
03/02/2025		trailer coupling R-16640 1 1 49G0017WABCO ATT054 TRIOMATIC TRAILER COUPLING - FEMALE 188.61 188.61	multispare
15/01/2025	827,430 kms	Hydraulic hoses R-16518 Hydraulink installed PTO feed hose and pressure feed and return hoses Remove all hydraulic oil due to being burnt and install 145ltrs of hydraulic oil Install new a/c fanbelt Pressure wash all chassis from gearbox to rear Test and check hoist operation	Simon Wade (Mechanic)
15/01/2025	827,430 kms	A - 15/30 days S-13855	
15/01/2025	804,318 kms	tarp belts R-16522 Tarp belts replaced	Simon Wade
15/01/2025		drive belt R-16798 Drive Belt	multispare
14/01/2025	810,995 kms	check taillights R-16521 Wiring repaired and 1 light changed	Simon Wade (Mechanic)
14/01/2025	834,245 kms 148,113 hrs	Hydraulic Leak R-16520 New hoses installed by Hydraulink	Simon Wade (Mechanic)
19/12/2024	827,430 kms	Hydraulic leak R-16519 Hydraulink replaced 3 hoses and new oil installed	Simon Wade (Mechanic)
09/12/2024		Clearance Lights R-16413 Repair wiring o/s rear	Simon Wade (Mechanic)
06/12/2024		Clutch brake R-16380 Adjust clutch and clutch brake	Blair Wade
05/12/2024	822,828 kms 148,113 hrs	couplings and adaptor R-16437 MAKE UP HOSES AND ADAPTORS AS PER SAMPLE 8.5 5C5D SAE 100 R5 COTTON COVER TYPE D \$62.78 MTR 20% \$426.90 GST 4 S05H-0704 JIC STRAIGHT FEMALE \$11.94 EA 20% \$38.21 GST 4 SNV-04 FERRULE TO SUIT C5C/C5D/C5E \$16.11 EA 20% \$51.55 GST 4 C Crimp \$14.00 EA \$56.00 GST 1 A-G-90-0207 ELBOW BSPT X JIC M/M 90 DEG. \$23.52 EA 20% \$18.82 GST 1 A-G-90-0407 ELBOW BSPT X JIC M/M 90 DEG. \$21.74 EA 20% \$17.39 GST	Hydraulink
04/12/2024	819,873 kms	governor air lines R-16371 Remove 2 x charge air lines from chassis Install 2 x new governor charge lines by Hydraulink Re cable tie all chassis lines and test	Simon Wade (Mechanic)
04/12/2024	819,874 kms	A - 15/30 days S-12700 A SERVICE NEXT B - 816,166 - Governor hoses - Backing plate	Blair Wade
13/11/2024		faulty wipers R-16277 Install new wiper blades	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
13/11/2024		Air leaks R-16278 Repair air leak at fire wall	Simon Wade (Mechanic)
07/11/2024		adjust clutch brake R-16226 Adjusted clutch and clutch brake	Simon Wade (Mechanic)
06/11/2024		Clearance Lights R-16225 Install new light	Simon Wade (Mechanic)
06/11/2024		Side tank lights R-16224 Install 1 x new n/s tank light Repair wiring to o/s tank light	Simon Wade (Mechanic)
04/11/2024	806,888 kms	A - 15/30 days S-12629 1st diff input shaft needs nut and seal 1st drive passenger side air bag needs replacing 2nd diff centre needs a re-seal	Christopher Watson-Mechanic
01/11/2024	805,601 kms	horton fan R-16207 Drained coolant due to being to weak from being topped up with water. Remove all intake piping and top radiator hoses. Used weight of bonnet to lean radiator Rebuild Horton fan assemble and test operation. Reassembled all components removed. Fit new top radiator hoses Fill wth new coolant. Take on road test up lapstone hill Recheck coolant level and park up.	Christopher Watson-Mechanic
31/10/2024	783,804 kms	Trailer bin holes at hoist R-15735 Checked at service has already been repaired	sloanbuilt
31/10/2024	784,234 kms	coolant hose leak R-15736 Checked at service has already been repaired	Christopher Watson-Mechanic
28/10/2024	804,506 kms	blinker wiring R-16163 Solder up wires and heat shrink to clean all up	Blair Wade
28/10/2024		blinkers R-16168 Repaired blinker wiring	Blair Wade
25/10/2024	803,698 kms	trailer tyres T-3238 Fitted 2 x Evergreen 295/149M EG901 - Steer - POS 1-2 2 x Balance Bead Bags	All Tyres Australia
17/10/2024		light globe R-16082 Install blinker globe	Blair Wade
10/10/2024	801,861 kms	A - 15/30 days S-12504 A SERVICE NEXT B - 816,166 - all exhaust gaskets needed - centre bearing needed	Blair Wade
16/09/2024	796,049 kms	A - 15/30 days S-13854	Blair Wade, Simon Wade
09/09/2024		lower trailing arm bushes R-15994 Replace 2 bushes	Blair Wade
02/09/2024		Parts O-3627 Service Parts	multispares
23/08/2024		Prestart fault R-15790 A/C repaired by Ace auto Ringfeder bush and wear plate repl;aced by Blair Wade Windscreen booked for replacement Adjust steer axle tyre pressures	Simon Wade (Mechanic)
13/08/2024	789,581 kms	A - 15/30 days S-13853	Blair Wade, Simon Wade
26/07/2024	782,088 kms	heater core R-15607 Install new heater core	Simon Wade (Mechanic)
25/07/2024		damage on front bar R-16217 Repair on damaged front bar	Tri City Trucks

Date	Reading / Units	Type / Repairer Notes	Repairer
25/07/2024		heater core R-15608 Install new heater core	Simon Wade (Mechanic)
25/07/2024		heater core R-15609 Install new heater core	Simon Wade (Mechanic)
23/07/2024	779,317 kms	repair side step lights R-15596 Cleaned up wiring	Blair Wade
05/07/2024	776,937 kms	A - 15/30 days S-12272 A SERVICE NEXT B - 783,639 - 4 Dash globes - Horton needs rebuilding - centre bearing needed - Front diff yoke nut & bearing kit - number plater	Blair Wade
28/06/2024	772,054 kms	check clearance light R-15380 Repaired broken wires	Christopher Watson-Mechanic
28/06/2024	772,054 kms	roof clearance light, step clearance lights R-14992 Repaired broken wires all ok.	Christopher Watson-Mechanic
28/06/2024	772,054 kms	clearance lights R-15475 Repaired broken wires.	Christopher Watson-Mechanic
28/06/2024	772,054 kms	park tail light out R-15382 At time of inspection all light working correctly.	Christopher Watson-Mechanic
11/06/2024	763,074 kms	Batteries R-15349 install 4 x new century N70ZZmf batteries	Simon Wade (Mechanic)
04/06/2024	761,518 kms	A - 15/30 days S-12170	Christopher Watson-Mechanic
16/05/2024	755,006 kms	check tyres R-15219 Install 4 x runout tyres to axle 3	Blair Wade
16/05/2024	755,006 kms	A - 15/30 days S-12092 Service completed	Blair Wade
09/05/2024		half windscreen R-15431 Supply & Fit O/S front windscreen	
30/04/2024		insurance repair R-14900 repaired through insurance	
24/04/2024		Faulty Tarps R-14899 tarps repaired	
04/04/2024	753,639 kms	A - 15/30 days S-11957 service completed	Simon Wade (Mechanic)
04/04/2024	753,639 kms	B - 30k S-11958 Service completed	Simon Wade (Mechanic)
29/03/2024		drivers window cracked R-14251 window replaced	
20/03/2024		7 pin female plug, axle, camera wiring, centre bearing, engine oil, Tyres R-14632 all done and completed except centre bearing that is on repair 15085	Blair Wade
19/03/2024		air R-14690 Check for air leaks through trailer Tightened air leak on axle 2 o/s brake booster Remove trailer ABS plug and clean corrosion off terminals Test and check ok	Simon Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
08/03/2024		Airconditioner R-14754 Sent to ace auto for repair problem fixed	Ace Air Auto Electrical
08/03/2024		uhf handpiece R-14748 replaced both uhf handpieces and solved problem	Jacob Rennex-Apprentice Mechanic
07/03/2024	745,279 kms	check tyres R-14626 Install 4 x new axle 2 tyres Move runout tyres from axle 2 to axle3 o/s	Blair Wade
06/03/2024		engine oil R-14622 Removed 5 ltr of engine oil	Simon Wade (Mechanic)
06/03/2024	745,279 kms	A - 15/30 days S-11864 Service completed	Simon Wade (Mechanic)
01/03/2024		Clearance LED R-14598 Install spacers behind light bplate	Simon Wade (Mechanic)
01/03/2024		oil level R-14599 check level ok	Simon Wade (Mechanic)
28/02/2024		oil level R-14555 oil level checked ok	Simon Wade (Mechanic)
23/02/2024		check tyres R-14492 Checked tyres and tread ok-to be changed next month	Blair Wade
15/02/2024		Registration O-3325	
09/02/2024		faulty UHF R-14398 Perform uhf test no fault found	Jacob Rennex-Apprentice Mechanic
09/02/2024	737,713 kms	A - 15/30 days S-11777 Service completed	Simon Wade (Mechanic)
07/02/2024		bald tyre R-14753 tyres replaced JR confirmed with driver they have been changed	Blair Wade
05/02/2024	735,904 kms	Checking Oil R-14352 check oil ok	Simon Wade (Mechanic)
31/01/2024		axle shocks, body damage, diff pinion nut, diffs weeping, Diverter Valve Leaking R-14251 Body damage noted Waiting on parts for other repairs listed	Jacob Rennex-Apprentice Mechanic
30/01/2024		damaged wiring R-14750 repaired wiring	Simon Wade
29/01/2024		change tyre R-14328 tyre changed	Simon Wade (Mechanic)
25/01/2024		Check oil R-14334 check and asjust level	Blair Wade
25/01/2024		change tyre R-14326 changed tyre	Simon Wade (Mechanic)
18/01/2024		damaged wiring R-14297 repair wiring	Simon Wade (Mechanic)
16/01/2024		numberplate resecured R-14733	Jacob Rennex-Apprentice Mechanic

Date	Reading / Units	Type / Repairer Notes	Repairer
		bolts replaced and retightened	
10/01/2024	729,026 kms	axle brakes R-14036 Install new axle 2 and 3 hub seals Install new axle 2 and 3 slack adjusters Install new axle 2 and 3 brake boosters 30/30 Install new axle 2 and 3 s-cams and bushes and seals Install new axle 2 and 3 brake linings and drums Install new axle 3 ABS sensor Install 3 new axle 3 airbags Test run and check	Simon Wade (Mechanic)
10/01/2024		brake lights R-14047 Repair brake light,number plate and reverse wiring	Jacob Rennex-Apprentice Mechanic
09/01/2024	729,000 kms	A - 15/30 days S-11671 Service completed	Simon Wade (Mechanic)
20/12/2023		roller brake test R-14363	Sydney Trucks and Machinery
19/12/2023		Parts O-3291 75PS pressure switch	Gilbert & Roach
19/12/2023	728,663 kms	auto slack adjuster R-14010 Install new axle 3 o/s slack adjuster	Simon Wade (Mechanic)
13/12/2023		Check oil R-14121 noted and drain some oil	Simon Wade (Mechanic)
12/12/2023		damaged hydraulic hose R-14208 replace hydraulic coupling	Simon Wade (Mechanic)
12/12/2023		After treat light R-14120 Clean adblue lines and reset	Simon Wade (Mechanic)
11/12/2023	723,457 kms	B - 20k S-11627 service completed	Corey Lonergan
07/12/2023		number plate lightr R-14122 Install new led light	Simon Wade (Mechanic)
07/12/2023		QRI Valve R-14000 completed	Jacob Rennex-Apprentice Mechanic, Simon Wade
06/12/2023	723,457 kms	A - 5k/ 21 days S-11615 Service completed	Corey Lonergan
06/12/2023	722,748 kms	chipped windscreen R-14119 monitor crack	Simon Wade
23/11/2023		faulty tyre R-13917 Tyre chanaged	Simon Wade
21/11/2023		bin floor R-13884 Simon spoke with Freddy from Sloanebuilt Trailers to be booked in for February 2024	Simon Wade
20/11/2023	715,471 kms	A - 15/30 days S-13852	Blair Wade, Simon Wade
20/11/2023	715,471 kms	front left steer tyre R-13863 1 STEER TYRE	Blair Wade
10/11/2023		air conditiner R-13916 ace air repaired	Ace Air Auto Electrical
09/11/2023		Faulty Tarps R-14027 Found earth to be all melted,repaired melted wiring,working ok	BSC Auto Electrical Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
03/11/2023	712,449 kms	tarp pulley bearing R-13795 Replace bearing Tensioned tarp cable	Blair Wade
31/10/2023		Hydraulic leak R-13800 Cleaned coupling & will monitor	Simon Wade
31/10/2023		Brake linings, drive shocks, radiator coolant hose, tail shaft centre bearing, trailing arm bush R-13637 Brake Linings done 31/10/2023 Jacob Rennex	Jacob Rennex-Apprentice Mechanic, Simon Wade
31/10/2023		cabin shock leaking, Dash globes, diff seals, lower trailing arm bushes, slack adjusters, Steer tyres, Windscreen chip R-13796	Blair Wade, Simon Wade, Jacob Rennex-Apprentice Mechanic
31/10/2023	711,712 kms	runout tyres T-2970 3rd axle o/s inner & outer drives with runout tyres as tyres were bald	Jacob Rennex-Apprentice Mechanic
31/10/2023	711,712 kms	A - 5k/ 21 days S-11503 Service completed	Simon Wade (Mechanic)
23/10/2023		rear drive tyres T-2978 rear drive tyres have been replaced	Simon Wade
17/10/2023	705,757 kms	Filter Leaking R-13668 Install new gearbox filter	
17/10/2023	699,680 kms	wiper blades R-13390 Install new wiper blades complete	
17/10/2023	703,342 kms	bonnet mirror R-13615 Remove and tighten bonnet mirror	
17/10/2023		coolant leak R-13700 Tighten both bottom radiator hose clamps Install 3 ltr coolant	Simon Wade
17/10/2023		faulty UHF R-13701 Install 2nd hand left UHF 80 channel and handpiece Make and install hand piece holder Test and check UHF	Simon Wade (Mechanic)
06/10/2023		Split tyre R-13620 1 x new steerTyre replaced	
06/10/2023	703,668 kms	A - 5k/ 21 days S-11420 Service completed	Simon Wade (Mechanic)
29/09/2023		Midlife R-13652	Cummins South Pacific Pty Ltd
12/09/2023	700,668 kms	A - 15/30 days S-13851	Blair Wade, Simon Wade
31/08/2023	698,232 kms	aftertreatment codes R-13384 Check fault codes on computer and found water in fuel code Install new fuel pro filter and clean out fuel housing Test run and check-ok	Andrew Grindrod, Simon Wade
24/08/2023	694,360 kms	sump gasket leak R-13300 Cleaned and been monitored	
11/08/2023		air filter, brake linings, clearance light, diverter valve, hub seals, ram seal, sump gasket leak R-13340 replaced 3 x faulty red clearance lights,r/h/s	Jacob Rennex-Apprentice Mechanic
10/08/2023	690,856 kms	maintenance R-13267 Replaced 3 hoses Exhaust cut out put all new pipes in Hydraulic leak replaced o-rings washed tightened hoses Diff leak still there 2 drive shocks in stock Missing wheel indicators replaced indicators Red lights ordered Lights in dash replaced Tarps still ripped	Corey Lonergan

Date	Reading / Units	Type / Repairer Notes	Repairer
09/08/2023	690,171 kms	brake drum, brake linings axle hub seal R-13248 Replace all broken/worn components	Blair Wade
08/08/2023	691,000 kms	B - 20k S-11282 B service completed	Simon Wade
07/08/2023		air conditioner faulty R-13209 Repaired- new belts	Simon Wade
07/08/2023		Coolant leak R-13136 Replaced header tank coolant hose Replaced coolant hose to thermostat at housing Replaced Horton Hose	
04/08/2023		centre bearing,tailshaft, gearbox filter, trailing arm bush R-13316	Simon Wade
02/08/2023	689,221 kms	A - 5k/ 21 days S-11259 A service completed	Simon Wade
31/07/2023		camera faulty, indicator R-13262 Monitor fault with camera Repaired indicator	
21/07/2023	687,074 kms	Lights R-13121 Repaired	
10/07/2023	680,684 kms	Air conditioner R-13151 Repaired	
07/07/2023	684,783 kms	A - 5k/ 21 days S-11180 A service completed Assisted Simon on LH Rear brake reline	A&C Heavy Repairs Pty Ltd
22/06/2023	680,023 kms	puncture repair, strip/flip tyre T-2893 2 x strip/flip tyres & 2 x balance beads bag positions 1,2 1 x puncture repair position 10	All Tyres Australia
05/06/2023	674,507 kms	Tyres T-2880 2 x tyres & 2 x disposals positions 7,8	All Tyres Australia
05/06/2023	675,141 kms	Gear Box Filter, Reverse spotlights, tank lights, Tank valve R-13016 o	Blair Wade
05/06/2023	675,141 kms	A - 5k/ 21 days S-11109 service completed	Simon Wade
30/05/2023		lower trailing arm bushes, shock lower mounts R-13010	A&C Heavy Repairs Pty Ltd
22/05/2023	670,001 kms	puncture repair T-2852 1 x puncture repair pos 7	All Tyres Australia
22/05/2023	667,480 kms	puncture repair T-2858 2 x puncture repairs position 3,6 call out fee	All Tyres Australia
19/05/2023		Parts O-2997 2 x bearing cup & cone assy 1 x seal assy 1 x snap ring 1 x pinion nut & washer 1 x yoke RPL20 meritor thrushaft labour & workshop charge	Truck Transmission Pty Ltd
19/05/2023	670,843 kms	B - 20k S-11035 service completed Needs lower trailing arm bushes Needs shocks,lower mounts worn	A&C Heavy Repairs Pty Ltd
04/05/2023	666,640 kms	A - 5k/ 21 days S-10995	Sean (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		service completed	
04/05/2023	666,640 kms	adjust brakes, clamps, Fire extinguisher R-12823	Sean (Mechanic)
		completed 4/5/2023	
20/04/2023		Parts O-2943	multispares
		drive belts filters king pin kit shackle pins	
18/04/2023		Steer Drag Link R-12935	A&C Heavy Repairs Pty Ltd
		completed	
04/04/2023	662,460 kms	A - 15/30 days S-13850	Blair Wade, Simon Wade
30/03/2023	658,726 kms	C - 100k/ Annual S-10903	Sean (Mechanic)
		service completed	
30/03/2023		Coolant leak, Exhaust leak, Ladder handle, Number plate faded, Sump leak R-12949	Sean (Mechanic)
		No paperwork handed in by Sean	
30/03/2023		Parts O-2910	Gilbert and Roach
		Knuckle assy LH with bush	
10/03/2023		Parts O-2916	sloanebuilt Trailers
		Jost T/Table steel plates DK39C	
07/03/2023	650,858 kms	B - 20k S-10813	Sean (Mechanic)
		Service completed repair list attached	
07/03/2023	650,858 kms	A - 5k/ 21 days S-10812	Sean (Mechanic)
		service completed	
06/03/2023		diff torque rod bushes, tank lights, tension shock R-12720	Sean (Mechanic)
		Torque rod bushes-Monitor Repaired tank lights Tensioned shocks	
06/03/2023		steering fault R-12735	Simon Wade
		Backlash within Spec	
06/03/2023	650,858 kms	Coolant R-12736	Simon Wade
		Checked fluid levels 6/3/2023	
17/02/2023		Registration O-2782	
16/02/2023		water leaks R-12760	A&C Heavy Repairs Pty Ltd
		water transfer tube	
15/02/2023	642,714 kms	Air leak maxi R-12711	Sean (Mechanic)
		Replaced trailer park valve 9/2/2023 Movement in draw bar bushes 9/2/2023 replaced ring eye feeder bush 9/2/2023 ringfeeder rebuild needed completed 15/2/2023	
09/02/2023	639,354 kms	A - 5k/ 21 days S-10728	Sean (Mechanic)
		Service completed Repair list attached	
09/02/2023	637,985 kms	clearance light R-12710	Sean (Mechanic)
		Drivers side & passenger side repaired 9/2/2023 Foot pedal not working properly-checks needed	
01/02/2023	635,289 kms	Engine codes, Intake pipe turbo, Shocks R-12674	Sean (Mechanic)
		completed	
25/01/2023		Parts O-2871	multispares
		filters,valves,trailer couplings	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/01/2023		Parts O-2870 air dryer assy	multispares
21/01/2023	633,992 kms	air conditioner operation R-12798 located no 8 leaking hose assy make & fir new hose	Ace Air Auto Electrical
20/01/2023		Air fault R-12629 completed	A&C Heavy Repairs Pty Ltd
10/01/2023	631,970 kms	A - 5k/ 21 days S-10613 Completed	Sean (Mechanic)
20/12/2022		Hoist control pad R-12617 completed	Simon Wade
15/12/2022		Parts O-2758 hood supports x 2	Gilbert and Roach
15/12/2022	627,518 kms	Exhausr pyro probe R-12616 completed	Sean (Mechanic)
07/12/2022		Parts O-2757 fuel tank sender	Gilbert and Roach
07/12/2022	625,591 kms	A - 5k/ 21 days S-10547 completed	Simon Wade
05/12/2022	624,318 kms	Coolant, Coolant filter R-12558 completed	Simon Wade
29/11/2022		puncture repair T-2732 Puncture repair position 9 after hours call out	All Tyres Australia
29/11/2022		New Tyres T-2735 2 x tyres positions 1,2 2 x balance bead bags 2 x disposals call out	All Tyres Australia
25/11/2022		Parts O-2717 pressure switch	Gilbert and Roach
18/11/2022		New tyres T-2728 2 x tyres positions 1,2 2 x balance beads bag 1 x call out	All Tyres Australia
11/11/2022	617,947 kms	B - 20k S-10482 completed Defect list attached	Simon Wade
03/11/2022	614,561 kms	A - 5k/ 21 days S-10442 completed List attached	Simon Wade
31/10/2022	612,174 kms	tyres T-2717 2 x tyres,balance bead bags position 1,2 2 x disposals	All Tyres Australia
05/10/2022	604,690 kms	Assorted R-12557 completed	Simon Wade
04/10/2022		Parts O-2676 heater tap USB charge port glass-sight radiator	Gilbert and Roach
04/10/2022	604,690 kms	A - 5k/ 21 days S-10375 completed	Simon Wade
20/09/2022	598,431 kms	New tyres T-2686	All Tyres Australia

Date	Reading / Units	Type / Repairer Notes	Repairer
		4 x new tyres positions 3,4,5,6 4 x disposals	
13/09/2022	599,013 kms	A - 5k/ 21 days S-10343 completed Repair list attached	Simon Wade
12/09/2022	599,013 kms	body guard, filter, governor valve R-12418 completed	Simon Wade
19/08/2022	588,193 kms	B - 20k S-10307 completed	A&C Heavy Repairs Pty Ltd
30/07/2022	575,560 kms	A - 5k/ 21 days S-10247 completed	A&C Heavy Repairs Pty Ltd
21/07/2022		Parts O-2561 Exhaust elbow pipe,clamp,gasket	Gilbert & Roach
21/07/2022		Parts O-2560 Clamp & exhaust gasket	Gilbert and Roach
16/07/2022		fire extinguisher, Under run protection R-12339 completed	sloanebuilt Trailers
05/07/2022	566,846 kms	A - 5k/ 21 days S-10205 completed	Jayden Haule
04/07/2022		Parts O-2568 combo switch	multispartes
04/07/2022	566,846 kms	B - 20k S-10207 completed	Jayden Haule
17/06/2022		New tyres, Rim T-2652 2 x tyres position 7,8 1 x disposal ,1 x kept for runout second hand rim	All Tyres Australia
17/06/2022		air bags, brake linings, rear shocks R-12260 completed	Jayden Haule
16/06/2022		Parts O-2491	multispartes
14/06/2022		Governor hose R-12303 completed	Hydraulink
27/05/2022	549,677 kms	A - 5k/ 21 days S-10107 completed List of repairs attached	Jayden Haule
26/05/2022		Alternator, check starting system R-12245 located faulty starter motor replaced	Ace Air Auto Electrical
18/05/2022	545,925 kms	Number plate hanging off R-12192 Corey put new bolts to tighten it Travel 1hr	Corey Lonergan
17/05/2022	545,567 kms	A - 5k/ 21 days S-10057 completed Repairs attached	Jayden Haule, Simon Wade
17/05/2022	545,567 kms	B - 20k S-10059 completed	Jayden Haule
12/05/2022		Parts O-2454 5 x silicone hose	multispartes
06/05/2022	542,900 kms	Clutch Replacement R-12145	A&C Heavy Repairs Pty Ltd

Date	Reading / Units	Type / Repairer Notes	Repairer
		completed	
05/05/2022		grease hose R-12250	Hydraulink
		completed	
29/04/2022		Defects R-12101	Simon Wade
		TPS roller kit installed 2 x Red reflectors	
21/04/2022	536,528 kms	Loosing power R-12097	A&C Heavy Repairs Pty Ltd
		Replaced both speed sensors	
14/04/2022	532,956 kms	computer fault codes, NOX sensor R-12098	Simon Wade
		completed	
14/04/2022	532,956 kms	A - 5k/ 21 days S-9993	Simon Wade
		completed	
08/04/2022	534,202 kms	C - 100k/ Annual S-10003	Simon Wade
		Completed List of defects attached	
24/03/2022		Parts O-2394	Gilbert and Roach
		pins-hood locating front engines bushings shock absorber anti vibration busshings	
23/03/2022		Defects R-12021	Simon Wade
22/03/2022	523,181 kms	A - 5k/ 21 days S-9918	Simon Wade
		completed	
22/03/2022	523,181 kms	B - 30k S-9919	Simon Wade
		completed	
14/03/2022	519,023 kms	Bin Gate lock R-12069	Corey Lonergan
		completed	
09/03/2022		Parts O-2384	
		A2R batteries 4 x batteries	
08/03/2022	516,820 kms	hubcap, mudflap, wiper arm R-12068	Simon Wade
		completed	
04/03/2022	501,254 kms	window regulator R-12032	Ace Air Auto Electrical
		completed	
03/03/2022		Parts O-2393	Gilbert and Roach
		screw-socket x 2	
03/03/2022		Defects R-11996	Corey Lonergan
03/03/2022	515,193 kms	power steering box leaking, step lights, wiring R-12067	Corey Lonergan
		completed	
03/03/2022	515,219 kms	A - 5k/ 21 days S-9892	Corey Lonergan
01/03/2022		adaptors R-12134	Hydraulink
		completed	
01/03/2022	515,193 kms	Batteries, diff locating bushes R-11977	Simon Wade
		completed	
18/02/2022	514,234 kms	leak steering box, Lights R-11975	Corey Lonergan
		completed	

Date	Reading / Units	Type / Repairer Notes	Repairer
16/02/2022		Registration O-2288	
09/02/2022	511,049 kms	A - 5k/ 21 days S-9080 completed	Simon Wade
09/02/2022		Defects R-10891 Steer box reconditioned by Direct Power Steering-Corey 22/2/2022 8 x top diff locating bushes replaced- Corey & Simon Tank Lights replaced and repaired-Corey	Simon Wade
09/02/2022	511,049 kms	shock absorber R-10893 completed	Simon Wade
31/01/2022	505,291 kms	clutch spring R-10886 replaced	Corey Lonergan
18/01/2022	501,254 kms	drivers side window R-12014 completed	Ace Air Auto Electrical
22/12/2021		Maint. Repairs R-11932 Ace Air 22/12/2021	
16/12/2021		Maint. Repairs R-11879 Install new n/s wiper arm complete Repair o/s tank wrap Complete full brake check and test Repair n/s wind visor mounting.	Simon Wade
30/11/2021		Tyre Repair T-2533 Install 4 new axle 3 tyres	Blair Wade, Simon Wade
26/11/2021		Maint. Repairs R-11828 Wire and install gps tracker	Simon Wade
26/11/2021		Maint. Repairs R-11822 See attached Drive Steer Air Conditioner not working	Simon Wade
26/11/2021		Tyre Repair T-2527 Install 2 new steer tyres Adjust tarp cables	Simon Wade
18/11/2021		Maint. Repairs R-11787 compressor leak found called cummins	Andrew Grindrod
16/11/2021		Maint. Repairs R-11749 Rewire and repair n/s rear tail light wiring	Simon Wade
12/11/2021		Maint. Repairs R-11745 Quicksilver needs attention Air leak at PTO Front hub cap	Simon Wade
05/11/2021		A - 5k/ 21 days S-9270 A service	
29/10/2021		Maint. Repairs R-11701 done	Andrew Grindrod
28/10/2021		B - 30k S-9286 B Service Manually generated 30000 km service	Andrew Grindrod
22/10/2021		Maint. Repairs R-11685 done	Simon Wade
18/10/2021		A - 5k/ 21 days S-9598 A service	
05/10/2021		A - 5k/ 21 days S-9614	

Date	Reading / Units	Type / Repairer Notes	Repairer
		A service	
22/09/2021		Rotate T-2497 done	Simon Wade
08/09/2021		Maint. Repairs R-11530 done	Simon Wade
07/09/2021		Maint. Repairs R-11522 done	
25/08/2021		Maint. Repairs R-11809 faulty sensor	
20/08/2021		Maint. Repairs R-11438 completed	
19/08/2021		Maint. Repairs R-11521 Call out to Ashfield	
19/08/2021		A - 5k/ 21 days S-9715 A service	
06/08/2021		Maint. Repairs R-11439 done	
04/08/2021		Maint. Repairs R-11408 done	Simon Wade
04/08/2021		B - 30k S-9746 checked not changed	Simon Wade
30/07/2021		A - 5k/ 21 days S-9753 A service	Simon Wade
19/07/2021		New T-2488 done	
14/07/2021		Maint. Repairs R-11481 done	
13/07/2021		Maint. Repairs R-11480 supplied	
07/07/2021		Maint. Repairs R-11482 Done	
06/07/2021		Maint. Repairs R-11326 done	Andrew Grindrod
05/07/2021		A - 5k/ 21 days S-9320 A service	Simon Wade
19/06/2021		A - 5k/ 21 days S-9367 A service	
17/06/2021		A - 5k/ 21 days S-9359 A service	Simon Wade
07/06/2021		Maint. Repairs R-11261 done	Simon Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
04/06/2021		Maint. Repairs R-11325 Cover inoperable,dryer inoperable,	Andrew Grindrod
04/06/2021		C - 100k/ Annual S-9392 C ServiceManually generated 100000 km service	Simon Wade
31/05/2021		A - 5k/ 21 days S-9400 A service	Simon Wade
11/05/2021		Maint. Repairs R-11269 wiring,solenoid	
14/04/2021		B - 30k S-9504 B Service	
23/03/2021		A - 5k/ 21 days S-9459 A service	James Hendry
11/03/2021		Maint. Repairs R-11114 completed	
10/03/2021		diverter valve, pressure wash R-9797 completed	Simon Wade (Mechanic)
10/03/2021		Maint. Repairs R-11063 Completed	
09/03/2021		Maint. Repairs R-11061 Completed	
09/03/2021		tank LED light wiring R-9795 completed	Simon Wade (Mechanic)
03/03/2021		A - 30 days S-8108 completed Replaced steer tyres found earth fault with front left indicator	James Hendry (Mechanic)
03/03/2021		A - 5k/ 21 days S-9560 A service	
19/02/2021		Registration O-1980	
11/02/2021		A - 5k/ 21 days S-9795 A service	
11/02/2021		clutch pedal, shock rubbers R-9648 fixed the clutch pedal 11/2/2021	
11/02/2021		Maint. Repairs R-11335 Completed	
11/02/2021	362,688 kms	A - 30 days S-8053 completed	Simon Wade (Mechanic)
05/02/2021		Maint. Repairs R-11021 Completed	
05/02/2021		Air leak R-9661 completed replaced governor valve on compressor	
29/01/2021	358,429 kms	Drive tyres T-2304 David thow Changed 4 x new drive tyres-Haulmax 307	

Date	Reading / Units	Type / Repairer Notes	Repairer
27/01/2021		adjust clutch, slack adjusters, tyre punctures, wiper blades R-9586 27/1/2021 2 x punctures repaired adjusted clutch	Simon Wade (Mechanic)
27/01/2021		B - 30k S-9862 B service	
27/01/2021		Maint. Repairs R-10997 Completed	
27/01/2021	356,620 kms	B - 30k S-8011 completed	Simon Wade (Mechanic)
20/01/2021		Parts O-1918 radiator cap	multispares
18/01/2021		A - 5k/ 21 days S-9856 A service	
18/01/2021		A - 30 days S-7975 completed replaced d/s steer tyre replaced wiper blades 3 out of 8 drive tyres under 20PSI	Simon Wade (Mechanic)
14/01/2021		Maint. Repairs R-10953 Completed	
14/01/2021		tracker unit R-9513 completed	James Hendry (Mechanic)
13/01/2021		New tyre T-2299 call out 1 x new tyre position 15 1 x disposal	JK Vella Earthwerx Pty Ltd
23/12/2020		Parts O-1858 torque rod bush x 4	multispares
23/12/2020		Parts O-1875 nuts bolts	Bolts & Industrial Supplies
22/12/2020		Tarp operation R-9452 completed by Air Tarps Australia	
15/12/2020		bonnet stops, cab shock weeping, engine mounts, stack loose, tyres , wheel markers R-9415	Corey Lonergan
14/12/2020	343,530 kms	coolant bypass orings R-8832 completed	Simon Wade (Mechanic)
14/12/2020	343,530 kms	A - 30 days S-7904 completed	Simon Wade (Mechanic)
24/11/2020		trailing arm bush R-9365 kit-50mm completed	multispares
23/11/2020		ABS to trailer, Clearance Lights, Ring Feeder, Tyres R-9254 completed	James Hendry (Mechanic)
23/11/2020	336,879 kms	A - 30 days S-7823 completed	James Hendry (Mechanic)
19/11/2020		Misc O-1748 Hydraulic ram bolts checks Truck & Trailer	Simon Wade (Mechanic)
03/11/2020		B - 30k S-7762	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		completed R9165 from A service	
03/11/2020		A - 30 days S-7742	Simon Wade (Mechanic)
		completed	
03/11/2020		brake relines, Damage to bonnet, damage to headlights R-9165	James Hendry (Mechanic)
27/10/2020	325,268 kms	airline R-9050	Simon Wade (Mechanic)
		completed	
15/10/2020		Drawbar safety inspection R-9027	James Hendry (Mechanic)
		completed	
14/10/2020	320,369 kms	A - 30 days S-7675	Simon Wade (Mechanic)
		completed	
14/10/2020	320,369 kms	adjust clutch R-9026	Simon Wade (Mechanic)
		completed	
21/09/2020	312,075 kms	A - 30 days S-7604	Simon Wade (Mechanic)
		completed	
21/09/2020	312,075 kms	Amber LED, coolant bypass orings, slack adjuster R-8917	Simon Wade (Mechanic)
04/09/2020	305,671 kms	tail light wiring R-8843	Simon Wade (Mechanic)
		completed	
04/09/2020	305,671 kms	A - 30 days S-7535	Simon Wade (Mechanic)
		completed	
24/08/2020		Parts O-1542	sloanebuilt Trailers
		grain lock stopper nylon tube nuts	
13/08/2020	297,069 kms	B - 30k S-7487	Simon Wade (Mechanic)
		completed	
13/08/2020	297,069 kms	A - 30 days S-7454	Simon Wade (Mechanic)
		completed	
13/08/2020	297,069 kms	coolant pipe orings, fire extinguisher tag, grainlocks, horton fan, hub cap, wiring R-8712	Simon Wade (Mechanic)
		grainlocks done,wiring done,new fanbelt 13/8/2020 re kit horton fan hub 14/8/2020	
11/08/2020		Truckwash O-1490	
		truck & dog wash	
23/07/2020		Truckwash O-1396	
		truck wash	
21/07/2020	287,528 kms	Coolant leak, front tow hooks, main fanbelt R-8580	Simon Wade (Mechanic)
21/07/2020	287,528 kms	A - 30 days S-7393	Simon Wade (Mechanic)
		completed	
07/07/2020		Truckwash O-1344	
		S&S Fleet truck wash	
01/07/2020		Truckwash O-1333	
		S&S Fleet Truck wash	
30/06/2020	278,576 kms	A - 30 days S-7328	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		completed	
30/06/2020		fanbelts R-8473	Simon Wade (Mechanic)
23/06/2020		Truckwash O-1248 truck & dog wash	
16/06/2020		Truckwash O-1223 truck & dog wash	
13/06/2020		tarp male plug R-8369 completed	Simon Wade (Mechanic)
12/06/2020	269,308 kms	exhaust flex R-8359 completed	Simon Wade (Mechanic)
11/06/2020		Truckwash O-1204 S&S Fleet truck wash	
10/06/2020		Parts O-1173 gaskets clamps flex bellow	Gilbert and Roach
09/06/2020	269,308 kms	A - 30 days S-7262 completed	Simon Wade (Mechanic)
09/06/2020	269,308 kms	input shaft leaking R-8344	
30/05/2020		air compressor belt, exhaust leak R-8227 Heater tap replaced 26/5/2020 Farao	
29/05/2020		Parts O-1165 1 x micro v belt	multispares
26/05/2020	265,288 kms	B - 30k S-7217 completed	Simon Wade (Mechanic)
26/05/2020		grain lock clips R-8312 completed	Simon Wade (Mechanic)
24/05/2020		Weighbridge O-1167 weighbridge ticket truck & trailer	sloanbuilt trailers
20/05/2020	262,039 kms	A - 30 days S-7188 completed	Simon Wade (Mechanic)
19/05/2020		Truckwash O-1130 S&S fleet truck wash	
04/05/2020	253,561 kms	clearance lights, governor valve, tarp trailer plug R-8148 completed	Simon Wade (Mechanic)
30/04/2020		adjust clutch brake, Hydraulic leak R-7967	Simon Wade (Mechanic)
30/04/2020		diverter valve, fan belts R-7932	Simon Wade (Mechanic)
28/04/2020	253,561 kms	A - 30 days S-7132 completed	Simon Wade (Mechanic)
28/04/2020	253,561 kms	diverter valve R-8048 completed	Simon Wade (Mechanic)
27/04/2020		C - 120k/ Annual S-7123	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
24/04/2020		Truckwash O-1035 anzac day wash	Narellan Truck Wash Services
13/04/2020	247,835 kms	New tyres T-2204 8 x Haulmax 8 x strip & ft 8 x disposal after hours call fee,Easter Monday	JK Vella Earthwerx Pty Ltd
08/04/2020	240,388 kms	red reflectors, tarp sensativity R-8047 completed	Simon Wade (Mechanic)
07/04/2020	245,259 kms	A - 30 days S-7061 completed	Simon Wade (Mechanic)
18/03/2020	236,571 kms	A - 30 days S-6999 completed	Simon Wade (Mechanic)
13/03/2020	220,794 kms	o/s aerial R-7754 completed	Simon Wade (Mechanic)
13/03/2020		Misc O-964 heater tap 4 x lined shoe kit Credit attached for the micro v belts	multispares
13/03/2020	2,347,030 kms	steer tyres T-2166 2 x steer tyres	JK Vella Earthwerx Pty Ltd
25/02/2020	226,417 kms	A - 30 days S-6936	Simon Wade (Mechanic)
24/02/2020		grain lock, tail gate handle, wheel nut indicator R-7745 completed	Simon Wade (Mechanic)
21/02/2020	226,417 kms	B - 30k S-6930 completed	Simon Wade (Mechanic)
20/02/2020		socket in fuel tank R-7776	Simon Wade (Mechanic)
18/02/2020		Registration O-872	
10/02/2020	220,794 kms	adjust clutch, brake linings, Bushes R-7600 completed	Simon Wade (Mechanic)
07/02/2020		Used tyre T-2116 1 x used tyre position 7 1 x disposal	Southwest Car & Truck Tyres
06/02/2020		puncture repair T-2115 puncture repair position 9	JK Vella Earthwerx Pty Ltd
03/02/2020	219,606 kms	A - 30 days S-6877 completed	Simon Wade (Mechanic)
01/02/2020		Truckwash O-799 truck and dog wash	Narellan Truck Wash Services
22/01/2020		blinker, drive light, rear light bar, rear tyres R-7491	Simon Wade (Mechanic)
15/01/2020	213,605 kms	A - 30 days S-6804 completed	Simon Wade (Mechanic)
17/12/2019	207,929 kms	A - 30 days S-6755 completed	Simon Wade (Mechanic)
12/12/2019		repair,strip and fit T-2109	Southwest Car & Truck Tyres

Date	Reading / Units	Type / Repairer Notes	Repairer
		1 x strip & fit 1 x repair position 10	
30/11/2019		driving lights, rear ladder, tailgate rubber, tyres R-7299	Simon Wade (Mechanic)
27/11/2019	199,983 kms	A - 30 days S-6676 completed	Simon Wade (Mechanic)
09/11/2019		rotations T-2083 8 x rotations front to rear	Tyreright
06/11/2019	191,479 kms	B - 30k S-6620 completed	Simon Wade (Mechanic)
04/11/2019	190,507 kms	A - 30 days S-6597 completed	Simon Wade (Mechanic)
24/10/2019	186,103 kms	puncture repair T-2075 2 x puncture repairs positions 2/7	Tyreright
17/10/2019	183,502 kms	A - 30 days S-6537 completed	Simon Wade (Mechanic)
25/09/2019	177,327 kms	axle brakes, brake drums R-7137 completed	Simon Wade (Mechanic)
25/09/2019	176,977 kms	A - 30 days S-6485 completed	Simon Wade (Mechanic)
20/09/2019		exhaust leak, tarps front & back R-7000	Simon Wade (Mechanic)
20/09/2019		gauge,engine temp R-6783	Simon Wade (Mechanic)
20/09/2019	176,389 kms	adjust clutch brake R-7061	Simon Wade (Mechanic)
16/09/2019		puncture repair T-1959 repair tyre position 3	Tyreright
02/09/2019	171,952 kms	Headlights R-7018 completed	Simon Wade (Mechanic)
02/09/2019	171,952 kms	A - 30 days S-6426 completed	Simon Wade (Mechanic)
13/08/2019	165,716 kms	A - 30 days S-6350 completed	Simon Wade (Mechanic)
29/07/2019	158,888 kms	nut indicators,hub cap,wiring R-6831 completed	Simon Wade (Mechanic)
29/07/2019	158,888 kms	B - 30k S-6298 completed	Simon Wade (Mechanic)
26/07/2019	157,934 kms	A - 30 days S-6280 completed	Simon Wade (Mechanic)
22/07/2019	155,668 kms	batteries ,traiole ABS light R-6677 completed	Simon Wade (Mechanic)
19/07/2019	154,240 kms	puncture repair T-1906 puncture repair position 2	Tyreright
01/07/2019	147,149 kms	A - 30 days S-6204	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
		completed	
01/07/2019		not starting R-6903	Ace Air Auto Electrical
		completed	
29/06/2019	147,149 kms	clutch ,batteries R-6764	Simon Wade (Mechanic)
		completed	
27/06/2019		puncture repair T-1889	Tyreright
		puncture repair position 2 steer	
21/06/2019		tail gate R-6672	Simon Wade (Mechanic)
13/06/2019	142,858 kms	A - 30 days S-6157	Simon Wade (Mechanic)
		completed	
23/05/2019	138,161 kms	A - 30 days S-6083	Simon Wade (Mechanic)
		completed	
14/05/2019	134,985 kms	damage from wheel washj R-6552	Simon Wade (Mechanic)
		Completed	
01/05/2019		Battery R-6441	Simon Wade (Mechanic)
29/04/2019	129,924 kms	A - 30 days S-6026	Simon Wade (Mechanic)
		completed	
12/04/2019		Heater Tap R-6424	Simon Wade (Mechanic)
		completed	
09/04/2019		tarps R-6388	Jayden Haule (Apprentice)
		Fixed under warranty by Air tarps	
03/04/2019	121,466 kms	Alignment R-6642	Sydney Truck and Machinery
		completed	
03/04/2019	122,517 kms	B - 30k S-5982	Simon Wade (Mechanic)
		completed	
02/04/2019	121,887 kms	A - 30 days S-5968	Simon Wade (Mechanic)
29/03/2019	120,618 kms	Strip and fit T-1795	Tyreright
		strip and fit positions 3/4/5/6/7/8/9/10	
26/03/2019	118,612 kms	Puncture T-1776	Tyreright
		puncture repair position 7	
23/03/2019		steer tyres T-1774	Tyreright
		2 x steer tyres position 8 1 x secondhand	
19/03/2019	116,388 kms	Puncture T-1781	Tyreright
		puncture position 8	
11/03/2019	116,349 kms	clutch needs adjusting R-6368	Simon Wade (Mechanic)
		completed	
06/03/2019	114,590 kms	A - 30 days S-5878	Simon Wade (Mechanic)
		completed	
25/02/2019		regrooving T-1755	Tyreright
		regrooving x 8 Positions 3 to 8	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/02/2019	112,071 kms	trio matic valve R-6367 completed	Simon Wade (Mechanic)
21/02/2019		Registration O-641	
19/02/2019	110,465 kms	A - 30 days S-5844 completed	Simon Wade (Mechanic)
15/02/2019	107,292 kms	front hub,brakes R-6366 completed	Simon Wade (Mechanic)
04/02/2019	107,292 kms	A - 30 days S-5782	Simon Wade (Mechanic)
04/02/2019		battery, head light R-6179	Simon Wade (Mechanic)
30/01/2019	107,292 kms	C - 120k/ Annual S-5798 completed	Simon Wade (Mechanic)
25/01/2019		Repair T-1659 strip and fit repair	Southwest Car & Truck Tyres
25/01/2019	105,674 kms	A - 30 days S-5732 completed	Simon Wade (Mechanic)
18/01/2019	102,902 kms	runout tyres T-1724 4 x runout tyres positions 3 4 5 6	Southern Tyre Service
16/01/2019		CTP O-546	
16/01/2019		Registration O-545	
10/01/2019		Repair T-1678 1 x repair position 10	Southern Tyre Service
08/01/2019	98,753 kms	A - 30 days S-5656 completed	Simon Wade (Mechanic)
21/12/2018		speedo check R-6101 completed	Gilbert and Roach
21/12/2018	96,774 kms	A - 30 days S-5628	Simon Wade (Mechanic)
05/12/2018		Repair T-1654 repair position 6	Southern Tyre Service
04/12/2018	91,465 kms	A - 30 days S-5552 completed	Simon Wade (Mechanic)
04/12/2018	91,465 kms	B - 30k S-5554 completed	Simon Wade (Mechanic)
04/12/2018	91,465 kms	tyres,rotation T-1653 rotation x 8 positions 3/4/5/6 to 7/8/9/10	
22/11/2018	86,748 kms	runout,repair T-1647 runout x 1 position 2 repair position 6	Southern Tyre Service
20/11/2018		maxi R-5909 completed	Simon Wade (Mechanic)
20/11/2018	85,812 kms	Repair T-1646	Southern Tyre Service

Date	Reading / Units	Type / Repairer Notes	Repairer
		repair position 10	
19/11/2018	85,189 kms	A - 30 days S-5507 completed	Simon Wade (Mechanic)
06/11/2018	82,037 kms	A - 30 days S-5462 completed	Simon Wade (Mechanic)
23/10/2018	78,217 kms	A - 30 days S-5412 completed	Simon Wade (Mechanic)
15/10/2018		head lights R-5802 completed	Simon Wade (Mechanic)
08/10/2018	74,182 kms	A - 30 days S-5356 completed	Simon Wade (Mechanic)
26/09/2018	70,721 kms	A - 30 days S-5325 completed	Simon Wade (Mechanic)
14/09/2018	67,559 kms	A - 30 days S-5269 completed	Simon Wade (Mechanic)
20/08/2018	60,894 kms	B - 30k S-5171 completed	Simon Wade (Mechanic)
20/08/2018	60,894 kms	bumper R-5490	Simon Wade (Mechanic)
15/08/2018	59,589 kms	A - 30 days S-5148 completed	Simon Wade (Mechanic)
03/08/2018	56,160 kms	A - 30 days S-5110 completed	Simon Wade (Mechanic)
16/07/2018	49,797 kms	A - 30 days S-5039 completed	Simon Wade (Mechanic)
03/07/2018	46,254 kms	A - 30 days S-4979 competed	Simon Wade (Mechanic)
26/06/2018	43,823 kms	lens R-5475 completed	Simon Wade (Mechanic)
26/06/2018	43,823 kms	heater valve R-5471 completed	Simon Wade (Mechanic)
18/06/2018	41,100 kms	A - 30 days S-4928 completed	Simon Wade (Mechanic)
08/06/2018	38,927 kms	weight gauge R-5060 completed with service 4887	Simon Wade (Mechanic)
08/06/2018	38,927 kms	A - 30 days S-4887 completed	Simon Wade (Mechanic)
08/06/2018	38,927 kms	trailer axle,engine light R-5066 completed with service 4887	Simon Wade (Mechanic)
22/05/2018	33,887 kms	A - 30 days S-4810 completed	Simon Wade (Mechanic)
09/05/2018	29,924 kms	B - 30k S-4782	SNE Mobile Mechanic

Date	Reading / Units	Type / Repairer Notes	Repairer
		completed	
30/04/2018	26,880 kms	fuldering noise R-5337	Gilbert and Roach
23/04/2018	25,423 kms	A - 30 days S-4719	SNE Mobile Mechanic
		completed	
17/04/2018		noise from floor R-5286	SNE Mobile Mechanic
		could be gearbox	
12/04/2018	22,797 kms	A - 30 days S-4680	SNE Mobile Mechanic
		completed	
29/03/2018		New tyres T-1736	
		8 x Haulmax ATT307 11R22.5	
15/03/2018	15,440 kms	A - 30 days S-4588	SNE Mobile Mechanic
		completed	
28/02/2018	10,399 kms	A - 30 days S-4536	Simon Wade (Mechanic)
		completed	
28/02/2018	11,088 kms	A - 30 days S-4561	Gilbert and Roach
		comp[leted	
13/02/2018	6,576 kms	A - 30 days S-4476	Simon Wade (Mechanic)
		completed	
30/01/2018	3,254 kms	A - 30 days S-4424	Simon Wade (Mechanic)
		completed	

Signed: _____

Name: _____

Date: _____