

BSB: 034 059  
ACC: 155 440

Email: debtors@brisbaneisuzu.com.au

**CUSTOMER COPY**

**Copy Invoice Only**

**Service Tax Invoice**

		<b>Date:</b> 06/05/2025		<b>Invoice No:</b> 8108299	
		<b>Reg No.</b> 02CFT	<b>Stock No.</b> I19604	<b>Advisor</b> CHLOE C	<b>Order No.</b>
		<b>Current Klms</b> 422194	<b>Body No.</b> B19918	<b>Wty Start Date</b> 29/11/2019	<b>Wty Expiry Date</b> 28/11/2022
		<b>Vehicle Identification Number</b> JALCXY52MJ7000048		<b>Build Date</b> 08/18	<b>Compliance Date</b> 08/18
<b>Contact No. Today</b> 0427 936 683	<b>Contact Today</b> CFT LOGISTICS &	<b>Engine Number</b> 6WG1436157		<b>Selling Dealer</b> BRISBANE	<b>Delivery Date</b> 29/11/2019
<b>Driver Name</b>	<b>Driver Phone</b>	<b>Driver Email Address</b>		<b>Radio/DVD Code</b>	<b>Tag Number</b>
<b>CCard No.</b> 21745	<b>Home No.</b>	<b>Vehicle Description</b> CXY240-460SWL/MLWB/LWB			<b>Body Type</b> CHASSIS
<b>Mobile No.</b> 0427 936 683	<b>Work No.</b>	<b>Model</b> CXY 240-460 MLWB	<b>Colour</b> ARC WHITE	<b>Sale Klms</b> 469	<b>Ext Wty Type</b>
<b>Email Address</b>		<b>Booked</b> 02/05/2025 01:45PM	<b>Required</b> 02/05/2025 11:15PM	<b>Ext Wty Exp Date</b>	<b>Ext Wty Exp KM</b>

#/TYP JOB DESCRIPTION

**1 / ON CARRY OUT 420,000KM SERVICE AS PER SCHEDULE (420K)**

CARRIED OUT 420,000KM SERVICE AS PER ISUZU SPECIFICATIONS.  
 REMOVED AND REPLACED WIPER INSERTS AS REQUIRED, DURING SERVICE FOUND REAR GEARBOX OUTPUT SEAL TO BE MISTING, WILL REQUIRE REINSPECTION AT NEXT SERVICE. ROAD TESTED AND WASHED VEHICLE ALL OKAY.  
 REPLACE ENGINE OIL AND ENGINE OIL FILTERS  
 REPLACE FUEL FILTERS  
 INSPECT FUEL SEDIMENTOR  
 INSPECT AIR FILTER ELEMENTS  
 INSPECT TRANSMISSION OIL - ISUZU AND EATON  
 INSPECT AXLE HUB OIL  
 ADJUST AMT GEAR/CLUTCH RELEARN  
 INSPECT ENGINE DRIVE BELTS  
 INSPECT TURBO CHARGER AND INTERCOOLER  
 INSPECT INTAKE SYSTEM AIR DUCT CONNECTIONS AND GASKETS  
 INSPECT POWER STEERING FLUID  
 INSPECT EXHAUST BRAKE OPERATION  
 TENSION EXHAUST PIPES AND MOUNTINGS  
 REPLACE DPD PRESSURE SENSOR HOSES (IF APPLICABLE)  
 INSPECT ALL COOLANT HOSES AND COOLANT CONCENTRATION  
 INSPECT COOLANT: NOTE REPLACE EVERY 2 YEARS  
 PRESSURE TEST COOLING SYSTEM  
 ADJUST CLUTCH  
 LUBE ALL GREASE POINTS,UNI JOINTS,SLIDING SLEEVE & KING PINS  
 INSPECT STEERING COMPONENTS  
 INSPECT WHEEL ALIGNMENT/FRONT WHEEL TOE - IN  
 INSPECT STEERING WHEEL FREE PLAY  
 INSPECT FRONT AND REAR SUSPENSION FOR WEAR OR DAMAGE  
 INSPECT SHOCK ABSORBERS FOR FLUID LEAKS AND OPERATION  
 INSPECT BRAKE LININGS/DRUMS OR BRAKE PADS/ROTORS FOR WEAR  
 INSPECT BRAKE PIPES AND HOSES  
 INSPECT "S" CAMS FOR DAMAGE OR WEAR  
 REPLACE RETARDER OIL  
 INSPECT PARK BRAKE FUNCTION  
 INSPECT FUNCTION OF AIR COMPRESSOR,GOVERNOR & UNLOADER VALVE  
 INSPECT AIR TANKS

#/TYP	JOB DESCRIPTION	
	TENSIONS WHEEL NUTS	
	INSPECT BATTERY SPECIFIC GRAVITY AND TERMINAL CONDITIONS	
	INSPECT TYRE WEAR, PRESSURES AND ROTATION	
	TENSION BODY MOUNT BOLTS AND NUTS (IF APPLICABLE)	
	INSPECT/CHECK RIDE HEIGHT (AIR SUSPENSION MODELS ONLY)	
	INSPECT:FUEL,BRAKE,COOLING,OIL,AIR & EXH SYSTEMS FOR LEAKS	
	INSPECT ALL FLUID LEVELS	
	INSPECT CAB SUSPENSION AND TILT OPERATION	
	INSPECT/CHANGE ELECTRIC/HYDROLIC CAB TILT SYSTEM OIL	
	INSPECT OPERATION OF ELEC DEVICES:A/C,HEATER,WARNING LIGHTS	
	CONNECT DIAGNOSTICS:CHECK, NOTE/REPAIR AND RECORDED CODES	
	ROAD TEST	
	<b>Labour</b>	740.25
	CARRY OUT 420,000KM SERVICE AS PER SCHEDULE (420K)	
	<b>Parts</b>	
	1 x (TP) ELEMENT; OIL FILTER (IG*1132402330)	27.98
	1 x (TP) ELEMENT; OIL FILTER (IG*1132402410)	62.25
	1 x (TP) ELEMENT KIT;FUEL (IG*8981749030)	38.82
	1 x (TP) GASKET; PLUG,OIL DRAIN (IG*1096230570)	4.95
	1 x (TP) DPD HOSE LGTH C (IG*0015583000CM)	48.02
	1 x (TP) BRAKE CLEANER 840ML (NN*68098)	8.50
	3 x (TP) WIPER INSERT 6MM X 600 (NN*0848070601)	19.50
	<b>Sundry</b>	
	1.00 x ENVIRONMENTAL LEVY (EW)	40.00
	1.00 x WORKSHOP SUPPLIES (WSI)	40.00
	30.00 x VECTON 15W40 (NGEN)	182.40
		<b>Amount (ex GST) \$1212.67</b>

2 / C NO ADDITIONAL REPAIRS AT TIME OF BOOKING (NA)

3 / C WE VALUE YOUR FEEDBACK, 10/10 IS OUR AIM (SV10)

IF YOU WERE HAPPY WITH YOUR SERVICE EXPERIENCE TODAY  
 DON'T FORGET TO GIVE US A 10/10 ON YOUR CUSTOMER SURVEY  
 OR SMS RESPONSE. THANK YOU AND HAVE A GREAT DAY

Total Costs	
Total Invoice (excluding GST)	\$1212.67
Total Goods And Services Tax	\$121.27
<b>Total Invoice (including GST)</b>	<b>\$1333.94</b>

Payment Details

SubAcct	Ref No.	Date	Detail	Amount Due
8191	8108299	06/05/2025	CHARGE DEBTOR	1333.94

Next Service Details

Your NEXT SERVICE is due at 480000 Klms or on 01/02/2026, whichever comes first.  
 Please call our Service Dept on 33854311 when you wish to make a booking.

"N" DENOTES ANY NON-GENUINE PARTS, ACCESSORIES, PRODUCTS OR ADDITIVES SUPPLIED THAT ARE NOT APPROVED BY THE VEHICLE'S MANUFACTURER. AS SUCH THEY ARE NOT COVERED BY THE MANUFACTURER'S WARRANTIES. ADDITIONALLY, THE USE OF THESE PRODUCTS MAY IMPACT ON THE PERFORMANCE, SPECIFICATIONS OR QUALITY OF THE VEHICLE AND THE WARRANTY ATTACHED TO THE VEHICLE.

Goods presented for repair may be replaced by refurbished goods of the same type rather than being repaired. Refurbished parts may be used to repair the goods. Our goods and services come with guarantees that cannot be excluded under the Australian Consumer Law. For major failures with the service, you are entitled: \* to cancel your service contract with us; and \*to a refund for the unused portion, or to compensation for its reduced value. You are also entitled to choose a refund or replacement for major failures with goods. If a failure with the goods or a service does not amount to a major failure, you are entitled to have the failure rectified in a reasonable time. If this is not done you are entitled to a refund for the goods and to cancel the contract for the service and obtain a refund of any unused portion. You are also entitled to be compensated for any other reasonably foreseeable loss or damage from a failure in the goods or service.

\*\*BRISBANE ISUZU GUARANTEE - GENERAL WORKMANSHIP 6 MONTHS / 10,000 KLM. DEALER FITTED GENUINE ISUZU PARTS CARRY EXTENDED WARRANTY 36 MONTHS UNLIMITED KLM \*\*

Reg No: 02CFT

ARC Lic AU00027. Inspection Station 7731

THANK YOU FOR HAVING YOUR TRUCK SERVICED AT BRISBANE ISUZU BURPENGARY  
SERVICE HOURS: MONDAY TO FRIDAY 6.00AM TO MIDNIGHT AND SATURDAY BY APPOINTMENT

**Administration**  
PO Box 1141  
Archerfield, QLD 4108  
**A/C Receivable:** 07 3632 0524  
**A/C Payable:** 07 3632 0523

**Archerfield**  
1121 Beaudesert Road  
Archerfield QLD 4108  
**P:** 07 3373 2400

**Burpengary**  
Eastern Service Road  
Burpengary QLD 4505  
**P:** 07 3385 4300

**Eagle Farm**  
208 Fison Avenue West  
Eagle Farm QLD 4009  
**P:** 07 3866 2200

**Stapylton**  
183 Burnside Road  
Stapylton QLD 4207  
**P:** 07 3382 4600