



Vehicle History Summary

Fleet #	16205
Registration	
Make	DAF
Model	
VIN / Chassis #	XLRTE75PCEG022801
Build Date	10/14

Date	Reading / Units	Type / Repairer Notes	Repairer
02/10/2025		NHVR ROADWORTHY R-32141 Check and repair lights Check and adjusted turntable jaw Wash and check engine oil leak - All ok Inspect V rod all ok	NHVR
04/09/2025	760,829 kms	B - 30000 S-14169 Carry out general service & check over Replace engine oil & fuel filters Replace engine air filter Replace x 2 drive guards - Black Replace white mud flaps Remove all HNL art work and logos - Prep for sale Carry out all general service checks - All ok	KJS Fleet
22/07/2025	760,819 kms	A - 10000 S-13942 Carried out vehicle A service and inspection as per HNL checklist Clean cabin and check over for sale	KJS Fleet
02/07/2025	760,817 kms	No Start R-31757 Jump started truck as requested.	KJS Fleet
12/03/2025	760,601 kms	Anderson Lead R-29581 Made a new anderson lead and fitted to vehicle.	KJS Fleet
17/12/2024	760,207 kms	Body Rear Door Repair R-28674 driver door wont open. carry out unlocking door.vehicle unable to lock door. to be booked in for repairs.	KJS Fleet
13/12/2024	760,206 kms	Cab Door Locks R-28516 Found door lock jammed,unjam lock and test all okay.	KJS Fleet
04/12/2024	760,030 kms	TOP UP COOLANT R-28390 Topped up coolant as required inspected door and found lock jammed,got door opened and tested a few times all okay.	KJS Fleet
06/11/2024	759,092 kms	Body Damage R-28086 Remove driver side exterior corner panel Sublet Workhorse for panel repair Re fit old part to vehicle All ok	KJS Fleet
04/11/2024		NHVR ROADWORTHY R-28038 NHVR annual inspection - PASSED	NHVR
29/10/2024	458,783 kms	Check Vehicle Lights R-27971 Indicator not working right side Replace blown globe All ok	KJS Fleet
23/10/2024	758,776 kms	Accident Damage, Check Vehicle Lights R-27908 Replace damaged right rear tail light assembly Tested all lights - All ok	KJS Fleet
29/08/2024	755,596 kms	Brake Test R-27285 Carry out rolling brake test & supply test print out attached. - PASSED	Big Wheel Truck Alignment
25/07/2024	267,638 kms	TurnTable Arm R-26807 Repaired turntable release arm and test operation,reinstall spring and handle.	KJS Fleet
19/07/2024	752,004 kms	No Start R-26774 Drove to dock,inspected and found truck has been run out of fuel.Bled fuel system and started.	KJS Fleet
14/06/2024	750,419 kms	DVR REPAIRS R-26222	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
		Inspected and tested turntable as requested was ok cleaned and greased. - DVR 01594	
12/06/2024		Puncture Repair T-4016 PUNCTURE REPAIR POS 7	Bridgestone Australia Ltd
06/06/2024	749,972 kms	Accident Damage R-25986 Driver : Gurwinder Singh Location: Huntingwood Time : 14:00 Gurwinder was reversing 16204 , due to poor conditions Gurwinder missed judged the distance between his truck and 16205 , he reversed into 16205 causing damage to the front RHS of 16205 and the rear LHS of 16204,16205 - has significant damage to the RHS head light , front bumper bar and step,16204- has a bent rear Bar and a broke LHS tail light both vehicle have been taken to the workshop.	Workhorse Collision Repair
16/05/2024	749,972 kms	REAR BARS R-25859 Re fitted rear bar and re mounted all removed parts and lights tested all okay.	KJS Fleet
09/05/2024	749,972 kms	REAR BARS R-25782 Removed rear bar and fitted to 16204 O/S headlight and front bar damaged vehicle is locked in workshop.Installed damaged bar.Swapped number plates.	KJS Fleet
29/04/2024		DAMAGED DRIVE TYRE T-3918 Advance 11R22.5 GL268D 146/143M Block Drive	Central Coast Tyres
22/04/2024	745,124 kms	B - 30000 S-11173 Carried out vehicle B service and inspection as per HNL checklist All ok Replace engine oil & fuel filter kit Grease turntable Check over rear suspension & tested operation All ok - No suspension fault found DVR 01753	KJS Fleet
19/04/2024	745,123 kms	STEER TYRES T-3903 STEER TYRES POS 1/2 FITTED 295/80R22.5 BRIDGESTONE R154	Bridgestone Australia Ltd
28/03/2024		No Start R-25297 Ignition key stuck in barrel and wont start - Tow from Lalor Park	Gilbert and Roach, ONEILLS TOWING
26/03/2024	743,016 kms	No Start R-25287 Truck could not be started needed to be towed.	KJS Fleet
14/03/2024		Exhaust Leak R-25125 Check exhaust manifold leak REPLACE EXHAUST MANIFOLD GASKETS	KJS Fleet
13/03/2024	739,848 kms	DAMAGED DRIVE TYRE T-3837 damaged drive tyre at Windale	Bridgestone Australia Ltd
05/01/2024	721,752 kms	No Start R-24432 Check battery flat and no start Remove and replace faulty batteries Tested charge rate all ok	KJS Fleet
27/11/2023	714,608 kms	Tyre Runouts T-3653 FIT RUN OUTS TO POS 1/2	Bridgestone Australia Ltd
27/11/2023		Rego Inspection R-24078 Registration Inspection Transfer rego from Queensland to NSW All ok New plates - XO71XL	KJS Fleet
27/11/2023	714,608 kms	A - 10000 S-10434 Carried out vehicle A service and inspection as per HNL checklist All ok (As a part of brown slip inspection)	KJS Fleet
22/11/2023		2024 REGO PAPERS R-24052 2024 REGO PAPERS	HNL WORKSHOP
30/10/2023	707,751 kms	B - 30000 S-10254 Carried out vehicle C service and inspection as per HNL checklist Replace engine oil and filters Carry out all general service checks Grease turntable	KJS Fleet
04/10/2023	701,037 kms	Coolant Leak R-23523 Travel to breakdown at Waterfall Found heater hose rubbed through, Carry out temporary repairs Parts on order - Topped up system and check over All ok to return to workshop	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
12/09/2023	695,794 kms	Coolant Leak R-23279 Check over vehicle for coolant leak Found heater hose clamp area leaking Remove and trim effected section of hose. Re fit and checked over for leaks All ok	KJS Fleet
01/09/2023	693,202 kms	Breakdown - Truck R-23216 Called to wash bay vehicle stuck in gear with no air. Prime tank and re-start clear code ALL ok.	HNL Fleet Sydney
24/08/2023	690,899 kms	Breakdown - Truck R-23084 TRUCK BREAKDOWN - LOST AIR AND STUCK IN GEAR FILL AIR SYSTEM / GET OUT OF GEAR / START TRUCK RUN OK	HNL Sydney Workshop
04/07/2023	679,472 kms	Breakdown - Truck R-22524 Travel to Garvan Rd Engadine - Check and report no start Damaged battery terminal - Replace x 1 battery with second hand battery Return to workshop Check over terminals on return All ok	HNL Fleet Sydney
04/07/2023	679,705 kms	Coolant Leak R-22534 Check coolant header tank Remove and replace cracked header tank Topped up coolant and check over Tested operation All ok	HNL Fleet Sydney
03/06/2023	672,212 kms	BRAKE PADS R-22231 Replace axle 2 brake pads All ok	HNL Sydney Workshop
03/06/2023	672,212 kms	C - 90000 S-9347 Carry out vehicle C service & check over as per HNL checklist Replace engine oil & filters Replace engine air filter Replace power steering filter Replace a/c pollen filter Replace male & female air fittings to trailer	HNL Fleet Sydney
28/04/2023		Anderson Lead Charge Fault R-21890 Check anderson lead missing Made up new lead with new ends - Solder, crimp & fit Bolt up lead to truck with new bracket All ok Check charge rate All ok	HNL Fleet Sydney
17/04/2023	659,840 kms	RECTIFY NO START R-21781 TRUCK WILL NOT START CHECK AND FOUND LOOSE BATTERY TERMINAL	HNL Sydney Workshop
23/02/2023	648,305 kms	A - 10000 S-8705 Carried out vehicle A service & inspection as per HNL checklist All ok Grease turntable	HNL Sydney Workshop
22/02/2023		Anderson Lead Fault R-21186 anderson lead fault repaired	HNL Fleet Sydney
10/02/2023	644,718 kms	No Start R-21080 Test & found faulty batteries Remove & replace batteries Found incorrect batteries supplied, made up wiring to suit Started all ok Next day remove & replace batteries with correct parts Tested operation All ok	HNL Fleet Sydney
08/02/2023	644,542 kms	Breakdown - Truck R-21050 ATTEND BREAKDOWN AT GATESHEAD - TRUCK WON'T START FOUND 1X FAULTY BATTERY JUMP START TRUCK TO FINISH RUN NEW BATTERIES TO BE FITTED WHEN TRUCK RETURNS TO SYDNEY	HNL WORKSHOP
02/02/2023		Check Vehicle Lights R-20993 Check trailer lights not working Remove & replace damaged trailer light plug lead Tested operation of all lights All ok	HNL Fleet Sydney
30/01/2023	642,346 kms	Check Vehicle Lights R-20968 Check headlights not working remove & replace driver side headlight globe Tested all ok	HNL Fleet Sydney
21/01/2023	640,603 kms	Anderson Lead Charge Fault R-20888 Check driver complaint no charge at anderson lead Check voltage with engine running 13v Check with engine off - battery voltage Could not fault charge system & anderson supply voltage	HNL Fleet Sydney
16/01/2023	638,935 kms	Change Vehicle Number Plates R-20874 Removed and refitted number plate	HNL Fleet Sydney
16/01/2023	638,925 kms	Registration Inspection R-20829 Rego Inspection - Brake test Queensland extension on COI	Gilbert and Roach

Date	Reading / Units	Type / Repairer Notes	Repairer
03/01/2023	638,013 kms	Anderson Lead, ANDERSON LEAD LOCK TAB R-20709 Driver complaint of missing anderson lead Refit new anderson lead & make up bracket to bolt lead on All ok	HNL Sydney Workshop
22/12/2022	637,728 kms	door repair R-20643 worn striker & door lock Remove & replace lock mechanism Tested operation All ok	HNL Sydney Workshop
05/12/2022	636,474 kms	A - 10000 S-8207 CARRY OUT 'A' SERVICE	HNL Sydney Workshop
24/11/2022		Registration O-2408	
19/10/2022		Windscreen Wiper Blades R-19947 WIPER BLADES REPLACED	HNL Sydney Workshop
09/08/2022	634,409 kms	Turntable Assembly R-19409 REPLACE TURNTABLE ASSEMBLY AND HARDWARE	HNL WORKSHOP
21/06/2022	633,916 kms	WASH AND DETAIL R-19021 WASH AND DETAIL REPAIR AIR LEAK	HNL WORKSHOP
18/05/2022	633,653 kms	A - 10000 S-7270 CARRY OUT 'A' SERVICE WASH AND DETAIL INSIDE AND OUTSIDE POLISH FUEL TANKS WASH DOWN ENGINE FIT NEW MUDGUARDS AND MUDFLAPS REPAIR LIGHTS	HNL WORKSHOP
08/03/2022	630,039 kms	Damage - Guards & Mudflaps R-18069 FITTED 2 NEW BRACKETS TO MUD GAURD AND REFIT GAURD AS NEEDED .	HNL Sydney Workshop
02/03/2022	630,573 kms	door indicator R-18037 REMOVE AND REPLACED L/H DOOR BLINKER AND CHECK ALL LIGHTS ALL OK	HNL Sydney Workshop
28/01/2022	628,448 kms	Air Line Fault R-17777 INSPECTED AND FOUND AIR SUAI LINES LEAKING AND ALSO FEMALE FITTING LEAKING . REPLACED SUZI LINES AND FITTING AND CHECK ALL OK .	HNL Sydney Workshop
15/12/2021	626,032 kms	B - 30000 S-6681 CARRY OUT B SERVICE . REPLACED FRONT BRAKE PADS AND ROTORS .	HNL Sydney Workshop
30/11/2021		Registration O-1953	
25/11/2021	623,618 kms	Rego Inspection R-17252 PINK SLIP INSPECTION FOR QUEENSLAND REGO	HNL Sydney Workshop
25/11/2021	623,618 kms	Turntable - Damaged Jaws R-17256 REPLACE TURNTABLE JAW KIT	HNL Sydney Workshop
21/10/2021	622,508 kms	Reverse Light Assembly R-16863 checked for no reverse light checked fuse and globes all ok checked reverse switch all ok found broken wire at switch repaired wiring all ok	HNL Sydney Workshop
15/10/2021	621,838 kms	Turntable Latching Cable/Pin R-16800 replace cable to unlatch turntable	HNL Sydney Workshop
31/08/2021	613,957 kms	Anderson Lead R-16318 FITTED NEW ANDERSON LEAD AND CHECK OPERATION ALL OK	HNL Sydney Workshop
09/07/2021	613,638 kms	Electric Window Fault R-15479 INSPECTED AND FOUND WINDOW REGULATOR MOTOR FAILED . REMOVE AND REPLACED AND CHECK OPERATION ALL OK .	HNL Fleet Sydney
09/07/2021	613,687 kms	long tail suzi coil R-15592 INSPECTED AND FOUND CUT WIRING ON SUZI COIL . REPLACED SUZI COIL AS NEEDED AND CHECK OPERATION ALL OK	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
30/06/2021	613,366 kms	Batteries R-15414 AFTER HOURS CALLOUT TO BREAKFAST POINT. CHECK FOR CAUSE OF VEHICLE NOT STARTING. CHECK BATTERIES AND CABLES. LOCATE AND REMOVE FAULTY BATTERIES. SUPPLY AND FIT NEW BATTERIES. RECHECK STARTING AND CHARGING.	Crowhurst Auto Electrical Pty Ltd
17/06/2021	612,660 kms	Battery Box Cover R-15112 REPLACED HINGE AND CLAMPS ON BATTERY BOX	HNL Fleet Sydney
09/06/2021	612,012 kms	Anderson Lead - Installation/Replacement R-15157 REPLACED ANDERSON PLUG	HNL Sydney Workshop
05/06/2021	611,892 kms	Anderson Lead Fault R-15117 REMOVE AND REPLACED ANDERSON PLUG AND CHECK ALL OK	HNL Sydney Workshop
03/06/2021	611,983 kms	Electrical - Blinker Stalk R-15074 Replace blinker stalk assembly	HNL Fleet Sydney
28/05/2021	611,076 kms	Puncture Repair T-1730 PUNCTURE REPAIR POS 6	Bridgestone Australia Ltd
19/05/2021	610,118 kms	door indicator R-14864 removed door lenses found globe blown removed and refitted new globe x1 24v-21w glboe checked all lights	HNL Fleet Sydney
14/05/2021	609,420 kms	Anderson Lead R-14818 made new lead with x2 new plugs	HNL Fleet Sydney
02/05/2021	608,051 kms	Damaged Step R-14613 Rectify left side cabin step missing / damaged Replaced damaged left side cabin step, shroud & support bracket All ok	HNL Fleet Sydney
16/04/2021	606,428 kms	drive tyre T-1569	Bridgestone Australia Ltd
26/03/2021	603,259 kms	Accident Damage R-14164 Replace left side mirror	HNL Fleet Sydney
17/03/2021	602,518 kms	Turntable - Damaged Jaws R-14058 Rectify turntable latch cable broken Remove & replace turntable release lever cable Check adjustment Grease top plate	HNL Fleet Sydney
04/03/2021	601,205 kms	Anderson Lead Fault R-13915 Rectify anderson lead damaged & dragged on the ground Confirm fault, remove lead & trim damaged section Solder & crimp x 2 new terminals to lead end Replace 175amp anderson housing All ok	HNL Fleet Sydney
02/03/2021	600,316 kms	Electrical - Fault R-13872 Check clearance lights to trailer not working Inspect & confirm fault, electrical coil to trailer damaged Remove & replace electrical lead to trailer & test operation of all lights to trailer All ok	HNL Fleet Sydney
10/02/2021	597,522 kms	Repairs, Wheel Alignment R-13619 Replace left tie rod end Carry out wheel alignment	Big Wheel Truck Alignment
27/01/2021	596,213 kms	Repairs, Turntable - Grease Plate & Jaws R-13414 Check & top up engine oil level as required Check coolant level Check operation of all lights Clean & grease turntable plate Check all brake pad wear & report Check vehicle exterior for damage Start engine & check for dash warnings Visual inspection of under body Check correct charge voltage at anderson plug All ok	HNL Fleet Sydney
04/01/2021	593,623 kms	Repairs, Turntable - Grease Plate & Jaws R-13150 Check & top up engine oil level as required Check coolant level Check operation of all lights Clean & grease turntable plate Check all brake pad wear & report Check vehicle exterior for damage Start engine & check for dash warnings Visual inspection of under body Check correct charge voltage at anderson plug All ok Note - Steer axle brake reline at next service Minor oil leak at rocker cover gasket V-stay bush worn	HNL Fleet Sydney
06/12/2020	589,850 kms	Repairs R-12850	HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check engine oil & coolant level Grease turntable	
27/11/2020		CTP O-1436	
27/11/2020		Registration O-1435	
24/11/2020	587,735 kms	Brake Test R-12676 Bake Test - PASSED attached	Gilbert & Roach Huntingwood
24/11/2020	587,737 kms	Registration Inspection, Service R-12672 Carry out vehicle A - Service & inspection (Rego Renewal) Top up engine oil level as required Replaced blown reverse lamp 15amp fuse - Test all lights Check turntable adjustment & grease top plate Gilbert & Roach Brake Test - PASSED attached.	HNL Fleet Sydney
28/10/2020	586,162 kms	Mirror Arms R-12273 Check side mirror adjustment Driver complaint, left side mirror not adjusted correctly Remove cover & unbolt, adjust to correct position Re fit covers All ok	HNL Fleet Sydney
07/10/2020	583,898 kms	Fire Extinguisher R-11826 Replace fire extinguisher at rear deck plate.	HNL Fleet Sydney
06/10/2020	583,898 kms	Anderson Lead Fault, Service R-11815 Carry out A - Service & inspection Check engine oil & coolant levels Visual inspection of vehicle under body Check front & rear brake wear Check tyre wear Carry out general A - Service checks as per HNL checklist Inspect & found anderson lead damaged (wrapped around tailshaft) Remove all damaged parts Rewire positive cable to batteries, including install manual circuit breaker Replaced isolation switch Replaced anderson lead	HNL Fleet Sydney
01/10/2020	1 kms	Pressure Check T-885 Pressures Only as per Attachment	ADZ Tyre & Battery
29/09/2020	583,352 kms	Brake Fault, Brake Test R-11711 Replace axle 2 brake disc rotors Replace axle 2 brake pads Supply brake test print out - PASSED Attached	Gilbert & Roach Huntingwood
25/09/2020	582,920 kms	B - 30000 S-4727 Carry out B service as per HNL checklist Replace engine oil & filters Replace engine fuel filters Replace engine air filter Replace cabin fresh air filter Check & adjusted brakes Grease chassis & turntable Check turntable adjustment Carry out all general service checks All ok Replaced male & female air fittings at suzi coils	HNL Fleet Sydney
19/09/2020	582,105 kms	Repairs R-11603 Remove & replaced right headlight globe Tested operation of all lights Check engine oil & top up Check coolant level Check all brake pads & tyres for wear Check voltage charge rate at anderson lead All ok	HNL Fleet Sydney
11/09/2020	1 kms	Pressure Check T-997 Pressure Check as per Attachment	ADZ Tyre & Battery
12/08/2020		Service - A Service R-11001 Check engine oil level Check coolant level Grease turntable	HNL Fleet Sydney
06/08/2020	577,336 kms	Electrical - Faulty Lights R-10929 Rectify trailer clearance lights not working Check & found trailer electrical coil damaged Remove & replaced lead to trailer Tested operation of all lights from trailer electrical lead All ok	HNL Fleet Sydney
25/07/2020	575,280 kms	Electrical - Fault R-10738 Rectify brake light not working Confirm fault, check & found right side brake globe blown Remove & replaced globe Tested operation of all lights All ok	HNL Fleet Sydney
10/07/2020	573,951 kms	Repairs R-10564 Remove stickers from left & right cabin exterior	HNL Sydney Workshop
03/07/2020		Pressure Check T-735 Pressures Only	ADZ Tyre & Battery
16/06/2020	571,567 kms	New Tyres T-598	ADZ Tyre & Battery

Date	Reading / Units	Type / Repairer Notes	Repairer
		Mid Range Steer (BFG) - 295/80r 22.5 (x2) pos 1,2 as per Attachment	
29/05/2020	569,218 kms	Service - A Service R-9965 Check engine oil level, topped up 2L Checked coolant level Grease turntable Remove & replaced turntable latch cable Reset correct clock time on dash as requested by driver	HNL Sydney Workshop
28/05/2020		Registration O-1085	
28/05/2020		CTP O-1086	
22/05/2020		Pressure Check T-442 Pressures Only as per Attachment	ADZ Tyre & Battery
06/03/2020	549,479 kms	B - 30000 S-3792 Carry out B service Flushed coolant and filled with new coolant	TRS Onsite Mechanic
05/02/2020	543,079 kms	Service R-7860 topped up engine oil topped up coolant checked all lights checked all tires cleaned cab greased and checked turn table checked and reported brakes: steer: 7mm 70% drive: 8mm 80% replaced LHS spotter mirror cover	HNL Sydney Workshop
14/01/2020	540,142 kms	AdBlue Cap R-7434 replaced missing ad blue cap inspected rear indicator out tested all lights found no lights inop	HNL Sydney Workshop
24/12/2019	536,128 kms	Registration Inspection R-7137 Carry out pink slip / safety inspection Brake Test report checked all lights checked all tires checked and reported brakes: steer: 8mm 80% drive: 9mm 90% cleaned, checked and greased turn table checked seat belt checked demister fan checked horn checked wheel bearings	HNL Sydney Workshop
19/12/2019	534,983 kms	Electrical - Fault R-7062 inspected fault found the light reset system had been tripped clicked reset button at back of cab tested lights on trailer all ok	HNL Sydney Workshop
26/11/2019	531,462 kms	Brake - Warning R-6502 Inspected brake warning on dash Found steer brakes to still have 8mm 80% left Drive have around 5mm 50% jacked up truck removed wheels removed and replaced drive axle brakes removed and replaced wear sensors fitted wheels lowered truck test drove all ok	HNL Sydney Workshop
18/10/2019	522,144 kms	Service - C Service R-5680 removed and replaced diff oil removed and replaced gear box oil removed and replaced air dryer filter removed and replaced ad blue filter removed and replaced a/c belt	HNL Sydney Workshop
28/09/2019	519,765 kms	Engine Fan Belt R-5413 Saturday - 28/9/2019 Rectify fan hub bracket broken Raise cabin, remove engine fan blade. Remove engine fan hub assembly, replace bracket to mount wiring harness to hub Remove & replace drive belt idler bearing Remove & replace drive belt tensioner Replace engine drive belt Re fit fan hub & tension all bolts Re fit engine fan. Run engine & check operation of fan. All ok	HNL Sydney Workshop
24/09/2019	518,378 kms	Alternator Warning Light R-5307 Check charge rate only battery voltage Remove & replace alternator Test charge rate running 28v Road Test Requires idler pulley & engine drive belt, parts on order	HNL Sydney Workshop
28/08/2019	514,030 kms	Electrical - Breakdown R-5030 TRAVEL TO BREAKDOWN AT ADAMSTOWN RE-SET CIRCUIT BREAKER	HNL WORKSHOP
27/08/2019	513,408 kms	C - 90000 S-2759 Carry out B service removed and replaced engine oil and filters removed and replaced fuel filters removed and replaced air filter removed and replaced air dryer cleaned cab checked all lights checked all tires checked and reported on brakes: steer: 8mm 80% drive: 8mm 80% cleaned and regressed turntable	HNL Sydney Workshop
19/08/2019		Damage - Rear Lights R-4810 Replace damaged tail light lense LEFT -	HNL Sydney Workshop
19/07/2019	504,952 kms	Anderson Lead Fault R-4500	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Replace anderson lead Replace electrical lead Replace suzi coil air lines Install fire extinguisher to rear deck plate All ok	
05/07/2019	503,313 kms	Anderson Plug R-4420 REMOVED AND REPLACED DAMAGED ANDERSON PLUG	HNL Sydney Workshop
28/06/2019	502,599 kms	Cab Window R-4390 checked all fuses for both windows all ok checked both controls all ok (drivers side needs to be replaced was diagnosed after repair) removed door trim inspected window regulator found it was faulty removed and replaced regulator tested system all ok refitted door trim cleaned door removed and replaced anderson plug	HNL Sydney Workshop
31/05/2019		Registration O-619	
29/05/2019	498,415 kms	Transmission Shifting Faults R-4204 DIAGNOSE TRANSMISSION NOT SHIFTING CORRECTLY FOUND EBS FAULT WITH SPEED SENSORS - ADJUST AND TEST DRIVE OK	HNL WORKSHOP
15/05/2019	498,393 kms	Suspension Fault R-4031 REPLACE REAR AIR BAGS - LEAKING REPAIR AIR LEAK AT EXHAUST BRAKE CONTROLLER GENERAL CHECK OVER	HNL WORKSHOP
10/05/2019	498,396 kms	Wheel Alignment R-4027 WHEEL ALIGNMENT CAMBER CORRECTION / CASTER WEDGE	National Central Mechanical Centre Pty Ltd
08/05/2019	498,350 kms	Tyres - Steer R-4026	Beaurepaires
04/03/2019	481,207 kms	B - 30000 S-2494 TRUCK HAD 'B' SERVICE IN QLD BEFORE COMING TO THORNTON	IDR

Signed: _____
Name: _____
Date: _____