


CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate

Traffic Safety Act


PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:		
GVW:	kg	Brake Type:	Air	
Owner Name:	Kropp Contracting Ltd.			
Address:	Box 237			
City:	Slave Lake	Province:	AB	Postal Code: T0G2A0
Telephone Number:	(780) 849-6229			
Vehicle Identification Number:	2C9GSX3Z5KM183889			
Make:	cross country	Model:	logger	
Year:	2019	Unit Number:	T89	
Odometer:	KM	Licence Plate Number:	6WU507	Province: AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2026/06/11

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle					Gross Vehicle Weight registered												
Hay Rack trailer					kg												
Vehicle Information																	
VIN	2	C	9	G	S	X	3	Z	5	K	M	1	8	3	8	8	9
Unit Number		Year		Make			Model			Odometer							
T89		2019		Cross Country			Hay Rack										
Registered Owner's Name													Plate Number				
Kropp Contracting													5PN359				
Address										Postal Code			Phone Number				
box 237 Slave lake										T0G2A0							

LEFT		FRONT		RIGHT			
100 psi 18 mm	100 psi 7 mm	16.572 mm 13/16 mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.598 mm 3/16 mm 1.5 mm	100 psi 18 mm 100 psi 18 mm		
100 psi 15 mm	100 psi 14 mm	New mm mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.585 mm 13/16 mm 1.5 mm	psi 10 mm psi 12 mm		
100 psi 14 mm	100 psi 14 mm	16.558/16.558 mm 11/16 mm 1.5 mm 75	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.558 mm 13/16 mm 1.5 mm	psi 12 mm psi 19 mm		
100 psi 13 mm	100 psi 11 mm	16.566 mm 11/16 mm 1.5 mm 75	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.571 mm 11/16 mm 1.5 mm 75	psi 6 mm psi 14 mm		
psi mm	psi mm					psi mm	psi mm
Park Brake Lining Left <u> </u> mm Right <u> </u> mm Trans <u> </u> mm Wheel Torque Checked ☒ Inner <u> </u> ft lbs Outer <u>50</u> ft lbs							

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System				1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System				A.3. Liquefied Natural Gas (LNG) Fuel System			
A.2. Compressed Natural Gas (CNG) Fuel System							

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments				2.5. Air Suspension			
2.2. Axle Attaching & Tracking Components				2.6. Self-Steer & Controlled-Steer Axle			
2.3. Axle & Axle Assembly				2.7. Shock Absorber/Strut Assembly			
2.4. Spring & Spring Attachment							

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components				3H.10. Electric Brake System			
3H.6. Air-Over-Hydraulic Brake System				3H.12. Drum Brake System Components			
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			
3H.8. Vacuum System				3H.19. Brake Performance			
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage				3A.16. S-Cam Drum Brake System			
3A.4. Air Tank				3A.17. Brake Shoe Travel (Wedge Brakes)			
3A.8. Brake Valves & Controls				3A.18. Disc Brake System Components			
3A.12. Parking Brake & Emergency Application				3A.20. Anti-Lock Brake System (ABS)			
3A.13. Air System Components				3A.22. Stability Control System (ESC) or (RSS)			
3A.14. Brake Chamber				3A.23. Brake Performance			
3A.15. Drum Brake System Components							

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage				4.5. Self Steer & Controlled-Steer Axle			
4.4. Kingpin							

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 5 - Instruments and Auxiliary Equipment							
Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				
NOTES:							

Section 6 - Lamps							
Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking			
6.2. Reflex Reflector		✓					
NOTES:							

Section 7 - Electrical System							
Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)			✓
7.2. Battery			✓				
NOTES:							

Section 8 - Body							
Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓		✓	8.11. Refrigeration/Heater Unit Fuel System			
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap			
8.7. Unitized Body Elements	✓			8.22. Landing Gear on Trailer			
8.8. Cab or Cargo Door				8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel				8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			
NOTES:							

Section 9 - Tires and Wheels							
Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth			✓	9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition			✓	9.8. Multi-Piece Wheel/Rim			
9.3. Tire Sidewall & Manufacturer Markings			✓	9.9. Spoke Wheel/Demountable Rim System			
9.4. Tire Inflation Pressure			✓	9.10. Disc Wheel System			
9.5. Wheel Hub			✓	9.11. Wheel Fasteners (Nuts, Bolts, & Studs)			
9.6. Wheel Bearing			✓				
NOTES:							

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)				10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch				10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch				10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				
NOTES:							

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Certification			
The Vehicle for which this Record of Inspection is issued has <u>Passed</u> the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection	Technician Number	Facility Number	Signature
June 11/26	C1246	18733	
Customer Acknowledgment			
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day)
			Customer Signature
			June 11/26 