

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
electrical	Mar 10, 2024	Mar 10, 2024		Mar 10, 2024 2:31 PM	Mar 10, 2024 2:31 PM

Line	Task			Parts	Labor	Total
1	✓ RH rear signal not working			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6050A oval light	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	May 10, 2024	May 10, 2024		May 13, 2024 5:48 AM	May 13, 2024 5:49 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Install lift axle	\$0.00	\$0.00	\$0.00
3	✓ Weld cracks on trailer	\$0.00	\$0.00	\$0.00

Notes

shock mount crossmember crack

4	✓ Front LH brake job			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Weld brackets back onto front LH beam			\$0.00	\$0.00	\$0.00
6	✓ Wheel seal leaking			\$0.00	\$0.00	\$0.00

Notes

#2 LH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jul 18, 2024	Jul 18, 2024		Jul 18, 2024 11:06 AM	Jul 18, 2024 11:06 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

ABS codes intermittent, verified WSS for proper gap/resistance
found loose 7 wire female pin, spread pin and test drove code did
not come back on

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2024	Jul 23, 2024		Jul 23, 2024 3:02 AM	Jul 23, 2024 3:02 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

Front axle inside both sides wore out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Scheduled	Due	Started	Closed
	Aug 29, 2024		Aug 29, 2024 3:50 PM	Aug 29, 2024 3:50 PM

Line	Task	Parts	Labor	Total
1	✓ Lift axle cracks	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Scheduled	Due	Started	Closed
	Oct 20, 2024		Oct 20, 2024 10:08 AM	Oct 20, 2024 10:08 AM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	license plate light out, lh marker			
2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	front LH, RH cracked			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 9:52 PM	Nov 2, 2024 9:52 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	front lh s cam tube spinning			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	hubs low			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Dec 15, 2024	Dec 15, 2024		Dec 15, 2024 2:40 PM	Dec 15, 2024 2:40 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	front axle low hubs			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	middle marker out, lh marker out rear bar			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	middle RH saddle			
4	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00
	Notes			
	LH middle wheels loose, RH rear missing stud			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
10082225 - Con met trailer hub	Kropp Shop		1.0	\$0.00	\$0.00
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2025	Jan 15, 2025		Jan 15, 2025 6:22 PM	Jan 15, 2025 6:22 PM

Line	Task	Parts	Labor	Total
1	✓ rear lh brake pot bracket need weld job	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Scheduled	Due	Started	Closed
	Jan 18, 2025		Jan 18, 2025 4:48 PM	Jan 18, 2025 4:48 PM

Line	Task	Parts	Labor	Total												
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	LH tube front spinning															
2	✓ Brakes	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	LH rear brake pot bracket broke, RH brake pot rear nfg															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>3030 brake pot</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00											
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	top up all around															
4	✓ Lights - All	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	marker lights out all around															
5	✓ Tires	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	front rh tires nfg															

Kropp Contracting
Shop

Work Order 1590
Trent Court, Nate Vandenberghe

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jan 28, 2025	Jan 28, 2025		Jan 28, 2025 8:11 PM	Jan 28, 2025 8:11 PM

Line	Task			Parts	Labor	Total
1	✓ RH middle inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 6:49 PM	Feb 2, 2025 6:49 PM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle RH cotter pin MIA					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle LH service line					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	bunk markers out, License plate light out					
4	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH front saddle cracked, u bolts loose					
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2025	Feb 25, 2025		Feb 25, 2025 1:38 PM	Feb 25, 2025 1:38 PM

Line	Task	Parts	Labor	Total
1	✓ Back RH pot bracket broke off	\$0.00	\$0.00	\$0.00
2	✓ Back LH brake pot loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 12:11 PM	Mar 3, 2025 12:11 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

LM and

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Hab 8 72 fs - Rubber air brake service 72" long	Kropp Shop		2.0	\$0.00	\$0.00

2	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

shoes missing springs, LHF,RHF dust covers mia

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

LHF, LHR, RHF low

4	✓ other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

LH Rear brake pot bracket broke off

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)

Kropp Contracting
Shop

Work Order 1736

Everett Twin

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Total Cost

\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 6:06 PM	Mar 6, 2025 6:06 PM

Line	Task			Parts	Labor	Total
1	✓ Middle rh inside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
Welding	May 3, 2025	May 3, 2025		May 3, 2025 9:16 AM	May 3, 2025 9:16 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ lift axle cracks	\$0.00	\$0.00	\$0.00
3	✓ Weld saddles	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	May 11, 2025	May 11, 2025		May 11, 2025 6:47 PM	May 11, 2025 6:47 PM

Line	Task	Parts	Labor	Total
1	✓ Lh middle wheel seal leaking	\$0.00	\$0.00	\$0.00

Notes

Changed shoes as they were at 5/16"

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Rh front outside flat	\$0.00	\$0.00	\$0.00
---	-------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Lift axle crack LH beam	\$0.00	\$0.00	\$0.00
---	---------------------------	--------	--------	--------

4	✓ Rh middle brakes wore out drum nfg	\$0.00	\$0.00	\$0.00
---	--------------------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 29, 2025	May 29, 2025		May 29, 2025 2:32 PM	May 29, 2025 3:56 PM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jul 29, 2025	Jul 29, 2025		Jul 29, 2025 7:33 PM	Jul 31, 2025 10:19 AM

Line	Task	Parts	Labor	Total
1	✓ Weld lift axel	\$0.00	\$0.00	\$0.00
2	✓ Adjust all brakes	\$0.00	\$0.00	\$0.00
3	✓ Diagnose brake issue on left side	\$0.00	\$0.00	\$0.00
4	✓ ABS codes	\$0.00	\$0.00	\$0.00
5	✓ Leveling rod	\$0.00	\$0.00	\$0.00
6	✓ Axel 7 inside tire	\$0.00	\$0.00	\$0.00

Notes

After further inspection tire was runnable

7	✓ Axel 6 outside right hand sude	\$0.00	\$0.00	\$0.00
8	✓ Air leak on lift axel	\$0.00	\$0.00	\$0.00
9	✓ Leaking shock	\$0.00	\$0.00	\$0.00
10	✓ Hub levels low	\$0.00	\$0.00	\$0.00
11	✓ Check dolly legs	\$0.00	\$0.00	\$0.00
12	✓ Fitting ontop of lift pusher bags leaking	\$0.00	\$0.00	\$0.00
13	✓ rh service line on lift leaking	\$0.00	\$0.00	\$0.00
14	✓ air leak at service valve by tank somewhere	\$0.00	\$0.00	\$0.00
15	✓ 4 slack adjusters	\$0.00	\$0.00	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

16	✓ Move bunk 5	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 19, 2025 6:43 AM	Aug 26, 2025 4:22 PM

Line	Task	Parts	Labor	Total		
1	✓ Lift axle down, bags over extend lift up ride height fine	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SE3100N - Ratio-relay valve lift axle	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Middle LH u bolts loose on beam	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Tighten u-bolts and weld saddle					
3	✓ Middle LH saddle crack	\$0.00	\$0.00	\$0.00		
4	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LR and RR					
5	✓ Shock absorber crossmember cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle and rear axle. Gouge out cracks and weld					
6	✓ Chafed air line	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Replace tire	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

LM

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00

Technician	Hours	Rate	Cost
Sam Hawksley	0.0	\$0.00	\$0.00

8 ✓ #5 wrapper handle \$0.00 \$0.00 \$0.00

Notes

Weld new wrapper handle

9 ✓ Loose air bag bolts \$0.00 \$0.00 \$0.00

Notes

RF, LR&RR

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Sep 12, 2025	Sep 12, 2025		Sep 12, 2025 5:18 AM	Sep 12, 2025 5:18 AM

Line	Task	Parts	Labor	Total		
1	✓ rh rear tires nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Sep 25, 2025	Sep 25, 2025		Sep 30, 2025 2:43 PM	Sep 30, 2025 2:43 PM

Line	Task	Parts	Labor	Total		
1	✓ rear axle brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	both sides					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ rear axle tri-functional bushings no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-24691 - TRI-FUNCIONAL QUIK-ALIGN	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ lift axle crossmember crack under air bags	\$0.00	\$0.00	\$0.00		
4	✓ lift axle rh steer shock	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	66502 - Lift axle shock	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ check hub levels	\$0.00	\$0.00	\$0.00		
6	✓ rh rear wheel seal	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
	75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
	hub gasket	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ check lights	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

Work Order 2148

Everett Twin

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Nov 13, 2025	Nov 13, 2025		Nov 14, 2025 2:06 PM	Nov 14, 2025 2:06 PM

Line	Task	Parts	Labor	Total
1	✓ No left hand tail marker	\$0.00	\$0.00	\$0.00
2	✓ Lift axle issues	\$0.00	\$0.00	\$0.00
3	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Dec 6, 2025	Dec 6, 2025		Dec 6, 2025 8:39 AM	Dec 6, 2025 8:39 AM

Line	Task			Parts	Labor	Total
1	✓ Rear rh axle lost wheels			\$486.00	\$0.00	\$486.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Wheel nut	Kropp Shop		10.0	\$0.00	\$0.00
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
	75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
	10082225 - Con met trailer hub	Kropp Shop		1.0	\$486.00	\$486.00
				Part Cost		\$486.00
				Labor		\$0.00
				Subtotal		\$486.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$486.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 19, 2025 9:30 AM	Dec 19, 2025 9:30 AM

Line	Task	Parts	Labor	Total
1	✓ other	\$0.00	\$0.00	\$0.00

Notes

#6 right hand dust cover

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2026	Jan 15, 2026		Jan 15, 2026 6:07 AM	Jan 15, 2026 6:07 AM

Line	Task	Parts	Labor	Total		
1	✓ Saddle crack middle rh	\$0.00	\$0.00	\$0.00		
2	✓ U bolt loose middle rh outside	\$0.00	\$0.00	\$0.00		
3	✓ No midship markers on both sides	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		2.0	\$0.00	\$0.00
	6050A oval light	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ to rear rh tail light	\$0.00	\$0.00	\$0.00		
5	✓ air leak on service line above dolly leg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3/8 Plastic Airline	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2026	Jan 31, 2026		Feb 1, 2026 12:05 PM	Feb 1, 2026 12:05 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> front lh jam nut	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> rh rear low	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> rh rear tail lights	\$0.00	\$0.00	\$0.00
4	✓ Suspension <u>Notes</u> rh front axle u bolts loose, air bag bolt	\$0.00	\$0.00	\$0.00
5	✓ Tires <u>Notes</u> RHMO nfg	\$0.00	\$0.00	\$0.00
6	✓ rh front saddle crack	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 2502

Trent Court

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2026	Feb 15, 2026		Feb 16, 2026 5:04 PM	Feb 16, 2026 5:04 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> no self check	\$0.00	\$0.00	\$0.00
2	✓ Brakes <u>Notes</u> rear rh dust cover MIA	\$0.00	\$0.00	\$0.00
3	✓ Bunk bolts <u>Notes</u> #3 lh	\$0.00	\$0.00	\$0.00
4	✓ Hub Levels <u>Notes</u> rear rh low	\$0.00	\$0.00	\$0.00
5	✓ Lights - All <u>Notes</u> marker rh out	\$0.00	\$0.00	\$0.00
6	✓ other <u>Notes</u> rear inside u bolts loose both sides, loose air tank	\$0.00	\$0.00	\$0.00
7	✓ Saddle cracks	\$0.00	\$0.00	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Notes

rear rh saddle crack

8	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

mid rh bag fitting leaking

9	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

rear lh outside flat

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 26, 2026 4:32 AM	Feb 26, 2026 4:32 AM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	LH outside marker out			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	Loose shock LH front, rh rear			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Scheduled	Due	Started	Closed
	Mar 24, 2026		Mar 24, 2026 5:14 AM	Mar 24, 2026 5:14 AM

Line	Task	Parts	Labor	Total		
1	✓ Rh rear axle saddle crack	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-21140 - U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Front rh u bolt loose	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z6JM183298	6NA328	

Type	Created	Scheduled	Due	Started	Closed
	Jul 2, 2026	Jul 2, 2026		Jul 7, 2026 11:43 AM	Jul 10, 2026 4:59 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Front left saddle cracked	\$0.00	\$0.00	\$0.00
4	✓ Middle left beam broken	\$0.00	\$0.00	\$0.00
5	✓ Back left saddle cracked	\$0.00	\$0.00	\$0.00
6	✓ Back right saddle broke	\$0.00	\$0.00	\$0.00
7	✓ U bolts loose on front righg	\$0.00	\$0.00	\$0.00
8	✓ U bolts loose on back left	\$0.00	\$0.00	\$0.00
9	✓ Lift axle craxks	\$0.00	\$0.00	\$0.00
10	✓ Lift axle slack missing snap ring on right side	\$0.00	\$0.00	\$0.00
11	✓ Middle axle shocks bad	\$0.00	\$0.00	\$0.00
12	✓ Front right shock bad	\$0.00	\$0.00	\$0.00
13	✓ Back left shock bad	\$0.00	\$0.00	\$0.00
14	✓ Multiple cracks along trailer frame	\$0.00	\$0.00	\$0.00
15	✓ License plate light	\$0.00	\$0.00	\$0.00
16	✓ Brake stuck on middle right axle	\$0.00	\$0.00	\$0.00
17	✓ Left hand tail bar lights not working	\$0.00	\$0.00	\$0.00

T298 - 2018 Cross Country Cross Country Mfg.

CLOSED

18	✓ Front left axle hub low	\$0.00	\$0.00	\$0.00
19	✓ Back right axle hub low	\$0.00	\$0.00	\$0.00
20	✓ Lift axle bolts loose	\$0.00	\$0.00	\$0.00
21	✓ Abs wire	\$0.00	\$0.00	\$0.00
22	✓ Dust ciber	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00