

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 26, 2024	Mar 26, 2024		Mar 26, 2024 2:26 PM	Mar 26, 2024 2:26 PM

Line	Task	Parts	Labor	Total
1	✓ Air bag	\$300.00	\$0.00	\$300.00

Notes

Back RH blown

Front LH blown

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		2.0	\$150.00	\$300.00

2	✓ Perform scheduled maintenance	\$0.00	\$0.00	\$0.00
---	---------------------------------	--------	--------	--------

Part Cost	\$300.00
Labor	\$0.00
Subtotal	\$300.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$300.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Apr 22, 2024	Apr 22, 2024		May 1, 2024 6:15 AM	May 6, 2024 5:03 AM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ Replace tire	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ licence plate light	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	licence plate light	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ LH marker light on light bar out	\$0.00	\$0.00	\$0.00		
5	✓ RH midship marker out	\$0.00	\$0.00	\$0.00		
6	✓ #5,#6 bunk mounts broke	\$0.00	\$0.00	\$0.00		
7	✓ saddle crack	\$0.00	\$0.00	\$0.00		

Notes

RH side all 3 cracked middle LH cracked

Rear RH beam cracked across top needs replaced

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
RH beam	Kropp Shop		1.0	\$0.00	\$0.00
S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
Eccentric washer	Kropp Shop		1.0	\$0.00	\$0.00
Concentric washer	Kropp Shop		1.0	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

8 ✓ limit chain \$0.00 \$0.00 \$0.00

Notes

middle rh

9 ✓ s cam bushings \$0.00 \$0.00 \$0.00

10 ✓ s cam tubes bent \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
X039 - CC S cam tube	Kropp Shop		3.0	\$0.00	\$0.00

11 ✓ Rear LH brakes no good \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00

12 ✓ Front axle shocks loose \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00

13 ✓ rear axle shocks leaking \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		2.0	\$0.00	\$0.00

14 ✓ lift axle cracks \$0.00 \$0.00 \$0.00

15 ✓ tie up hanging air lines \$0.00 \$0.00 \$0.00

16 ✓ mudflap bracket loose \$0.00 \$0.00 \$0.00

17 ✓ brake pot jam nut middle lh tighten \$0.00 \$0.00 \$0.00

18 ✓ air leak on supply line to leveling valve \$0.00 \$0.00 \$0.00

19 ✓ LH rear Tri functional bushing no good \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Eccentric washer	Kropp Shop		1.0	\$0.00	\$0.00
Concentric washer	Kropp Shop		1.0	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	S-24679 - Quick align pivot bolt	Kropp Shop	1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop	2.0	\$0.00	\$0.00
	Tri functional bushing	Kropp Shop	1.0	\$0.00	\$0.00
20	✓ Perform scheduled maintenance		\$0.00	\$0.00	\$0.00
				Part Cost	\$0.00
				Labor	\$0.00
				Subtotal	\$0.00
				Tax 1 (0.0%)	\$0.00
				Tax 2 (0.0%)	\$0.00
				Credit	(\$0.00)
				Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jul 9, 2024	Jul 9, 2024	Jul 9, 2024	Jul 10, 2024 4:33 AM	Jul 10, 2024 4:33 AM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

#3 outside left wore out #3 rh outside flat #4 rh inside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		3.0	\$0.00	\$0.00

2	✓ Perform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jul 18, 2024	Jul 18, 2024		Jul 18, 2024 11:05 AM	Jul 18, 2024 11:05 AM

Line	Task	Parts	Labor	Total
1	✓ Lift axle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Bottom of suspension beam cracked both sides			
2	✓ Bunk 5 loose	\$0.00	\$0.00	\$0.00
	Notes			
	Tightened bunk			
3	✓ Perform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
	Notes			
	Visual inspection			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Oct 5, 2024	Oct 5, 2024		Oct 5, 2024 1:18 PM	Oct 5, 2024 1:18 PM

Line	Task			Parts	Labor	Total
1	✓ Broken stake			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Oct 12, 2024	Oct 12, 2024		Oct 12, 2024 10:30 AM	Oct 12, 2024 10:30 AM

Line	Task			Parts	Labor	Total
1	✓ LH middle tire outside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Oct 16, 2024		Oct 16, 2024 6:49 PM	Oct 16, 2024 6:49 PM

Line	Task	Parts	Labor	Total
1	✓ Lift axle tire LH inside nfg	\$0.00	\$0.00	\$0.00
2	✓ Front rh scam tube loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Oct 24, 2024	Oct 24, 2024		Oct 25, 2024 9:15 AM	Oct 25, 2024 9:15 AM

Line	Task	Parts	Labor	Total
1	✓ Lift axle right hand, tire rod no good	\$0.00	\$0.00	\$0.00

Notes

changed rod end and checked alignment

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
R230069 - Tie rod end	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 7:40 PM	Nov 2, 2024 7:40 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	Hubs low			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	Last axle air bag			
		Part Cost	\$0.00	
		Labor	\$0.00	
		Subtotal	\$0.00	
		Tax 1 (0.0%)	\$0.00	
		Tax 2 (0.0%)	\$0.00	
		Credit	(\$0.00)	
		Total Cost	\$0.00	

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Nov 11, 2024		Nov 11, 2024 12:17 PM	Nov 11, 2024 12:17 PM

Line	Task	Parts	Labor	Total		
1	✓ RH lift axle outside tire NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH lift axle inside tire NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Rh marker lights out (broken wire)	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Nov 28, 2024	Nov 28, 2024		Nov 29, 2024 10:26 AM	Nov 29, 2024 10:26 AM

Line	Task	Parts	Labor	Total		
1	✓ Flat tire	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#8 rh low #6inner					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LH beam	Kropp Shop		1.0	\$0.00	\$0.00
	U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ S cam tubes loose	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Everett Twin	0.0	\$0.00	\$0.00		
4	✓ Air leak on lift axle	\$0.00	\$0.00	\$0.00		
5	✓ RH tie rod clamp loose on lift axle	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

Work Order 1471
Everett Twin, Nate Vandenberghe

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2024	Dec 13, 2024		Dec 13, 2024 8:54 PM	Dec 13, 2024 8:54 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

S cam tubes spin front RH Middle both sides

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S cam tube brackets	Kropp Shop		3.0	\$0.00	\$0.00

2	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

front RH brakes no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ middle RH slack adjuster no good	\$0.00	\$0.00	\$0.00
---	------------------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jan 17, 2025	Jan 17, 2025		Jan 17, 2025 6:01 PM	Jan 17, 2025 6:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle lh brake springs mia, rear rh shoes wore out					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	Q plus hardware kit	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh rear low					
3	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh signal unplugged					
4	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	s cam tubes all spin					
5	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear rh saddle crack					

Kropp Contracting
Shop

Work Order 1582

Nate Vandenberghe

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Feb 7, 2025		Feb 7, 2025 9:20 AM	Feb 7, 2025 9:20 AM

Line	Task	Parts	Labor	Total		
1	✓ rh front outside rim bent	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Feb 12, 2025		Feb 12, 2025 8:35 PM	Feb 12, 2025 8:35 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes <u>Notes</u> loose brake pot	\$0.00	\$0.00	\$0.00
2	✓ Bunk bolts <u>Notes</u> #2 rh bunk bolts loose	\$0.00	\$0.00	\$0.00
3	✓ Bunk cracks <u>Notes</u> #2,3,4,6 mount gusset small cracks	\$0.00	\$0.00	\$0.00
4	✓ Suspension <u>Notes</u> rear rh lower shock bolt loose	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:43 AM	Mar 3, 2025 11:43 AM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LH side tubes all loose					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front LH out of adjust					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus hardware kit	Kropp Shop		1.0	\$0.00	\$0.00
	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Bunk bolts	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#2 rh bunk bolts loose					
4	✓ Bunk cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#5 rh cracked					
5	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#5 winch handle					
6	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Notes

middle and rear LH cracked

7	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

bracket broke off

front LH shock

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 5:04 PM	Mar 6, 2025 5:04 PM

Line	Task			Parts	Labor	Total
1	✓ Front rh inside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Middle LH outside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2025	Mar 11, 2025		Mar 13, 2025 7:08 AM	Mar 13, 2025 7:08 AM

Line	Task	Parts	Labor	Total		
1	✓ FLO, FLMO tires flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ LH red oval tail light out	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 18, 2025	Mar 18, 2025		Mar 18, 2025 10:17 AM	Mar 18, 2025 10:17 AM

Line	Task			Parts	Labor	Total
1	✓ LHRO tire flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ RHRO tire flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 19, 2025	Mar 19, 2025		Mar 19, 2025 2:38 PM	Mar 19, 2025 2:38 PM

Line	Task	Parts	Labor	Total
1	✓ middle LH marker shorted to ground	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Apr 1, 2025	Apr 1, 2025		Apr 4, 2025 2:34 PM	Apr 22, 2025 7:06 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Install lift axle	\$0.00	\$0.00	\$0.00
4	✓ Fix siezed dolly legs	\$0.00	\$0.00	\$0.00
5	✓ replace molly	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	1" molly Kropp Shop 1.0 \$0.00 \$0.00			
6	✓ LH rear brake pot bracket broken	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	05-162 - Brake pot bracket Kropp Shop 1.0 \$0.00 \$0.00			
7	✓ RH rear scam tube bent and cracked	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	999195-290 - S cam tube for 29" cam Kropp Shop 1.0 \$0.00 \$0.00			
8	✓ LH rear scam loose	\$0.00	\$0.00	\$0.00
9	✓ RH rear brake pot rod bent	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	3030 brake pot Kropp Shop 1.0 \$0.00 \$0.00			
10	✓ RH middle scam NFG	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	999195-290 - S cam tube for 29" cam Kropp Shop 1.0 \$0.00 \$0.00			

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	202102-290-RH - 29" RH S cam	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ LH middle Scam bent			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	999195-290 - S cam tube for 29" cam	Kropp Shop		1.0	\$0.00	\$0.00
	202102-290-LH - 29" LH s cam	Kropp Shop		1.0	\$0.00	\$0.00
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ LH front scam bent			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	999195-290 - S cam tube for 29" cam	Kropp Shop		1.0	\$0.00	\$0.00
	202102-290-LH - 29" LH s cam	Kropp Shop		1.0	\$0.00	\$0.00
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ LH middle beam NFG			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LH beam	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
14	✓ LH rear saddle crack			\$0.00	\$0.00	\$0.00
	<u>Notes</u>					
	Cracked up passed u bolts					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LH beam	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		1.0	\$0.00	\$0.00
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ LH rear inside saddle ubolt loose			\$0.00	\$0.00	\$0.00
16	✓ RH front Limit chain			\$0.00	\$0.00	\$0.00
17	✓ RH front Slack adj NFG			\$0.00	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Front axle chafed lines			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Hab 8 72 fs - Rubber air brake service 72" long	Kropp Shop		2.0	\$0.00	\$0.00
19	✓ Front axle green suspension line NFG wore to cords			\$0.00	\$0.00	\$0.00
20	✓ Middle RH air bag line kinked			\$0.00	\$0.00	\$0.00
21	✓ Middle axle lines chafed			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00
22	✓ Middle to rear axle along frame electrical wrapped around cross member			\$0.00	\$0.00	\$0.00
23	✓ Rear trailer DOT tape			\$0.00	\$0.00	\$0.00
24	✓ #5 bunk pockets cracked			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	CC bunk	Kropp Shop		1.0	\$0.00	\$0.00
25	✓ R/H rear hub low			\$0.00	\$0.00	\$0.00
	Notes					
	Wheel seal leaking					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
	hub gasket	Kropp Shop		1.0	\$0.00	\$0.00
26	✓ #6 bunk mounts shifted and not clamping on frame			\$0.00	\$0.00	\$0.00
27	✓ #3 bunk wrapper hook broke			\$0.00	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

28	✓ Check abs codes	\$0.00	\$0.00	\$0.00
29	✓ #2 bunk bolts loose	\$0.00	\$0.00	\$0.00
30	✓ shock mount cross member frame cracks	\$0.00	\$0.00	\$0.00
31	✓ gusset cracks along frame	\$0.00	\$0.00	\$0.00
32	✓ LH lift shock NFG	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
66502 - Lift axle shock	Kropp Shop		1.0	\$0.00	\$0.00

33	✓ measure brake stroke after repairs	\$0.00	\$0.00	\$0.00
34	✓ grease trailer after repairs	\$0.00	\$0.00	\$0.00
35	✓ RH lift axle brake pot no good	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Type 30 service pot	Kropp Shop		1.0	\$0.00	\$0.00
Hab 8 72 fs - Rubber air brake service 72" long	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
Service	May 30, 2025		May 30, 2025 4:28 AM	May 30, 2025 4:28 AM

Line	Task	Parts	Labor	Total
1	✓ air bag	\$0.00	\$0.00	\$0.00

Notes

R/H lift axle bag 8006 bag

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jun 18, 2025	Jun 18, 2025		Jun 18, 2025 8:13 PM	Jun 18, 2025 8:14 PM

Line	Task	Parts	Labor	Total
1	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	RF scam tube loose. Weld tube, new brake shoes due to damage			
2	✓ Loose shock	\$0.00	\$0.00	\$0.00
3	✓ Trailer lights	\$0.00	\$0.00	\$0.00

Notes

License plate light

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jul 11, 2025	Jul 11, 2025		Aug 8, 2025 3:22 PM	Aug 8, 2025 3:22 PM

Line	Task	Parts	Labor	Total
1	✓ Replace rear light bar	\$0.00	\$0.00	\$0.00
	Technician	Hours	Rate	Cost
	Trent Court	0.0	\$0.00	\$0.00
	Cam Nadeau	0.0	\$0.00	\$0.00
2	✓ Get ready for paint	\$0.00	\$0.00	\$0.00
3	✓ Weld small cracks throughout trailer	\$0.00	\$0.00	\$0.00
4	✓ put on new junction box on the rear of trailer	\$0.00	\$0.00	\$0.00
	Technician	Hours	Rate	Cost
	Everett Twin	0.0	\$0.00	\$0.00
5	✓ Fix midship oval holes	\$0.00	\$0.00	\$0.00
	Technician	Hours	Rate	Cost
	Sam Hawksley	0.0	\$0.00	\$0.00
6	✓ replace airlines with multiple splices	\$0.00	\$0.00	\$0.00
7	✓ run new wires where they have been spliced multiple times	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3050A-P - Amber 2" round light	Kropp Shop		4.0	\$0.00	\$0.00
146-18 - 2" round light grommet	Kropp Shop		4.0	\$0.00	\$0.00
3 wire pigtail	Kropp Shop		8.0	\$0.00	\$0.00
2 wire cord	Kropp Shop		1.0	\$0.00	\$0.00
93906 - 2 wire 3 plug Daisey chain	Kropp Shop		1.0	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	2 wire pigtail	Kropp Shop	5.0	\$0.00	\$0.00
	licence plate light	Kropp Shop	1.0	\$0.00	\$0.00
8	✓ Re assemble trailer once back from paint		\$0.00	\$0.00	\$0.00

Notes

Reinstall front and rear mudflaps, reinstall fifth wheel plate cover,
reinstall air tank plate covers

9	✓ Leveling rod		\$0.00	\$0.00	\$0.00
---	----------------	--	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
48100267 - Leveling rod kit	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Sep 17, 2025	Sep 17, 2025		Sep 17, 2025 3:19 PM	Sep 17, 2025 3:22 PM

Line	Task	Parts	Labor	Total
1	✓ Replace shock	\$0.00	\$0.00	\$0.00

Notes

LM

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

LM out of adjustment

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Oct 29, 2025	Oct 29, 2025		Oct 29, 2025 4:38 PM	Oct 31, 2025 9:02 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ ABS codes	\$0.00	\$0.00	\$0.00
	Notes			
	6 blink code, 5.0V out of ECM, both sensors within 1.100-1.600K ohms for wheel speed sensors. Tap both wheel speed sensors back into tone ring			
3	✓ S cam tube loose	\$0.00	\$0.00	\$0.00
	Notes			
	LHR			
4	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Nov 22, 2025	Nov 22, 2025		Nov 22, 2025 8:27 AM	Nov 22, 2025 8:27 AM

Line	Task	Parts	Labor	Total		
1	✓ Front LH outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2025	Nov 30, 2025		Nov 30, 2025 5:45 AM	Nov 30, 2025 5:45 AM

Line	Task	Parts	Labor	Total
1	✓ Landing Gear	\$0.00	\$0.00	\$0.00
	Notes			
	bent brackets			
2	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	lh liftaxle inside nfg			
3	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00
	Notes			
	rh rear outside cracked			
4	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	scam tubes loose frnt rh, middle both sides			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 1:39 PM	Dec 14, 2025 1:39 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> Abs wire	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> Brake line leaking	\$0.00	\$0.00	\$0.00
3	✓ Hub Levels <u>Notes</u> #7LH	\$0.00	\$0.00	\$0.00
4	✓ Suspension <u>Notes</u> Suspension line leaking, airbag quick connect leaking	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jan 11, 2026	Jan 11, 2026		Jan 12, 2026 7:15 PM	Jan 12, 2026 7:15 PM

Line	Task			Parts	Labor	Total
1	✓ Front LH axle hub (driver ran wheels loose)			\$1,794.70	\$0.00	\$1,794.70
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	10082225 - Con met trailer hub	Kropp Shop		1.0	\$486.00	\$486.00
	Wheel Missing - Complete 24.5 rim and tire	Kropp Shop		2.0	\$479.00	\$958.00
	Brake Drum	Kropp Shop		1.0	\$97.00	\$97.00
	Wheel nut	Kropp Shop		10.0	\$25.37	\$253.70
				Part Cost		\$1,794.70
				Labor		\$0.00
				Subtotal		\$1,794.70
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,794.70

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jan 12, 2026	Jan 12, 2026		Jan 12, 2026 10:49 AM	Jan 12, 2026 5:09 PM

Line	Task	Parts	Labor	Total		
1	✓ Dust cover front left	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Wheel seal back left	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2106 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Middle light in back bumper out	\$0.00	\$0.00	\$0.00		
4	✓ Adjust all brakes	\$0.00	\$0.00	\$0.00		
5	✓ Abs wire	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2026	Jan 31, 2026		Jan 31, 2026 4:53 PM	Jan 31, 2026 4:53 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	Front rh slack adjuster pushed past 90			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	License plate light out			
3	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	Front axle 3/8 airline cracked			
4	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	RHMI nfg RHRI nfg			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2026	Feb 11, 2026		Feb 11, 2026 6:08 PM	Feb 11, 2026 8:13 PM

Line	Task	Parts	Labor	Total		
1	✓ Brake kit missing middle left	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Dust shield middle left	\$0.00	\$0.00	\$0.00		
3	✓ License plate light out	\$0.00	\$0.00	\$0.00		
4	✓ Fucked up tire middle left outside	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Feb 23, 2026	Feb 23, 2026		Feb 24, 2026 10:26 AM	Feb 24, 2026 10:26 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> trailer abs	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> broke s cam back right middle rh s cam bushing	\$0.00	\$0.00	\$0.00
3	✓ Bunk bolts <u>Notes</u> #5 right hand loose	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> license plate light out, middle 3 markers out	\$0.00	\$0.00	\$0.00
5	✓ other <u>Notes</u> mud flap rh loose	\$0.00	\$0.00	\$0.00
6	✓ Suspension <u>Notes</u> back air bags flat	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 2568

Sam Hawksley

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Mar 2, 2026		Mar 2, 2026 7:06 PM	Mar 2, 2026 7:06 PM

Line	Task			Parts	Labor	Total
1	✓ #6 LH stake broke			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 13, 2026	Mar 13, 2026		Mar 13, 2026 6:11 PM	Mar 13, 2026 6:11 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> Abs code	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> Service air line leak	\$0.00	\$0.00	\$0.00
3	✓ Brakes <u>Notes</u> Front rh cotter pin mia middle LH scam weld	\$0.00	\$0.00	\$0.00
4	✓ Bunk bolts <u>Notes</u> Rear bunk slid foward	\$0.00	\$0.00	\$0.00
5	✓ Hub Levels <u>Notes</u> Rh rear hub cap MIA	\$0.00	\$0.00	\$0.00
6	✓ Rh rear scam weld	\$0.00	\$0.00	\$0.00
7	✓ Middle axle air leak somewhere	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 2630

Trent Court

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2026	Mar 17, 2026		Mar 17, 2026 8:29 AM	Mar 17, 2026 8:29 AM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

No LH signal no license plate light

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Scheduled	Due	Started	Closed
	Mar 18, 2026		Mar 18, 2026 5:50 PM	Mar 18, 2026 5:50 PM

Line	Task			Parts	Labor	Total
1	✓ Middle rh outside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	Mar 27, 2026	Mar 27, 2026		Mar 27, 2026 4:16 AM	Mar 27, 2026 4:16 AM

Line	Task			Parts	Labor	Total
1	✓ Rh middle tires skidded off			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3ZCJM183413	6PB992	

Type	Created	Scheduled	Due	Started	Closed
	May 6, 2026	May 6, 2026		May 11, 2026 6:19 AM	May 13, 2026 1:11 PM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ front lh fender MIA	\$0.00	\$0.00	\$0.00
4	✓ lift axle cracks	\$0.00	\$0.00	\$0.00
5	✓ ABS codes	\$0.00	\$0.00	\$0.00
6	✓ Bunk light front rh	\$0.00	\$0.00	\$0.00
7	✓ air bag bolt loose rear axle	\$0.00	\$0.00	\$0.00
8	✓ lift axle switch	\$0.00	\$0.00	\$0.00
9	✓ low hub middle Lh	\$0.00	\$0.00	\$0.00
10	✓ cracked cross members along frame	\$0.00	\$0.00	\$0.00
11	✓ Rh rear slack nfg	\$0.00	\$0.00	\$0.00
Part Warehouse Vendor/Bin Qty Unit Cost Cost				
6" slack adjuster CC Kropp Shop 1.0 \$0.00 \$0.00				
12	✓ airline to air back back Lh axle	\$0.00	\$0.00	\$0.00
Part Warehouse Vendor/Bin Qty Unit Cost Cost				
3/8 Plastic Airline Kropp Shop 1.0 \$0.00 \$0.00				
13	✓ scam tube broke rh rear	\$0.00	\$0.00	\$0.00
14	✓ scam tube broke middle lh	\$0.00	\$0.00	\$0.00

T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

15	✓ bunk bolt back Lh			\$0.00	\$0.00	\$0.00
16	✓ brake job rear lh			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
17	✓ brake job middle rh			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Wheelseal back right			\$0.00	\$0.00	\$0.00
19	✓ Lift axle king pin			\$0.00	\$0.00	\$0.00
Part Cost						\$0.00
Labor						\$0.00
Subtotal						\$0.00
Tax 1 (0.0%)						\$0.00
Tax 2 (0.0%)						\$0.00
Credit						(\$0.00)
Total Cost						\$0.00