

- Front L/H marker - 1/3 hr
- middle L/H brake pot bracket
- # 8 RHS inside tree
- # 7 RHS inside tree
-

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Certification			
The Vehicle for which this Record of Inspection is issued has <u>PASS</u> the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection <u>July 15/26</u>	Technician Number <u>C1246</u>	Facility Number <u>18733</u>	Signature 
Customer Acknowledgment			
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			Date (Year/Month/Day) <u>July 15/26</u> Customer Signature 

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher							

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps				6.3. Retro-Reflective Marking			
6.2. Reflex Reflector							

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring				7.3. Trailer Cord (output to towed vehicle)			
7.2. Battery							

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body				8.11. Refrigeration/Heater Unit Fuel System			
8.6. Frame Rails & Mounts				8.21. Fender/Mud Flap			
8.7. Unitized Body Elements				8.22. Landing Gear on Trailer			
8.8. Cab or Cargo Door				8.23. Sliding Axle Assembly (Sliding Bogie)			
8.9. Cargo Tank or Vessel				8.24. Aerodynamic Device & Attachment			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle				8.25. Rear Impact Guard (RIG)			

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth				9.7. Wheel/Rim			
9.2. Tire Tread Condition				9.8. Multi-Piece Wheel/Rim			
9.3. Tire Sidewall & Manufacturer Markings				9.9. Spoke Wheel/Demountable Rim System			
9.4. Tire Inflation Pressure				9.10. Disc Wheel System			
9.5. Wheel Hub				9.11. Wheel Fasteners (Nuts, Bolts, & Studs)			
9.6. Wheel Bearing							

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components				10.6. Automated Coupling Device			
10.2. Secondary Attachment (Safety Chain or Cable)				10.7. Fifth Wheel Coupler			
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch				10.8. Oscillating Fifth Wheel Coupler			
10.4. Ball Type Hitch				10.9. Ball-Bearing Type Turntable on Trailer			
10.5. Roll-Coupling Hitch							

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			☒	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			☒

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			☒	A.3. Liquefied Natural Gas (LNG) Fuel System			☒
A.2. Compressed Natural Gas (CNG) Fuel System			☒				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	☒			2.5. Air Suspension			☒
2.2. Axle Attaching & Tracking Components	☒			2.6. Self-Steer & Controlled-Steer Axle	☒		
2.3. Axle & Axle Assembly	☒			2.7. Shock Absorber/Strut Assembly	☒		
2.4. Spring & Spring Attachment			☒				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components				3H.10. Electric Brake System			☒
3H.6. Air-Over-Hydraulic Brake System				3H.12. Drum Brake System Components			☒
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			☒
3H.8. Vacuum System				3H.19. Brake Performance			☒
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	☒			3A.16. S-Cam Drum Brake System	☒		
3A.4. Air Tank	☒			3A.17. Brake Shoe Travel (Wedge Brakes)			☒
3A.8. Brake Valves & Controls	☒			3A.18. Disc Brake System Components			☒
3A.12. Parking Brake & Emergency Application	☒			3A.20. Anti-Lock Brake System (ABS)	☒		
3A.13. Air System Components	☒			3A.22. Stability Control System (ESC) or (RSS)			☒
3A.14. Brake Chamber	☒			3A.23. Brake Performance	☒		
3A.15. Drum Brake System Components	☒						

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage	☒			4.5. Self Steer & Controlled-Steer Axle	☒		
4.4. Kingpin	☒						

NOTES:

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle <u>Trailer</u>										Gross Vehicle Weight registered kg									
Vehicle Information																			
VIN		<u>2 C 9 G S X 3 Z 9 H M 1 8 3 8 0 7</u>																	
Unit Number <u>T807</u>				Year <u>2017</u>				Make <u>Cross Country</u>				Model <u>Hayrack</u>				Odometer <u> </u>			
Registered Owner's Name <u>Kropp Contracting Ltd</u>														Plate Number <u>6KX7-27</u>					
Address <u>Box 237 Shure Lake AB</u>										Postal Code <u>T0G 2A0</u>					Phone Number <u>800-849-6229</u>				

		LEFT		FRONT		RIGHT			
100 psi 0.377 mm	100 psi 0.357 mm	16.545 mm 3/4 mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.598 mm 3/4 mm 1.5 mm	mm mm mm mm	100 psi 0.398 mm	100 psi 0.395 mm		
100 psi 0.422 mm	100 psi 0.417 mm	16.562 mm 3/4 mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.589 mm 3/4 mm 1.5 mm	mm mm mm mm	100 psi 0.183 mm	100 psi 0.167 mm		
100 psi 0.413 mm	100 psi 0.310 mm	16.599 mm 4/2 mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.558 mm 3/4 mm 1.5 mm	mm mm mm mm	100 psi 0.227 mm	100 psi 0.28 mm		
100 psi 0.431 mm	100 psi 0.514 mm	16.591 mm 3/8 mm 1.5 mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	16.575 mm 1/4 mm 1.5 mm	mm mm mm mm	100 psi 0.205 mm	100 psi 0.345 mm		
psi mm	psi mm	mm mm mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	mm mm mm	mm mm mm	psi mm	psi mm		
Park Brake Lining Left <u> </u> mm Right <u> </u> mm Trans <u> </u> mm Wheel Torque Checked ☒ Inner <u> </u> ft lbs Outer <u>500</u> ft lbs									


CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

H01-177

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Kropp Contracting Ltd.		
Address:	Box 237		
City:	Slave Lake	Province:	AB
Postal Code:	T0G2A0		
Telephone Number:	(780) 849-6229		
Vehicle Identification Number:	2C9GSX3Z9HM183807		
Make:	Cross Country	Model:	Hayrack Logger
Year:	2017	Unit Number:	T807
Odometer:	KM	Licence Plate Number:	6KX722
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2026/07/15