

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 16, 2024 | Mar 16, 2024 |     | Mar 16, 2024 1:07 PM | Mar 16, 2024 1:07 PM |

| Line | Task      | Parts  | Labor  | Total  |
|------|-----------|--------|--------|--------|
| 1    | ✓ hub cap | \$0.00 | \$0.00 | \$0.00 |

**Notes**

replaced #6 LH

| Part             | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|------------------|------------|------------|-----|-----------|----------|
| hub cap          | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| 80 w 90 gear oil | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost        |            |            |     |           | \$0.00   |
| Labor            |            |            |     |           | \$0.00   |
| Subtotal         |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)     |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)     |            |            |     |           | \$0.00   |
| Credit           |            |            |     |           | (\$0.00) |
| Total Cost       |            |            |     |           | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started             | Closed              |
|------|--------------|--------------|-----|---------------------|---------------------|
|      | May 30, 2024 | May 30, 2024 |     | Jun 5, 2024 6:09 AM | Jun 5, 2024 6:09 AM |

| Line | Task                             | Parts      | Labor      | Total  |           |        |
|------|----------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Wheels off CVIP inspection     | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ front LH beam broke            | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LH beam                          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | S-24679 - Quick align pivot bolt | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | S-21099 - Teflon washer          | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
|      | U bolt kit                       | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 3    | ✓ Middle LH beam broke           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LH beam                          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | S-24679 - Quick align pivot bolt | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | S-21099 - Teflon washer          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | U bolt kit                       | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 4    | ✓ Middle LH shock leaking        | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | S-20126 - Trailer shock          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 5    | ✓ LH middle light not working    | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ 7 wire plug NFG                | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 7 wire female plug               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7    | ✓ front fenders bent             | \$0.00     | \$0.00     | \$0.00 |           |        |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

|    |                                               |            |            |        |           |              |
|----|-----------------------------------------------|------------|------------|--------|-----------|--------------|
| 8  | ✓ LH lift axle s cam bushing                  |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | cc s cam bushing                              | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
|    | 2110 wheel seal                               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
|    | 80 w 90 gear oil                              | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
| 9  | ✓ RH middle brake pot broke                   |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | 3030 brake pot                                | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
| 10 | ✓ RH middle Slack stripped                    |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | 6" slack adjuster CC                          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
| 11 | ✓ re shim middle LH s cam                     |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | shims s-cam                                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
| 12 | ✓ re shim Front LH s cam                      |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | shims s-cam                                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00       |
| 13 | ✓ limit chains                                |            |            | \$0.00 | \$0.00    | \$0.00       |
|    | Part                                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost         |
|    | 3/8 bitch link                                | Kropp Shop |            | 4.0    | \$0.00    | \$0.00       |
| 14 | ✓ airlines rubbing/hanging all over to tie up |            |            | \$0.00 | \$0.00    | \$0.00       |
|    |                                               |            |            |        |           | Part Cost    |
|    |                                               |            |            |        |           | \$0.00       |
|    |                                               |            |            |        |           | Labor        |
|    |                                               |            |            |        |           | \$0.00       |
|    |                                               |            |            |        |           | Subtotal     |
|    |                                               |            |            |        |           | \$0.00       |
|    |                                               |            |            |        |           | Tax 1 (0.0%) |
|    |                                               |            |            |        |           | \$0.00       |
|    |                                               |            |            |        |           | Tax 2 (0.0%) |
|    |                                               |            |            |        |           | \$0.00       |
|    |                                               |            |            |        |           | Credit       |
|    |                                               |            |            |        |           | (\$0.00)     |
|    |                                               |            |            |        |           | Total Cost   |
|    |                                               |            |            |        |           | \$0.00       |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jun 8, 2024 | Jun 8, 2024 |     | Jun 8, 2024 8:59 AM | Jun 8, 2024 8:59 AM |

| Line | Task                | Parts  | Labor  | Total  |
|------|---------------------|--------|--------|--------|
| 1    | ✓ Brake Connections | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Lift axle LH brake line rubbed on tire

| Part                                            | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------------------------------------|------------|------------|-----|-----------|--------|
| Hab 8 72 fs - Rubber air brake service 72" long | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |         |        |        |        |
|---|---------|--------|--------|--------|
| 2 | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |
|---|---------|--------|--------|--------|

**Notes**

RH middle inside flat

| Part                       | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------------------|------------|------------|-----|-----------|--------|
| 245 Trailer - Trailer Tire | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Oct 8, 2024 |     | Oct 8, 2024 7:01 AM | Oct 8, 2024 7:01 AM |

| Line | Task                         | Parts      | Labor      | Total        |           |          |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ RH lift axle hub cap broke | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | hub cap                      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | 75 W 90 gear oil             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 19, 2024 | Oct 19, 2024 |     | Oct 20, 2024 9:50 AM | Oct 20, 2024 9:50 AM |

| Line         | Task                                                                   | Parts  | Labor  | Total    |
|--------------|------------------------------------------------------------------------|--------|--------|----------|
| 1            | ✓ ABS codes<br><br><u>Notes</u><br>trailer abs code (light out)        | \$0.00 | \$0.00 | \$0.00   |
| 2            | ✓ Brake Connections<br><br><u>Notes</u><br>tie up chafing air lines    | \$0.00 | \$0.00 | \$0.00   |
| 3            | ✓ other<br><br><u>Notes</u><br>lift axle cracks,                       | \$0.00 | \$0.00 | \$0.00   |
| 4            | ✓ Suspension<br><br><u>Notes</u><br>air bag bolts loose RH middle axle | \$0.00 | \$0.00 | \$0.00   |
| Part Cost    |                                                                        |        |        | \$0.00   |
| Labor        |                                                                        |        |        | \$0.00   |
| Subtotal     |                                                                        |        |        | \$0.00   |
| Tax 1 (0.0%) |                                                                        |        |        | \$0.00   |
| Tax 2 (0.0%) |                                                                        |        |        | \$0.00   |
| Credit       |                                                                        |        |        | (\$0.00) |
| Total Cost   |                                                                        |        |        | \$0.00   |

T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Nov 2, 2024 | Nov 2, 2024 |     | Nov 2, 2024 7:41 PM | Nov 2, 2024 7:41 PM |

| Line | Task         | Parts  | Labor  | Total  |
|------|--------------|--------|--------|--------|
| 1    | ✓ Suspension | \$0.00 | \$0.00 | \$0.00 |

Notes

shocks loose mddle and rear axle

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 | Nov 16, 2024 |     | Nov 16, 2024 6:41 PM | Nov 16, 2024 6:42 PM |

| Line | Task           | Parts  | Labor  | Total  |
|------|----------------|--------|--------|--------|
| 1    | ✓ Loose shock  | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ saddle crack | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Lift axle LHS shock damaged-keep eye on

lift axle RHS tie rod-keep eye on

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Dec 14, 2024 | Dec 14, 2024 |     | Dec 14, 2024 10:09 AM | Dec 14, 2024 10:09 AM |

| Line | Task                                      | Parts        | Labor    | Total  |
|------|-------------------------------------------|--------------|----------|--------|
| 1    | ✓ Bunk bolts                              | \$0.00       | \$0.00   | \$0.00 |
|      | <b>Notes</b>                              |              |          |        |
|      | #2 and #4 LH loose #4 RH loose            |              |          |        |
| 2    | ✓ Lights - All                            | \$0.00       | \$0.00   | \$0.00 |
|      | <b>Notes</b>                              |              |          |        |
|      | marker lights and license plate light out |              |          |        |
| 3    | ✓ Suspension                              | \$0.00       | \$0.00   | \$0.00 |
|      | <b>Notes</b>                              |              |          |        |
|      | LH front shock mount broke off from beam  |              |          |        |
| 4    | ✓ Tires                                   | \$0.00       | \$0.00   | \$0.00 |
|      | <b>Notes</b>                              |              |          |        |
|      | LMO and LRI NFG                           |              |          |        |
|      |                                           | Part Cost    | \$0.00   |        |
|      |                                           | Labor        | \$0.00   |        |
|      |                                           | Subtotal     | \$0.00   |        |
|      |                                           | Tax 1 (0.0%) | \$0.00   |        |
|      |                                           | Tax 2 (0.0%) | \$0.00   |        |
|      |                                           | Credit       | (\$0.00) |        |
|      |                                           | Total Cost   | \$0.00   |        |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Jan 18, 2025 |     | Jan 18, 2025 4:32 PM | Jan 18, 2025 4:32 PM |

| Line         | Task                 | Parts  | Labor  | Total    |
|--------------|----------------------|--------|--------|----------|
| 1            | ✓ Bunk cracks        | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>         |        |        |          |
|              | #6 bunk crack        |        |        |          |
| 2            | ✓ Lights - All       | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>         |        |        |          |
|              | rh middle marker out |        |        |          |
| Part Cost    |                      |        |        | \$0.00   |
| Labor        |                      |        |        | \$0.00   |
| Subtotal     |                      |        |        | \$0.00   |
| Tax 1 (0.0%) |                      |        |        | \$0.00   |
| Tax 2 (0.0%) |                      |        |        | \$0.00   |
| Credit       |                      |        |        | (\$0.00) |
| Total Cost   |                      |        |        | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Feb 2, 2025 |     | Feb 2, 2025 6:31 PM | Feb 2, 2025 6:31 PM |

| Line | Task                 | Parts  | Labor  | Total  |
|------|----------------------|--------|--------|--------|
| 1    | ✓ Lights - All       | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>         |        |        |        |
|      | rh middle marker out |        |        |        |
| 2    | ✓ Saddle cracks      | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>         |        |        |        |
|      | LH rear saddle crack |        |        |        |
| 3    | ✓ Tires              | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>         |        |        |        |
|      | RRO nfg              |        |        |        |

| Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|----------------------------|------------|------------|--------------|-----------|----------|
| 245 Trailer - Trailer Tire | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|                            |            |            | Part Cost    |           | \$0.00   |
|                            |            |            | Labor        |           | \$0.00   |
|                            |            |            | Subtotal     |           | \$0.00   |
|                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|                            |            |            | Credit       |           | (\$0.00) |
|                            |            |            | Total Cost   |           | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Feb 13, 2025 |     | Feb 13, 2025 8:09 PM | Feb 13, 2025 8:09 PM |

| Line         | Task                           | Parts  | Labor  | Total    |
|--------------|--------------------------------|--------|--------|----------|
| 1            | ✓ Brakes                       | \$0.00 | \$0.00 | \$0.00   |
|              | <b><u>Notes</u></b>            |        |        |          |
|              | #5 RH adjust brake stroke      |        |        |          |
| 2            | ✓ Suspension                   | \$0.00 | \$0.00 | \$0.00   |
|              | <b><u>Notes</u></b>            |        |        |          |
|              | #5 LH lower shock mount broken |        |        |          |
| Part Cost    |                                |        |        | \$0.00   |
| Labor        |                                |        |        | \$0.00   |
| Subtotal     |                                |        |        | \$0.00   |
| Tax 1 (0.0%) |                                |        |        | \$0.00   |
| Tax 2 (0.0%) |                                |        |        | \$0.00   |
| Credit       |                                |        |        | (\$0.00) |
| Total Cost   |                                |        |        | \$0.00   |

**T796 - 2017 Cross Country Cross Country Mfg.**

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 27, 2025 | Feb 27, 2025 |     | Feb 27, 2025 4:52 PM | Feb 27, 2025 4:52 PM |

| Line | Task                                  | Parts        | Labor  | Total    |
|------|---------------------------------------|--------------|--------|----------|
| 1    | ✓ #5 LH shock absorber bracket broken | \$0.00       | \$0.00 | \$0.00   |
|      |                                       | Part Cost    |        | \$0.00   |
|      |                                       | Labor        |        | \$0.00   |
|      |                                       | Subtotal     |        | \$0.00   |
|      |                                       | Tax 1 (0.0%) |        | \$0.00   |
|      |                                       | Tax 2 (0.0%) |        | \$0.00   |
|      |                                       | Credit       |        | (\$0.00) |
|      |                                       | Total Cost   |        | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Mar 3, 2025 | Mar 3, 2025 |     | Mar 3, 2025 11:27 AM | Mar 3, 2025 11:27 AM |

| Line | Task    | Parts  | Labor  | Total  |
|------|---------|--------|--------|--------|
| 1    | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |

**Notes**

inspect RMI questionable

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

### Notes

| Notes                                      | User        | Time                 |
|--------------------------------------------|-------------|----------------------|
| inspected tire and found still able to run | Trent Court | Mar 3, 2025 11:27 AM |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started             | Closed              |
|------|--------------|--------------|-----|---------------------|---------------------|
|      | Apr 25, 2025 | Apr 25, 2025 |     | May 1, 2025 4:15 AM | May 1, 2025 4:16 AM |

| Line         | Task                                              | Parts  | Labor  | Total    |
|--------------|---------------------------------------------------|--------|--------|----------|
| 1            | ✓ Preform Scheduled Maintenance                   | \$0.00 | \$0.00 | \$0.00   |
| 2            | ✓ CVIP inspection (wheels off)                    | \$0.00 | \$0.00 | \$0.00   |
| 3            | ✓ No ABS power                                    | \$0.00 | \$0.00 | \$0.00   |
| 4            | ✓ lh lift axle shock bent                         | \$0.00 | \$0.00 | \$0.00   |
| 5            | ✓ RH tie rod clamp needs to be moved and tightend | \$0.00 | \$0.00 | \$0.00   |
| 6            | ✓ middle RH inside tire NFG                       | \$0.00 | \$0.00 | \$0.00   |
| 7            | ✓ Front RH tires NFG                              | \$0.00 | \$0.00 | \$0.00   |
| 8            | ✓ Change grease fittings                          | \$0.00 | \$0.00 | \$0.00   |
| 9            | ✓ Weld cracks                                     | \$0.00 | \$0.00 | \$0.00   |
| Part Cost    |                                                   |        |        | \$0.00   |
| Labor        |                                                   |        |        | \$0.00   |
| Subtotal     |                                                   |        |        | \$0.00   |
| Tax 1 (0.0%) |                                                   |        |        | \$0.00   |
| Tax 2 (0.0%) |                                                   |        |        | \$0.00   |
| Credit       |                                                   |        |        | (\$0.00) |
| Total Cost   |                                                   |        |        | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | May 6, 2025 | May 6, 2025 |     | May 6, 2025 5:12 AM | May 6, 2025 5:12 AM |

| Line | Task          | Parts  | Labor  | Total  |
|------|---------------|--------|--------|--------|
| 1    | ✓ Oil hub cap | \$0.00 | \$0.00 | \$0.00 |

**Notes**

#7LHS

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type    | Created      | Scheduled    | Due | Started              | Closed               |
|---------|--------------|--------------|-----|----------------------|----------------------|
| Service | May 29, 2025 | May 29, 2025 |     | May 29, 2025 5:39 AM | May 29, 2025 5:39 AM |

| Line | Task      | Parts  | Labor  | Total  |
|------|-----------|--------|--------|--------|
| 1    | ✓ air bag | \$0.00 | \$0.00 | \$0.00 |

**Notes**

R/H lift bag blown 8006 airbag

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jul 3, 2025 | Jul 3, 2025 |     | Jul 3, 2025 8:08 AM | Jul 3, 2025 8:08 AM |

| Line | Task                       | Parts      | Labor      | Total        |           |          |
|------|----------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Lift axle RH inside NFG  | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 245 Trailer - Trailer Tire | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                            |            |            | Part Cost    |           | \$0.00   |
|      |                            |            |            | Labor        |           | \$0.00   |
|      |                            |            |            | Subtotal     |           | \$0.00   |
|      |                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                            |            |            | Credit       |           | (\$0.00) |
|      |                            |            |            | Total Cost   |           | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Jul 7, 2025 |     | Jul 7, 2025 7:46 AM | Jul 7, 2025 7:46 AM |

| Line | Task                       | Parts      | Labor      | Total        |           |          |
|------|----------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Front rh tires nfg       | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 245 Trailer - Trailer Tire | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
|      |                            |            |            | Part Cost    |           | \$0.00   |
|      |                            |            |            | Labor        |           | \$0.00   |
|      |                            |            |            | Subtotal     |           | \$0.00   |
|      |                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                            |            |            | Credit       |           | (\$0.00) |
|      |                            |            |            | Total Cost   |           | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 17, 2025 | Jul 17, 2025 |     | Jul 17, 2025 4:42 PM | Jul 18, 2025 6:50 AM |

| Line | Task                    | Parts  | Labor  | Total  |
|------|-------------------------|--------|--------|--------|
| 1    | ✓ Adjust Brakes         | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ lift axle cracks      | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Lift axle steer shock | \$0.00 | \$0.00 | \$0.00 |

## Notes

RHS

| Part                    | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------------|------------|------------|-----|-----------|--------|
| 66502 - Lift axle shock | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                             |        |        |        |
|---|-----------------------------|--------|--------|--------|
| 4 | ✓ Tighten lift axle tie rod | \$0.00 | \$0.00 | \$0.00 |
| 5 | ✓ Trailer Brakes            | \$0.00 | \$0.00 | \$0.00 |

## Notes

Found roller in RF dust cover. Remove wheels and install new Q+ shoe kit due to low lining.

| Part            | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------|------------|------------|-----|-----------|--------|
| Q plus shoe kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |             |        |        |        |
|---|-------------|--------|--------|--------|
| 6 | ✓ Weld RIG  | \$0.00 | \$0.00 | \$0.00 |
| 7 | ✓ brake pot | \$0.00 | \$0.00 | \$0.00 |

## Notes

LM pot NFG, install new pot and adjust brakes

| Part           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------|------------|------------|-----|-----------|--------|
| 3030 brake pot | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |              |        |        |        |
|---|--------------|--------|--------|--------|
| 8 | ✓ Loose scam | \$0.00 | \$0.00 | \$0.00 |
|---|--------------|--------|--------|--------|

## Notes

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Weld LR Scam

| 9                           | ✓ Leveling rod |            |              | \$0.00    | \$0.00 | \$0.00 |  |  |
|-----------------------------|----------------|------------|--------------|-----------|--------|--------|--|--|
| Part                        | Warehouse      | Vendor/Bin | Qty          | Unit Cost | Cost   |        |  |  |
| 48100267 - Leveling rod kit | Kropp Shop     |            | 1.0          | \$0.00    | \$0.00 |        |  |  |
|                             |                |            | Part Cost    | \$0.00    |        |        |  |  |
|                             |                |            | Labor        | \$0.00    |        |        |  |  |
|                             |                |            | Subtotal     | \$0.00    |        |        |  |  |
|                             |                |            | Tax 1 (0.0%) | \$0.00    |        |        |  |  |
|                             |                |            | Tax 2 (0.0%) | \$0.00    |        |        |  |  |
|                             |                |            | Credit       | (\$0.00)  |        |        |  |  |
|                             |                |            | Total Cost   | \$0.00    |        |        |  |  |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started               | Closed              |
|------|--------------|--------------|-----|-----------------------|---------------------|
|      | Jul 31, 2025 | Jul 31, 2025 |     | Jul 31, 2025 10:39 AM | Aug 5, 2025 5:39 PM |

| Line | Task                            | Parts        | Labor  | Total    |
|------|---------------------------------|--------------|--------|----------|
| 1    | ✓ Weld lift axel                | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Loose air bag bolt            | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Replace stake                 | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ ABS codes                     | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ Weld bunk #6                  | \$0.00       | \$0.00 | \$0.00   |
| 6    | ✓ LH lift axel king pin         | \$0.00       | \$0.00 | \$0.00   |
| 7    | ✓ Flat tire axle #7 LH out side | \$0.00       | \$0.00 | \$0.00   |
|      |                                 | Part Cost    |        | \$0.00   |
|      |                                 | Labor        |        | \$0.00   |
|      |                                 | Subtotal     |        | \$0.00   |
|      |                                 | Tax 1 (0.0%) |        | \$0.00   |
|      |                                 | Tax 2 (0.0%) |        | \$0.00   |
|      |                                 | Credit       |        | (\$0.00) |
|      |                                 | Total Cost   |        | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Aug 26, 2025 |     | Aug 26, 2025 5:31 PM | Aug 26, 2025 5:31 PM |

| Line | Task                       | Parts      | Labor      | Total        |           |          |
|------|----------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Flat tire                | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 245 Trailer - Trailer Tire | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
|      |                            |            |            | Part Cost    |           | \$0.00   |
|      |                            |            |            | Labor        |           | \$0.00   |
|      |                            |            |            | Subtotal     |           | \$0.00   |
|      |                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                            |            |            | Credit       |           | (\$0.00) |
|      |                            |            |            | Total Cost   |           | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
| Tire | Sep 8, 2025 | Sep 8, 2025 |     | Sep 8, 2025 5:35 AM | Sep 8, 2025 5:36 AM |

| Line | Task           | Parts  | Labor  | Total  |
|------|----------------|--------|--------|--------|
| 1    | ✓ Replace tire | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Lift axle inside both sides. 2 used tires

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Oct 1, 2025 | Oct 1, 2025 |     | Oct 1, 2025 5:04 PM | Oct 1, 2025 5:05 PM |

| Line | Task                            | Parts      | Labor      | Total    |           |        |
|------|---------------------------------|------------|------------|----------|-----------|--------|
| 1    | ✓ Loose shock                   | \$0.00     | \$0.00     | \$0.00   |           |        |
|      | <b>Notes</b>                    |            |            |          |           |        |
|      | LR shock loose                  |            |            |          |           |        |
| 2    | ✓ Replace shock                 | \$0.00     | \$0.00     | \$0.00   |           |        |
|      | <b>Notes</b>                    |            |            |          |           |        |
|      | RR shock bushing NFG            |            |            |          |           |        |
|      | Part                            | Warehouse  | Vendor/Bin | Qty      | Unit Cost | Cost   |
|      | S-20126 - Trailer shock         | Kropp Shop |            | 1.0      | \$0.00    | \$0.00 |
| 3    | ✓ Adjust Brakes                 | \$0.00     | \$0.00     | \$0.00   |           |        |
| 4    | ✓ air bag                       | \$0.00     | \$0.00     | \$0.00   |           |        |
|      | <b>Notes</b>                    |            |            |          |           |        |
|      | Middle airbag lift axle down    |            |            |          |           |        |
| 5    | ✓ Preform Scheduled Maintenance | \$0.00     | \$0.00     | \$0.00   |           |        |
|      | Part Cost                       |            |            | \$0.00   |           |        |
|      | Labor                           |            |            | \$0.00   |           |        |
|      | Subtotal                        |            |            | \$0.00   |           |        |
|      | Tax 1 (0.0%)                    |            |            | \$0.00   |           |        |
|      | Tax 2 (0.0%)                    |            |            | \$0.00   |           |        |
|      | Credit                          |            |            | (\$0.00) |           |        |
|      | Total Cost                      |            |            | \$0.00   |           |        |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Dec 1, 2025 | Dec 1, 2025 |     | Dec 5, 2025 6:20 PM | Dec 5, 2025 6:20 PM |

| Line | Task         | Parts  | Labor  | Total  |
|------|--------------|--------|--------|--------|
| 1    | ✓ Suspension | \$0.00 | \$0.00 | \$0.00 |

**Notes**

lh lift shock bent

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Dec 8, 2025 | Dec 8, 2025 |     | Dec 9, 2025 9:58 PM | Dec 9, 2025 9:58 PM |

| Line | Task                  | Parts        | Labor  | Total    |
|------|-----------------------|--------------|--------|----------|
| 1    | ✓ Adjusted all brakes | \$0.00       | \$0.00 | \$0.00   |
|      |                       | Part Cost    |        | \$0.00   |
|      |                       | Labor        |        | \$0.00   |
|      |                       | Subtotal     |        | \$0.00   |
|      |                       | Tax 1 (0.0%) |        | \$0.00   |
|      |                       | Tax 2 (0.0%) |        | \$0.00   |
|      |                       | Credit       |        | (\$0.00) |
|      |                       | Total Cost   |        | \$0.00   |

T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Dec 8, 2025 | Dec 8, 2025 |     | Dec 9, 2025 9:58 PM | Dec 9, 2025 9:58 PM |

| Line | Task              | Parts        | Labor  | Total    |
|------|-------------------|--------------|--------|----------|
| 1    | ✓ Adjusted brakes | \$0.00       | \$0.00 | \$0.00   |
|      |                   | Part Cost    |        | \$0.00   |
|      |                   | Labor        |        | \$0.00   |
|      |                   | Subtotal     |        | \$0.00   |
|      |                   | Tax 1 (0.0%) |        | \$0.00   |
|      |                   | Tax 2 (0.0%) |        | \$0.00   |
|      |                   | Credit       |        | (\$0.00) |
|      |                   | Total Cost   |        | \$0.00   |

**T796 - 2017 Cross Country Cross Country Mfg.**

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Dec 14, 2025 | Dec 14, 2025 |     | Dec 14, 2025 5:57 PM | Dec 14, 2025 5:57 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Brakes                   | \$0.00       | \$0.00 | \$0.00   |
|      | <b><u>Notes</u></b>        |              |        |          |
|      | Front right hand brake pot |              |        |          |
| 2    | ✓ Hub Levels               | \$0.00       | \$0.00 | \$0.00   |
|      | <b><u>Notes</u></b>        |              |        |          |
|      | #5 left hand               |              |        |          |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

**T796 - 2017 Cross Country Cross Country Mfg.**

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jan 4, 2026 | Jan 4, 2026 |     | Jan 8, 2026 4:08 PM | Jan 8, 2026 4:08 PM |

| Line | Task                         | Parts      | Labor      | Total        |           |          |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ #6 drivers slack adjuster  | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | H801042N - 6" slack adjuster | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 28, 2026 | Jan 28, 2026 |     | Jan 30, 2026 2:25 PM | Jan 30, 2026 2:25 PM |

| Line | Task                                                | Parts        | Labor  | Total    |
|------|-----------------------------------------------------|--------------|--------|----------|
| 1    | ✓ Cut out corroded 7 wire and spliced back together | \$0.00       | \$0.00 | \$0.00   |
|      |                                                     | Part Cost    |        | \$0.00   |
|      |                                                     | Labor        |        | \$0.00   |
|      |                                                     | Subtotal     |        | \$0.00   |
|      |                                                     | Tax 1 (0.0%) |        | \$0.00   |
|      |                                                     | Tax 2 (0.0%) |        | \$0.00   |
|      |                                                     | Credit       |        | (\$0.00) |
|      |                                                     | Total Cost   |        | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Jan 30, 2026 |     | Jan 30, 2026 8:42 PM | Jan 30, 2026 8:42 PM |

| Line | Task    | Parts  | Labor  | Total  |
|------|---------|--------|--------|--------|
| 1    | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |

**Notes**

FRHO tire nfg

| Part                       | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|----------------------------|------------|------------|-----|-----------|----------|
| 245 Trailer - Trailer Tire | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost                  |            |            |     |           | \$0.00   |
| Labor                      |            |            |     |           | \$0.00   |
| Subtotal                   |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)               |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)               |            |            |     |           | \$0.00   |
| Credit                     |            |            |     |           | (\$0.00) |
| Total Cost                 |            |            |     |           | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 13, 2026 | Feb 13, 2026 |     | Feb 13, 2026 5:24 PM | Feb 13, 2026 5:24 PM |

| Line | Task                                   | Parts        | Labor  | Total    |
|------|----------------------------------------|--------------|--------|----------|
| 1    | ✓ Broken airbag bolt middle right axle | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Cracked saddle back left             | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Abs wire                             | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Back right out side tire             | \$0.00       | \$0.00 | \$0.00   |
|      |                                        | Part Cost    |        | \$0.00   |
|      |                                        | Labor        |        | \$0.00   |
|      |                                        | Subtotal     |        | \$0.00   |
|      |                                        | Tax 1 (0.0%) |        | \$0.00   |
|      |                                        | Tax 2 (0.0%) |        | \$0.00   |
|      |                                        | Credit       |        | (\$0.00) |
|      |                                        | Total Cost   |        | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 24, 2026 | Feb 24, 2026 |     | Feb 24, 2026 9:27 PM | Feb 24, 2026 9:27 PM |

| Line         | Task                       | Parts  | Labor  | Total    |
|--------------|----------------------------|--------|--------|----------|
| 1            | ✓ Brakes                   | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>               |        |        |          |
|              | check brake stroke         |        |        |          |
| 2            | ✓ other                    | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>               |        |        |          |
|              | #6 wrapper handle mia      |        |        |          |
| 3            | ✓ Tires                    | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>               |        |        |          |
|              | lh front tires skidded off |        |        |          |
| Part Cost    |                            |        |        | \$0.00   |
| Labor        |                            |        |        | \$0.00   |
| Subtotal     |                            |        |        | \$0.00   |
| Tax 1 (0.0%) |                            |        |        | \$0.00   |
| Tax 2 (0.0%) |                            |        |        | \$0.00   |
| Credit       |                            |        |        | (\$0.00) |
| Total Cost   |                            |        |        | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 17, 2026 | Mar 17, 2026 |     | Mar 19, 2026 4:28 PM | Mar 19, 2026 4:28 PM |

| Line | Task                                     | Parts        | Labor      | Total  |           |          |
|------|------------------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Brake Connections                      | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>                      |              |            |        |           |          |
|      | Back LH brake pot bracket broke off axle |              |            |        |           |          |
| 2    | ✓ Lights - All                           | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>                      |              |            |        |           |          |
|      | LH rear outside 2" marker out            |              |            |        |           |          |
|      | Part                                     | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | 3050 - 2" red marker light               | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 3    | ✓ Saddle cracks                          | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>                      |              |            |        |           |          |
|      | Front LH cracked                         |              |            |        |           |          |
| 4    | ✓ Suspension                             | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>                      |              |            |        |           |          |
|      | Front LH u bolt loose outside            |              |            |        |           |          |
|      | Part                                     | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | S-21140 - U bolt kit                     | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 5    | ✓ Front rh airbag leaking at fitting     | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                                          | Part Cost    |            |        |           | \$0.00   |
|      |                                          | Labor        |            |        |           | \$0.00   |
|      |                                          | Subtotal     |            |        |           | \$0.00   |
|      |                                          | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                                          | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                                          | Credit       |            |        |           | (\$0.00) |
|      |                                          | Total Cost   |            |        |           | \$0.00   |

## T796 - 2017 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Apr 15, 2026 | Apr 15, 2026 |     | Apr 16, 2026 5:45 AM | Apr 16, 2026 5:45 AM |

| Line | Task                                         | Parts        | Labor  | Total    |
|------|----------------------------------------------|--------------|--------|----------|
| 1    | ✓ Welded brake pot on middle axle right hand | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Changed inside middle axle right hand tire | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Changed lift axle shock on left sude       | \$0.00       | \$0.00 | \$0.00   |
|      |                                              | Part Cost    |        | \$0.00   |
|      |                                              | Labor        |        | \$0.00   |
|      |                                              | Subtotal     |        | \$0.00   |
|      |                                              | Tax 1 (0.0%) |        | \$0.00   |
|      |                                              | Tax 2 (0.0%) |        | \$0.00   |
|      |                                              | Credit       |        | (\$0.00) |
|      |                                              | Total Cost   |        | \$0.00   |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters |
|-------------------|--------|---------------|
| 2C9GSX3Z8HM183796 | 5DA830 |               |

| Type | Created      | Scheduled    | Due | Started              | Closed                |
|------|--------------|--------------|-----|----------------------|-----------------------|
|      | Apr 20, 2026 | Apr 20, 2026 |     | Apr 22, 2026 4:46 PM | Apr 30, 2026 10:22 AM |

| Line | Task                                                   | Parts      | Labor      | Total  |           |        |
|------|--------------------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Preform Scheduled Maintenance                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Broken brake pot bracket middle axle right hand side | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ Lift axle cracks                                     | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ Passenger side tie rod clamp loose                   | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ Loose u bolts on back left                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                                   | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | S-21140 - U bolt kit                                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 6    | ✓ Cracked saddle back left axle                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 7    | ✓ Cracked saddle back right axle                       | \$0.00     | \$0.00     | \$0.00 |           |        |
| 8    | ✓ Lift axle loose                                      | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                                    |            |            |        |           |        |
|      | Mounting bolts loose                                   |            |            |        |           |        |
| 9    | ✓ No left signal                                       | \$0.00     | \$0.00     | \$0.00 |           |        |
| 10   | ✓ No clearance lights                                  | \$0.00     | \$0.00     | \$0.00 |           |        |
| 11   | ✓ Bunk two right hand bunk handle                      | \$0.00     | \$0.00     | \$0.00 |           |        |
| 12   | ✓ Right hand signal no midway marker                   | \$0.00     | \$0.00     | \$0.00 |           |        |
| 13   | ✓ Back left air bag mount broke                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 14   | ✓ CVIP inspection (wheels off)                         | \$0.00     | \$0.00     | \$0.00 |           |        |

# T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

|    |                                       |        |        |        |
|----|---------------------------------------|--------|--------|--------|
| 15 | ✓ Broken shock mount middle left axle | \$0.00 | \$0.00 | \$0.00 |
| 16 | ✓ Broken stake back right bunk        | \$0.00 | \$0.00 | \$0.00 |
| 17 | ✓ Replace lift axle drum              | \$0.00 | \$0.00 | \$0.00 |

## Notes

Check shoes once apart

|    |                                            |            |            |        |           |        |
|----|--------------------------------------------|------------|------------|--------|-----------|--------|
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Brake Drum                                 | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 18 | ✓ Back 2 axle brake jobs both sides        |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Q plus shoe kit                            | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
| 19 | ✓ Dust cover Mia lift lh                   |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Dust cover bolt on                         | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 20 | ✓ Middle rh tri-functional bushing no good |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | S-24691 - TRI-FUNCTIONAL QUIK-ALIGN        | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 21 | ✓ Wire up lift axle switch                 |            |            | \$0.00 | \$0.00    | \$0.00 |
| 22 | ✓ Middle rh outside rim cracked            |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 24.5 rim                                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 23 | ✓ #6 wrapper handle                        |            |            | \$0.00 | \$0.00    | \$0.00 |
| 24 | ✓ ABS codes                                |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 400 850 600 0 - Abs ecu                    | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |