



CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act**

**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Kropp Contracting Ltd.		
Address:	Box 237		
City:	Slave Lake	Province:	AB
		Postal Code:	T0G2A0
Telephone Number:	(780) 849-6229		
Vehicle Identification Number:	2C9GSX3Z8HM183796		
Make:	Cross Country	Model:	Hayrack Logger
Year:	2017	Unit Number:	T796
Odometer:	KM	Licence Plate Number:	5DA830
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2025/05/01

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
										kg									
Vehicle Information																			
VIN		2	C	9	6	5	X	3	2	8	H	m	1	8	3	7	9	6	
Unit Number				Year				Make				Model				Odometer			
t-796				2016				Gerry's				Hayfork							
Registered Owner's Name																Plate Number			
Kropp Contracting Ltd.																5DA8-30			
Address												Postal Code				Phone Number			
Box 237 Slave Lake AB												T0G 2A0				780 847 6229			

		LEFT		FRONT		RIGHT			
100 psi 14 mm	100 psi 16 mm	16.576	mm	Drums/Rotors	16.512	mm	100 psi 5 mm	100 psi 6 mm	
		3/4	mm	Linings/Pads	3/4	mm			
		1.5	mm	Push Rod Travel	1.5	mm			
		65		Cam Rotation	45				
grabs									
100 psi 10 mm	100 psi 10 mm	16.537	mm	Drums/Rotors	16.538	mm	100 psi 8 mm	100 psi 7 mm	
		3/4	mm	Linings/Pads	3/8	mm			
		40 1/2	mm	Push Rod Travel	1 1/2	mm			
				Cam Rotation					
100 psi 12 mm	100 psi 16 mm	16.583	mm	Drums/Rotors	16.56	mm	100 psi 13 mm	100 psi 12 mm	
		1/2	mm	Linings/Pads	1/4 7/8	mm			
		1 1/2	mm	Push Rod Travel	1 1/2	mm			
		45		Cam Rotation	35				
needs new									
100 psi 12 mm	100 psi 11 mm	16.592	mm	Drums/Rotors	16.591	mm	100 psi 13 mm	100 psi 10 mm	
		3/8	mm	Linings/Pads	1/2	mm			
		1050 1/2	mm	Push Rod Travel	1010 1 1/2	mm			
				Cam Rotation					
psi	psi	mm	mm	Drums/Rotors	mm	mm	psi	psi	
		mm	mm	Linings/Pads	mm	mm			
		mm	mm	Push Rod Travel	mm	mm			
		mm	mm	Cam Rotation	mm	mm			

Park Brake Lining Left mm Right mm Trans mm

Wheel Torque Checked ☒ Inner ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			/	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			/

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			/	A.3. Liquefied Natural Gas (LNG) Fuel System			/
A.2. Compressed Natural Gas (CNG) Fuel System			/				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments		/		2.5. Air Suspension	/		
2.2. Axle Attaching & Tracking Components	/			2.6. Self-Steer & Controlled-Steer Axle	/		
2.3. Axle & Axle Assembly	/			2.7. Shock Absorber/Strut Assembly	/		
2.4. Spring & Spring Attachment	/						

NOTES: Cracked beam #6 LH

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components				3H.10. Electric Brake System			
3H.6. Air-Over-Hydraulic Brake System				3H.12. Drum Brake System Components			
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			
3H.8. Vacuum System				3H.19. Brake Performance			
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	/			3A.16. S-Cam Drum Brake System	/		
3A.4. Air Tank	/			3A.17. Brake Shoe Travel (Wedge Brakes)	/		
3A.8. Brake Valves & Controls	/			3A.18. Disc Brake System Components	/		
3A.12. Parking Brake & Emergency Application	/			3A.20. Anti-Lock Brake System (ABS)	/		
3A.13. Air System Components	/			3A.22. Stability Control System (ESC) or (RSS)	/		
3A.14. Brake Chamber	/			3A.23. Brake Performance	/		
3A.15. Drum Brake System Components	/						

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage	/			4.5. Self Steer & Controlled-Steer Axle	/		
4.4. Kingpin	/						

NOTES: LH Steer 5600K Gear+ cracks

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			/				

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	/	/		6.3. Retro-Reflective Marking			/
6.2. Reflex Reflector							

NOTES: needs new Rig marker tape

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	/			7.3. Trailer Cord (output to towed vehicle)	/		/
7.2. Battery			/				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	/		/	8.11. Refrigeration/Heater Unit Fuel System			/
8.6. Frame Rails & Mounts	/			8.21. Fender/Mud Flap	/		
8.7. Unitized Body Elements			/	8.22. Landing Gear on Trailer			/
8.8. Cab or Cargo Door			/	8.23. Sliding Axle Assembly (Sliding Bogie)			/
8.9. Cargo Tank or Vessel	/		/	8.24. Aerodynamic Device & Attachment			/
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	/			8.25. Rear Impact Guard (RIG)	/		

NOTES: Rig new Dot tape

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	/			9.7. Wheel/Rim	/		/
9.2. Tire Tread Condition	/			9.8. Multi-Piece Wheel/Rim	/		/
9.3. Tire Sidewall & Manufacturer Markings	/			9.9. Spoke Wheel/Demountable Rim System			/
9.4. Tire Inflation Pressure	/			9.10. Disc Wheel System	/		/
9.5. Wheel Hub	/			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)			
9.6. Wheel Bearing	/						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	/		/	10.6. Automated Coupling Device			/
10.2. Secondary Attachment (Safety Chain or Cable)	/		/	10.7. Fifth Wheel Coupler	/		/
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			/	10.8. Oscillating Fifth Wheel Coupler			/
10.4. Ball Type Hitch			/	10.9. Ball-Bearing Type Turntable on Trailer			/
10.5. Roll-Coupling Hitch							

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Certification			
The Vehicle for which this Record of Inspection is issued has _____ the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.			
Date of Inspection <i>May 1/25</i>	Technician Number <i>C1246</i>	Facility Number <i>18733</i>	Signature 
Customer Acknowledgment			Date (Year/Month/Day)
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.			<i>May 1/25</i>
			Customer Signature 

LH Steer Shock Bent /

bunk #4 cracked /

Rhmm cracked + LHmm /

#12 bunk wrapper hooker bent /

tape 7 wire and glad end hoses /

dif filters /

ass light joint light rp / green wire

Power Steering Low /

washer fluid low /

Lift axle cracks

RH tie rod loose in threads

#6 RH Pot cracked cracked /

#6 LH beam /

Chafing lines everywhere /

bunk #4 cracked /

#7 RH cracks /