

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER**

Certification

The Vehicle for which this Record of Inspection is issued has _____ the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
July 15/26	C1246	18733	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

June 15/26

Customer Signature



COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				✓

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery	✓		✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			
8.6. Frame Rails & Mounts				8.21. Fender/Mud Flap			
8.7. Unitized Body Elements				8.22. Landing Gear on Trailer			
8.8. Cab or Cargo Door				8.23. Sliding Axle Assembly (Sliding Bogie)			
8.9. Cargo Tank or Vessel				8.24. Aerodynamic Device & Attachment			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle				8.25. Rear Impact Guard (RIG)			

NOTES:

vin tag damaged broken bunk #5, #6

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components			✓	10.6. Automated Coupling Device	✓		✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler			
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle	✓		
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment	✓						

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			
3H.8. Vacuum System				3H.19. Brake Performance			
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System			
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			
3A.8. Brake Valves & Controls		✓		3A.18. Disc Brake System Components			
3A.12. Parking Brake & Emergency Application				3A.20. Anti-Lock Brake System (ABS)			
3A.13. Air System Components				3A.22. Stability Control System (ESC) or (RSS)			
3A.14. Brake Chamber				3A.23. Brake Performance			
3A.15. Drum Brake System Components							

NOTES:

exhaust sticking on emergency brake valve and service brake valve was by passing

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage	✓			4.5. Self Steer & Controlled-Steer Axle	✓		
4.4. Kingpin	✓						

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle <u>log trailer</u>										Gross Vehicle Weight registered <u>kg</u>									
Vehicle Information																			
VIN		<u>2 A 9 1 4 5 1 3 8 M A 0 0 3 2 3 9</u>																	
Unit Number <u>1239</u>				Year <u>2021</u>				Make <u>Peak</u>				Model <u>hayrack</u>				Odometer <u>—</u>			
Registered Owner's Name <u>Kropp Contracting</u>														Plate Number <u>6PB993</u>					
Address <u>Box 231 box 231</u>												Postal Code <u>T0G2A3</u>				Phone Number <u>780-844-6225</u>			

LEFT		FRONT		RIGHT	
<u>100</u> psi <u>14</u> mm	<u>100</u> psi <u>15</u> mm	<u>16.539</u> mm <u>3/4</u> mm <u>55°</u>	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u>6.545</u> mm <u>3/4</u> mm <u>58°</u>	<u>100</u> psi <u>17</u> mm
<u>100</u> psi <u>6</u> mm	<u>100</u> psi <u>6</u> mm	<u>16.570</u> mm <u>5/8</u> mm <u>93°</u>	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u>16.582</u> mm <u>11/16</u> mm <u>77°</u>	<u>100</u> psi <u>12</u> mm
<u>100</u> psi <u>11</u> mm	<u>100</u> psi <u>10</u> mm	<u>16.598</u> mm <u>11/2</u> mm <u>113°</u>	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u>16.579</u> mm <u>11/16</u> mm <u>68°</u>	<u>100</u> psi <u>10</u> mm
<u>100</u> psi <u>10</u> mm	<u>100</u> psi <u>8</u> mm	<u>16.574</u> mm <u>3/4</u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u>16.575</u> mm <u>3/4</u> mm <u>60°</u>	<u>100</u> psi <u>9</u> mm
<u>100</u> psi <u>10</u> mm	<u>100</u> psi <u>10</u> mm	mm mm mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	mm mm mm	<u>100</u> psi <u>7</u> mm
<u>100</u> psi <u>10</u> mm	<u>100</u> psi <u>10</u> mm	mm mm mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	mm mm mm	<u>100</u> psi <u>10</u> mm

Park Brake Lining Left — mm Right — mm Trans — mm

Wheel Torque Checked ☒ Inner — ft lbs Outer 500 ft lbs



CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

H01-180

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Kropp Contracting Ltd.		
Address:	Box 237		
City:	Slave Lake	Province:	AB
		Postal Code:	T0G2A0
Telephone Number:	(780) 849-6229		
Vehicle Identification Number:	2A9145138MA003239		
Make:	Peak	Model:	51LF3X3T HAY
Year:	2021	Unit Number:	T239
Odometer:	KM	Licence Plate Number:	6PB993
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2026/07/15