

BRITISH
COLUMBIACommercial Vehicle
Inspection ReportDecal Number: GH08224
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21237393Inspection Result:
PASS

FACILITY:	FIRST TRUCK CENTRE INC. / S20099	INSP. TYPE:	Re-inspection	INSP. START:	2025-Feb-13 02:11 PM PST
INSPECTOR:	HARPER, CURTIS DWAYNE / 203396	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Feb-13 03:11 PM PST
WORK ORDER #:	38527	INSP. REASON:	Annual		
ORIGINAL INSPI. #:	21223993				
VEHICLE JUR:	British Columbia	REGI:	13401271	VIN:	4UGFG3034LD035188
PLATE #:	38293K	UNIT/FLEET#:	167	OWNER/LESSEE NAME:	HYDRO INC., VOITH
LICENCED GW(kg):	0	BODY STYLE:	Flat Deck Trailer	ADDRESS:	160-9955 RUE, DE CHATEUNEUF BROSSARD, Quebec
VEHICLE YEAR:	2020	ODOMETER:			J4Z 3V5, Canada
MAKE:	ABU	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Electric		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	BRAKES NOT WORKING ON #1 AXLE RIGHT SIDE BRAKAWAY BRAKE SYSTEM NOT WORKING/REPLACED FAILED BRAKAWAY BRAKES ON #1 AXLE RIGHT SIDE REPAIRED
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Repaired (same day)	RIGHT REAR MARKER FAILED/REPLACED LEFT FRONT MARKER FAILED/REPLACED MISSING LICENCE PLATE LIGHT/REPAIRED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Repaired (same day)	#2 AXLE RIGHT INSIDE TIRE FLAT TIRE WAS REPLACED
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Failed	BRAKES NOT WORKING ON #1 AXLE RIGHT SIDE BRAKAWAY BRAKE SYSTEM NOT WORKING
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Failed	RIGHT REAR MARKER FAILED LEFT FRONT MARKER FAILED MISSING LICENCE PLATE LIGHT
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Failed	#2 AXLE RIGHT INSIDE TIRE FLAT
Section 9B - Wheels	Failed	WHEEL SEALS ON AXLE #1 AND RIGHT SIDE AXLE #2 LEAKING
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Axles	Tire Tread Depth (mm)				Brake Lining/Pad (mm)	Rotor Thickness or Drum Inside Diameter (mm)				
	Outer L	Inner L	Inner R	Outer R		Left	Right	Rotor/Drum	Left	Right
1	9	9	9	9	Lining (Shoe)	7.3	7.3	Drum	312.77	312.41
2	8	11	10	11	Lining (Shoe)	7.1	7.8	Drum	312.79	312.80
3	9	9	10	10	Lining (Shoe)	8.4	7.8	Drum	312.83	312.92

Comment:

Comment:

Comment:

Inspection Comments:

Has this Vehicle been road tested?

Yes

Road Test Date: Before Inspection

Inspector: HARPER, CURTIS DWAYNE

Signature: 

Road Tester: CURTIS HARPER

This Inspection Report was submitted to CVSE on 2025-Feb-13 03:13 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

2/13/2025 3:13:15 PM PST