

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1028

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,323 hr & 582,675 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2024	Mar 11, 2024		Mar 11, 2024 6:17 PM	Mar 11, 2024 6:17 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00

Notes

tighten airline

#2 service line loose at brake pot

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,436 hr & 587,188 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 28, 2024	Mar 28, 2024		Mar 28, 2024 7:10 AM	Mar 28, 2024 7:10 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

grease T465 and truck

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Oil change	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,436 hr & 587,188 km

Type	Created	Scheduled	Due	Started	Closed
	May 14, 2024	May 14, 2024		May 16, 2024 5:32 AM	May 21, 2024 9:39 PM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ Air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front 1/4 fender flaps MIA					
	Chain hanger mudflaps tore					
5	✓ u joint behind transmission NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ replace wishbone bushings	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	3rd drive axle bushings wore out					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	V rod bushings kit	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ LH west coast mirror NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

	T800 west coast mirror	Kropp Shop	1.0	\$0.00	\$0.00	
8	✓ Egr outlet pipe leaking coolant		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cummins egr cooler o-rings	Kropp Shop		2.0	\$0.00	\$0.00
9	✓ Egr valve exhaust leak		\$0.00	\$0.00	\$0.00	
10	✓ spring pins		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	spring pin bushings	Kropp Shop		4.0	\$0.00	\$0.00
11	✓ Free up clutch linkage sticking		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	CLUTCH ARM BEARING	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,436 hr & 587,188 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2024	Jul 10, 2024		Jul 10, 2024 4:38 AM	Jul 10, 2024 4:38 AM

Line	Task	Parts	Labor	Total
1	✓ Air Compressor	\$0.00	\$0.00	\$0.00

Notes

Purge valve leaking out air will not seat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K022105 - AD-IS purge valve	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1192

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,608 hr & 593,676 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 16, 2024	Jul 16, 2024		Jul 16, 2024 7:38 AM	Jul 16, 2024 7:38 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,608 hr & 593,676 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 16, 2024	Jul 16, 2024		Jul 16, 2024 7:55 AM	Jul 16, 2024 7:56 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Air Lines	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Red line of of range had hole

Air leak under cab ontop of transmission

2	✓ Service Brakes	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

LH slack adjustment backed off, adjust and will monitor if issue persists

Pulls to the right under brake application

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1209

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,666 hr & 596,588 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 23, 2024	Jul 23, 2024	Jul 23, 2024	Jul 25, 2024 1:32 PM	Jul 25, 2024 1:39 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Transmission making noise	\$0.00	\$0.00	\$0.00
---	-----------------------------	--------	--------	--------

Notes

Installed used transmission rebuilt by Trent, new clutch kit

2	✓ Replace tire	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

#8LHS outside, install used tire

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,857 hr & 596,588 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 16, 2024	Aug 16, 2024		Aug 16, 2024 3:48 AM	Aug 16, 2024 3:48 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,881 hr & 607,267 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 19, 2024	Aug 19, 2024		Aug 19, 2024 3:11 PM	Aug 19, 2024 3:11 PM

Line	Task	Parts	Labor	Total
1	✓ coolant leaks	\$0.00	\$0.00	\$0.00

Notes

Resivoir to water pump hose leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
1" heater hose	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1269

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,971 hr & 612,099 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 31, 2024	Aug 31, 2024		Sep 4, 2024 3:37 PM	Sep 4, 2024 3:37 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1280

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	12,974 hr & 612,108 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2024	Sep 16, 2024		Sep 16, 2024 10:43 AM	Sep 16, 2024 10:43 AM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00
	Notes			
	Coolant leaks on transmission cooler and lower rad hose			
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	Notes			
	Loose strap bolts on main shaft			
3	✓ Fluid Levels	\$0.00	\$0.00	\$0.00
	Notes			
	Coolant level low			
4	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	Rear light at loose			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1293

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,040 hr & 615,676 km

Type	Scheduled	Due	Started	Closed
	Sep 19, 2024		Sep 19, 2024 4:26 AM	Sep 19, 2024 4:26 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,097 hr & 618,651 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 5, 2024	Oct 5, 2024		Oct 8, 2024 6:57 AM	Oct 8, 2024 6:57 AM

Line	Task	Parts	Labor	Total		
1	✓ Inspect front axle tie rod bar	\$0.00	\$0.00	\$0.00		
2	✓ Exhaust leak possible	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00
	2880215 - DOC inlet gasket 5"	Kropp Shop		1.0	\$0.00	\$0.00
	2880213 - DOC inlet v clamp 5"	Kropp Shop		1.0	\$0.00	\$0.00
	90-0012 - 4" v clamp	Kropp Shop		1.0	\$0.00	\$0.00
	2866636 - 4" exhaust gasket	Kropp Shop		2.0	\$0.00	\$0.00
	M66-8483-001 - DOC inlet pipe t800	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Engine derate code	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,241 hr & 626,785 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 20, 2024 8:55 AM	Oct 20, 2024 8:57 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Exhaust	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

flex pipe missing

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5" flex pipe	Kropp Shop		1.0	\$0.00	\$0.00
5" step clamp	Kropp Shop		2.0	\$0.00	\$0.00

2	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Notes

replaced and tightened bolts

T rail bolts loose

3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

4	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

headache rack markers burned out, top RH work light out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3050 - 2" red marker light	Kropp Shop		3.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,263 hr & 627,950 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 23, 2024	Oct 23, 2024		Oct 23, 2024 3:57 PM	Oct 23, 2024 3:57 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,345 hr & 631,944 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 1, 2024	Nov 1, 2024		Nov 1, 2024 10:12 PM	Nov 1, 2024 10:12 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Air Lines	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

#4 rh supply line leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
---	--------------------------	--------	--------	--------

Notes

low coolant low power steering

3	✓ Exhaust	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

flex pipe clamp broke

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5" step clamp	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1415

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,345 hr & 631,944 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 4, 2024	Nov 4, 2024		Nov 4, 2024 6:33 PM	Nov 4, 2024 6:33 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,646.4 hr & 647,603 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 4, 2024	Dec 4, 2024		Dec 4, 2024 7:46 AM	Dec 4, 2024 7:49 AM

Line	Task	Parts	Labor	Total		
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	cracked belt					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Clutch	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	intermediate shift linkage					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	shift linkage	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Driveline	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front input leaky					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	R945007 - Input diff seal rockwell	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
5	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LH upper and RH upper inop					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

6 ✓ Radiator \$0.00 \$0.00 \$0.00

Notes

Rebuild rad in downtime

slow drip from rad

7 ✓ Suspension System \$0.00 \$0.00 \$0.00

Notes

middle drive wishbone NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00

8 ✓ Tires \$0.00 \$0.00 \$0.00

Notes

12 new drive tires

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00

9 ✓ Windows \$0.00 \$0.00 \$0.00

Notes

driver side windshield

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,798 hr & 654,655 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 15, 2024	Dec 15, 2024		Dec 15, 2024 8:32 PM	Dec 15, 2024 8:32 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> front diff lh rubbing	\$0.00	\$0.00	\$0.00
2	✓ Engine <u>Notes</u> coolant leaks off lower rad hose and tranny cooler loose clamps	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> RH lower work light out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1547

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	13,860 hr & 654,655 km

Type	Scheduled	Due	Started	Closed
	Dec 20, 2024		Dec 20, 2024 7:08 PM	Dec 20, 2024 7:08 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1567

Trent Court, Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,071 hr & 667,956 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 12, 2025	Jan 12, 2025		Jan 12, 2025 7:03 PM	Jan 12, 2025 7:03 PM

Line	Task	Parts	Labor	Total		
1	✓ RH scale pad NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8301900-10R - Scale pad 28"	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,147 hr & 671,465 km

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 7:08 AM	Jan 19, 2025 7:08 AM

Line	Task	Parts	Labor	Total
1	✓ Engine <u>Notes</u> y pipe cracked	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> bottom LH work light	\$0.00	\$0.00	\$0.00
3	✓ Windows <u>Notes</u> both windshields nfg	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1609

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,178 hr & 672,778 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 22, 2025	Jan 22, 2025		Jan 25, 2025 9:19 AM	Jan 25, 2025 9:19 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,253 hr & 675,948 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 2, 2025 6:50 PM	Feb 2, 2025 6:50 PM

Line	Task	Parts	Labor	Total
1	✓ Driveline <u>Notes</u> middle diff input yoke loose	\$0.00	\$0.00	\$0.00
2	✓ Fuel Tanks <u>Notes</u> fuel tank strap bolt loose	\$0.00	\$0.00	\$0.00
3	✓ Steering System <u>Notes</u> power steering cap loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,283 hr & 677,097 km

Type	Scheduled	Due	Started	Closed
	Feb 7, 2025		Feb 7, 2025 9:12 AM	Feb 7, 2025 9:12 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1659

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,283 hr & 677,097 km

Type	Scheduled	Due	Started	Closed
	Feb 7, 2025		Feb 7, 2025 9:13 AM	Feb 7, 2025 9:13 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,488 hr & 686,165 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:31 AM	Mar 3, 2025 11:31 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

middle LH brake pot no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

top rh work light out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Work light	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Radiator	\$0.00	\$0.00	\$0.00
---	------------	--------	--------	--------

Notes

rad core leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
t800 radiator	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 1744

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,540 hr & 688,467 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 4:24 PM	Mar 6, 2025 4:24 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,552 hr & 688,956 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 7, 2025	Mar 7, 2025		Mar 7, 2025 2:25 PM	Mar 7, 2025 2:25 PM

Line	Task			Parts	Labor	Total
1	✓ steer shocks no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	85070 - Steer shock T800	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ replace wishbone bushings			\$0.00	\$0.00	\$0.00

Notes

1st diff wishbone

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,638 hr & 692,667 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2025	Mar 11, 2025		Mar 13, 2025 3:33 PM	Mar 13, 2025 3:33 PM

Line	Task	Parts	Labor	Total		
1	✓ Doser quantity code 6486	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5578983RX - Doser	Kropp Shop	EKW	1.0	\$0.00	\$0.00
2	✓ aux splitter line fitting broke off	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,735 hr & 696,694 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 21, 2025	Mar 21, 2025		Mar 21, 2025 2:10 PM	Mar 21, 2025 2:10 PM

Line	Task	Parts	Labor	Total		
1	✓ rh middle axle brake pot NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	14,791 hr & 699,124 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 24, 2025	Mar 24, 2025		Apr 7, 2025 7:33 AM	Apr 10, 2025 1:03 PM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	14794 hrs					
	699125 km					
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ LH drag link	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	346-572 - LH drag link T800	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Window rubber not lined up with windshields	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 window rubber	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
7	✓ replace air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
8	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

9	✓ replace fan belt			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ replace air dryer filter			\$0.00	\$0.00	\$0.00
11	✓ replace purge valve			\$0.00	\$0.00	\$0.00
12	✓ RH front drive supply line chafed			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ Front drive axle mudflaps/anti sails			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	24" plastic mudflap	Kropp Shop		1.0	\$0.00	\$0.00
	anti sail bracket	Kropp Shop		1.0	\$0.00	\$0.00
14	✓ LH mirror loose and glass no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost						\$0.00
Labor						\$0.00
Subtotal						\$0.00
Tax 1 (0.0%)						\$0.00
Tax 2 (0.0%)						\$0.00
Credit						(\$0.00)
Total Cost						\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,123 hr & 717,886 km

Type	Scheduled	Due	Started	Closed
Service	May 8, 2025		May 8, 2025 4:51 AM	May 8, 2025 4:51 AM

Line	Task	Parts	Labor	Total		
1	✓ Overheating	\$0.00	\$0.00	\$0.00		
2	✓ Fan hub	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,123 hr & 717,886 km

Type	Scheduled	Due	Started	Closed
engine	May 23, 2025		May 23, 2025 6:02 AM	May 23, 2025 6:02 AM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00
2	✓ Replace Def injector	\$0.00	\$0.00	\$0.00

Notes

Install used injector

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,123 hr & 717,886 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 11, 2025	Jun 11, 2025		Jun 11, 2025 4:01 PM	Jun 11, 2025 4:01 PM

Line	Task	Parts	Labor	Total
1	✓ Lights INOP	\$0.00	\$0.00	\$0.00

Notes

Broken wire, install new weather pack female pin in ground wire for hood light

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,215 hr & 722,749 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 25, 2025	Jun 25, 2025		Jun 25, 2025 6:18 AM	Jun 25, 2025 6:18 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	Bh216 - Water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,276 hr & 726,073 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 6, 2025	Jul 6, 2025		Jul 6, 2025 7:51 AM	Jul 6, 2025 7:51 AM

Line	Task	Parts	Labor	Total
1	✓ Def pressure code	\$0.00	\$0.00	\$0.00

Notes

Ran pressure test topped out at 80 psi...

Disconnected pressure line and hooked up gauge pump puts out 196psi

Cleaned out injector check valve and leak test now passes

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,336 hr & 729,896 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 14, 2025	Jul 14, 2025		Jul 16, 2025 8:08 AM	Jul 16, 2025 8:08 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Rear drive RH brake pot NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Steering column shaft loose excissive movement	\$0.00	\$0.00	\$0.00		
4	✓ DEF prime code	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,494 hr & 739,574 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 1, 2025	Aug 1, 2025		Aug 5, 2025 5:02 PM	Aug 5, 2025 5:27 PM

Line	Task	Parts	Labor	Total
1	✓ diagnose Check engine light	\$0.00	\$0.00	\$0.00

Notes

Code 1682. Found 80PSI from pump to doser, unable to prime doser.
Replace DEF pump, found 120PSI, able to prime doser module.
Perform doser override test, found doser to work. Found code 1682
no longer present, reinstall removed components and tie up wiring.

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5509448RX - DEF pump t880	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Steer Tires	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
steer tires	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Exhaust leak	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2866636 - 4" exhaust gasket	Kropp Shop		1.0	\$0.00	\$0.00
4" exhaust hanger clamp	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2040

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,494 hr & 739,574 km

Type	Scheduled	Due	Started	Closed
	Aug 5, 2025		Aug 5, 2025 5:35 PM	Aug 5, 2025 5:35 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2062

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,566 hr & 744,303 km

Type	Scheduled	Due	Started	Closed
	Aug 18, 2025		Aug 18, 2025 3:45 AM	Aug 18, 2025 3:45 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,596 hr & 746,115 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 20, 2025	Aug 20, 2025		Aug 20, 2025 5:05 PM	Aug 20, 2025 5:05 PM

Line	Task	Parts	Labor	Total		
1	✓ Oil change	\$0.00	\$0.00	\$0.00		
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
3	✓ Exhaust leak	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5" flex pipe	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Lights INOP	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Mickey Mouse light harness	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,725 hr & 754,002 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 9, 2025	Sep 9, 2025		Sep 9, 2025 4:37 AM	Sep 9, 2025 4:37 AM

Line	Task	Parts	Labor	Total		
1	✓ Fan belt tensioner not tracking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Fan belt tensioner	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Clean out dirty rad	\$0.00	\$0.00	\$0.00		
3	✓ Change thermostat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4318947 - Thermostat Cummins 15L	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Replace water valve	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Water valve	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2140

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,812 hr & 759,486 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 1:09 PM	Sep 22, 2025 1:09 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,850 hr & 761,705 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 1, 2025	Oct 1, 2025		Oct 1, 2025 8:12 AM	Oct 1, 2025 8:12 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,935 hr & 766,287 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 16, 2025	Oct 16, 2025		Oct 16, 2025 4:18 AM	Oct 16, 2025 4:18 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ Blower motor now blowing	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	1001401792BSM - linear power module	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Top rh MM work light out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Front LH air tank has hole in it	\$0.00	\$0.00	\$0.00		

Notes

Used spare tank off of wrecked truck

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2197

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,960 hr & 767,619 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2025	Oct 20, 2025		Oct 20, 2025 1:25 PM	Oct 20, 2025 1:25 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	15,960 hr & 767,619 km

Type	Scheduled	Due	Started	Closed
	Nov 14, 2025		Nov 14, 2025 2:06 PM	Nov 14, 2025 2:06 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

top lh mm light broke

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,119 hr & 775,861 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 17, 2025	Nov 17, 2025		Nov 17, 2025 4:05 PM	Nov 17, 2025 4:05 PM

Line	Task	Parts	Labor	Total		
1	✓ Power steering pump locked up	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Sp33126 - TRP power steering pump Cummins	Kropp Shop		1.0	\$0.00	\$0.00
	87904M - T800 power steering filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Rh stack bushing broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Fan hub not working	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2287

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,153 hr & 777,452 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 21, 2025	Nov 21, 2025		Nov 24, 2025 2:54 PM	Nov 24, 2025 2:54 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2298

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,201 hr & 780,163 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 24, 2025	Nov 24, 2025		Nov 24, 2025 5:22 PM	Nov 24, 2025 5:22 PM

Line	Task	Parts	Labor	Total
1	✓ Coolant hose on heater core	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,256 hr & 782,664 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2025	Nov 30, 2025		Nov 30, 2025 5:45 AM	Nov 30, 2025 5:45 AM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses <u>Notes</u> lower rad hose clamp loose	\$0.00	\$0.00	\$0.00
2	✓ Check all fluid levels <u>Notes</u> power steering level low	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> top lh marker lights unplugged	\$0.00	\$0.00	\$0.00
5	✓ Suspension System <u>Notes</u> middle lh shock nfg	\$0.00	\$0.00	\$0.00
6	✓ Tire Chains <u>Notes</u> chains wore out- replace	\$0.00	\$0.00	\$0.00
7	✓ Tires <u>Notes</u> front drive inside flat both sides	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2319

Trent Court

CLOSED

8	✓ Windows	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

both windshields nfg

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,271 hr & 783,396 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 3, 2025	Dec 3, 2025		Dec 3, 2025 7:43 PM	Dec 3, 2025 7:43 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2353

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,367 hr & 787,654 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 11, 2025	Dec 11, 2025		Dec 13, 2025 8:22 AM	Dec 13, 2025 8:22 AM

Line	Task	Parts	Labor	Total
1	✓ Coolant leak	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,411 hr & 789,037 km

Type	Scheduled	Due	Started	Closed
	Dec 16, 2025		Dec 16, 2025 5:08 PM	Dec 16, 2025 5:08 PM

Line	Task	Parts	Labor	Total		
1	✓ Def filter leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5579176 - DEF filter kit	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2402

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,469 hr & 791,862 km

Type	Scheduled	Due	Started	Closed
	Dec 26, 2025		Dec 26, 2025 8:20 AM	Dec 26, 2025 8:20 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,504 hr & 793,263 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 8, 2026	Jan 8, 2026		Jan 8, 2026 5:55 AM	Jan 8, 2026 5:55 AM

Line	Task	Parts	Labor	Total		
1	✓ EGR silicone hose tore open	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3687223 - EGR silicone hose Cummins	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Air to air intercooler split open	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Charge air cooler	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,602 hr & 797,944 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 9, 2026	Jan 9, 2026		Jan 12, 2026 5:07 PM	Jan 12, 2026 5:07 PM

Line	Task	Parts	Labor	Total		
1	✓ Codes	\$0.00	\$0.00	\$0.00		
2	✓ Changed air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ Changed outlet nox sensor	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4326874RX - Outlet NOX sensor	Kropp Shop	EKW	1.0	\$0.00	\$0.00
4	✓ Particulate matter sensor	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5461553RX - Particulate matter sensor	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Exhaust gas pressure sensor code	\$0.00	\$0.00	\$0.00		
6	✓ RH scale pad nfg	\$1,300.00	\$0.00	\$1,300.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8301900-10R - Scale pad 28"	Kropp Shop		1.0	\$1,300.00	\$1,300.00
				Part Cost		\$1,300.00
				Labor		\$0.00
				Subtotal		\$1,300.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,300.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,690 hr & 801,831 km

Type	Scheduled	Due	Started	Closed
	Jan 23, 2026		Jan 23, 2026 5:37 PM	Jan 23, 2026 5:37 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,794 hr & 808,090 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 26, 2026	Jan 26, 2026		Jan 26, 2026 2:11 PM	Jan 26, 2026 2:11 PM

Line	Task			Parts	Labor	Total
1	✓ Replace radiator			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	t800 radiator	Kropp Shop		1.0	\$0.00	\$0.00
	Coolant	Kropp Shop		12.0	\$0.00	\$0.00
2	✓ Front engine mounts nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K066-423 - Front engine mount rubber washer cummins	Kropp Shop		2.0	\$0.00	\$0.00
	K066-404 - Front engine mount cummins	Kropp Shop		2.0	\$0.00	\$0.00
	HWC01079 - Engine mount bolt kit cummins	Kropp Shop		1.0	\$0.00	\$0.00
	HWC04916 - Engine mount nut cummins	Kropp Shop		2.0	\$0.00	\$0.00
	Hwc05722 - Front engine mount washer Cummins	Kropp Shop		4.0	\$0.00	\$0.00
3	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,782 hr & 806,137 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2026	Jan 31, 2026		Jan 31, 2026 7:33 PM	Jan 31, 2026 7:33 PM

Line	Task	Parts	Labor	Total												
1	✓ Air Compressor	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	air dryer heater															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>109495 - Bendix air dryer heater</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	109495 - Bendix air dryer heater	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
109495 - Bendix air dryer heater	Kropp Shop		1.0	\$0.00	\$0.00											
2	✓ Brake Accessories	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	LH rear drive dust cover mia															
3	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	tranny level															
4	✓ Clutch	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	adjust clutch															
5	✓ Driveline	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	middle carrier u joint cap spinning															
6	✓ Transmission	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2499
Sam Hawksley, Trent Court
CLOSED

leak

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2538

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,897 hr & 811,761 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 12, 2026	Feb 12, 2026		Feb 12, 2026 8:03 PM	Feb 12, 2026 8:03 PM

Line	Task	Parts	Labor	Total
1	✓ Loose yoke of transmission	\$0.00	\$0.00	\$0.00
2	✓ Spinning cap on #1 ujoint	\$0.00	\$0.00	\$0.00
3	✓ Hood light out	\$0.00	\$0.00	\$0.00
4	✓ Check tranny fluid	\$0.00	\$0.00	\$0.00
5	✓ Loose clevis nut on middle right axle	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2566

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	16,969 hr & 814,965 km

Type	Scheduled	Due	Started	Closed
	Feb 23, 2026		Feb 23, 2026 3:50 PM	Feb 23, 2026 3:50 PM

Line	Task	Parts	Labor	Total
1	✓ Heater blower motor not working	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,027 hr & 817,595 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 2, 2026	Mar 2, 2026		Mar 2, 2026 7:03 PM	Mar 2, 2026 7:03 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Truck			
2	✓ Air Lines	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Blue glad hand broke			
3	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Back left scam ubolt			
4	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Check tranny fluid, leaking			
5	✓ Engine	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Coolant leaks			
6	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
7	✓ Transmission	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Leaking			

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2609

Sam Hawksley

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,121 hr & 821,850 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 8, 2026	Mar 8, 2026		Mar 8, 2026 7:45 PM	Mar 8, 2026 7:45 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,363 hr & 833,794 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 9, 2026	Apr 9, 2026		Apr 9, 2026 5:19 PM	Apr 9, 2026 5:24 PM

Line	Task			Parts	Labor	Total
1	✓ Lh mirror nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Egr coolant leaking internally			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5693915 - EGR cooler kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Exhaust manifold bolt broken			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5486657 - Cummins exhaust manifold gasket	Kropp Shop		4.0	\$0.00	\$0.00
	4965698 - Cummins manifold bolt	Kropp Shop		12.0	\$0.00	\$0.00
	4965512 - Cummins manifold spacer	Kropp Shop		12.0	\$0.00	\$0.00
4	✓ Lh hood light out			\$0.00	\$0.00	\$0.00
5	✓ AC compressor failed			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	F50-1798-1275 - T800 discharge ac line	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Upper ac discharge line has hole in it			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Ac compressor	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2670

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2677

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,363 hr & 833,794 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 13, 2026	Apr 13, 2026		Apr 13, 2026 6:56 AM	Apr 13, 2026 6:56 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,481 hr & 837,956 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 29, 2026	Apr 29, 2026		Apr 30, 2026 8:18 AM	Apr 30, 2026 8:18 AM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
4	✓ Rh hood light broke	\$0.00	\$0.00	\$0.00		
5	✓ both windshields cracked	\$0.00	\$0.00	\$0.00		
6	✓ Air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
7	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
8	✓ Replace Belt	\$0.00	\$0.00	\$0.00		
9	✓ Lh headlight wiring tore apart	\$0.00	\$0.00	\$0.00		
10	✓ rear rh drive brake pot loose	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Tightened with wrench, bottom nut moved half a quarter turn and top nut slightly budged					
11	✓ real Lh scam u bolt	\$0.00	\$0.00	\$0.00		
12	✓ Diagnostic wheel in cab pushes into dash	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2698

Trent Court

CLOSED

13	✓ ABS codes	\$0.00	\$0.00	\$0.00
14	✓ Top Lh Mickey Mouse light out	\$0.00	\$0.00	\$0.00
15	✓ Exhaust leak at decomp tube v clamp	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,508 hr & 838,595 km

Type	Created	Scheduled	Due	Started	Closed
	May 14, 2026	May 14, 2026		May 14, 2026 3:52 PM	May 14, 2026 3:52 PM

Line	Task	Parts	Labor	Total
1	✓ Ac not working	\$0.00	\$0.00	\$0.00
Notes				
Leak test with nitrogen, fount leak at condenser to ac line connection at 200 psi... removed line and inspected found o ring Mia, recharged and tested				
2	✓ Bottom side step falling off	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,546 hr & 840,149 km

Type	Created	Scheduled	Due	Started	Closed
	May 23, 2026	May 23, 2026		May 27, 2026 10:47 AM	May 27, 2026 10:47 AM

Line	Task	Parts	Labor	Total
1	✓ Def fail to prime	\$0.00	\$0.00	\$0.00

Notes

In tank filter fell off, changed,

Harness no good def pump no pressure

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5509448RX - DEF pump t880	Kropp Shop		1.0	\$0.00	\$0.00
M92-1037 - Def tank harness	Kropp Shop		1.0	\$0.00	\$0.00
M37-6267 - Def in tank filter	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Oil change	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2778

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,933 hr & 857,262 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 29, 2026	Jul 29, 2026		Jul 29, 2026 10:06 AM	Jul 29, 2026 10:07 AM

Line	Task	Parts	Labor	Total
1	✓ Replace Grille	\$0.00	\$0.00	\$0.00
	Notes			
	1 used grille			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Change grease fittings	\$0.00	\$0.00	\$0.00

Notes

Replace all defective grease fittings

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	17,973 hr & 858,818 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 4, 2026	Aug 4, 2026		Aug 4, 2026 5:52 AM	Aug 5, 2026 12:00 PM

Line	Task	Parts	Labor	Total
1	✓ Tested battires and changed the first one on the left hand side	\$0.00	\$0.00	\$0.00
2	✓ Changed left hand steer tire	\$0.00	\$0.00	\$0.00
3	✓ Fixed broken brake pot fitting middle drive axle left hand side	\$0.00	\$0.00	\$0.00
4	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

281 - 2020 Kenworth t800

Parent: T465 - 2018 Cross Country Cross Country Mfg.

Work Order 2791

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX7LR963955	E91005	18,022 hr & 860,968 km

Type	Scheduled	Due	Started	Closed
	Aug 10, 2026		Aug 10, 2026 5:10 AM	Aug 10, 2026 5:10 AM

Line	Task	Parts	Labor	Total
1	✓ Steady bearing	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00