

## 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 7,750 hr & 734,939 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 10, 2024 | Mar 10, 2024 |     | Mar 10, 2024 3:48 PM | Mar 10, 2024 3:48 PM |

| Line | Task     | Parts  | Labor  | Total  |
|------|----------|--------|--------|--------|
| 1    | ✓ Engine | \$0.00 | \$0.00 | \$0.00 |

**Notes**

lost prime, def leak test passed

Engine derate

|   |                |        |        |        |
|---|----------------|--------|--------|--------|
| 2 | ✓ Lights - All | \$0.00 | \$0.00 | \$0.00 |
|---|----------------|--------|--------|--------|

**Notes**

Right hand Mickey Mouse marker out

| Part             | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|------------------|------------|------------|-----|-----------|--------|
| 6050A oval light | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| 3 wire pigtail   | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 7,791 hr & 736,385 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Mar 14, 2024 | Mar 14, 2024 |     | Mar 14, 2024 11:03 AM | Mar 14, 2024 11:03 AM |

| Line | Task         | Parts  | Labor  | Total  |
|------|--------------|--------|--------|--------|
| 1    | ✓ Def derate | \$0.00 | \$0.00 | \$0.00 |

**Notes**

def pressure below normal

def dosing erratic

| Part              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|-------------------|------------|------------|-----|-----------|----------|
| 5578983RX - Doser | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost         |            |            |     |           | \$0.00   |
| Labor             |            |            |     |           | \$0.00   |
| Subtotal          |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)      |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)      |            |            |     |           | \$0.00   |
| Credit            |            |            |     |           | (\$0.00) |
| Total Cost        |            |            |     |           | \$0.00   |

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 7,900 hr & 741,400 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 26, 2024 | Mar 26, 2024 |     | Mar 26, 2024 2:30 PM | Mar 26, 2024 2:30 PM |

| Line | Task                  | Parts  | Labor  | Total  |
|------|-----------------------|--------|--------|--------|
| 1    | ✓ Lights shorting out | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Top RH Mickey Mouse light shorting out and blowing breaker,  
harness wore thru, Remove and replace

| Part                       | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|----------------------------|------------|------------|-----|-----------|----------|
| Mickey Mouse light harness | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost                  |            |            |     |           | \$0.00   |
| Labor                      |            |            |     |           | \$0.00   |
| Subtotal                   |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)               |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)               |            |            |     |           | \$0.00   |
| Credit                     |            |            |     |           | (\$0.00) |
| Total Cost                 |            |            |     |           | \$0.00   |

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 7,954 hr & 744,010 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | May 1, 2024 | May 1, 2024 |     | May 2, 2024 1:50 PM | May 2, 2024 4:13 PM |

| Line | Task                           | Parts  | Labor  | Total  |
|------|--------------------------------|--------|--------|--------|
| 1    | ✓ Wheels off CVIP inspection   | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Clutch linkage needs rebuilt | \$0.00 | \$0.00 | \$0.00 |

**Notes**

clutch rod end on transmission bushing pounded out

| Part                | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------------|------------|------------|-----|-----------|--------|
| Clutch linkage ends | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

|   |                   |        |        |        |
|---|-------------------|--------|--------|--------|
| 3 | ✓ Replace starter | \$0.00 | \$0.00 | \$0.00 |
|---|-------------------|--------|--------|--------|

| Part                               | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|------------------------------------|------------|------------|-----|-----------|--------|
| D61-6005-003 - Starter x15 cummins | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                     |        |        |        |
|---|---------------------|--------|--------|--------|
| 4 | ✓ change windshield | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------|--------|--------|--------|

**Notes**

Right hand windshield cracked

|   |               |        |        |        |
|---|---------------|--------|--------|--------|
| 5 | ✓ Air filters | \$0.00 | \$0.00 | \$0.00 |
|---|---------------|--------|--------|--------|

| Part        | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------|------------|------------|-----|-----------|--------|
| air filters | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

|   |                            |        |        |        |
|---|----------------------------|--------|--------|--------|
| 6 | ✓ Battery box cover broken | \$0.00 | \$0.00 | \$0.00 |
|---|----------------------------|--------|--------|--------|

**Notes**

top lefthand corner needs welded

|   |                                      |        |        |        |
|---|--------------------------------------|--------|--------|--------|
| 7 | ✓ Replace Stack bushings and bearing | \$0.00 | \$0.00 | \$0.00 |
|---|--------------------------------------|--------|--------|--------|

**Notes**

# 801 - 2019 Kenworth t800

CLOSED

Right hand side

| Part                              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------------------------|------------|------------|-----|-----------|--------|
| EM75-69000-HT - Stack bushing kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| muffler bearing                   | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| 8 ✓ Replace missing/tore mudflaps |            |            |     | \$0.00    | \$0.00 |

## Notes

Chain hanger mudflaps tore

Anti sails broke

| Part                    | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------------|------------|------------|-----|-----------|--------|
| 24" mudflap             | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |
| anti sail bracket       | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |
| 9 ✓ change diff filters |            |            |     | \$0.00    | \$0.00 |

| Part                          | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------------------|------------|------------|-----|-----------|--------|
| LF3311 - Rockwell diff filter | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

|                         |  |  |  |        |        |
|-------------------------|--|--|--|--------|--------|
| 10 ✓ loose yoke on diff |  |  |  | \$0.00 | \$0.00 |
|-------------------------|--|--|--|--------|--------|

## Notes

Front diff output yoke loose

|                             |  |  |  |        |        |
|-----------------------------|--|--|--|--------|--------|
| 11 ✓ Diff breather tore off |  |  |  | \$0.00 | \$0.00 |
|-----------------------------|--|--|--|--------|--------|

## Notes

middle drive axle LH side

|                                |  |  |  |        |        |
|--------------------------------|--|--|--|--------|--------|
| 12 ✓ Re seal splitter cylinder |  |  |  | \$0.00 | \$0.00 |
|--------------------------------|--|--|--|--------|--------|

| Part             | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|------------------|------------|------------|-----|-----------|--------|
| eaton o-ring kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|                       |  |  |  |        |        |
|-----------------------|--|--|--|--------|--------|
| 13 ✓ replace fan belt |  |  |  | \$0.00 | \$0.00 |
|-----------------------|--|--|--|--------|--------|

| Part     | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------|------------|------------|-----|-----------|--------|
| fan belt | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|                    |  |  |  |        |        |
|--------------------|--|--|--|--------|--------|
| 14 ✓ adjust clutch |  |  |  | \$0.00 | \$0.00 |
|--------------------|--|--|--|--------|--------|

## 801 - 2019 Kenworth t800

CLOSED

| 15                     | ✓ LH mirror cracked |            |     | \$0.00       | \$0.00   | \$0.00 |
|------------------------|---------------------|------------|-----|--------------|----------|--------|
| Part                   | Warehouse           | Vendor/Bin | Qty | Unit Cost    | Cost     |        |
| T800 west coast mirror | Kropp Shop          |            | 1.0 | \$0.00       | \$0.00   |        |
|                        |                     |            |     | Part Cost    | \$0.00   |        |
|                        |                     |            |     | Labor        | \$0.00   |        |
|                        |                     |            |     | Subtotal     | \$0.00   |        |
|                        |                     |            |     | Tax 1 (0.0%) | \$0.00   |        |
|                        |                     |            |     | Tax 2 (0.0%) | \$0.00   |        |
|                        |                     |            |     | Credit       | (\$0.00) |        |
|                        |                     |            |     | Total Cost   | \$0.00   |        |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 7,954 hr & 744,010 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | May 3, 2024 |     | May 3, 2024 5:33 PM | May 3, 2024 5:33 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters           |
|-------------------|--------|-------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,013.5 hr & 747,410 km |

| Type       | Created      | Scheduled    | Due | Started              | Closed               |
|------------|--------------|--------------|-----|----------------------|----------------------|
| electrical | May 13, 2024 | May 13, 2024 |     | May 13, 2024 6:22 AM | May 13, 2024 6:22 AM |

| Line | Task        | Parts  | Labor  | Total  |
|------|-------------|--------|--------|--------|
| 1    | ✓ Repai a/c | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Top off refrigerant, change zone actuator

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,260 hr & 759,584 km |

| Type | Created      | Scheduled    | Due | Started             | Closed              |
|------|--------------|--------------|-----|---------------------|---------------------|
|      | Jun 29, 2024 | Jun 29, 2024 |     | Jul 9, 2024 6:54 AM | Jul 9, 2024 6:54 AM |

| Line | Task                         | Parts  | Labor  | Total  |
|------|------------------------------|--------|--------|--------|
| 1    | ✓ Power steering pump failed | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Change pump, shaft broke off, breakdown in red earth

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,260 hr & 759,584 km |

| Type | Created     | Scheduled   | Due         | Started             | Closed              |
|------|-------------|-------------|-------------|---------------------|---------------------|
|      | Jul 4, 2024 | Jul 4, 2024 | Jul 4, 2024 | Jul 4, 2024 4:28 AM | Jul 8, 2024 2:26 PM |

| Line | Task                                                                                                             | Parts        | Labor    | Total  |
|------|------------------------------------------------------------------------------------------------------------------|--------------|----------|--------|
| 1    | ✓ Clutch linkage<br><br><u>Notes</u><br>Change clutch arm bearing                                                | \$0.00       | \$0.00   | \$0.00 |
| 2    | ✓ Air conditioning not working<br><br><u>Notes</u><br>Repair broken wire on top of engine, clean out heater core | \$0.00       | \$0.00   | \$0.00 |
| 3    | ✓ Weld broken mudflap angle iron<br><br><u>Notes</u><br>Bar in front of lift axle was broken                     | \$0.00       | \$0.00   | \$0.00 |
|      |                                                                                                                  | Part Cost    | \$0.00   |        |
|      |                                                                                                                  | Labor        | \$0.00   |        |
|      |                                                                                                                  | Subtotal     | \$0.00   |        |
|      |                                                                                                                  | Tax 1 (0.0%) | \$0.00   |        |
|      |                                                                                                                  | Tax 2 (0.0%) | \$0.00   |        |
|      |                                                                                                                  | Credit       | (\$0.00) |        |
|      |                                                                                                                  | Total Cost   | \$0.00   |        |

# 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,260 hr & 759,584 km |

| Type | Created     | Scheduled   | Due         | Started             | Closed               |
|------|-------------|-------------|-------------|---------------------|----------------------|
|      | Jul 8, 2024 | Jul 8, 2024 | Jul 6, 2024 | Jul 8, 2024 2:41 PM | Jul 17, 2024 5:51 AM |

| Line | Task                                  | Parts      | Labor      | Total  |           |        |
|------|---------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Replace tire                        | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                   |            |            |        |           |        |
|      | #1 LH steer                           |            |            |        |           |        |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | steer tires                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 2    | ✓ Replace drag link                   | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 346-574 - RH drag link T800           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 3    | ✓ front diff airlines rubbing on diff | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ middle diff brake pot line leaking  | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                   |            |            |        |           |        |
|      | loose fitting                         |            |            |        |           |        |
| 5    | ✓ rear diff air lines rubbing         | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ LH leaf shackle loose               | \$0.00     | \$0.00     | \$0.00 |           |        |
| 7    | ✓ DOC inlet gasket leaking            | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 2880215 - DOC inlet gasket 5"         | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | 90-0013 - 5" v clamp                  | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 801 - 2019 Kenworth t800

**Work Order 1164**  
Cam Nadeau, Nate Vandenberghe

**CLOSED**

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,260 hr & 759,584 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jul 9, 2024 | Jul 9, 2024 |     | Jul 9, 2024 6:52 AM | Jul 9, 2024 6:52 AM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer               |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | grease tubes                             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,587 hr & 774,648 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 19, 2024 | Aug 19, 2024 |     | Aug 19, 2024 1:36 PM | Aug 19, 2024 1:36 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,619 hr & 776,481 km |

| Type    | Created      | Scheduled    | Due          | Started              | Closed               |
|---------|--------------|--------------|--------------|----------------------|----------------------|
| Service | Aug 22, 2024 | Aug 22, 2024 | Aug 22, 2024 | Aug 22, 2024 2:55 AM | Aug 22, 2024 2:55 AM |

| Line | Task                    | Parts  | Labor  | Total  |
|------|-------------------------|--------|--------|--------|
| 1    | ✓ Power steering cooler | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Power steering cooler leaking, replaced with new

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,653 hr & 778,173 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 26, 2024 | Aug 26, 2024 |     | Aug 27, 2024 3:34 PM | Aug 27, 2024 3:34 PM |

| Line | Task                          | Parts        | Labor  | Total    |
|------|-------------------------------|--------------|--------|----------|
| 1    | ✓ Oil change                  | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Bellows pipe broken         | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Loose exhaust elbow off DOC | \$0.00       | \$0.00 | \$0.00   |
|      |                               | Part Cost    |        | \$0.00   |
|      |                               | Labor        |        | \$0.00   |
|      |                               | Subtotal     |        | \$0.00   |
|      |                               | Tax 1 (0.0%) |        | \$0.00   |
|      |                               | Tax 2 (0.0%) |        | \$0.00   |
|      |                               | Credit       |        | (\$0.00) |
|      |                               | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,667 hr & 778,908 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 28, 2024 | Aug 28, 2024 |     | Aug 28, 2024 7:44 PM | Aug 28, 2024 7:44 PM |

| Line | Task                               |            |            | Parts        | Labor     | Total    |
|------|------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Thru shaft broken                |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                               | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | A23226T1112S - Rockwell thru shaft | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | Side gear                          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | Bearing cup and cone set           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                    |            |            | Part Cost    |           | \$0.00   |
|      |                                    |            |            | Labor        |           | \$0.00   |
|      |                                    |            |            | Subtotal     |           | \$0.00   |
|      |                                    |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Credit       |           | (\$0.00) |
|      |                                    |            |            | Total Cost   |           | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,670 hr & 778,909 km |

| Type | Created     | Scheduled   | Due | Started             | Closed                |
|------|-------------|-------------|-----|---------------------|-----------------------|
|      | Sep 4, 2024 | Sep 4, 2024 |     | Sep 6, 2024 7:23 AM | Sep 16, 2024 10:45 AM |

| Line | Task                                                                      | Parts  | Labor  | Total  |
|------|---------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Body<br><br><u>Notes</u><br>Hood cables not attached to radiator frame  | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Brake Accessories<br><br><u>Notes</u><br>Front drive LH brake pot loose | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Coupling Device/Hitch<br><br><u>Notes</u><br>T rail bolt rh side loose  | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Engine<br><br><u>Notes</u><br>Front engine mounts gone                  | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Front Axle<br><br><u>Notes</u><br>Spring pins wore out                  | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Other<br><br><u>Notes</u><br>Mud flap and anti sail rh side tore off    | \$0.00 | \$0.00 | \$0.00 |
| 7    | ✓ Transmission                                                            | \$0.00 | \$0.00 | \$0.00 |

## 801 - 2019 Kenworth t800

CLOSED

**Notes**

Oil leak on back of transmission

|    |                                  |              |        |          |
|----|----------------------------------|--------------|--------|----------|
| 8  | ✓ RH steer tire                  | \$0.00       | \$0.00 | \$0.00   |
| 9  | ✓ Gear cover loose               | \$0.00       | \$0.00 | \$0.00   |
| 10 | ✓ Scale pad bolt loose           | \$0.00       | \$0.00 | \$0.00   |
| 11 | ✓ Scam ubolt loose rh rear drive | \$0.00       | \$0.00 | \$0.00   |
|    |                                  | Part Cost    |        | \$0.00   |
|    |                                  | Labor        |        | \$0.00   |
|    |                                  | Subtotal     |        | \$0.00   |
|    |                                  | Tax 1 (0.0%) |        | \$0.00   |
|    |                                  | Tax 2 (0.0%) |        | \$0.00   |
|    |                                  | Credit       |        | (\$0.00) |
|    |                                  | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,670 hr & 778,909 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Sep 9, 2024 |     | Sep 9, 2024 2:20 PM | Sep 9, 2024 2:20 PM |

| Line | Task                |            |            | Parts        | Labor     | Total    |
|------|---------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Replace batteries |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Group 31S battery   | Kropp Shop |            | 4.0          | \$0.00    | \$0.00   |
|      |                     |            |            | Part Cost    |           | \$0.00   |
|      |                     |            |            | Labor        |           | \$0.00   |
|      |                     |            |            | Subtotal     |           | \$0.00   |
|      |                     |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                     |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                     |            |            | Credit       |           | (\$0.00) |
|      |                     |            |            | Total Cost   |           | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,724 hr & 780,975 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Sep 17, 2024 | Sep 17, 2024 |     | Sep 17, 2024 5:22 AM | Sep 17, 2024 5:22 AM |

| Line | Task                                        | Parts      | Labor      | Total  |           |        |
|------|---------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ 7 wire lift plug nfg                      | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                        | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 7 wire male plug                            | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 2    | ✓ Front LH brake pot service line broke off | \$0.00     | \$0.00     | \$0.00 |           |        |

**Notes**

Fitting broke off, changed

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,724 hr & 780,975 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Sep 17, 2024 |     | Sep 17, 2024 5:23 AM | Sep 17, 2024 5:23 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

# 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,983 hr & 793,901 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Oct 18, 2024 | Oct 18, 2024 |     | Oct 20, 2024 11:07 AM | Oct 20, 2024 11:07 AM |

| Line          | Task                                                                                                                                                                                                                       | Parts      | Labor     | Total      |        |           |      |               |            |  |     |        |        |  |  |  |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|--------|-----------|------|---------------|------------|--|-----|--------|--------|--|--|--|
| 1             | ✓ Driveline                                                                                                                                                                                                                | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <b><u>Notes</u></b>                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | First diff input yoke loose, second diff input yoke loose                                                                                                                                                                  |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
| 2             | ✓ Fluid Levels                                                                                                                                                                                                             | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <b><u>Notes</u></b>                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | middle diff low oil level                                                                                                                                                                                                  |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
| 3             | ✓ Grease truck and trailer                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>grease tubes</td><td>Kropp Shop</td><td></td><td>4.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>  | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | grease tubes  | Kropp Shop |  | 4.0 | \$0.00 | \$0.00 |  |  |  |
| Part          | Warehouse                                                                                                                                                                                                                  | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |               |            |  |     |        |        |  |  |  |
| grease tubes  | Kropp Shop                                                                                                                                                                                                                 |            | 4.0       | \$0.00     | \$0.00 |           |      |               |            |  |     |        |        |  |  |  |
| 4             | ✓ Lights - All                                                                                                                                                                                                             | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <b><u>Notes</u></b>                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | RH mirror light out                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
| 5             | ✓ Other                                                                                                                                                                                                                    | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <b><u>Notes</u></b>                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | DPF Codes                                                                                                                                                                                                                  |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
| 6             | ✓ Radiator                                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <b><u>Notes</u></b>                                                                                                                                                                                                        |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | Leaking needs replaced                                                                                                                                                                                                     |            |           |            |        |           |      |               |            |  |     |        |        |  |  |  |
|               | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>t800 radiator</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table> | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | t800 radiator | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |  |  |  |
| Part          | Warehouse                                                                                                                                                                                                                  | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |               |            |  |     |        |        |  |  |  |
| t800 radiator | Kropp Shop                                                                                                                                                                                                                 |            | 1.0       | \$0.00     | \$0.00 |           |      |               |            |  |     |        |        |  |  |  |

Kropp Contracting  
Shop

## 801 - 2019 Kenworth t800

**Work Order 1340**  
Everett Twin, Nate Vandenberghe

**CLOSED**

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 8,983 hr & 793,901 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 21, 2024 | Oct 21, 2024 |     | Oct 25, 2024 9:15 AM | Oct 25, 2024 9:15 AM |

| Line | Task                    | Parts        | Labor  | Total    |
|------|-------------------------|--------------|--------|----------|
| 1    | ✓ Replace grille        | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Replace hood bushings | \$0.00       | \$0.00 | \$0.00   |
|      |                         | Part Cost    |        | \$0.00   |
|      |                         | Labor        |        | \$0.00   |
|      |                         | Subtotal     |        | \$0.00   |
|      |                         | Tax 1 (0.0%) |        | \$0.00   |
|      |                         | Tax 2 (0.0%) |        | \$0.00   |
|      |                         | Credit       |        | (\$0.00) |
|      |                         | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,071 hr & 798,599 km |

| Type | Scheduled   | Due | Started              | Closed               |
|------|-------------|-----|----------------------|----------------------|
|      | Nov 1, 2024 |     | Nov 1, 2024 10:14 PM | Nov 1, 2024 10:14 PM |

| Line | Task         | Parts  | Labor  | Total  |
|------|--------------|--------|--------|--------|
| 1    | ✓ Oil change | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Other      | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Stack bushing LH loose

| Part                              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|-----------------------------------|------------|------------|-----|-----------|----------|
| EM75-69000-HT - Stack bushing kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost                         |            |            |     |           | \$0.00   |
| Labor                             |            |            |     |           | \$0.00   |
| Subtotal                          |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)                      |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)                      |            |            |     |           | \$0.00   |
| Credit                            |            |            |     |           | (\$0.00) |
| Total Cost                        |            |            |     |           | \$0.00   |

# 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,184 hr & 804,918 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 | Nov 16, 2024 |     | Nov 16, 2024 7:44 AM | Nov 16, 2024 9:34 AM |

| Line | Task                       | Parts      | Labor      | Total              |
|------|----------------------------|------------|------------|--------------------|
| 1    | ✓ Flat tire                | \$0.00     | \$0.00     | \$0.00             |
|      | <b>Notes</b>               |            |            |                    |
|      | LH rear drive inside       |            |            |                    |
|      | Part                       | Warehouse  | Vendor/Bin | Qty Unit Cost Cost |
|      | 245 Truck - Drive tire     | Kropp Shop |            | 1.0 \$0.00 \$0.00  |
| 2    | ✓ Replace tire             | \$0.00     | \$0.00     | \$0.00             |
|      | Part                       | Warehouse  | Vendor/Bin | Qty Unit Cost Cost |
|      | 245 Trailer - Trailer Tire | Kropp Shop |            | 1.0 \$0.00 \$0.00  |
| 3    | ✓ Mirror cracked, replace  | \$0.00     | \$0.00     | \$0.00             |
|      | Part                       | Warehouse  | Vendor/Bin | Qty Unit Cost Cost |
|      | west coast mirror          | Kropp Shop |            | 1.0 \$0.00 \$0.00  |
| 4    | ✓ loose leveling valve     | \$0.00     | \$0.00     | \$0.00             |
|      | Part                       | Warehouse  | Vendor/Bin | Qty Unit Cost Cost |
|      | VS227 - leveling valve     | Kropp Shop |            | 1.0 \$0.00 \$0.00  |
| 5    | ✓ Bunk Crack - Weld/Repair | \$0.00     | \$0.00     | \$0.00             |
| 6    | ✓ Hood Light-Replace       | \$0.00     | \$0.00     | \$0.00             |
|      | Part                       | Warehouse  | Vendor/Bin | Qty Unit Cost Cost |
|      | G5543 - hood light T800    | Kropp Shop |            | 1.0 \$0.00 \$0.00  |

Kropp Contracting  
Shop

## 801 - 2019 Kenworth t800

**Work Order 1435**  
Nate Vandenberghe, Everett Twin

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,184 hr & 804,918 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 |     | Nov 16, 2024 9:38 AM | Nov 16, 2024 9:38 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,355 hr & 813,637 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 30, 2024 | Nov 30, 2024 |     | Nov 30, 2024 7:05 PM | Nov 30, 2024 7:05 PM |

| Line | Task                           | Parts        | Labor  | Total    |
|------|--------------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer     | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Steer Tires                  | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Coolant leak by bell housing | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Y pipe cracked               | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ Rear RH scam u bolt          | \$0.00       | \$0.00 | \$0.00   |
|      |                                | Part Cost    |        | \$0.00   |
|      |                                | Labor        |        | \$0.00   |
|      |                                | Subtotal     |        | \$0.00   |
|      |                                | Tax 1 (0.0%) |        | \$0.00   |
|      |                                | Tax 2 (0.0%) |        | \$0.00   |
|      |                                | Credit       |        | (\$0.00) |
|      |                                | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,460 hr & 819,144 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Dec 12, 2024 |     | Dec 12, 2024 3:44 AM | Dec 12, 2024 3:44 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Oil change               | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,520 hr & 821,864 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Dec 14, 2024 |     | Dec 14, 2024 5:15 PM | Dec 14, 2024 5:15 PM |

| Line | Task                                                             | Parts        | Labor  | Total    |
|------|------------------------------------------------------------------|--------------|--------|----------|
| 1    | ✓ Brake Accessories<br><br><u>Notes</u><br>scam ubolt loose #4RH | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Lights - All<br><br><u>Notes</u><br>rh mirror lights out       | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Other<br><br><u>Notes</u><br>7 wire plug corroded              | \$0.00       | \$0.00 | \$0.00   |
|      |                                                                  | Part Cost    |        | \$0.00   |
|      |                                                                  | Labor        |        | \$0.00   |
|      |                                                                  | Subtotal     |        | \$0.00   |
|      |                                                                  | Tax 1 (0.0%) |        | \$0.00   |
|      |                                                                  | Tax 2 (0.0%) |        | \$0.00   |
|      |                                                                  | Credit       |        | (\$0.00) |
|      |                                                                  | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,520 hr & 821,864 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Jan 6, 2025 | Jan 6, 2025 |     | Jan 11, 2025 7:15 PM | Jan 11, 2025 7:15 PM |

| Line | Task                                      | Parts        | Labor  | Total    |
|------|-------------------------------------------|--------------|--------|----------|
| 1    | ✓ Will not go into gear                   | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Loose all air when pressing brake pedal | \$0.00       | \$0.00 | \$0.00   |
|      |                                           | Part Cost    |        | \$0.00   |
|      |                                           | Labor        |        | \$0.00   |
|      |                                           | Subtotal     |        | \$0.00   |
|      |                                           | Tax 1 (0.0%) |        | \$0.00   |
|      |                                           | Tax 2 (0.0%) |        | \$0.00   |
|      |                                           | Credit       |        | (\$0.00) |
|      |                                           | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 9,884 hr & 839,222 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 17, 2025 | Jan 17, 2025 |     | Jan 18, 2025 8:13 AM | Jan 18, 2025 9:40 PM |

| Line | Task                                                                                                     | Parts  | Labor  | Total  |
|------|----------------------------------------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Air Compressor<br><b>Notes</b><br>compressor line wet, needs replaced                                  | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Battery<br><b>Notes</b><br>battery box bolt MIA                                                        | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Body<br><b>Notes</b><br>LH door not latching                                                           | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Brake Accessories<br><b>Notes</b><br>RH middle drive s cam u bolt loose                                | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Check all fluid levels<br><b>Notes</b><br>loose clamps- tightened<br>coolant leak by RH spring shackle | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Clutch<br><b>Notes</b><br>Release bearing grease whip not connected                                    | \$0.00 | \$0.00 | \$0.00 |

# 801 - 2019 Kenworth t800

CLOSED

| Part           | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|----------------|------------|------------|--------|-----------|--------|
| 7" grease whip | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7 ✓ Engine     |            |            | \$0.00 | \$0.00    | \$0.00 |

**Notes**

water pump leaking

| Part                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|-------------------------------|------------|------------|--------|-----------|--------|
| 5719751 - X15 water pump core | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 8 ✓ Fifth Wheel               |            |            | \$0.00 | \$0.00    | \$0.00 |

**Notes**

T rail bolts loose front both sides

|                              |  |  |        |        |        |
|------------------------------|--|--|--------|--------|--------|
| 9 ✓ Grease truck and trailer |  |  | \$0.00 | \$0.00 | \$0.00 |
| 10 ✓ Oil change              |  |  | \$0.00 | \$0.00 | \$0.00 |
| 11 ✓ Other                   |  |  | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Headache rack box loose

|                    |  |  |        |        |        |
|--------------------|--|--|--------|--------|--------|
| 12 ✓ Parking Brake |  |  | \$0.00 | \$0.00 | \$0.00 |
|--------------------|--|--|--------|--------|--------|

**Notes**

RH front brake pot NFG

| Part                | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|---------------------|------------|------------|--------|-----------|--------|
| 3030 brake pot      | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 13 ✓ Service Brakes |            |            | \$0.00 | \$0.00    | \$0.00 |

**Notes**

housing broke- replaced pot

RH rear axle brake pot loose

| Part           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------|------------|------------|-----|-----------|--------|
| 3030 brake pot | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

## Notes

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |



## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,037 hr & 845,648 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Feb 1, 2025 | Feb 1, 2025 |     | Feb 1, 2025 11:01 AM | Feb 1, 2025 11:01 AM |

| Line                          | Task                                                                                                                                                                                                                                       | Parts      | Labor     | Total      |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|-------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|--------|-----------|------|-------------------------------|------------|--|-----|--------|--------|--|--|--|--|
| 1                             | ✓ Brake Accessories                                                                                                                                                                                                                        | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <b><u>Notes</u></b>                                                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | LH front drive loose pot, LH rear scam u bolt loose                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
| 2                             | ✓ Engine                                                                                                                                                                                                                                   | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <b><u>Notes</u></b>                                                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | coolant filter leaking                                                                                                                                                                                                                     |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Wf2127 - Cummins water filter</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table> | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | Wf2127 - Cummins water filter | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |  |  |  |  |
| Part                          | Warehouse                                                                                                                                                                                                                                  | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                               |            |  |     |        |        |  |  |  |  |
| Wf2127 - Cummins water filter | Kropp Shop                                                                                                                                                                                                                                 |            | 1.0       | \$0.00     | \$0.00 |           |      |                               |            |  |     |        |        |  |  |  |  |
| 3                             | ✓ Frame & Assembly                                                                                                                                                                                                                         | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <b><u>Notes</u></b>                                                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | front rad mount crossmember bolt loose                                                                                                                                                                                                     |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
| 4                             | ✓ Front Axle                                                                                                                                                                                                                               | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <b><u>Notes</u></b>                                                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | tie rod bar bent, RH tie rod NFG                                                                                                                                                                                                           |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>347-205 - t800 tie rod bar</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>    | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | 347-205 - t800 tie rod bar    | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |  |  |  |  |
| Part                          | Warehouse                                                                                                                                                                                                                                  | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                               |            |  |     |        |        |  |  |  |  |
| 347-205 - t800 tie rod bar    | Kropp Shop                                                                                                                                                                                                                                 |            | 1.0       | \$0.00     | \$0.00 |           |      |                               |            |  |     |        |        |  |  |  |  |
| 5                             | ✓ Grease truck and trailer                                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
| 6                             | ✓ Suspension System                                                                                                                                                                                                                        | \$0.00     | \$0.00    | \$0.00     |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | <b><u>Notes</u></b>                                                                                                                                                                                                                        |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |
|                               | middle wishbone bolts loose                                                                                                                                                                                                                |            |           |            |        |           |      |                               |            |  |     |        |        |  |  |  |  |

Kropp Contracting  
Shop

## 801 - 2019 Kenworth t800

**Work Order 1628**  
Trent Court, Everett Twin  
**CLOSED**

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,118 hr & 849,018 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 10, 2025 | Feb 10, 2025 |     | Feb 10, 2025 8:57 PM | Feb 10, 2025 8:57 PM |

| Line | Task                      |            |            | Parts        | Labor     | Total    |
|------|---------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Clutch no good wore out |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                      | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 308925-25-pac - Clutch    | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | Input shaft kit           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | Cross shafts              | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                           |            |            | Part Cost    |           | \$0.00   |
|      |                           |            |            | Labor        |           | \$0.00   |
|      |                           |            |            | Subtotal     |           | \$0.00   |
|      |                           |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                           |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                           |            |            | Credit       |           | (\$0.00) |
|      |                           |            |            | Total Cost   |           | \$0.00   |

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,149 hr & 85,360 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 12, 2025 | Feb 12, 2025 |     | Feb 13, 2025 9:43 AM | Feb 13, 2025 9:43 AM |

| Line | Task                                      | Parts      | Labor      | Total  |           |        |
|------|-------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Body                                    | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                       |            |            |        |           |        |
|      | RH hood fender crack- prep and glue crack |            |            |        |           |        |
| 2    | ✓ Engine                                  | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                       |            |            |        |           |        |
|      | gear cover bolts loose- oil leak          |            |            |        |           |        |
| 3    | ✓ Radiator                                | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                       |            |            |        |           |        |
|      | surge tank leaking                        |            |            |        |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | st3008d - T800 surge tank                 | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 4    | ✓ Windows                                 | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                       |            |            |        |           |        |
|      | both windshields nfg                      |            |            |        |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | Windshield LH                             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | windshield RH                             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 5    | ✓ Grease truck and trailer                | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | grease tubes                              | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 801 - 2019 Kenworth t800

**Work Order 1673**

Trent Court

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,286 hr & 856,800 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 25, 2025 | Feb 25, 2025 |     | Feb 25, 2025 1:36 PM | Feb 25, 2025 1:36 PM |

| Line | Task                          |            |            | Parts        | Labor     | Total    |
|------|-------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                  |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                          | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter  | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ blow out DPF, DOC           |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                          | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5417859 - Cummins Can gaskets | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
|      | 2880215 - DOC inlet gasket 5" | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                               |            |            | Part Cost    |           | \$0.00   |
|      |                               |            |            | Labor        |           | \$0.00   |
|      |                               |            |            | Subtotal     |           | \$0.00   |
|      |                               |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                               |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                               |            |            | Credit       |           | (\$0.00) |
|      |                               |            |            | Total Cost   |           | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,337 hr & 859,595 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 27, 2025 | Feb 27, 2025 |     | Mar 3, 2025 10:41 AM | Mar 3, 2025 10:41 AM |

| Line | Task                                          | Parts        | Labor  | Total    |
|------|-----------------------------------------------|--------------|--------|----------|
| 1    | ✓ differential pressure codes, stuck in range | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Grease truck and trailer                    | \$0.00       | \$0.00 | \$0.00   |
|      |                                               | Part Cost    |        | \$0.00   |
|      |                                               | Labor        |        | \$0.00   |
|      |                                               | Subtotal     |        | \$0.00   |
|      |                                               | Tax 1 (0.0%) |        | \$0.00   |
|      |                                               | Tax 2 (0.0%) |        | \$0.00   |
|      |                                               | Credit       |        | (\$0.00) |
|      |                                               | Total Cost   |        | \$0.00   |

# 801 - 2019 Kenworth t800

**CLOSED**

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,337 hr & 859,595 km |

| Type | Created      | Scheduled    | Due | Started              | Closed              |
|------|--------------|--------------|-----|----------------------|---------------------|
|      | Feb 28, 2025 | Feb 28, 2025 |     | Feb 28, 2025 3:57 PM | Mar 1, 2025 7:47 PM |

| Line | Task                    | Parts      | Labor      | Total        |           |          |
|------|-------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Lights - All          | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | <u>Notes</u>            |            |            |              |           |          |
|      | RH upper worklight INOP |            |            |              |           |          |
|      | Part                    | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Work light              | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Windshield Wipers     | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | <u>Notes</u>            |            |            |              |           |          |
|      | RH nozzle sprayer       |            |            |              |           |          |
|      | Part                    | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | t800 WW nozzle          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 3    | ✓ Air filters           | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                    | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | air filters             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                         |            |            | Part Cost    |           | \$0.00   |
|      |                         |            |            | Labor        |           | \$0.00   |
|      |                         |            |            | Subtotal     |           | \$0.00   |
|      |                         |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                         |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                         |            |            | Credit       |           | (\$0.00) |
|      |                         |            |            | Total Cost   |           | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,409 hr & 862,526 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Mar 8, 2025 |     | Mar 8, 2025 2:21 PM | Mar 8, 2025 2:21 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,409 hr & 862,526 km |

| Type | Scheduled    | Due | Started               | Closed                |
|------|--------------|-----|-----------------------|-----------------------|
|      | Mar 11, 2025 |     | Mar 11, 2025 11:07 AM | Mar 11, 2025 11:07 AM |

| Line | Task                               |            |            | Parts        | Labor     | Total    |
|------|------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Doser quantity and pressure code |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                               | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5578983RX - Doser                  | Kropp Shop | EKW        | 1.0          | \$0.00    | \$0.00   |
|      |                                    |            |            | Part Cost    |           | \$0.00   |
|      |                                    |            |            | Labor        |           | \$0.00   |
|      |                                    |            |            | Subtotal     |           | \$0.00   |
|      |                                    |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Credit       |           | (\$0.00) |
|      |                                    |            |            | Total Cost   |           | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,484 hr & 865,455 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Mar 14, 2025 | Mar 14, 2025 |     | Mar 14, 2025 11:06 AM | Mar 14, 2025 11:06 AM |

| Line | Task                                                 | Parts      | Labor      | Total        |           |          |
|------|------------------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Truck running cold no coolant temperature on guage | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                                 | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 4318947 - Thermostat Cummins 15L                     | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                                      |            |            | Part Cost    |           | \$0.00   |
|      |                                                      |            |            | Labor        |           | \$0.00   |
|      |                                                      |            |            | Subtotal     |           | \$0.00   |
|      |                                                      |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                                      |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                                      |            |            | Credit       |           | (\$0.00) |
|      |                                                      |            |            | Total Cost   |           | \$0.00   |

# 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,570 hr & 868,926 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 21, 2025 | Mar 21, 2025 |     | Mar 21, 2025 2:16 PM | Mar 21, 2025 2:16 PM |

| Line | Task        | Parts  | Labor  | Total  |
|------|-------------|--------|--------|--------|
| 1    | ✓ def codes | \$0.00 | \$0.00 | \$0.00 |

**Notes**

ASH load high, blow out can

Doer line condition exists code narrowed down to harness removed and replaced

def pump would not prime, replace def pump (power and harness good)

| Part                                             | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------------------------------------------|------------|------------|-----|-----------|--------|
| 5506956RX - Pump, doser                          | Kropp Shop | EKW        | 1.0 | \$0.00    | \$0.00 |
| M92-1044-30424 - cummins after treatment harness | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,574 hr & 868,939 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Mar 22, 2025 |     | Mar 22, 2025 3:25 PM | Mar 22, 2025 3:25 PM |

| Line | Task                                           | Parts        | Labor  | Total    |
|------|------------------------------------------------|--------------|--------|----------|
| 1    | ✓ DPF, DOC breached remove and install cleaned | \$0.00       | \$0.00 | \$0.00   |
|      |                                                | Part Cost    |        | \$0.00   |
|      |                                                | Labor        |        | \$0.00   |
|      |                                                | Subtotal     |        | \$0.00   |
|      |                                                | Tax 1 (0.0%) |        | \$0.00   |
|      |                                                | Tax 2 (0.0%) |        | \$0.00   |
|      |                                                | Credit       |        | (\$0.00) |
|      |                                                | Total Cost   |        | \$0.00   |

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,574 hr & 868,939 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Apr 23, 2025 | Apr 23, 2025 |     | Apr 30, 2025 6:44 PM | Apr 30, 2025 6:44 PM |

| Line | Task                                      | Parts      | Labor      | Total  |           |        |
|------|-------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Grease truck and trailer                | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Preform Scheduled Maintenance           | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ CVIP inspection (wheels off)            | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ Rh windshield washer nozzle not working | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ LH mirror arm loose                     | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ Air filters                             | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | air filters                               | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 7    | ✓ change diff filters                     | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LF3311 - Rockwell diff filter             | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 8    | ✓ rear leveling valve bracket bent        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 9    | ✓ rear leveling rod flipped               | \$0.00     | \$0.00     | \$0.00 |           |        |
| 10   | ✓ front drive shocks                      | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | drive shock                               | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 11   | ✓ front diff pinion plate reseal          | \$0.00     | \$0.00     | \$0.00 |           |        |
| 12   | ✓ middle diff pinion plate re seal        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 13   | ✓ air dryer filter change                 | \$0.00     | \$0.00     | \$0.00 |           |        |

# 801 - 2019 Kenworth t800


**CLOSED**

|              |                                            |            |            |        |           |          |
|--------------|--------------------------------------------|------------|------------|--------|-----------|----------|
| 14           | ✓ purge valve replace                      |            |            | \$0.00 | \$0.00    | \$0.00   |
|              | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost     |
|              | K022105 - AD-IS purge valve                | Kropp Shop |            | 1.0    | \$0.00    | \$0.00   |
| 15           | ✓ wash of tranny and find leak             |            |            | \$0.00 | \$0.00    | \$0.00   |
| 16           | ✓ LH high beam bulb broke                  |            |            | \$0.00 | \$0.00    | \$0.00   |
| 17           | ✓ power steering leak                      |            |            | \$0.00 | \$0.00    | \$0.00   |
| 18           | ✓ loose gear cover                         |            |            | \$0.00 | \$0.00    | \$0.00   |
| 19           | ✓ lh fuel tank cap leaking                 |            |            | \$0.00 | \$0.00    | \$0.00   |
|              | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost     |
|              | Fuel cap                                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00   |
| 20           | ✓ Drive brakes all around                  |            |            | \$0.00 | \$0.00    | \$0.00   |
|              | Part                                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost     |
|              | Es2 shoe kit                               | Kropp Shop |            | 6.0    | \$0.00    | \$0.00   |
|              | Brake Drum                                 | Kropp Shop |            | 5.0    | \$0.00    | \$0.00   |
| 21           | ✓ Check clutch adjustment                  |            |            | \$0.00 | \$0.00    | \$0.00   |
| 22           | ✓ wrap exposed harness by inlet nox sensor |            |            | \$0.00 | \$0.00    | \$0.00   |
| 23           | ✓ coolant leak by lower rad hose           |            |            | \$0.00 | \$0.00    | \$0.00   |
| 24           | ✓ Middle diff breather tube MIA            |            |            | \$0.00 | \$0.00    | \$0.00   |
| Part Cost    |                                            |            |            |        |           | \$0.00   |
| Labor        |                                            |            |            |        |           | \$0.00   |
| Subtotal     |                                            |            |            |        |           | \$0.00   |
| Tax 1 (0.0%) |                                            |            |            |        |           | \$0.00   |
| Tax 2 (0.0%) |                                            |            |            |        |           | \$0.00   |
| Credit       |                                            |            |            |        |           | (\$0.00) |
| Total Cost   |                                            |            |            |        |           | \$0.00   |

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,745 hr & 877,931 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | May 24, 2025 | May 24, 2025 |     | May 24, 2025 3:26 PM | May 24, 2025 3:26 PM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Intake nox sensor code                 |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 3687930RX - Inlet NOX sensor             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |



## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,757 hr & 878,609 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | May 26, 2025 |     | May 26, 2025 7:09 PM | May 26, 2025 7:09 PM |

| Line | Task            | Parts        | Labor  | Total    |
|------|-----------------|--------------|--------|----------|
| 1    | ✓ Adjust clutch | \$0.00       | \$0.00 | \$0.00   |
|      | Technician      | Hours        | Rate   | Cost     |
|      | Everett Twin    | 0.0          | \$0.00 | \$0.00   |
|      |                 | Part Cost    |        | \$0.00   |
|      |                 | Labor        |        | \$0.00   |
|      |                 | Subtotal     |        | \$0.00   |
|      |                 | Tax 1 (0.0%) |        | \$0.00   |
|      |                 | Tax 2 (0.0%) |        | \$0.00   |
|      |                 | Credit       |        | (\$0.00) |
|      |                 | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,900 hr & 885,858 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Jun 19, 2025 |     | Jun 19, 2025 4:48 PM | Jun 19, 2025 4:48 PM |

| Line | Task                      | Parts        | Labor  | Total    |
|------|---------------------------|--------------|--------|----------|
| 1    | ✓ Drive tires (set of 12) | \$0.00       | \$0.00 | \$0.00   |
|      |                           | Part Cost    |        | \$0.00   |
|      |                           | Labor        |        | \$0.00   |
|      |                           | Subtotal     |        | \$0.00   |
|      |                           | Tax 1 (0.0%) |        | \$0.00   |
|      |                           | Tax 2 (0.0%) |        | \$0.00   |
|      |                           | Credit       |        | (\$0.00) |
|      |                           | Total Cost   |        | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,954 hr & 888,604 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jul 6, 2025 | Jul 6, 2025 |     | Jul 6, 2025 6:27 AM | Jul 6, 2025 6:27 AM |

| Line | Task                                               | Parts  | Labor  | Total  |
|------|----------------------------------------------------|--------|--------|--------|
| 1    | ✓ Air leak behind dash at firewall push to connect | \$0.00 | \$0.00 | \$0.00 |

**Notes**

used compression union

|   |                                      |        |        |        |
|---|--------------------------------------|--------|--------|--------|
| 2 | ✓ primary air transducer air leaking | \$0.00 | \$0.00 | \$0.00 |
|---|--------------------------------------|--------|--------|--------|

| Part                | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------------|------------|------------|-----|-----------|--------|
| pressure transducer | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,989 hr & 890,412 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 21, 2025 | Jul 21, 2025 |     | Jul 21, 2025 4:23 AM | Jul 21, 2025 4:27 AM |

| Line | Task                                     | Parts      | Labor      | Total  |           |        |
|------|------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Air Lines                              | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                      |            |            |        |           |        |
|      | Chaffing on diff                         |            |            |        |           |        |
| 2    | ✓ Brake Accessories                      | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                      |            |            |        |           |        |
|      | Adjust front brakes, and scam u bolts    |            |            |        |           |        |
| 3    | ✓ Engine                                 | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                      |            |            |        |           |        |
|      | Exhust leak egr                          |            |            |        |           |        |
| 4    | ✓ Grease truck and trailer               | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ Transmission                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                      |            |            |        |           |        |
|      | Leaking                                  |            |            |        |           |        |
| 6    | ✓ Oil change                             | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | oil 15w-40                               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

## 801 - 2019 Kenworth t800

CLOSED

|              |                             |        |        |          |
|--------------|-----------------------------|--------|--------|----------|
| 7            | ✓ Rh hood light out         | \$0.00 | \$0.00 | \$0.00   |
| 8            | ✓ coolant level sensor code | \$0.00 | \$0.00 | \$0.00   |
| Part Cost    |                             |        |        | \$0.00   |
| Labor        |                             |        |        | \$0.00   |
| Subtotal     |                             |        |        | \$0.00   |
| Tax 1 (0.0%) |                             |        |        | \$0.00   |
| Tax 2 (0.0%) |                             |        |        | \$0.00   |
| Credit       |                             |        |        | (\$0.00) |
| Total Cost   |                             |        |        | \$0.00   |

## 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 10,989 hr & 890,412 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Sep 5, 2025 | Sep 5, 2025 |     | Sep 14, 2025 6:52 PM | Sep 30, 2025 2:44 PM |

| Line | Task                                          | Parts  | Labor  | Total  |
|------|-----------------------------------------------|--------|--------|--------|
| 1    | ✓ Install PTO                                 | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Install hydraulic cooler pack               | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Run heat trace                              | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Cut off RH cabinet on tank                  | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Remove LH fuel tank                         | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Extend frame                                | \$0.00 | \$0.00 | \$0.00 |
| 7    | ✓ Install work lights on tank                 | \$0.00 | \$0.00 | \$0.00 |
| 8    | ✓ Wire lights on tank                         | \$0.00 | \$0.00 | \$0.00 |
| 9    | ✓ Install mounting brackets on frame          | \$0.00 | \$0.00 | \$0.00 |
| 10   | ✓ Install pump box heater                     | \$0.00 | \$0.00 | \$0.00 |
| 11   | ✓ Remove plumbing and install 3" product pump | \$0.00 | \$0.00 | \$0.00 |
| 12   | ✓ Make spool valve bracket and run lines      | \$0.00 | \$0.00 | \$0.00 |
| 13   | ✓ Modify plumbing to fit pump                 | \$0.00 | \$0.00 | \$0.00 |
| 14   | ✓ Make 3" load lines                          | \$0.00 | \$0.00 | \$0.00 |
| 15   | ✓ Make water spreader                         | \$0.00 | \$0.00 | \$0.00 |

## 801 - 2019 Kenworth t800

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

### Notes

| Notes                     | User        | Time                |
|---------------------------|-------------|---------------------|
| Make into new water truck | Trent Court | Sep 5, 2025 4:24 PM |

# 801 - 2019 Kenworth t800

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 11,185 hr & 900,098 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 12, 2025 | Nov 12, 2025 |     | Nov 28, 2025 8:59 AM | May 13, 2026 1:11 PM |

| Line | Task                               | Parts        | Labor      | Total  |           |          |
|------|------------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Preform Scheduled Maintenance    | \$0.00       | \$0.00     | \$0.00 |           |          |
| 2    | ✓ exhaust manifold gaskets leaking | \$0.00       | \$0.00     | \$0.00 |           |          |
| 3    | ✓ DEF derate code                  | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                               | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | turbo actuator                     | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 4    | ✓ LH king pin nfg                  | \$0.00       | \$0.00     | \$0.00 |           |          |
| 5    | ✓ Sand tank for paint              | \$0.00       | \$0.00     | \$0.00 |           |          |
| 6    | ✓ CVIP inspection (wheels off)     | \$0.00       | \$0.00     | \$0.00 |           |          |
| 7    | ✓ change diff filters              | \$0.00       | \$0.00     | \$0.00 |           |          |
| 8    | ✓ Air filters                      | \$0.00       | \$0.00     | \$0.00 |           |          |
| 9    | ✓ Replace Belt                     | \$0.00       | \$0.00     | \$0.00 |           |          |
| 10   | ✓ Grease truck and trailer         | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                                    | Part Cost    |            |        |           | \$0.00   |
|      |                                    | Labor        |            |        |           | \$0.00   |
|      |                                    | Subtotal     |            |        |           | \$0.00   |
|      |                                    | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                                    | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                                    | Credit       |            |        |           | (\$0.00) |
|      |                                    | Total Cost   |            |        |           | \$0.00   |

## 801 - 2019 Kenworth t800

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX0KR951077 | 0AZ867 | 11,210 hr & 900,581 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 20, 2026 | Jul 20, 2026 |     | Jul 23, 2026 1:14 PM | Jul 23, 2026 1:14 PM |

| Line | Task                          | Parts  | Labor  | Total  |
|------|-------------------------------|--------|--------|--------|
| 1    | ✓ Installed missing grill bar | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Fixed A/C                   | \$0.00 | \$0.00 | \$0.00 |

### Notes

Inspected ac compressor checked fuse and inspected wiring  
checked high and low pressures and added R-134 freon 2lbs.

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |