



80087700008383034

CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Kropp Contracting Ltd.		
Address:	Box 237		
City:	Slave Lake	Province:	AB
Postal Code:	T0G2A0		
Telephone Number:	(780) 849-6229		
Vehicle Identification Number:	2PLH012192BF10740		
Make:	Peerless	Model:	sat10
Year:	2002	Unit Number:	B01
Odometer:	KM	Licence Plate Number:	4BU369
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2026/07/08



80087700008383034

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	Kropp Contracting Ltd.		
Address:	Box 237		
City:	Slave Lake	Province:	AB
Postal Code:	T0G2A0		
Telephone Number:	(780) 849-6229		
Vehicle Identification Number:	2PLH012192BF10740		
Make:	Peerless	Model:	sat10
Year:	2002	Unit Number:	B01
Odometer:	KM	Licence Plate Number:	4BU369
Province:	AB		

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
Kropp Contracting Ltd.	18733
Inspection Technician Name:	Technician Number:
Westley Nadeau	C1246
Inspection Technician Signature:	
Inspection Date:	2026/07/08

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle <u>Booster</u>										Gross Vehicle Weight registered kg									
Vehicle Information																			
VIN		<u>2</u>	<u>P</u>	<u>L</u>	<u>H</u>	<u>0</u>	<u>1</u>	<u>2</u>	<u>1</u>	<u>9</u>	<u>2</u>	<u>B</u>	<u>F</u>	<u>1</u>	<u>0</u>	<u>7</u>	<u>4</u>	<u>0</u>	
Unit Number <u>801</u>				Year <u>2002</u>				Make <u>Peerless</u>				Model <u>Booster</u>				Odometer			
Registered Owner's Name <u>Kropp Contracting</u>																Plate Number <u>4BU3-69</u>			
Address <u>box 237</u>												Postal Code <u>TOG 2A3</u>				Phone Number			

LEFT		FRONT		RIGHT	
<u>100</u> psi <u>15</u> mm	<u>100</u> psi <u>15</u> mm	<u>16.535</u> mm <u>111/16</u> mm <u>48°</u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u>16.526</u> mm <u>111/16</u> mm <u>42°</u> mm	<u>100</u> psi <u>12</u> mm
<u> </u> psi <u> </u> mm	<u> </u> psi <u> </u> mm	<u> </u> mm <u> </u> mm <u> </u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u> </u> mm <u> </u> mm <u> </u> mm	<u> </u> psi <u> </u> mm
<u> </u> psi <u> </u> mm	<u> </u> psi <u> </u> mm	<u> </u> mm <u> </u> mm <u> </u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u> </u> mm <u> </u> mm <u> </u> mm	<u> </u> psi <u> </u> mm
<u> </u> psi <u> </u> mm	<u> </u> psi <u> </u> mm	<u> </u> mm <u> </u> mm <u> </u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u> </u> mm <u> </u> mm <u> </u> mm	<u> </u> psi <u> </u> mm
<u> </u> psi <u> </u> mm	<u> </u> psi <u> </u> mm	<u> </u> mm <u> </u> mm <u> </u> mm	Drums/Rotors Linings/Pads Push Rod Travel Cam Rotation	<u> </u> mm <u> </u> mm <u> </u> mm	<u> </u> psi <u> </u> mm

Park Brake Lining Left mm Right mm Trans mm

Wheel Torque Checked ☒ Inner ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System			✓	1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System			✓	A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System			✓				

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments				2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components				2.6. Self-Steer & Controlled-Steer Axle			
2.3. Axle & Axle Assembly				2.7. Shock Absorber/Strut Assembly			
2.4. Spring & Spring Attachment							

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System	✓		✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components	✓		
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance	✓		
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		✓
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)			✓
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage	✓			4.5. Self Steer & Controlled-Steer Axle	✓		
4.4. Kingpin	✓						

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher			✓				✓

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery			✓				

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body			✓	8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements			✓	8.22. Landing Gear on Trailer			✓
8.8. Cab or Cargo Door			✓	8.23. Sliding Axle Assembly (Sliding Bogie)			✓
8.9. Cargo Tank or Vessel			✓	8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle			✓	8.25. Rear Impact Guard (RIG)	✓		

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		✓
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim			✓
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System			✓
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)			✓	10.7. Fifth Wheel Coupler			✓
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch			✓	10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch			✓	10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch			✓				

NOTES:

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY AND COVERTER**

Certification

The Vehicle for which this Record of Inspection is issued has passed the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection

July 8/20

Technician Number

C1246

Facility Number

1873

Signature



Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

July 8/20

Customer Signature

