

04018127

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE



Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920



Date Inspection Started
08 / 12 / 25
DAY MO. YR.

Date Inspection Completed
08 / 12 / 25
DAY MO. YR.

Inspection Expiry Date
31 / 12 / 26
DAY MO. YR.

Station Number
A6059

Station Name
MUDDY RIVER ENTERPRISE

City
Morden

Province
MB

Postal Code
R6X 1G0

Phone
204-729-1460

Mechanic Number
M7623

Mechanic Signature
[Signature]

Station Phone Number
204-729-1460

Vehicle Owner
ITL FARMS

Address
BOX 1825 KILLARNEY MB

City
Killarney

Province
MB

Postal Code
R6X 1G0

Phone
204-729-1460

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number
KSY242

Prov.
MB

NSC #
MB1099960

Odometer Reading
1478161

Odom. Type
☒ km ☐ mi

Vehicle Identification Number
1XPXD49X7GD293990

Make
PETE

Model
389

Year
16

Unit #
—

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ GVWR 24132 KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X	X	Section 1 - Power Train: Defects (if any) 2A - EXH. MANIFOLD LEAKING																																																																							
		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 13E - AIR LEAKS @ TANK UNDER DRIVER'S DOOR + ON FIREWALL 13A - BLUE GLAD HAND CORRODED																																																																							
X	X	Section 4 - Steering: Defects (if any) 1A - PWR STEER BOX INPUT SEAL LEAK 2A - RESERVOIR LEAKING																																																																							
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 7C - RH WIPER ARM MISSING																																																																							
X	X	Section 6 - Lamps: Defects (if any) 1F - RH FRONT + LH REAR TURN SIGNALS N/F 1K - REVERSE LAMP N/F																																																																							
		Section 7 - Electrical System: Defects (if any) 2C - BATT. HOLD DOWN LOOSE																																																																							
X	X	Section 8 - Body: Defects (if any)																																																																							
		Section 9 - Tire & Wheel: Defects (if any) 5C - A3 RH WHEEL SEAL LEAK 5D - A1 BOTH HUB CAPS LEAKING																																																																							
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>12</td><td>12</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>14</td><td>13</td><td>12</td><td>13</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>13</td><td>12</td><td>11</td><td>12</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	12	12			100	100			2	14	13	12	13	100	100	100	100	3	13	12	11	12	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	12	12			100	100																																																																			
2	14	13	12	13	100	100	100	100																																																																	
3	13	12	11	12	100	100	100	100																																																																	
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

PRESENT THIS COPY WHEN REGISTERING VEHICLE

