



# Commercial Vehicle Inspection Report

Decal Number: GH33859  
Decal Expiry Date: 2025-Dec-31  
Inspection Number: 21401436

Inspection Result:

**PASS**

<b>FACILITY:</b>	RIVERSIDE REPAIRS / S5662	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Jun-23 10:10 AM PDT
<b>INSPECTOR:</b>	GAINOR, ARLAN RICHARD / 111197	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2025-Jun-23 11:10 AM PDT
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Semi-annual		
<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	12855138	<b>VIN:</b>	5KJRALD11KPKV1843
<b>PLATE #:</b>		<b>UNIT/FLEET#:</b>	012	<b>OWNER/LESSEE NAME:</b>	LOST CREEK HOLDINGS, lost
<b>LICENCED GVW(kg):</b>	63500	<b>BODY STYLE:</b>	Logging Truck	<b>ADDRESS:</b>	box 107, box 107
<b>VEHICLE YEAR:</b>	2019	<b>ODOMETER:</b>	569611 KM		Fort St James, British Columbia
<b>MAKE:</b>	WESTERN ST	<b>HUB ODOMETER:</b>			v0j1p0, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) TORSION RODS ON DIFFS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) MAXI POT AXLE 4 L S
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) R KING PIN BOTH TIE RODS
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	45	40
2	Clamp	30	Automatic	45	45
3	Clamp	30	Automatic	40	40
4	Clamp	30	Automatic	45	40

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
15			16	✓
21	21	21	21	
20	20	19	19	
21	21	20	20	

Comment:

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CV/SE014

6/24/2025 9:52:46 AM PDT



Commercial Vehicle  
Inspection Report

Decal Number: GH33859  
Decal Expiry Date: 2025-Dec-31  
Inspection Number: 21401436

Inspection Result:  
**PASS**

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	30	Lining (Shoe)	18	18	Drum		
2	35	40	Lining (Shoe)	18	16	Drum		
3	70	50	Lining (Shoe)	10	14	Drum		
4	70	45	Lining (Shoe)	10	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Signature: Road Tester:

Inspector: GAINOR, ARLAN RICHARD

This Inspection Report was submitted to CVSE on 2025-Jun-24 09:52 AMPDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.