



Commercial Vehicle Inspection Report

Decal Number: GH33860
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21401461

Inspection Result:
PASS

FACILITY: RIVERSIDE REPAIRS / S5662
INSPECTOR: GAINOR, ARLAN RICHARD / 111197
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2025-Jun-23 01:00 PM PDT
INSP. COMPLETE: 2025-Jun-23 03:20 PM PDT

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 26958J
LICENCED GVW(kg): 0
VEHICLE YEAR: 2019
MAKE: FREFLYT
MODEL:
REGI: 13141865
UNIT/FLEET#: 012A
BODY STYLE: LOGGING TRAILER
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2F9FHL133K1101721
OWNER/LESSEE NAME: LOST CREEK HOLDINGS, lost
ADDRESS: box 107, box 107
Fort St James, British Columbia
v0j1p0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Repaired (same day) SHOCK BOLTS
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) SHOES AXLE 2 L S AXLE 3 B S
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	45	45
2	Clamp	30	Automatic	45	40
3	Clamp	30	Automatic	45	45

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12	12	10	10	
10	10	9	9	
12	12	8	8	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	45
2	35	35
3	35	40

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	14
Lining (Shoe)	22	14
Lining (Shoe)	22	22


Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: GAINOR, ARLAN RICHARD
Road Test Date: 
Signature: _____
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-24 10:01 AMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/24/2025 10:02:03 AM PDT