



Plant History

Model: Isuzu FXR Service Truck

Serial No: JALFXZ77UD7000084

Registration No: 932 TZS

Plant No: ST02

Date/Hours	Description
20.09.19	CQ Diesel – Carry out buyers’ inspection. Report on defects.
	Purchase Truck.
	Signature Mechanical – carry out road worthy.
28.10.19 – 15.11.19	ACES – Change isolation to double pole isolation, change out isolator and lock out on compressor, fit and wire up mine radio with reducer, wire up hand brake door alarm, wire up key on lights module, wire up 175A plug for 12V jump start, check over all electrics, lights and air conditioning system, inspect fault with SRS system and notify customer of faulty module
04.11.19	ACES – Replaced unserviceable isolators. Fitted door alarms. Fitted mine radio. Checked SRS fault code. Module unserviceable – parts ordered. Repaired jump start receptacles.
06.11.19	Pronto – Replace front windscreen and Perspex in isolator door.
07.11.19	Full wash and detail.
08.11.19	Paint handrails. Fabricate handrails for around rear section of truck and fold down steps.
12.11.19	Fit logo stickers. Fit call signs. Fit plant number on compressor. Fit exhaust guards. Replaced unserviceable regulator. Drain coolant tank and flush to take AdBlue. Fit new fuel counter. Fit trigger/handpiece for AdBlue pump.
13.11.19	CQ Diesel – replace 2 x bolts in rear body mount rh side, tighten body mounts. Tighten a/c belt, tidy wiring under cab, place / manufacture fire extinguisher, started to build muffler guard
14.11.19	CQ Diesel – remove and replace air reg, tested for valves, replace exhaust guard on machine, exhaust wrap / flush out coolant tank, adjust top door spring, place anti bust on grease line / hose – tested okay

15.11.19	CQ Diesel – carry out pre hire inspection, place mud guard, remove and replace air filter
23.11.19	CQ Diesel Moranbah – check over truck, assess mounting points for access step extensions
24.11.19	CQ Diesel Moranbah – remove diaphragm pump, dismantle tyres to get parts
03.12.19	CQ Diesel Moranbah – BMA Compliance
04.12.19	CQ Diesel Moranbah – Fitted drivers sidestep, seat cover passenger and middle, replaced airbag module, put 205L of engine oil, transmission oil and hydraulic 68 oil into their tanks
09.12.19	CQ Diesel Moranbah – fit new seat belt and driver's seat cover, repair air leak to air pressure regulator
10.12.19	CQ Diesel Moranbah – diagnose why 2-way and reverse camera not working. Repaired, started putting dash back together
11.12.19	CQ Diesel Moranbah – finish off putting dash together, pumped out evac. Waste oil
17.12.19	CQ Diesel Moranbah – change over all gear, oil / fluids from CST079
20.12.19	CQ Diesel Moranbah – cigarette lighter not working, found had no fuse, test all okay
05.01.20	CQ Diesel Moranbah – fill all oils
08.01.20	CQ Diesel Moranbah – delayed due to damaged boom gate at rail crossing, had to drive out through Goonyella access and back on main road to GS1, service truck had an air leak to grease pump. Found fitting to make joiner, fitted and hose blew 3 inches away, cut that bit out re-joined then that blew, organised some more hose and joiners
09.01.20 3264hrs	CQ Diesel Moranbah – change high volume grease air line
13.01.20 57373kms	CQ Diesel Moranbah – investigate high and low flow grease pumps not working, low pump breathers blocked, disassemble breathers, clean and reassemble, high flow, found air side of pump faulty
14.01.20 57373kms	CQ Diesel Moranbah – move to another yard
16.01.20	CQ Diesel Moranbah – replaced bulb fuel hose and wound up spring, shortened L/V fuel hose, put swivel on grease gun, fit tap and quick connect to bulk grease reel, fit handle to water tap, put nut and spring washer on handle

18.01.20 57373kms	CQ Diesel Moranbah – repair grease leaks
08.02.20	CQ Diesel Moranbah – start to disassemble grease pump
09.02.20 3298hrs	CQ Diesel Moranbah – rebuild and assemble grease pump, test operation, okay
11.02.20 3303hrs	CQ Diesel Moranbah – investigate diesel leak, tighten fitting
16.02.20 3307hrs	CQ Diesel Moranbah – repaired fuel leak on fuel nozzle
19.02.20 3312hrs	CQ Diesel Moranbah – investigate pos 3 brake lock up, find service brake system and park brake system by-passing
20.02.20	CQ Diesel Moranbah – investigate faulty air system further, possible treadle valve failure
21.02.20 57582km	CQ Diesel Moranbah – investigate air leak, foot brake treadle valve faulty
27.02.20 4517hrs	CQ Diesel Moranbah – remove and fit treadle valve, test operation, okay
29.02.20 3314hrs	CQ Diesel Moranbah – repair leaking fuel gun. Investigate brake lock up, find park brake relay valve failure. Remove and strip valve, organise new valve, transfer grease from ST02 to CST079, find bulk fill grease pump not working, remove pump. Strip and clean pump components
01.03.20 3314hrs	CQ Diesel Moranbah – clean pump parts, seals damaged, seal kit required. Reassemble pump, clean work area
03.03.20 3314hrs	CQ Diesel Moranbah – swap fittings from u/s valve onto new valve, install and test, brake fault repaired.
05.03.20 3318hrs	CQ Diesel Moranbah – investigate engine light on and limp mode, clean out MAF sensor, start engine, no engine light on or limp mode
08.03.20 3320hrs	CQ Diesel Moranbah – adjust Gov air pressure to correct specs, repair air leak at tank, check and clean ABS plugs and sensors, re-set ABS light, run up and road test for engine derate fault, no fault codes or derate fault
14.03.20	CQ Diesel Moranbah – drain waste oil, fill 50w oil, grease front end of truck, repair oil leaks at e-vac pump and engine oil reel
17.03.20	CQ Diesel Moranbah – strip down bulk grease pump, re-kit air side of pump, 2 seals missing, ordered new seals
22.03.20 4546hrs	CQ Diesel Moranbah – fit grease pump, test, okay
06.04.20 4551hrs	CQ Diesel Moranbah – carry out off-hire inspection

07.02.20 57774km	CQ Diesel Moranbah – remove unnecessary items in cab, give cab a clean, clean and drain oil in oil cabinet, hose off rood of truck body
19.04.20	CQ Diesel Moranbah – thorough wash of truck outside and inside, service cabinets, grease tray, check for defects
22.04.20	CQ Diesel Moranbah – detail in cab of truck, clean windows
26.06.20	CQ Diesel –check over truck, clean nozzle and wiper blade, replace fire extinguisher, repair straps on door arm stopper, refit rear chevrons
29.06.20	CQ Diesel – remove waste oil, remove diaphragm pump, reseal, place back in and test
30.06.20 3342hrs 250hr service	CQ Diesel – carry out 250hr service, engine / transmission. Replace interior light assembly, plated rear toolbox left-hand and right-hand. Place 3 x new pieces on. Filled with diesel.
14.10.20	CQ Diesel – carry out off-hire inspection
15.10.20	ACES – replace all top deck ducting. Change reverse camera to accessories and change work light. Tested
16.10.20	ACES – inspect air conditioning system on service truck. Found air conditioning unit working as normal.
16.10.20	CQ Diesel – carry out service, repair both roller doors, drain and flush ad-blue tank
17.10.20	Remove stickers
19.10.20	Place reflective tape on, paint behind call sign. Replace chain for rear toolbox, tube up hinges
20.10.20	Remove call sign stickers
20.10.20	CQ Diesel – weld handrails, repair rear step lock, repair rear handrail
21.10.20	Paint rear call sign sticker placement. Place call sign sticker on, replace pos 9/10 tyre
21.10.20	CQ Diesel – repair handrails, fit chevrons / replace rear chevrons, carry out service, fit/replace power steering reservoir, fit new fan belts
21.10.20 3748hrs 500hr service	B Inman – carry out 500-hour service and inspection
21.10.2020 3747hrs	Flush out oil/water/ add blue tanks, replace electrical conduit on top of body, replace missing steering stop, replace damaged call

	signs, replace led lights in diesel compartment, replace front hub cap and oil, replaced high lights, replaced battery in engine oil counter, freed up toolbox doors. Full wash and detail and pre-hire conducted.
22.10.20	Repair bulk grease pump
22.10.20	CQ Diesel – fit gate latch
09.12.20	CQ Diesel – carry out off-hire inspection and report
16.12.20	CQ Diesel – fabricate bracket for step extension, secure ultra coax, paint step bracket, repair door latch, repair door stopper, remove and wash seat cover, seal bulk tank sander, fit new fuel cap, repair gate and latch on walkway
17.12.20	CQ Diesel – refit seat cover, connect laptop to connect to ABS, unable to fault. Remove broken section of diff breather, fabricate plates for grease pod
18.12.20	CQ Diesel – remove grease pod, weld in plates, weld up cracks in floor, refit grease pod and secure, fit new diff breather, secure electrical harness
18.12.20 63081km	ACES – inspect fault with ABS. connect scan tool, carry out tests, could not fault. Remove and replace faulty condenser, test operation
11.01.21	Complete off-hire inspection
12.01.21	Full wash and detail. Pre hire inspection completed.
13.01.21	Remove mine radio for programming
14.01.21 5125hrs	CQ Diesel – cover compressor lifting lug, repair mirror drives, loose seat belt return (rear slide loose), change out pump air valve
15.01.21 5125hrs	CQ Diesel – fabricate and fit new grease pump. Fit stickers and repair handrail
17.01.21	CQ Diesel Moranbah – unload machine from transport
18.01.21	CQ Diesel Moranbah – check over machine, BHP hire inspection, clean cab, install mine radio
19.01.21	CQ Diesel Moranbah – remove and paint front recovery hook. Remove leaking hydraulic hose on reel. Replace left-hand head light.
20.01.21	CQ Diesel Moranbah – replace flashing light.
31.01.21	CQ Diesel Moranbah – replace damaged e-stop

18.02.21 3855hrs	CQ Diesel Moranbah – inspect and measure up fittings for ad-blue. Assemble fittings to pump ad-blue into truck. Repair leaking fuel hose for HV gun
19.02.21 3861hrs	CQ Diesel Moranbah – set up pumps to adapt to truck, fill engine, hydraulic and gear oils
20.02.21 5177hrs	CQ Diesel Moranbah – replace battery isolator
24.02.21 3871hrs	CQ Diesel Moranbah – remove and replace u/s fuel hose from pump to reel. Replace grease hose and grease air fitting. Change out start isolator.
08.03.21	CQ Diesel Moranbah – inspect bulk fuel gauge
09.03.21	CQ Diesel Moranbah – BMA compliance inspection and brake test
11.03.21 3959hrs	CQ Diesel Moranbah – repair grease gun handle, repair leak on fittings on LV fuel hose
20.03.21 5369hrs	CQ Diesel – Replace bolt small hose reel rollers
25.03.21	CQ Diesel Moranbah – fill tank and clean
27.03.21 4054hrs 1000hr service	CQ Diesel Moranbah – carry out 1000-hour service and inspection.
30.03.21 4068hrs	CQ Diesel Moranbah – change transmission oil and filters. Grease truck.
31.03.21	CQ Diesel Moranbah – replace Wiggins gun and bulk fuel sender
09.04.21	CQ Diesel Moranbah – carry out brake test
13.04.21	AC03 1618hrs. CQ Diesel Moranbah -Fill and bleed compressor fuel system
08.05.21	Repair damaged low volume grease hand piece
14.05.21	CQ Diesel Moranbah – put tap on bulk fuel cavity.
19.05.21	CQ Diesel Moranbah – empty waste oil tank fill 44 50w and load filters parts and oils for ADANI machine services and repairs.
26.05.21	CQ Diesel Moranbah – Replace blown head light globe. Replace damaged grease gun swivel. Inspect reported worn steer tyres.
11.06.21	CQ Diesel Moranbah – put 400lt engine oil into truck put 600lt 50W into truck and empty waste oil tank.
16.06.21	CQ Diesel Moranbah – drain waste, put 205lt of ND68 in to tank.
16.06.21	CQ Diesel Moranbah – take to town and fill oil, Peak Downs service

	truck fill with oil and grease deliver to Peak Downs
23.06.21 4508hrs	CA Diesel Moranbah – inspect UHF cutting in and out. Find power connection at unit damaged – new unit.
21.06.21	CQ Diesel Moranbah – brake test on site.
23.06.21	CQ Diesel Moranbah – Replace UHF unit.
28.06.21	CQ Diesel Moranbah – Pump 400L engine oil into truck, empty waste tank.
08.07.21 4607hrs	CQ Diesel Moranbah – repair air leak at fuel pump.
12.07.21	CQ Diesel Moranbah – repair air leak for serv module supply hose put 1 x 205 of 15 W 40 into truck.
15.07.21	CQ Diesel Moranbah – empty waste tank tidy wash trucks clean out toolboxes.
16.07.21 4652hrs	CQ Diesel Moranbah – Jack and steer Pos 1 wheel
17.07.21 4652hrs	CQ Diesel Moranbah – wait for BHP tyre fitter, remove Pos 1 Steer tyre run tyre into Moranbah to be replaced BHP tyre fitter installed POS 1 Wheel.
18.07.21 4656hrs 500hr service	CQ Diesel Moranbah- carry out 500 hr service.
21.07.21	CQ Diesel Moranbah – inspect and repair leak on AD blue.
06.08.21	CQ Diesel Moranbah – fill with 2 x 4l of 15W40 and 1 x 4 l HD68 replaced faulty batteries.
05.08.21 4771hrs	CQ Diesel Moranbah – repair air leaks in service body.
02.09.21	CQ Diesel Moranbah – repair leak on service truck.
14.09.21	CQ Diesel Moranbah – repair air leak in service body.
19.09.21	Change bulk fuel handle.
08.11.21	CQ Diesel Moranbah – replace blown headlight bulb.
09.11.21	CQ Diesel Moranbah – service compressor.
20.11.21 5450hrs	CQ Diesel Moranbah – replace damaged air fitting on bulk grease pump
05.12.21 5524hrs	CQ Diesel Moranbah – AdBlue and water diaphragm pump not pumping. Strip, lubricate and reassemble. Test operation.
06.01.22	ASG Diesel - investigate diesel leak and air leaks, clean diesel leak

08.01.22 500hr service	ASG Diesel - start service
11.01.22	ASG Diesel – repair air and oil leaks in service module. Fill oils. Service air compressor and C/O truck, begin cleaning up.
12.01.22	ASG Diesel - Finish service
21.01.22	ASG Diesel – begin washing truck, clean, grease and oil from service module.
24.01.22	ASG Diesel – disassemble dash, clean out blocked evaporator. Fix air leaks in fuel bay and oil leaks, run new air lines to oil pumps, clean out wash fuel and oil reel bags, wash and scrub cab
26.01.22	ASG Diesel - detail cab, remove pos 3 + 4 wheels remove tyres from rims.
03.02.22	ASG Diesel – fit new tyres to pos 3, 4, 5 and 6. Jack up rear diff.
07.02.22	ASG Diesel – wash and detail truck. Fabricate new mounting plates for rear tray to chassis mounts. Repair handrails. Weld cracked mounts.
08.02.22 5583hrs	ASG Diesel – compliance and brake test.
10.02.22	ASG Diesel – replace blown air lines
18.02.22	ASG Diesel – blow out cab filters, repair and re-run water and hydraulic oil ½” hose
20.02.22	ASG Diesel – repair broken spring on high pressure hose reel
07.03.22	ASG Diesel – investigate air leak from underneath. Pos 3 booster air line leaking, grease truck.
10.03.22	ASG Diesel – repair air leak on pos 3 booster hose.
11.03.22	ASG Diesel – check start fault, check E stop and cab tilt circuits, check fuses and relay. Found and repaired corroded earth.
16.03.22	ASG Diesel – adjust brakes for brake test.
25.03.22	ASG Diesel – inspect and repair damage to access step.
03.04.22	ASG Diesel – resecure broken right hand side cab step.
04.04.22	ASG Diesel – investigate truck not starting. Operator didn’t put cab down properly.
17.04.22	ASG Diesel – inspect faulty air/hydraulic oil pump fault. Dismantle and clean, lube and re assemble.

21.04.22	ASG Diesel – inspect and repair blocked e-vac pump. Pulled apart and cleaned.
12.05.22	ASG Diesel – pump 205l hydraulic oil onto truck.
15.05.22 7870hrs	ASG Diesel – remove right hand sidestep.
16.05.22	ASG Diesel – fit right hand step, fit hydraulic push lock fitting. Run new airline.
24.05.22 6110hrs 6000hr Service	ASG Diesel – carry out 6000hr service and inspection. Repair trans cooler mount. Replaced broken bolts, remove and weld up toolbox mounts. Repair faulty cab tilt switch wires.
07.06.22	ASG Diesel – repair driver’s seat rails/adjustment,
11.06.22	ASG Diesel – replace air hose and add blue pump.
17.06.22	ASG Diesel – inspect and diagnose fault, EGR circuit fault. Check and swap out solenoids, remove and check EGR valves, clean and test, check harness and plugs.
20.06.22 6280HRS	ASG Diesel – EGR engine faults open and inspect harness, test plugs to pins and flex points in harness between fuel reel runs.
7. 7. 22	ASG Diesel - service compressor, repair fault with left hand headlight. Flickering and dull wash down truck.
12.9.22	Grease unit. Remove diesel hose reels. De grease and wash unit.
13.9.22	Remove hoses. Change wiper blades. Find crack in fuel tank. Fit fittings to pressurise tank.
15.9.22	Fit and fabricate rear reflectors. Remove mud guards. Fill tank with water.
14.9.22	Replace oil hoses. Jump start machine. Fabricate panels. Investigate fuel tank leak. Investigate and repair brake lines to pos 6 wheel, repair reversing camera, remove and replace sight tube on tanks, remove and replace waste oil pump.
15.09.22	Remove and replace air lines.
16.09.22 250HR Service 3682hrs	Carry out 250hr service
16.09.22 Service Compressor	Service compressor
19.09.22	Fabricate and paint wheel chock mounts, fit belts and compressor wheel, fit covers and doors, remove and replace seat height control valve.

20.09.22	Inspect tank for cracks, vac banded area and inspect for cracks.
29.09.22	Investigate low power issue, found turbo to be u/s – ordered new turbo
06.10.22	Prime and paint diesel tank, fit hose reels to machine.
07.10.22	Fit covers and hatch to fuel tank.
11.10.22	Remove and replace turbo – test and run ok.
06.12.22	Full wash and detail
12.12.22	Luke – ASG Diesel – Obtain operators manual for compressor, stand up aerials, fit tare stickers
6.3.23	ASG Diesel – Remove and replace U/S exhaust brake assembly. Replace Wiggins breather.
12.4.23	ASG Diesel – Drain waste oil tank. Fill engine, hydraulic and gear oil tanks. Clean down truck. Empty out LVBBXSH.
17.8.23 84915kms	Replace 2" fuel receiver with light rated banlaw. Test operation of Wiggins fill into tank. Replace out of date first aid kit. Fit orange flashing light. Fit wheel nut indicators. Service compressor, oil and filter. Install hose to main fuel tank breather. Wash, detail and grease machine. Carry out and complete pre hire inspection.
18.08.23	ACES – Inspect fault with starting. Carry out tests, found faulty batteries and bad connection. Fit new batteries and repair wiring. Test operation.



Service History Customer Report Equipment No. ST02

Description: SERVICE TRUCK - DIESEL

Serial No.: JALFXZ77UD7000084

Make: ISUZU

Registration: 932TZS

Model: FXR

Registration Expiry: 30/04/2026

Date	Job Number	Eng. Hours	Job Description
31/07/2024	2376	7687.00	REPLACE DRIVE TYRES
			Comment: REPLACED DRIVE TYRES.
14/10/2024	3308	8015.00	DIESEL FUEL REEL WILL NOT SELF REWIND
			Comment: REPLACED FAULTY SOCKET (DELIVERY ELBOW TO HOSE REEL).
17/01/2025	4436	8116.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 16.01.25
			Comment: COMPLETED OFF HIRE INSPECTION. REPAIRED TOOLBOX LID. REPLACED FIRST AID KIT. REPLACED PRE-START BOOK. REPAIRED CLEARANCE LIGHT NOT WORKING. REPLACED AG STICKERS ON DOORS THAT WERE PEELING AND FADED. REPLACED REFLECTIVE TAPE ON CAB THAT WAS FADED INCLUDING LHR/RHF OF TRAY. REPLACED MISSING WHEEL NUT INDICATOR ON LHF WHEEL. REPAIRED D/S SEAT CUSHION COVER WORN THROUGH AND FOAM EXPOSED. REPLACED RHF PARK LIGHT. REPLACED EXHAUST WRAP MISSING FROM PIPE. REPLACED LATCH MISSING FROM ACCESS GATE. REPLACED BROKEN / RUSTED HANDRAIL BOLTS FOR ACCESS STEPS TO TOP TANK. CLEANED DIRT BEHIND TAILLIGHTS LENS LED SEAL LIGHTS. REPLACED BROKEN POP RIVETS ON REAR MARKER PLATE. REPAIRED EXPOSED WIRE ON QUICK FILL HOSE. REPLACED WORKING HEIGHT STICKER. REPAIRED WASHER ON RH WIPER. REPLACED JUMP START STICKER ON COMPRESSOR, AND BATTERY AND START ISOLATOR STICKERS. INSPECTED TYRE PRESSURES. REPLACED MISSING KEY FOR LOCK ON COMPRESSOR DOOR. REPAIRED CRACK IN FLOOR AROUND COMPRESSOR. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION. ACES TECHNICIAN INSPECTED ABS FAULT. REPAIRED BAD CONNECTIONS AT MODULE. CLEARED CODES. ACES TECHNICIAN CARRIED OUT FURTHER TESTING ON ABS SYSTEM. FOUND FAULT ON RH FRONT ACTIVE AFTER ISOLATING. FOUND FAULTY WIRING IN HARNESS. RAN NEW WIRES TO WHEEL SPEED SENSOR AND TESTED.



Service History Customer Report Equipment No. ST02

Description: SERVICE TRUCK - DIESEL

Serial No.: JALFXZ77UD7000084

Make: ISUZU

Registration: 932TZS

Model: FXR

Registration Expiry: 30/04/2026

			CARRIED OUT TESTS ON TURBO ACTUATOR AS PER OEM TESTING PROCEDURE. FAULT WITH TURBO. TO BE REPAIRED AT A LATER DATE. REMOVED AND REPLACED COMPRESSOR SAFETY VALVE. REMOVED AND REPLACED TURBO.
17/01/2025	4437	8116.00	TRUCK IS DUE FOR 20000KM SERVICE
			Comment: CARRIED OUT 20,000KM SERVICE (B SERVICE).
17/01/2025	4438	8116.00	COMPRESSOR ON TRUCK IS DUE FOR A SERVICE
			Comment: CARRIED OUT SERVICE ON COMPRESSOR.
26/05/2025	5775	8116.00	BMA Compliance Spec
			Comment: BMA COMPLIANCE SPEC COMPLETED
30/05/2025	5919	8132.00	JUNE ON SITE REPAIRS AT PEAK DOWNS MINE
02/06/2025	5939	8132.00	Scheduled Service Job. COMPLIANCE BMA INSPECTION AND BRAKE TEST
			Comment: CENTRAL QLD COMPLIANCING COMPLETED 12 MONTHLY BMA COMPLIANCE AND 6 MONTHLY BRAKE TEST INCLUDING 12 MONTHLY COMPLIANCE ON COMPRESSOR.
30/06/2025	6337	8132.00	JULY ON SITE REPAIRS AT PEAK DOWNS MINE
			Comment: JULY REPAIRS INCLUDED - INVESTIGATING & REPAIRING FUEL LEAK / INSPECT POS 6 INNER FLAT TYRE
12/08/2025	6848	8244.00	DEFECT REPAIRS IDENTIFIED ON OFF HIRE 12.8.25 / 250HR SERVICE COMPLETED
			Comment: COMPLETED OFF HIRE INSPECTION REPLACED FUEL TANK (SERVICE TANK) REPAIRED DRAINS IN FUEL CABINET REPLACED MISSING FUEL NOZZLE REPAIRED MACNAUGHT FUEL GAUGE MOUNTED HOSE IN OTHER SPOT, STOPPED RUBBING IN FUEL CABINET REPLACED MISSING BOLT ON FUEL HOSE REEL SWIVEL REPAIRED BULK GREASE HOSE LEAK REPAIRED LEAKING WIGGINS FITTINGS IN OIL CABINET REPLACED BROKEN COOLANT/ADBLUE HOSE NOZZLES REPLACED BROKEN LATCH ON SAFETY RAIL GATE TREATED RUST SPOTS ON TOP OF BULK FUEL TANK FIRE EXTINGUISHERS REPLACED REPLACED COMPRESSOR ENGINE OIL LEAK FROM VALVE COVER REPLACED COMPRESSOR BAT AND START ISOLATOR INVESTIGATED & RECTIFIED COMPRESSOR HARD TO START TOPPED UP TRUCK ENGINE OIL



Service History Customer Report Equipment No. ST02

Description: SERVICE TRUCK - DIESEL

Serial No.: JALFXZ77UD7000084

Make: ISUZU

Registration: 932TZS

Model: FXR

Registration Expiry: 30/04/2026

			TOPPED UP TRUCK COOLANT AM/FM RADIO REPAIRED RECTIFIED ABS LIGHT ON DASH WASHED, DETAILED AND GREASED MACHINE COMPLETED ON HIRE INSPECTION 250HR SERVICE COMPLETED 21.08.25
24/10/2025	8315	8244.00	Scheduled Service Job. COMPLIANCEBRAKE 3MONTHLY
29/10/2025	8361	8244.00	DECOMMISSION