

## Service History Customer Report Equipment No. EXC31

**Description:** 34T EXCAVATOR - DIESEL **Serial No.:** KMTPC247CJC081706

Make: KOMATSU Registration: 78227C

Model: PC300LC-8MO Registration Expiry: 30/09/2026

Date	Job Number	Eng. Hours	Job Description
15/04/2024	323	5006.00	Clean out Blocked Grease Nipples
			<b>Comment:</b> Grease nipples on bucket blocked - Used porta power to unblock grease nipples.
21/05/2024	579	5006.00	Scheduled Service - Inspection Initiated Service job COMPLIANCEFIRESUPPRESSION 5Y CYLINDER AND FIRE EXT
31/05/2024	655	5006.00	Repair Cab Pressuriser Monitor
			<b>Comment:</b> Made new bracket for cab pressuriser. Installed cab pressuriser monitor and ran wiring to suit.
29/06/2024	982	5006.00	Adani Spec Machine
			Comment: 04.07.24 Prepped and painted walkway gate that was removed for additional 9kg fire extinguisher bracket to be fitted. Refit walkway gate.  11.07.24 Removed panels from centre console. Installed seat belt and begin running harness for seatbelt alarm.  12.07.24 Finished running wiring harness and installed seatbelt alarm. Reinstalled all cab panels.
05/07/2024	1029	5006.00	Repair GPS Brackets
			Comment: REPAIRED GPS BRACKETS.
22/07/2024	2203	5006.00	Machine Wash and Detail/Pre Hire Inspection
			<b>Comment:</b> 05.07.24 Completed full wash and detail on machine. 05.07.24 Fit GPS sensors and brackets to bucket. Welded repair bucket hardware. Prepped machine with GP Bucket and Ripper for transport. 14.07.24 Removed walkway gate and cut off fire extinguisher bracket - Prepped and primed gate ready for painting. 15.07.24 - Applied rear call sign to machine. Painted walkway gate and fit back to machine as well as fire extinguisher and bracket. 16.07.24 Removed mine radio and detailed cab. Reinstalled mine radio and completed on hire inspection.
29/07/2024	2333	5006.00	Fit New Bucket Teeth to 750mm Bucket heading to Adani
			Comment: FIT NEW BUCKET TEETH.
01/08/2024	2394	5006.00	REPLACE BROKEN QUICK HITCH SWITCH
			Comment: REPLACED BROKEN QUICK HITCH SWITCH.
17/09/2024	2993	5173.00	DEFECTS FROM OFF HIRE INSPECTION 09.09.24
			Comment: COMPLETED OFF HIRE INSPECTION. RECTIFIED QUICK HITCH CYLINDER LEAKING. CUT TAILS OFF ZIP TIES ON LHS OF STICK.

Date/Time Printed:10/11/2025 10:07 AM



## Service History Customer Report Equipment No. EXC31

**Description:** 34T EXCAVATOR - DIESEL **Serial No.:** KMTPC247CJC081706

Make: KOMATSU Registration: 78227C

Model: PC300LC-8MO Registration Expiry: 30/09/2026

Model: PC300LC-8MO			Registration Expiry: 30/09/2026	
			MOVED RETURN LINE AND TEE INTO DIFFERENT SPOT. REPLACED LEAKING BOTTOM SEAL ON AUTO LUBE CANISTER. RECTIFIED FUEL LEAK ON ENGINE - WASHED AND RAN ENGINE TO IDENTIFY SOURCE OF LEAK. REPLACED LEAKING QUICK HITCH LINES ON BOOM. REPLACED LEAKING PRESSURE RELIEF RADIATOR CAP (MANSAFE CAP - GLADSTONE RADIATORS). REPLACED MISSING GROUSER BOLTS AND NUTS ON LH AND RH TRACKS. ADJUSTED SHIMS ON CENTRE PIN ON TILT BUCKET. TENSIONED LOOSE BOLTS/NUTS ON CUTTING EDGE. CONFIRMED PARTS TO RECTIFY MOVEMENT IN BOTTOM PIN ON HLINK. REPAIRED PANEL DAMAGE BENEATH CAB. REMOVED DENTED BELLY GUARD COVERS, STRAIGHTENED AND REINSTATED. PREPARED SURFACE COUNTERWEIGHT AND REPAINTED. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.	
16/12/2024	4194	5224.00	DEFECT REPAIRS FROM OFF HIRE 16/12/24	
20/12/2024	4262	5224.00	Comment: COMPLETED OFF HIRE INSPECTION.  REPLACED MISSING CAPS OFF ROCK BREAKER PIPE VALVES.  REPLACED MISSING STICK GPS SENSOR.  CHECKED AND CLEANED CRANK CASE BREATHER.  REPAIRED DAMAGED PAINT ON COUNTERWEIGHT AND FIT STICKERS.  REPLACED MISSING BOLTS ON HYDRAULIC TANK COVER.  REPLACED SCREWS IN RH ARM REST.  REPAIRED WORKLIGHT BEHIND CABIN NOT WORKING.  REPLACED MANSAFE RADIATOR CAP.  DMS FIRE TECHNICIAN COMPLETED 6 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES 17/12/24 (LABOUR CHARGED TO SERVICE JOB 4262).  SITEC PERFORMED HEALTH CHECK AND MEASURED UP ON SITEC EQUIPMENT.  CHANGED OUT 9KG FIRE EXTINGUISHERS TO 4.5KG.  REPLACED MISSING O-RING ON BOTTOM H-LINK PIN.  REPLACED FRONT WINDOW SEAL.  FIT REFLECTIVE TAPE TO ACCESS STEPS.  REMOVED RUST FROM RADIATOR BOTTOM SUPPORT AND PAINTED.  PREPARED AND PAINTED MIRROR BRACKET AND RH REAR DOOR.  WASHED, DETAILED AND GREASED MACHINE.  COMPLETED ON HIRE INSPECTION.  Scheduled Service Job. COMPLIANCE FIRE SUPPRESSION6M AND FIRE	
LU/ 12/2024	7202	JLLT.00	SCHEGATER SERVICE JOD. CONTILLIAINCE LINE SOFF NESSIONOWI AND FINE	



## Service History Customer Report Equipment No. EXC31

**Description:** 34T EXCAVATOR - DIESEL **Serial No.:** KMTPC247CJC081706

Make: KOMATSU Registration: 78227C

Model: PC300LC-8MO Registration Expiry: 30/09/2026

Model: PC30	ULC-OIVIO		Registration Expiry: 30/09/2026
			EXTINGUISHE
			<b>Comment:</b> DMS FIRE TECHNICIAN COMPLETED 6 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES.
05/03/2025	4924	5224.00	Scheduled Service Job. COMPLIANCE BMA INSPECTION AND BRAKE TEST
			<b>Comment:</b> CENTRAL QLD COMPLIANCING COMPLETED 12 MONTHLY BMA COMPLIANCE AND 6 MONTHLY BRAKE TEST.
30/04/2025	5429	5256.00	APRIL ON SITE REPAIRS AT PEAK DOWNS MINE
06/05/2025	5456	5355.00	MAY ON SITE REPAIRS AT PEAK DOWNS MINE
22/05/2025	5729	5355.00	RECTIFY BREAKDOWN ISSUES (SPOOL AND VALVE BODY ISSUE)
			Comment: REMOVE BUCKET CYLINDER HOSES AND IDENTIFIED INTERNAL HOSE FAILURE. REMOVED HOSES AND BUCKET CYLINDER, CLEANED OUT AND RESEALED BUCKET CYLINDER. REMOVED MAIN CONTROL VALVE AND REMOVED ALL SPOOL VALVES CLEANED AND FLUSHED OUT CIRCUITS. INSTALLED SPOOL VALVES AND REPLACED ALL EXTERNAL SEALS ON MAIN CONTROL VALVE. DRAINED HYDRAULIC TANK AND REMOVED ALL CONTAMINATES FROM INSIDE OF HYD TANK. REMOVED ALL HYDRAULIC FILTERS AND REPLACED WIITH NEW FILTERS. REFILLED HYDRAULIC TANK AND TESTED OPERATIONS. RETURNED MACHINE TO SERVICE
30/05/2025	5866	5404.00	DEFECTS FROM OFF HIRE INSPECTION 29/05/25
			<b>Comment:</b> COMPLETED OFF HIRE INSPECTION. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
04/11/2025	8500	5404.00	DECOMMISION AND MAKE READY FOR SALE
			Comment: MACHINE DECOMMISSIONED READY FOR SALE.  - REMOVED ALL AG STICKERS & CALL SIGNS - REMOVED MINE RADIO & INSTALL KIT REMOVED DRIVER MONITOR CAMERA & HARDWARE ALL AG DOCUMENTATION & FIRST AID TAKEN OUT OF CABIN WASHED, DETAILED & GREASED MACHINE.