8/14/25, 9:03 AM **HEM Data Dashboard**



2011 International PayStar 5900i

Test Information

Engine Cummins Signature 600 ISX AHD (15.0)

Engine Serial CMMNS*6X3u07D1500000000*79396349*000000000

> VIN <u>1HSXYAPT5BJ266941</u>

Driveline Class 8 6x4

Body Truck-Tractor MDHD: Conventional

Test Time July 28, 2025, 9:08 a.m.

File Length 34.025 s

Usage

Label	Value	Units
Engine Odometer	499,270	mi
Engine Total Hours of Operation	19,692.8	h

Engine On/Off

Engine running

Check Engine Light



Amber Warning Lamp - Warning, but OK to drive

8/14/25, 9:03 AM HEM Data Dashboard

Emissions Deleted/Tampered

No

Faults Controller Name DM **SPN Name FMI Name** Count 126 Engine #1 Engine Coolant Level 1 Low-moderate severity Active Brakes - System Controller Wheel Sensor ABS Axle 2 Left 127 Not Responding Properly Active Previous Engine #1 Engine Coolant Level 1 Low-least severe 24 Erratic, Intermittent, or Incorrect Previous Engine #1 ECU Power Output Supply Voltage #1 Previous Engine #1 Engine Exhaust Gas Recirculation 1 Temperature Voltage Above Normal 1 Previous Engine #1 Engine Exhaust Gas Recirculation 1 Differential Pressure High-moderate severity 1 Engine Turbocharger 1 Calculated Turbine Intake Temperature 3 Previous Engine #1 High-least severe Engine Variable Geometry Turbocharger Actuator #1 Previous Engine #1 Not Responding Properly Engine #1 **Engine Speed** High-most severe Previous Previous Engine #1 Engine Turbocharger 1 Compressor Intake Temperature Voltage Above Normal Previous Engine #1 **Engine Coolant Temperature** Condition Exists Brakes - System Controller J1939 Network #1. Primary Vehicle Network Previous Special Instruction Brakes - System Controller Wheel Sensor ABS Axle 2 Left Not Responding Properly Previous 1