

Plant History

Model: Volvo A45G Serial No: VCE0A45GH00322545

Date/Hours	Description
08.03.20	Machine delivered from Melbourne.
09.03.20	Inspect machine. Pick up number plates from department of transport.
10.03.20 - 3hrs	CQ Diesel – remove step assembly to move fire suppression button, place front / rear number plates on, place truck on trailer
10.03.20	Fit fire extinguishers, AG Stickers to machine. Pre hire inspection completed, check all oil levels – ok.
24.03.20	CQ Diesel – change out quick / high flow grease fitting out of bulk grease to grease nipple
01.04.20 - 334hrs	CQ Diesel – found seat belt twisted, repaired, tested okay
15.07.20	CQ Diesel – carry out service as per service sheet
16.07.20	CQ Diesel – replace aircon vent
14.08.20	DMS Fire – find muster system had discharged, found button in cab had been pressed to set off system, refilled cylinder and re-gassed the system, refit battery to fire panel, reset fire panel
22.09.20 - 2024hrs 2000hr service	CQ Diesel – carry out 2000-hour service
12.10.20	CQ Diesel – remove beacon and middle bracket
16.10.20 - 2043hrs	CQ Diesel – fabricate handrails
19.10.20	CQ Diesel – fabricate handrails
20.10.20	CQ Diesel – paint and fit handrails
22.10.20	CQ Diesel – extend revolving light, fabricate kick plate, paint triangles and kick plates
23.10.20	CQ Diesel – fit kick plates, fit triangle mounts, inspect machine.

Full wash and detail, Pre-hire conducted.
CQ Diesel – fit call sign, fit call triangle
Heavy Duty Welding – handrail repairs
DMS – 6 monthly fire suppression service
CQ Diesel – paint tail gate
eq bieser punit tan gate
CQ Diesel – paint tail gate, fit wheel nut indicators, carry out pre- hire inspection, polish reverse camera lens
CQ Diesel – continue painting tail gate
CQ Diesel – fit pos 1 tyre
ACES – remove and replace faulty Anderson plug. Test operation, check over electrics.
ACES – mount and wire up hand brake door alarm. Tested – okay
Prep trailer and pick parts for service.
Carried out 500hr service onsite. Check over machine, travel back to workshop clean trailer and evac waste oil.
Full wash and detail. Pre hire inspection completed.
Inspect on hire paperwork
B Inman - Check over.
ASG Diesel – inspect machine, top up coolant top up auto greaser.
ASG Diesel - inspect transmission leak, filters loose.
ASG Diesel investigate a/c fault glow out filters reset aircon test ok
ASG Diesel – repair dinted belly guards remove belly guards straighten.
ASG Diesel – investigate park brake fault seat sensor.
ASG Diesel – remove park brake coil from truck to get AT 456 off ramp. Fit P/brake coil back to truck.
ASG Diesel – carry out 1000 hr service.

13.11.21	ASG Diesel – investigate reverse camera not working
15.12.21	Carry out return hire inspection.
30.12.21	DMS Fire Services – carried out 6 monthly fire suppression service
10.02.22	Heavy Duty Welding – cut and move handrail and kick plate to clear door opening
01.03.22	place manifold guards back on
01.03.22	Aces – fit and wire up cab pressuriser system. Changed over beacon to green. Check over electrics. Horn and mine radio need to be fitted.
02.03.22	Anti-burst protection done manifold guards done
01.07.22	DMS Fire – Carry out fire suppression service.
29.7.22	ASG Diesel - wash machine repaired leaking hydraulic hose under hydraulic tank, adjusted fitting on fuel pressure side, fitted hose wrap to two airlines as rubbed through, hand rails loose and adjusted. Found starter isolator seized and replaced, clean cab.
11.8.22 - 3812hrs	ASG Diesel – Drill holes to fit strobe light. Fit light.
19.9.22	ASG Diesel - inspect E stop fault repair join in wiring for offside aftermarket E stop
13.10.22	ASG Diesel – check rough suspension ride, adjust tyre pressure from 75psi to 55/60psi.
18.10.22 – 4022 hrs <u>4000hr service</u>	4000hr service completed. Rear tyres getting low. Small damage to left steer tyre.
16.10.22	Heavy Maintenance – repair auto grease fault. Purge lines.
6.1.23	Heavy Maintenance – Diagnose and repair tray body not down fault. Inspect and repair auto grease fault. Top up grease cannister.
20.01.23	DMS Fire Services – carry out fire suppression service
30.3.23	ASG Diesel – Complete BMA compliance inspection.
3.4.23	Heavy Maintenance – Carry out general machine inspection and check fluids.
10.04.23	Earthmover Tyre Service – change out pos 5 tyre
16.4.23 - 4453 hrs 500 hr Service	Heavy maintenance – carry out 500hr service.
12.05.23 - 4569hrs	Heavy Maintenance – reseal all glass joins with Sikaflex

30.05.23 - 4606hrs	Heavy Maintenance – fluid check and machine check over. Clean and unblock washer jets
16.06.23	ASG Diesel – inspect tray lever not working.
18.06.23	ASG Diesel – investigate body sensor fault. Calibrate body sensor. Unable to calibrate weight scales – faulty.
20.06.23	DMS Fire – carry out 12 monthly fire suppression service
27.06.23 - 4757hrs	Heavy Maintenance – fluid check and machine check over. Remove and replace left hand bulb
29.06.23	ASG Diesel – inspect body position fault. Continuous faulting. Remove and clean sensor. Adjust mount. Recalibrate and run up.
03.08.23	Compliance and brake test.
08.08.23 - 4946hrs	Heavy Maintenance – fluid check and machine check over.
23.08.23 - 5039hrs 1000 Hr Service	ASG Diesel – Complete 1000 hr service and noted the truck scales are showing 57 tonnes continuously. 5039 hr – 1000hr service and inspection.
30.08.23	ASG – Check over trucks organise transport back to Moranbah for clean and repairs.
01.09.23 - 5042 hrs	ASG Diesel - Investigate load cell and body position fault, 5042 hrs: Carry on with prosis diagnosis, test wiring
02.09.23 - 5042hrs	Heavy Maintenace - Identify and repair fault with load sensors and body fault intermittently appearing, repairs new Pos 6 loaded cell. ASG – 5042hrs, carry on with prosis diagnosis, test wiring from ECM to all plugs, check voltage from ECM and down to both sensors and position sensor.
03.09.23 - 5042hrs	Heavy Maintenance – 5042hrs, Remove and replace load call with AT455 to confirm load cell at fault, Change load cell back to original machine, clean exterior, and interior of machine. ASG – 5042hrs, Swap load cells with AT455 and test operation, fault transferred, carry out off hire, wash machine and detail cab.
04.09.23	Heavy Maintenance – Install mine radio, install green beacon, repair cab pressuriser monitor wiring.
06.09.23	Heavy Maintenance – 5042hrs, Remove and replace Pos 6 load cell, calibrate weight.
07.09.23 - 5043hrs	ASG – 5043hrs, cleaned cab checked radio channels for south walker, prestart book, first aid kit, replaced Anderson plug jump start to cat spec, repairs work light out. Got parts from exceed.

08.09.23 - 5043hrs	ASG – Sorted tyres for tyre fitter and moved around machine for
	fitter to access. 5043hrs.
08.11.23 - 5286hrs 500 Hr Service	CPH fitters completed 500 hr service. Service was completed early at 250 hrs will get another 500 hr service when due.
03.02.24 - 5570 hrs <u>500 Hr Service</u>	CPH fitters completed 500 hr service at Blackwater Mine.
03.02.24 - 5720hrs	Replace interior cab light assembly. Switch damaged. Replace missing ash tray cover, fill grease, replace first aid kit, fit BMA compliance access steps, replace broken tail gate rope, replace damaged call signs — 1x triangle, 1x rear chassis and 2x tray call signs. Replace safety decals. Prepare surfaces and paint tray and rims. Wash, detail and grease machine. Carry out and complete pre hire inspection.
07.03.24	Carried out pre hire inspection. Carried out fire suppression compliance, fire extinguisher compliance, first aid kit compliance, 6mthly break compliance, BMA compliance.
12.03.24 - 5722hrs	Full wash and detail.
21/07/2024 6043hrs	INSTALL DRIVER MONITORING CAMERA
30/07/2024 6192hrs	DEFECTS FROM OFF HIRE INSPECTION 29/07/24
30/07/2024 6192hrs	6000HR SERVICE
28/08/24 6192hrs	DMS COMPLETED 12 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICE.
22/10/24 6374hrs	Replace broken transmission filter housing
04/11/24 6426hrs	Replace Reverse Camera Cable
26/11/24 6614hrs	500hr Service
05/12/24 6634hrs	REPLACE RUSTED EXHUAST AND BODY LOCK PIN
12/02/25 6850hrs	Scheduled Service Job. 6 Monthly Fire Suppression and Extinguisher service.