



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GL39392
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21653616

Inspection Result:

PASS

FACILITY: BERK'S INTERTRUCK LTD / S5159 INSP. TYPE: Complete INSP. START: 2026-Feb-04 07:30 AM PST
INSPECTOR: SUMEN, RYAN / 300439 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more INSP. COMPLETE: 2026-Feb-04 08:30 AM PST
WORK ORDER #: 9372 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 03700988 VIN: 4V5KC9GH17N432674
PLATE #: VR5018 UNIT/FLEET#: 87 OWNER/LESSEE NAME: DOLANS CONCRETE LTD., DOLANS CONCRETE LTD.
LICENSED GVW(kg): 48500 BODY STYLE: Dump Truck ADDRESS: 4779 ROGER ST, 4779 ROGER ST
VEHICLE YEAR: 2007 ODOMETER: 655632 KM Port Alberni, British Columbia
MAKE: VOLVO HUB ODOMETER: V9Y 3Z3, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) REPLACED WORN JACKSHAFT U-JOINT
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPAIRED VARIOUS AIR LEAKS
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) TIGHTENED LOOSE PITMAN ARM
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	44.5	44.5
2	Clamp	30	Automatic	44.5	41.3
3	Clamp	30	Automatic	41.3	41.3

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	14			14	
	15	14	15	13	✓
	6	10	7	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	77	65
2	47	54
3	84	68

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	15	16
	Lining (Shoe)	17	17
	Lining (Shoe)	15	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SUMEN, RYAN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Feb-04 10:03 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQV/P at the Commercial Vehicle Safety Enforcement

CVSE0014

1/4/2026 10:03:20 AM PST