



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM53648
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21702545

Inspection Result:

PASS

FACILITY: BERK'S INTERTRUCK LTD / S5159 INSP. TYPE: Complete INSP. START: 2026-Mar-19 07:30 AM PDT
INSPECTOR: SUMEN, RYAN / 300439 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 55Q1 kg or more INSP. COMPLETE: 2026-Mar-19 08:30 AM PDT
WORK ORDER #: 9641 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14083314 VIN: 2FZHAWBS85AU15681
PLATE #: SK7552 UNIT/FLEET#: 325 OWNER/LÉSSEE NAME: DOLANS CONCRETE LTD., DOLANS CONCRETE LTD. DOLANS CONCRETE LTD.
LICENCED GVW(kg): 30845 BODY STYLE: Cement Mixer ADDRESS: 4779 ROGER ST, 4779 ROGER ST
VEHICLE YEAR: 2005 ODOMETER: 229650 KM Port Alberni, British Columbia
MAKE: STERLING HUB ODOMETER: V9Y 3Z3, Canada
MODEL: BRAKE TYPE: Air FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REPAIRED EXHAUST LEAKS,BEHIND TURBO
Section 2 - Suspension	Repaired (same day)	REPLACED CAB LEVELING ROD BUSHINGS
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIRED L/H TURN SIGNAL
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	41.3	41.3	15			15	✓
2	Clamp	30L	Automatic	38.1	38.1	13	12	12	14	
3	Clamp	30L	Automatic	38.1	41.3	23	16	17	19	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
			Lining/Pad			Rotor/Drum		
1	41	38	Lining (Shoe)	17	17	Drum		
2	67	60	Lining (Shoe)	15	16	Drum		
3	48	51	Lining (Shoe)	17	17	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: SUMEN, RYAN

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-19 01:44 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/19/2026 1:44:45 PM PDT