



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN93002
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21785920

Inspection Result:

PASS

FACILITY:	PACIFIC CROSSROAD INDUSTRIAL REPAIRS / S17080	INSP. TYPE:	Complete	INSP. START:	2026-May-26 11:30 AM PDT
INSPECTOR:	BERNSTEIN, RALPH HERBERT / 106846	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-May-26 03:22 PM PDT
WORK ORDER #:	7675	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	02062654	VIN:	1M2K197C44M024211
PLATE #:	NL0756	UNIT/FLEET#:	1	OWNER/LESSEE NAME:	Bowmark Concrete Ltd., .
LICENCED GVW(kg):	26700	BODY STYLE:	Pumper Truck	ADDRESS:	4924 Broughton Street
VEHICLE YEAR:	2004	ODOMETER:	811253 KM		Port Alberni, British Columbia
MAKE:	MACK	HUB ODOMETER:			V9Y8R6, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) Repair Right Rear Tail/Turn Signal Light Wiring, Replace Rear ID Right Outer Light, Replace Left Rear Side Marker Light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	33	35	21			21	✓
2	Clamp	30	Automatic	40	40	19	17	18	18	
3	Clamp	30	Automatic	45	40	17	17	16	24	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	44
2	72	55
3	65	81

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
1	Lining (Shoe)	18	18
2	Lining (Shoe)	14	18
3	Lining (Shoe)	16	12

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
1	Drum		
2	Drum		
3	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: BERNSTEIN, RALPH HERBERT

Road Test Date: R. Bl
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-May-26 03:23 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 215 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/26/2026 3:24:01 PM PDT