



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GL39398
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21659674

Inspection Result:
PASS

FACILITY: BERK'S INTERTRUCK LTD / S5159 INSP. TYPE: Complete INSP. START: 2026-Feb-10 07:30 AM PST
INSPECTOR: SUMEN, RYAN / 300439 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2026-Feb-10 08:30 AM PST
WORK ORDER #: 9411 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 07507026 VIN: 1FDZY82A4LVA41237
PLATE #: WV3482 UNIT/FLEET#: DC-27 OWNER/LESSEE NAME: DOLANS CONCRETE LTD., DOLANS CONCRETE LTD.
LICENCED GVW(kg): 25500 BODY STYLE: Cement Mixer ADDRESS: 4779 ROGER ST, 4779 ROGER ST
VEHICLE YEAR: 1990 ODOMETER: 337685 KM Port Alberni, British Columbia
MAKE: FORD HUB ODOMETER: V9Y 3Z3, Canada
MODEL: 2WHDR BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	SECURED EXHAUST STACK
Section 2 - Suspension	Repaired (same day)	REPLACED REAR AXLE TORQUE ROD
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	SECURED REAR AIR TANK
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Repaired (same day)	REPLACED R/H DRAG LINK
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Repaired (same day)	REPLACED R1 WHEEL SEAL
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	44.5	44.5	9			7	✓
2	Clamp	30	Automatic	41.3	44.5	18	17	13	14	
3	Clamp	30	Automatic	41.3	41.3	13	13	13	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	62	68	Lining (Shoe)	16	15	Drum		
2	40	48	Lining (Shoe)	18	18	Drum		
3	71	89	Lining (Shoe)	16	15	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SUMEN, RYAN

Signature:

This Inspection Report was submitted to CVSE on 2026-Feb-10 09:07 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

2/10/2026 9:08:00 AM PST